SCHRADER TIRE PRESSURE MONITORING SYSTEMS

SENSOR & SERVICE PACK APPLICATION CATALOG

OE REPLACEMENT

EZ-sensor®

SERVICE PACKS

Sensata Technologies

The World Depends on Sensors and Controls

SCHRADER® PERFORMANCE SENSORS

Table of Contents

TPMS Tools and Accessories ..... A - G

OEM Interchanges ..... H - I

TPMS Sensors / Transmitters & Service Packs - Alphabetical Listing..... 1 - 134

TPMS Sensors / Transmitters - Numerical Listing .....135 - 159

TPMS Service Packs - Numerical Listing ..... 160 - 180

NHTSA TREAD Act ..... Inside Back Cover

Schrader International, Inc.
Limited Warranty

Schrader Bridgeport International, Inc. ("Schrader") warrants that its products will be free from defects in materials and workmanship for a period of twelve (12) months from the date of shipment from Schrader's facility or delivery (whichever occurs first). Schrader will, at its option, replace or repair any product proved defective in materials or workmanship, or both, during the warranty period. This shall be the sole and exclusive remedy for breach of warranty. THE FOREGOING WARRANTY IS EXCLUSIVE AND IN LIEU OF ALL OTHER WARRANTIES EXCEPT THAT OF TITLE, WHETHER WRITTEN, ORAL OR IMPLIED, IN FACT OR IN LAW (INCLUDING ANY WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE). LIABILITY FOR SPECIAL, INDIRECT, INCIDENTAL, PUNITIVE OR CONSEQUENTIAL DAMAGES (INCLUDING, WITHOUT LIMITATION, DAMAGES FOR LOSS OF PROFITS, BUSINESS INTERRUPTION OR ANY OTHER LOSS), HEREBY ARE EXPRESSLY EXCLUDED TO THE EXTENT PERMITTED BY LAW, WHETHER BASED IN CONTRACT, NEGLIGENCE, TORT, WARRANTY OR OTHER WRONGFUL ACT OR OMISSION OF SELLER AND EVEN IF SELLER HAS BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.

This warranty does not extend to (a) any defects or losses due to misuse, accident, abuse, neglect, or normal wear and tear; (b) any use not recommended in writing by Schrader; (c) any defects or losses relating to or caused by purchaser or a third party; or (d) any defects or losses relating to or caused by the effects of weathering, air pollution, corrosion, or exposure to harmful/caustic materials and/or chemicals.

Additionally, Schrader can not endorse the use of non-OE validated parts. Schrader has not validated testing of the compatibility of products of any supplier other than Schrader for fit and suitability of use in conjunction with Schrader parts. Therefore, use of BOTH Schrader sensors, and Schrader service packs or replacement "snap-in" stems, are required for warranty protection.

©2012-2016, Schrader International

The statements contained in this application catalog are for informational purposes only and have not been independently verified. While the statements were believed to be accurate at the time of publication, they should not be definitively relied upon.

Nut Torque Tool with Sockets – 20138

Torque wrench for valve nuts on TPMS installations. Kit includes 12mm and 11mm sockets for the two nut sizes used today, plus screwdriver handle for easy use. Torque range from 4.25 N.m. to 7.5 N.m. Accuracy plus or minus 4 percent. Includes plastic storage case. (One per carton)

Nut Torque Wrench Kit – 20139

Torque tool and precision quality torque wrench for installing TPMS sensor nuts. Includes 12 mm and 11 mm sockets. Torque range from 2 N.m. to 10 N.m. Accuracy plus or minus 2 percent. Includes plastic storage tray. (One per carton)

T-10 Torque Tool – 20140

Installs replacement snap-in valves to Schrader® OE sensors. T-10 Torx head installs screws to recommended torque for proper sealing and secure installation. Order individually. (One per box)

Valve Core Torque Tool – 20141

Tighten valve cores to OE specifications. Helps guard against over or under-torquing. Meets Tire and Rim Association (TRA) recommended torque values of 3" to 5" lbs. on TRC1 valve cores. Serves as both a core remover and installer.
Order individually. (One per box)

Universal Nut Torque Tool – 20142

Serves as a torque wrench for valve nuts on TPMS installations. Kit includes 11mm and 12mm sockets and T-handle torque wrench with ergonomic
design. Torque range from 30 to 90 in/lbs.
(One per plastic storage case)

Replacement 11mm Socket – 21310

Order Individually.

Replacement 12mm Socket – 21315

Order Individually.

Grommet Removal Tool – 20144

This hand tool is designed to safely remove the rubber grommet from the aluminum stem of a TPMS sensor. Receiving hole can be used to install a new grommet. (10 per carton)

T-20 Torque Tool – 20145

A pre-set torque tool specially designed for use with TPMS sensors that use a T-20 screw to attach the aluminum valve stem to the sensor body. The T-20 Torx head installs screws to recommended torque for proper sealing and secure installation.

Schrader TPMS Training DVD (English) – 21355

Order Individually.

Schrader TPMS Training DVD (French) – 21356

Order Individually.

Schrader TPMS Training DVD (Spanish) – 21357

Order Individually.

Chrome Caps and Sleeves

Make your TPMS valve stems look as good as the rest of your ride with dress-up sleeves. Chrome finish dress up kits are available for rubber snap-in sensors. Each kit includes a fully plated sleeve and sealing cap to resist galvanic corrosion of TPMS sensors.

Chrome caps and sleeves for rubber snap-in sensor

22005 Order in multiples of 50.
Bulk Packaged (50 caps and 50 sleeves per carton)

Complete snap-in valve service pack with chrome caps and sleeves

22008 Individual bags. (50 bags per carton)
Each bag contains one sleeve, one cap and one TT valve. Order in multiples of 50.

Banded TPMS Replacement Parts

All of the components required to repair banded TPMS systems. These parts to be used with sensor part numbers 28385, 28390 and 28395.

Replacement Clip

22100 Order individually.
Bulk Packaged. (25 per box)

Replacement Cradle

22101 Order individually. (10 per carton)

Universal band

Fits rims 14-26"

22102 Order individually. (One per bag)

SCHRADER®

Accessory and loose part items

20055 nickel-plated valve cores – 100/box

20395 plastic sealing valve caps – 100/box

20595 long black sealing valve caps for Schrader snap-in sensors
Fits EZ-sensors 33000, 33100 & 33200, replacement sensors 20153, 20398, 28203, 28206, 28308, 28362, 28434, 28461 & 28505, and Service Pack 20008 & 20018 valves – 100/box

20695 long green (Nitrogen) sealing valve caps for snap-in sensors – 100/box

20795 green (Nitrogen) sealing valve caps – 100/box

20895 replacement T-10 screw – 25/bag

20995 long black sealing valve caps for Ford snap-in sensors
Fits EZ-sensors 33000, 33100 & 33200, replacement sensor 20315 and Service Pack 20008 & 20018 valves – 100/box

21085 black sealing valve caps
Fits EZ-sensor 33500, service pack 20046 valve and all new Schrader style snap-in OEM sensors - 100/box

TPMS Retrofit Kits

Schrader® TPMS Retrofit Kits install on vehicles not equipped with original equipment systems. The stand-alone kits include a dash-mounted receiver display, four wheel-mounted transmitters that fit most wheel applications and installation instructions.

TPMS retrofit kits:

- Continually monitor tire pressure in all four tires
- Monitor tire temperature
- Signal audible warning at under-inflation of 25 percent or more
- Capable of monitoring spare tire (Fifth sensor sold separately as part no. **20154**)

TPMS systems monitor proper tire pressure to maintain vehicle performance and support safety.

Properly inflated tires:

- Improve vehicle handling
- Reduce braking distances
- Lower the risk of hydroplaning
- Decrease tire wear
- Improve fuel efficiency

Schrader offers two kits:

- **SCH-WRK-4PC** - hard wired display
- **SCH-BRK-4PC** - battery operated display (two AA batteries included)
- **20154** – 433 MHz sensor (Fits both kits)

GM® is a registered trademark of General Motors Corporation
Subaru® is a registered trademark of Fuji Heavy Industries Ltd.
Ford® is a registered trademark of Ford Motor Company

EZ-SENSOR TOOL COMPATIBILTY

▸▸ CONTACT YOUR TOOL SUPPLIER FOR SOFTWARE UPGRADES

* Ask your tool supplier for 33500 programming capability

ATEQ	ATEQ	Bartec	Bartec	Bartec	Bartec	Bartec	Bartec	Bartec
*VT-55	VT-56	Tech200	Tech300SD	Tech300Pro	Tech400 Plus Tech400	Tech400SD	Tech400Pro	Tech500

Bartec	MAC	Matco	NAPA	OTC	Schrader	Schrader	Schrader	Snap-on	Snap-on
TPMS Pad	ET3824	TPR3834	92-1525	3834	EZ-sensor Pad	21230	EZ-programmer	TPMS2	TPMS3

EZ-sensor® PAD

Part No. 27028

- **Quick and simple** programming tool for TPMS
- **LIVE vehicle coverage updates** are available immediately after release. No tool update required.
- **Both mobile and desktop friendly** compatible with iOS, Android and Windows
- **Long battery life** 8 hours or up to 120 sensors

Learn Tools - Continued

21280CHG

The 21280CHG replaces the charger that comes standard with the Bartec Tech400Pro TPMS scan and relearn tool. It is an inductive pad charger that plugs into a standard electrical outlet. Simply place the tool on the pad to maintain a fully charged scan tool, so it's ready when you need it to be.

21285CHG

The 21285CHG replaces the charger that comes standard with the Bartec Tech300Pro TPMS scan and relearn tool. It plugs into a standard electrical outlet, and into the tool to maintain a fully charged scan tool, so it is ready when you need it to be.

Aluminum clamp-in style valve – 34000

Aluminum stem service pack to rebuild the Schrader rubber valve snap-in sensor with an aluminum clamp-in style valve stem to match or upgrade existing look.

Fits Schrader OE replacement sensor part numbers: 20153, 20315, 20398, 28203, 28206, 28308, 28434, 28461, 28362, 28505

Fits Schrader EZ-sensor part numbers: 33000, 33100, 33200, 33500

Service Pack Assortment - 20598

Schrader® offers a Service Pack Assortment that contains the most popular vehicle-specific service packs in a handy plastic box.

20598 assortment with 8 each of twelve service packs.

Contents:	Qty.
20002	8
20003	8
20004	8
20008	8
20013	8
20014	8
20020	8
20021	8
20023	8
20030	8
20032	8
20036	8

CAUTION: Always use new grommets, nuts, valve caps and valve cores when performing any tire service. Use nickel-plated electroless valve cores with aluminum valve stems and use rubber snap-in replacement stems when servicing snap-in sensors. Refer to manufacturer's specifications for proper torque requirements when replacing nuts and valve cores.

OEM INTERCHANGES

OEM Part Number	Schrader Number
0009054100	28214
0009057200	28214
0025406817	20094
0025406917	20095
0025407917	20094
0025408017	20095
0025408617	28214
0025409017	28214
0035400217	28214
0045421518	28214
06421S3VA02	28981
06421S3VA03	28981
06421S3VA04	28981
06421S9VA01	28982
06421S9VA03	28982
10394110	20158
10438853	28006
12768826	28206
13172567	28078
13172567	28078
13227143	20159
13581558	28206
13581559	20228
13581560	20223
13586335	20153
13589597	20283
13598773	20154
15114379	20107
15122618	20131
15136883	20115
15254101	20153
15268606	20158
15825475	20158
15921013	20158
15922396	20153
185189	20077
1K0907253D	20088
20922900	28206
20923680	20153
20925924	20158
20964159	28423
224549	20077
224551	20084
22853741	20153
22854866	28206
22959744	28206
24437708	28078
25758220	20076
25773946	20117
25774006	20116
25799331	20153
25920615	20153
28103AG00A	20081
28103AG01A	28203
28103AG01B	28203
28103AG01C	28203
28103SA001	28203
28103SA002	28203
28103SG000	28203
28103SG010	28203
307489910	20156
31200923	20156
31200923	28362
312009230	20156
312802970	20097
313020960	20097
36106790054	28081
36106798872	28126
36106856227	28081
36118378682	20080
36146752128	28082
36236781847	20083
36236798726	28081
40700-1A00D	28342
40700-1AA0B	28204
40700-1AA0D	28204
40700-1PA0A	28342
40700-CD001	20064
40700-CK001	20161
40700-CK002	20069
40700-JA00C	28204
40700-JA01A	28167
40700-JA01B	28204
40700-JA01C	28204
40700-JA02B	28204
40700-JK00B	28210
42508875	28129
4250A030	28129
4250A225	28096
4250B875	28129
4250B877	20034
4250B8975	28096
4260702010	28365
4260704010	28380
4260706011	28360
4260706020	28360
4260706020	28360
4260708010	28670
426070C010	28300
426070C020	28305
426070C030	28670
426070C050	28670
426070E011	28370
4260724010	28310
4260724020	28315
4260724030	28320
4260724040	28325
4260730030	28335
4260733011	28360
4260733011	28365
4260733021	28370
4260733022	28370
4260735010	28345
4260775010	28345
42607AD020	28355
42753SHJA53	28981
42753SHJA54	28981
42753SHJA82	28983
42753SNAA82	20100
42753SNAA83	28720
42753SNAA84	28720
42753STKA01	20098
42753STKA02	20098
42753STKA03	20098
42753STKA04	20098
42753SWA306	20099
42753SWA316	20099
42753TK4A01	20720
42753TL2A51	20098
42753TL2A52	20098
42753TP6A82	20100
42753TR0A81	28720
42753TR3A81	28720
42753TX4A51	28128
4313054J20	20087
4313054J21	20087
4313054J22	20087
4313078J10	20158
4313085Z00	20153
4313086Z20	20082
4321182Z10	28204
4815132	28004
4815132AB	28004
4D0907275	20077

OEM INTERCHANGES

OEM Part Number	Schrader Number
4D0907275C	20077
4D0907275D	20079
4F0907275B	20078
4F0907275D	20103
4F0907275D	20103
4F0907275H	20077
4L2Z 1A150	20096
BA 5096808AA	20028
5127335AB	20335
5142340AA	28308
52088990AC	20028
52088990AD	20028
529331FA00	28983
529331FA00	28983
529332F000	28849
529332F000	28849
529332F001	28849
529332G200	20086
529332G201	20086
529332M00	20092
529332M000	20092
529332M000	20092
529332M001	20092
529332M001	20092
529332M550	20092
529332V000	28505
529333E000	28983
529333X200	20086
529334D200	20085
52933A5000	20092
52933A5000	28849
56029319AA	28461
56029319AB	28461
56029359AA	28434
56029359AB	28434
56029398AA	20398
56029398AB	20398
56029400AB	28291
56029400AC	28291
56029400AD	28291
56029465AB	28308
56029465AC	28308
56029479AA	28308
56029479AB	28308
56029481AB	28434
56053030AB	28308
56053036AA 5L1Z	28308
1A150 AA	20135
68001696AA	28308
68001696AA	28434
68001696AB	28308
68001698AA	28434
68001698AB	28434
68006771AA	20089
68038945AA	20089
68078861AA	28308
68193586AA	28586
68193586AB	28586
6F2Z1A189A	28385
6F2Z1A189A	28385
7L1Z1A189A	28390
7P0907275	20103
7P0907275	20103
7P0907275A	20077
7PP907275F	20103
8257740060	20116
86517000	20156
88974915	28360
8973271890	20028 28395
8C2Z1A189A	
8C2Z1A189A	28395
95536105300	20077
95836166100	20103
99760602120	28087
9L3Z1A189A	20315
A0009050030	20213
BBM237140B	20093
BBM2-37-140B	20093
C2C25519	20090
C2C40476	20090
C2C40725	20091
C2S40710	20091
C2Z15016	20091
C2Z15017	20090
CM5T 1A180 AA	20315
CM5T-1A180-AA	20315
DE8T-1A180-A	20315
DE8T-1A180-AA	20315
GN3A37140B	20093
GS1D37140	20093
LR010532	20091
LR010533	20090
LR018860	20090
LR018861	20091
LR021936	20090
LR0500461	20090
MN103033	20028
MN103081	20034
RQH500471	20091
XR855949	20091
XR855950	20090
YBD000060	28082
YBD000061	28082
ZZC137140	28385
ZZDA37140	20315
ZZDA-37-140	28385

Application	Part No.	Torque in-lbs	Torque N.m.
Acura			
CSX			
2008-2011			
OE Sensor: Honda - 42753SNAA83			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28720	35	4
Service Pack	20019	35	4
2012			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
MDX, RDX			
2004-2006			
OE Sensor: Honda - 06421S3VA02			
Sensor	28981	35	4
Service Pack; Includes Valve	20036	35	4
2007-2013			
OE Sensor: Honda - 42753STKA01, 42753STKA02, 42753STKA04			
Sensor	20098	35	4
2013-2015			
OE Sensor: Honda - 42753TX4A51			
Sensor	28128	71	8
RL			
2005-2012			
OE Sensor: Honda - 06421S3VA02, 06421S3VA03, 06421S3VA04, 42753SHJA53			
Sensor	28981	35	4
Service Pack; Includes Valve	20036	35	4
RLX			
2016			
OE Sensor: Honda - 42753-TX4A51			
Sensor	28128	71	8
TL			
2005-2008			
OE Sensor: Honda - 06421S3VA02, 06421S3VA04			
Sensor	28981	35	4
Service Pack; Includes Valve	20036	35	4
2009-2013			
OE Sensor: Honda - 42753TK4A01			
Sensor	20720	35	4
Service Pack	20019	35	4
TSX			
2007-2014			
OE Sensor: Honda - 42753STKA02, 42753TL2A51, 42753TL2A52			
Sensor	20098	35	4

Application	Part No.	Torque in-lbs	Torque N.m.
Acura (cont'd)			
ZDX			
2010-2013			
OE Sensor: Honda - 42753TK4A01			
Sensor	20720	35	4
Service Pack	20019	35	4
Alfa Romeo			
4C			
2012-2016			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20398	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
8C			
2007-2009			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Audi			
A3, A4,A5 & Quattro			
2002-2007			
OE Sensor: Volkswagen - 4F0907275B			
Sensor; Includes Transmitter Only	20078	35	4
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
2008			
OE Sensor: Volkswagen - 1K0907253D, 4F0907275B			
Sensor	20088	71	8
Sensor; Includes Transmitter Only	20078	35	4
Service Pack	20017	71	8
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
2009-2012			
OE Sensor: Volkswagen - 1K0907253D			
Sensor	20088	71	8
Service Pack	20017	71	8
2013-2016			
Sensor	INDIRECT [D]		
A4 allroad			
2013-2016			
Sensor	INDIRECT [D]		

A-Programming Tool Required C-20018 and 20008 are interchangeable. D-Indirect TPMS system. No sensor in wheel DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Audi (cont'd)			
A6			
2002-2004			
OE Sensor: Volkswagen - 4D0907275D			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Includes Transmitter Only	20079	35	4
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
2006-2008			
OE Sensor: Volkswagen - 4F0907275B			
Sensor; Includes Transmitter Only	20078	35	4
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
2009			
OE Sensor: Volkswagen - 4F0907275D			
Sensor; Includes Transmitter Only; Quattro	20103	35	4
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
2010			
OE Sensor: Volkswagen - 4F0907275D			
Sensor; Includes Transmitter Only	20103	35	4
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
2011			
OE Sensor: Volkswagen - 4F0907275H			
Sensor; Includes Transmitter Only	20077	35	4
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
2013-2016			
Sensor	INDIRECT [D]		
A6 Quattro			
2006-2008			
OE Sensor: Volkswagen - 4F0907275B			
Sensor; Includes Transmitter Only	20078	35	4
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4

Application	Part No.	Torque in-lbs	Torque N.m.
Audi (cont'd)			
A6 Quattro (cont'd)			
2010			
OE Sensor: Volkswagen - 4F0907275D			
Sensor; Includes Transmitter Only	20103	35	4
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
2011			
OE Sensor: Volkswagen - 4F0907275H			
Sensor; Includes Transmitter Only	20077	35	4
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
A7 Quattro			
2013-2014			
Sensor	INDIRECT [D]		
A8			
2000			
OE Sensor: Volkswagen - 4D0907275A			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Includes Transmitter Only	20079	35	4
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
2001-2003			
OE Sensor: Volkswagen - 4D0907275A			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Includes Transmitter Only	20079	35	4
2004-2005			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2006-2011			
OE Sensor: Volkswagen - 44D0907275			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Includes Transmitter Only	20077	35	4
2013-2016			
Sensor	INDIRECT [D]		

A-Programming Tool Required C-20018 and 20008 are interchangeable. D-Indirect TPMS system. No sensor in wheel DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Audi (cont'd)			
A8 Quattro			
2000-2002			
OE Sensor: Volkswagen - 4D0907275D			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Includes Transmitter Only	20079	35	4
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
2003			
OE Sensor: Volkswagen - 4D0907275, 4D0907275D			
EZ-Sensor	33000 [A]	11.5	1.3
	33100 [A]	11.5	1.3
	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Includes Transmitter Only; Chassis No. 4D3004999 & Before	20079	35	4
Sensor; Includes Transmitter Only; Chassis No. 4E3000001 & After	20077	35	4
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
2004-2011			
OE Sensor: Volkswagen - 4D0907275C			
EZ-Sensor	33100 [A]	11.5	1.3
	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Includes Transmitter Only	20077	35	4
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
Allroad			
2001-2005			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3

Application	Part No.	Torque in-lbs	Torque N.m.
Audi (cont'd)			
Allroad Quattro			
2001-2005			
OE Sensor: Volkswagen - 4D0907275D			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Includes Transmitter Only	20079	35	4
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
Q5			
2009-2012			
OE Sensor: Volkswagen - 1K0907253D			
Sensor	20088	71	8
Service Pack	20017	71	8
2013-2016			
Sensor	INDIRECT [D]		
Q7			
2007-2009			
OE Sensor: Volkswagen - 4F0907275B			
Sensor; Includes Transmitter Only	20078	35	4
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
2010			
OE Sensor: Volkswagen - 4F0907275D			
Sensor; Includes Transmitter Only	20103	35	4
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
2011			
OE Sensor: Volkswagen - 4F0907275H			
Sensor; Includes Transmitter Only	20077	35	4
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
2012			
OE Sensor: Volkswagen - 4F0907275D			
Sensor; Includes Transmitter Only	20103	35	4
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
2013-2016			
Sensor	INDIRECT [D]		

A-Programming Tool Required C-20018 and 20008 are interchangeable. D-Indirect TPMS system. No sensor in wheel DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Audi (cont'd)			
R8			
2008-2009			
OE Sensor: Volkswagen - 4F0907275B			
Sensor; Includes Transmitter Only.	20078	35	4
Service Pack; Does Not Include Valve.	20023	35	4
Service Pack; W/43mm Silver Insert.	20037	35	4
Service Pack; W/48mm Green Insert.	20038	35	4
Service Pack; W/49mm Black Insert.	20039	35	4
Service Pack; W/51mm Orange Insert.	20040	35	4
2010			
OE Sensor: Volkswagen - 4F0907275D			
Sensor; Includes Transmitter Only.	20103	35	4
Service Pack; Does Not Include Valve.	20023	35	4
Service Pack; W/43mm Silver Insert.	20037	35	4
Service Pack; W/48mm Green Insert.	20038	35	4
Service Pack; W/49mm Black Insert.	20039	35	4
Service Pack; W/51mm Orange Insert.	20040	35	4
2011			
OE Sensor: Volkswagen - 4F0907275D			
Sensor.	20103	35	4
Service Pack; Does Not Include Valve.	20023	35	4
Service Pack; W/43mm Silver Insert.	20037	35	4
Service Pack; W/48mm Green Insert.	20038	35	4
Service Pack; W/49mm Black Insert.	20039	35	4
Service Pack; W/51mm Orange Insert.	20040	35	4
2012			
OE Sensor: Volkswagen - 4F0907275D			
Sensor; Includes Transmitter Only.	20103	35	4
Service Pack; Does Not Include Valve.	20023	35	4
Service Pack; W/43mm Silver Insert.	20037	35	4
Service Pack; W/48mm Green Insert.	20038	35	4
Service Pack; W/49mm Black Insert.	20039	35	4
Service Pack; W/51mm Orange Insert.	20040	35	4
2014-2015			
OE Sensor: Volkswagen - 4F0907275D			
Sensor; Includes Transmitter Only.	20103	35	4
Service Pack; Does Not Include Valve.	20023	35	4
Service Pack; W/43mm Silver Insert.	20037	35	4
Service Pack; W/48mm Green Insert.	20038	35	4
Service Pack; W/49mm Black Insert.	20039	35	4
Service Pack; W/51mm Orange Insert.	20040	35	4
RS4			
2007-2008			
OE Sensor: Volkswagen - 4F0907275B			
Sensor; Includes Transmitter Only.	20078	35	4
Service Pack; Does Not Include Valve.	20023	35	4
Service Pack; W/43mm Silver Insert.	20037	35	4
Service Pack; W/48mm Green Insert.	20038	35	4
Service Pack; W/49mm Black Insert.	20039	35	4
Service Pack; W/51mm Orange Insert.	20040	35	4
RS5			
2013-2015			
Sensor.	INDIRECT [D]		

Application	Part No.	Torque in-lbs	Torque N.m.
Audi (cont'd)			
RS6			
2003			
OE Sensor: Volkswagen - 4F0907275H			
EZ-Sensor.	33100 [A]	11.5	1.3
	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 [C]	11.5	1.3
Sensor; Includes Transmitter Only.	20077	35	4
Service Pack; Does Not Include Valve.	20023	35	4
Service Pack; W/43mm Silver Insert.	20037	35	4
Service Pack; W/48mm Green Insert.	20038	35	4
Service Pack; W/49mm Black Insert.	20039	35	4
Service Pack; W/51mm Orange Insert.	20040	35	4
RS7			
2014-2016			
OE Sensor: Volkswagen - 7PP-907-275F			
Sensor.	20103	35	4
Service Pack; Does Not Include Valve.	20023	35	4
Service Pack; W/43mm Silver Insert.	20037	35	4
Service Pack; W/48mm Green Insert.	20038	35	4
Service Pack; W/49mm Black Insert.	20039	35	4
Service Pack; W/51mm Orange Insert.	20040	35	4
S4			
2002			
OE Sensor: Volkswagen - 4D0907275D			
EZ-Sensor.	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 [C]	11.5	1.3
Sensor; Includes Transmitter Only.	20079	35	4
Service Pack; Does Not Include Valve.	20023	35	4
Service Pack; W/43mm Silver Insert.	20037	35	4
Service Pack; W/48mm Green Insert.	20038	35	4
Service Pack; W/49mm Black Insert.	20039	35	4
Service Pack; W/51mm Orange Insert.	20040	35	4
2003			
EZ-Sensor.	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 [C]	11.5	1.3
Sensor; Includes Transmitter Only.	20079	35	4
Service Pack; Does Not Include Valve.	20023	35	4
2004-2009			
OE Sensor: Volkswagen - 4F0907275B			
Sensor; Includes Transmitter Only.	20078	35	4
Service Pack; Does Not Include Valve.	20023	35	4
Service Pack; W/43mm Silver Insert.	20037	35	4
Service Pack; W/48mm Green Insert.	20038	35	4
Service Pack; W/49mm Black Insert.	20039	35	4
Service Pack; W/51mm Orange Insert.	20040	35	4
2010-2011			
OE Sensor: Volkswagen - 1K0907253D			
Sensor.	20088	71	8
Service Pack.	20017	71	8

A-Programming Tool Required C-20018 and 20008 are interchangeable. D-Indirect TPMS system. No sensor in wheel DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Audi (cont'd)			
S4 (cont'd)			
2013-2014			
Sensor	INDIRECT [D]		
S5			
2008-2012			
OE Sensor: Volkswagen - 1K0907253D			
Sensor	20088	71	8
Service Pack	20017	71	8
2013-2015			
Sensor	INDIRECT [D]		
S6			
2007-2009			
OE Sensor: Volkswagen - 4F0907275B			
Sensor; Includes Transmitter Only	20078	35	4
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
2010			
OE Sensor: Volkswagen - 4F0907275D			
Sensor; Includes Transmitter Only	20103	35	4
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
2011			
OE Sensor: Volkswagen - 4F0907275H			
Sensor; Includes Transmitter Only	20077	35	4
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
2013-2015			
Sensor	INDIRECT [D]		
S7			
2013-2015			
Sensor	INDIRECT [D]		
S8			
2000			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
Sensor; Includes Transmitter Only	20079	35	4

Application	Part No.	Torque in-lbs	Torque N.m.
Audi (cont'd)			
S8 (cont'd)			
2001-2002			
OE Sensor: Volkswagen - 4D0907275D			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Includes Transmitter Only	20079	35	4
Service Pack; Does Not Include Valve	20023	35	4
2003			
OE Sensor: Volkswagen - 4D0907275, 4D0907275D			
EZ-Sensor	33000 [A]	11.5	1.3
	33100 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Includes Transmitter Only; Chassis No. 4D3004999 & Before	20079	35	4
Sensor; Includes Transmitter Only; Chassis No. 4E3000001 & After	20077	35	4
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
2004-2006			
OE Sensor: Volkswagen - 4D0907275			
EZ-Sensor	33000 [A]	11.5	1.3
	33100 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Includes Transmitter Only; Chassis No. 4E3000001 & After	20077	35	4
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
2007-2008			
OE Sensor: Volkswagen - 4D0907275C			
EZ-Sensor	33000 [A]	11.5	1.3
	33100 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Includes Transmitter Only	20077	35	4
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4

A-Programming Tool Required C-20018 and 20008 are interchangeable. D-Indirect TPMS system. No sensor in wheel DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Audi (cont'd)			
S8 (cont'd)			
2009			
OE Sensor: Volkswagen - 4D0907275			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Includes Transmitter Only; Chassis No. 4E3000001 & After	20077	35	4
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
2013-2014			
Sensor	INDIRECT [D]		
2015			
OE Sensor: Volkswagen - 4D0907275			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	INDIRECT [D]		
Sensor; Includes Transmitter Only; Chassis No. 4E3000001 & After	20077	35	4
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
SQ5			
2013-2014			
Sensor	INDIRECT [D]		
2015			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
TT			
2008-2009			
OE Sensor: Volkswagen - 1K0907253D			
Sensor	20088	71	8
Service Pack	20017	71	8
2013-2015			
Sensor	INDIRECT [D]		
TT Quattro			
2008-2009			
OE Sensor: Volkswagen - 1K0907253D			
Sensor	20088	71	8
Service Pack	20017	71	8

Application	Part No.	Torque in-lbs	Torque N.m.
Bentley			
Arnage			
2008			
OE Sensor: Original Equipment Manufacturer - 4F0 907 275			
Sensor; Includes Transmitter Only	20078	35	4
Azure			
2007-2009			
OE Sensor: Volkswagen - 4F0907275D			
Sensor; Includes Transmitter Only	20103	35	4
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
Brooklands			
2008			
OE Sensor: Original Equipment Manufacturer - 4F0 907 275			
Sensor; Includes Transmitter Only	20078	35	4
Continental			
2003-2005			
OE Sensor: Volkswagen - 4D0907275C			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Includes Transmitter Only	20077	35	4
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
2006-2010			
OE Sensor: Volkswagen - 4F0907275B			
Sensor; Includes Transmitter Only	20078	35	4
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
2012-2014			
OE Sensor: Volkswagen - 4F0907275D, 7PP907275F			
Sensor; Includes Transmitter Only	20103	35	4
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
2015-2016			
OE Sensor: Volkswagen - 7PP907275F			
Sensor; Includes Transmitter Only	20103	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4

A-Programming Tool Required C-20018 and 20008 are interchangeable. D-Indirect TPMS system. No sensor in wheel DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Bentley (cont'd)			
Mulsanne			
2009			
OE Sensor: Original Equipment Manufacturer - 4F0 907 275			
Sensor; Includes Transmitter Only.	20078	35	4
2011-2015			
OE Sensor: Volkswagen - 4F0907275D, 7PP907275F			
Sensor; Includes Transmitter Only.	20103	35	4
Service Pack; Does Not Include Valve.	20023	35	4
Service Pack; W/43mm Silver Insert.	20037	35	4
Service Pack; W/48mm Green Insert.	20038	35	4
Service Pack; W/49mm Black Insert.	20039	35	4
Service Pack; W/51mm Orange Insert.	20040	35	4
2016			
OE Sensor: Volkswagen - 7PP907275F			
Sensor; Includes Transmitter Only.	20103	35	4
Service Pack; W/43mm Silver Insert.	20037	35	4
Service Pack; W/48mm Green Insert.	20038	35	4
Service Pack; W/49mm Black Insert.	20039	35	4
Service Pack; W/51mm Orange Insert.	20040	35	4
BMW			
1 Series			
2008			
OE Sensor: BMW - 36 10 6 790 054, 36236781847			
Sensor; Includes Transmitter Only.	20083	31	3.5
	28081	40	4.5
Service Pack; Does Not Include Valve.	20023	31	3.5
Service Pack; W/43mm Silver Insert.	20037	31	3.5
Service Pack; W/48mm Green Insert.	20038	31	3.5
Service Pack; W/49mm Black Insert.	20039	31	3.5
Service Pack; W/51mm Orange Insert.	20040	31	3.5
2009-2010			
OE Sensor: BMW - 36236781847			
Sensor; Includes Transmitter Only.	20083	31	3.5
Service Pack; Does Not Include Valve.	20023	31	3.5
Service Pack; W/43mm Silver Insert.	20037	31	3.5
Service Pack; W/48mm Green Insert.	20038	31	3.5
Service Pack; W/49mm Black Insert.	20039	31	3.5
Service Pack; W/51mm Orange Insert.	20040	31	3.5
2011-2013			
OE Sensor: BMW - 36 10 6 790 054			
EZ-Sensor.	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
Sensor; Includes Transmitter Only.	28081	40	4.5
Service Pack; Does Not Include Valve.	20023	31	3.5
Service Pack; W/43mm Silver Insert.	20037	31	3.5
Service Pack; W/48mm Green Insert.	20038	31	3.5
Service Pack; W/49mm Black Insert.	20039	31	3.5
Service Pack; W/51mm Orange Insert.	20040	31	3.5

Application	Part No.	Torque in-lbs	Torque N.m.
BMW (cont'd)			
228i			
2014			
OE Sensor: BMW - 36 10 6 798 872			
EZ-Sensor.	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
Sensor.	28126	40	4.5
Service Pack; W/43mm Silver Insert.	20037	31	3.5
Service Pack; W/48mm Green Insert.	20038	31	3.5
Service Pack; W/49mm Black Insert.	20039	31	3.5
Service Pack; W/51mm Orange Insert.	20040	31	3.5
2015			
OE Sensor: BMW - 36 10 6 798 872			
EZ-Sensor.	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
Sensor.	28126	40	4.5
Service Pack.	20023	31	3.5
Service Pack; W/43mm Silver Insert.	20037	31	3.5
Service Pack; W/48mm Green Insert.	20038	31	3.5
Service Pack; W/49mm Black Insert.	20039	31	3.5
Service Pack; W/51mm Orange Insert.	20040	31	3.5
320i			
2000			
EZ-Sensor.	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
2001-2002			
OE Sensor: BMW - 36118378682			
EZ-Sensor.	33000 A	11.5	1.3
	33100 A	11.5	1.3
	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
Sensor; Includes Transmitter Only; W/433 MHz			
Sensor.	20080	31	3.5
Service Pack; Does Not Include Valve.	20023	31	3.5
Service Pack; W/43mm Silver Insert.	20037	31	3.5
Service Pack; W/48mm Green Insert.	20038	31	3.5
Service Pack; W/49mm Black Insert.	20039	31	3.5
Service Pack; W/51mm Orange Insert.	20040	31	3.5
2003-2005			
OE Sensor: BMW - 36118378682			
EZ-Sensor.	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
Sensor; Includes Transmitter Only.	20080	31	3.5
Service Pack; Does Not Include Valve.	20023	31	3.5
Service Pack; W/43mm Silver Insert.	20037	31	3.5
Service Pack; W/48mm Green Insert.	20038	31	3.5
Service Pack; W/49mm Black Insert.	20039	31	3.5
Service Pack; W/51mm Orange Insert.	20040	31	3.5

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
BMW (cont'd)			
320i (cont'd)			
2014			
OE Sensor: BMW - 36 10 6 798 872			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28126	40	4.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
320i xDrive			
2014			
OE Sensor: BMW - 36 10 6 798 872			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28126	40	4.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
323Ci			
2000			
OE Sensor: BMW - 36118378682			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Includes Transmitter Only	20080	31	3.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
323i			
2000			
OE Sensor: BMW - 36118378682			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Includes Transmitter Only	20080	31	3.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
2001-2002			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3

Application	Part No.	Torque in-lbs	Torque N.m.
BMW (cont'd)			
323i (cont'd)			
2003			
OE Sensor: BMW - 36118378682			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Includes Transmitter Only	20080	31	3.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
2004-2005			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
2006			
OE Sensor: BMW - 36118378682			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Includes Transmitter Only	20080	31	3.5
Service Pack; Does Not Include Valve; Jun. & Newer	20023	31	3.5
Service Pack; W/43mm Silver Insert; Jun. & Newer	20037	31	3.5
Service Pack; W/48mm Green Insert; Jun. & Newer	20038	31	3.5
Service Pack; W/49mm Black Insert; Jun. & Newer	20039	31	3.5
Service Pack; W/51mm Orange Insert; Jun. & Newer	20040	31	3.5
2007-2010			
OE Sensor: BMW - 36236781847			
Sensor; Includes Transmitter Only	20083	31	3.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
2014			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
BMW (cont'd)			
325			
2001-2002			
OE Sensor: BMW - 36118378682			
EZ-Sensor	33000 [A]	11.5	1.3
	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Includes Transmitter Only; W/433 MHz Sensor	20079	31	3.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
2003-2006			
OE Sensor: BMW - 36118378682			
EZ-Sensor	33100 [A]	11.5	1.3
	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Includes Transmitter Only	20079	31	3.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
2007			
OE Sensor: BMW - 36236781847			
Sensor; Includes Transmitter Only	20083	31	3.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
2014			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
328Ci			
2000			
OE Sensor: BMW - 36118378682			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Includes Transmitter Only	20080	31	3.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5

Application	Part No.	Torque in-lbs	Torque N.m.
BMW (cont'd)			
328d			
2014			
OE Sensor: BMW - 36 10 6 798 872			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28126	40	4.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
328d xDrive			
2014			
OE Sensor: BMW - 36 10 6 798 872			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28126	40	4.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
328i			
2000			
OE Sensor: BMW - 36118378682			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Includes Transmitter Only; W/433 MHz Sensor	20080	31	3.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
2007-2008			
OE Sensor: BMW - 36236781847			
Sensor; Includes Transmitter Only	20083	31	3.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
2009			
OE Sensor: BMW - 36236781847			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Includes Transmitter Only	28081	31	3.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
BMW (cont'd)			
328i (cont'd)			
2010-2013			
OE Sensor: BMW - 36 10 6 790 054			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Includes Transmitter Only	28081	40	4.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
2014-2016			
OE Sensor: BMW - 36 10 6 798 872			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Includes Transmitter Only	28126	40	4.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
328i GT xDrive			
2014-2016			
OE Sensor: BMW - 36 10 6 798 872			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Includes Transmitter Only	28126	40	4.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
328i xDrive			
2009			
OE Sensor: BMW - 36236781847			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Includes Transmitter Only	28081	31	3.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5

Application	Part No.	Torque in-lbs	Torque N.m.
BMW (cont'd)			
328i xDrive (cont'd)			
2010-2013			
OE Sensor: BMW - 36 10 6 790 054			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Includes Transmitter Only	28081	40	4.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
2014-2015			
OE Sensor: BMW - 36 10 6 798 872			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Includes Transmitter Only	28126	40	4.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
2016			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
328xi			
2007-2008			
OE Sensor: BMW - 36236781847			
Sensor; Includes Transmitter Only	20083	31	3.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
330			
2001-2002			
OE Sensor: BMW - 36118378682			
EZ-Sensor	33000 A	11.5	1.3
	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Includes Transmitter Only; W/433 MHz			
Sensor	20080	31	3.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
BMW (cont'd)			
330 (cont'd)			
2003-2006			
OE Sensor: BMW - 36118378682			
EZ-Sensor	33100 [A]	11.5	1.3
	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Includes Transmitter Only	20080	31	3.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
335d			
2009			
OE Sensor: BMW - 36236781847			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Includes Transmitter Only	20083	31	3.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
2010-2011			
OE Sensor: BMW - 36 10 6 790 054			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Includes Transmitter Only	28081	40	4.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
335i			
2007-2008			
OE Sensor: BMW - 36236781847			
Sensor; Includes Transmitter Only	20083	31	3.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
2009			
OE Sensor: BMW - 36236781847			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Includes Transmitter Only	28081	31	3.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5

Application	Part No.	Torque in-lbs	Torque N.m.
BMW (cont'd)			
335i (cont'd)			
2010-2012			
OE Sensor: BMW - 36 10 6 790 054			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Includes Transmitter Only	28081	40	4.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
2013-2014			
OE Sensor: BMW - 36 10 6 790 054, 36 10 6 798 872			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Includes Transmitter Only	28126	40	4.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
335i GT xDrive			
2014-2015			
OE Sensor: BMW - 36 10 6 798 872			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Includes Transmitter Only	28126	40	4.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
335i xDrive			
2009			
OE Sensor: BMW - 36236781847			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Includes Transmitter Only	28081	31	3.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
BMW (cont'd)			
335i xDrive (cont'd)			
2010-2012			
OE Sensor: BMW - 36 10 6 790 054			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Includes Transmitter Only	28081	40	4.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
2013-2015			
OE Sensor: BMW - 36 10 6 790 054, 36 10 6 798 872			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Includes Transmitter Only	28126	40	4.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
335is			
2012-2013			
OE Sensor: BMW - 36 10 6 790 054			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Includes Transmitter Only	28081	40	4.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
335xi			
2007-2008			
OE Sensor: BMW - 36236781847			
Sensor; Includes Transmitter Only	20083	31	3.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
428i			
2014			
OE Sensor: BMW - 36 10 6 798 872			
Sensor; Includes Transmitter Only	28126	40	4.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5

Application	Part No.	Torque in-lbs	Torque N.m.
BMW (cont'd)			
428i (cont'd)			
2015			
OE Sensor: BMW - 36 10 6 798 872			
EZ-Sensor; Programmable sensor. Programming tool reqired.	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminum valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28126	35	4
Service Pack; Does Not Include Valve	20023	31	3.5
2016			
OE Sensor: BMW - 36 10 6 798 872			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminum valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28126	35	4
428i xDrive			
2014			
OE Sensor: BMW - 36 10 6 798 872			
Sensor	28126	40	4.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
2015			
OE Sensor: BMW - 36 10 6 798 872			
EZ-Sensor; Programmable sensor. Programming tool reqired.	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminum valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28126	35	4
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
2016			
EZ-Sensor; Programmable sensor. Programming tool reqired.	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminum valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
435i			
2014			
OE Sensor: BMW - 36 10 6 798 872			
Sensor	28126	40	4.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
BMW (cont'd)			
435i (cont'd)			
2015			
OE Sensor: BMW - 36 10 6 798 872			
EZ-Sensor; Programmable sensor. Programming tool reqired..	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminum valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
Sensor.	28126	35	4
Service Pack; Does Not Include Valve.	20023	31	3.5
Service Pack; W/43mm Silver Insert.	20037	31	3.5
Service Pack; W/48mm Green Insert.	20038	31	3.5
Service Pack; W/49mm Black Insert.	20039	31	3.5
Service Pack; W/51mm Orange Insert.	20040	31	3.5
2016			
OE Sensor: BMW - 36 10 6 798 872			
EZ-Sensor; Progammable sensor. Programming tool required.	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminum valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
Sensor.	28126	35	4
Service Pack; Does Not Include Valve.	20023	31	3.5
Service Pack; W/43mm Silver Insert.	20037	31	3.5
Service Pack; W/48mm Green Insert.	20038	31	3.5
Service Pack; W/49mm Black Insert.	20039	31	3.5
Service Pack; W/51mm Orange Insert.	20040	31	3.5
435i xDrive			
2014			
OE Sensor: BMW - 36 10 6 856 227			
Sensor.	28126	40	4.5
Service Pack; Does Not Include Valve.	20023	31	3.5
Service Pack; W/43mm Silver Insert.	20037	31	3.5
Service Pack; W/48mm Green Insert.	20038	31	3.5
Service Pack; W/49mm Black Insert.	20039	31	3.5
Service Pack; W/51mm Orange Insert.	20040	31	3.5
2015			
OE Sensor: BMW - 36 10 6 798 872			
EZ-Sensor; Programmable sensor. Programming tool reqired..	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminum valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
Sensor.	28126	35	4
Service Pack; Does Not Include Valve.	20023	31	3.5
Service Pack; W/43mm Silver Insert.	20037	31	3.5
Service Pack; W/48mm Green Insert.	20038	31	3.5
Service Pack; W/49mm Black Insert.	20039	31	3.5
Service Pack; W/51mm Orange Insert.	20040	31	3.5
2016			
EZ-Sensor; Programmable sensor. Programming tool reqired..	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminum valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3

Application	Part No.	Torque in-lbs	Torque N.m.
BMW (cont'd)			
525i			
2001			
Service Pack; Does Not Include Valve.	20023	31	3.5
Service Pack; W/43mm Silver Insert.	20037	31	3.5
Service Pack; W/48mm Green Insert.	20038	31	3.5
Service Pack; W/49mm Black Insert.	20039	31	3.5
Service Pack; W/51mm Orange Insert.	20040	31	3.5
2002			
OE Sensor: BMW - 36118378682			
EZ-Sensor.	33000 A	11.5	1.3
	33100 A	11.5	1.3
	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
Sensor; Includes Transmitter Only.	20079	35	4
Sensor; Includes Transmitter Only; W/433 MHz Sensor.	20080	31	3.5
Service Pack; Does Not Include Valve.	20023	31	3.5
Service Pack; W/43mm Silver Insert.	20037	31	3.5
Service Pack; W/48mm Green Insert.	20038	31	3.5
Service Pack; W/49mm Black Insert.	20039	31	3.5
Service Pack; W/51mm Orange Insert.	20040	31	3.5
2003-2005			
OE Sensor: BMW - 36118378682			
EZ-Sensor.	33100 A	11.5	1.3
	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
Sensor; Includes Transmitter Only.	20080	31	3.5
Service Pack; Does Not Include Valve.	20023	31	3.5
Service Pack; W/43mm Silver Insert.	20037	31	3.5
Service Pack; W/48mm Green Insert.	20038	31	3.5
Service Pack; W/49mm Black Insert.	20039	31	3.5
Service Pack; W/51mm Orange Insert.	20040	31	3.5
2006-2007			
OE Sensor: BMW - 36236781847			
Sensor; Includes Transmitter Only.	20083	31	3.5
Service Pack; Does Not Include Valve.	20023	31	3.5
Service Pack; W/43mm Silver Insert.	20037	31	3.5
Service Pack; W/48mm Green Insert.	20038	31	3.5
Service Pack; W/49mm Black Insert.	20039	31	3.5
Service Pack; W/51mm Orange Insert.	20040	31	3.5
525xi			
2006-2007			
OE Sensor: BMW - 36236781847			
Sensor; Includes Transmitter Only.	20083	31	3.5
Service Pack; Does Not Include Valve.	20023	31	3.5
Service Pack; W/43mm Silver Insert.	20037	31	3.5
Service Pack; W/48mm Green Insert.	20038	31	3.5
Service Pack; W/49mm Black Insert.	20039	31	3.5
Service Pack; W/51mm Orange Insert.	20040	31	3.5

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
BMW (cont'd)			
528			
1997-1998			
Service Pack; Does Not Include Valve.	20023	31	3.5
Service Pack; W/43mm Silver Insert.	20037	31	3.5
Service Pack; W/48mm Green Insert.	20038	31	3.5
Service Pack; W/49mm Black Insert.	20039	31	3.5
Service Pack; W/51mm Orange Insert.	20040	31	3.5
1999-2000			
EZ-Sensor.	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
Service Pack; Does Not Include Valve.	20023	31	3.5
Service Pack; W/43mm Silver Insert.	20037	31	3.5
Service Pack; W/48mm Green Insert.	20038	31	3.5
Service Pack; W/49mm Black Insert.	20039	31	3.5
Service Pack; W/51mm Orange Insert.	20040	31	3.5
2008			
OE Sensor: BMW - 36236781847			
Sensor; Includes Transmitter Only.	20083	31	3.5
Service Pack; Does Not Include Valve.	20023	31	3.5
Service Pack; W/43mm Silver Insert.	20037	31	3.5
Service Pack; W/48mm Green Insert.	20038	31	3.5
Service Pack; W/49mm Black Insert.	20039	31	3.5
Service Pack; W/51mm Orange Insert.	20040	31	3.5
2009-2011			
OE Sensor: BMW - 36236781847			
EZ-Sensor.	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
Sensor; Includes Transmitter Only.	20083	31	3.5
Service Pack; Does Not Include Valve.	20023	31	3.5
Service Pack; W/43mm Silver Insert.	20037	31	3.5
Service Pack; W/48mm Green Insert.	20038	31	3.5
Service Pack; W/49mm Black Insert.	20039	31	3.5
Service Pack; W/51mm Orange Insert.	20040	31	3.5
2012-2014			
OE Sensor: BMW - 36 10 6 790 054, 36 10 6 856 227			
EZ-Sensor.	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
Sensor; Includes Transmitter Only.	28081	40	4.5
Service Pack; Does Not Include Valve.	20023	31	3.5
Service Pack; W/43mm Silver Insert.	20037	31	3.5
Service Pack; W/48mm Green Insert.	20038	31	3.5
Service Pack; W/49mm Black Insert.	20039	31	3.5
Service Pack; W/51mm Orange Insert.	20040	31	3.5
2015-2016			
OE Sensor: BMW - 36 10 6 856 872			
EZ-Sensor.	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
Sensor.	28081	40	4.5
	28126	40	4.5
Service Pack; Does Not Include Valve.	20023	31	3.5
Service Pack; W/43mm Silver Insert.	20037	31	3.5
Service Pack; W/48mm Green Insert.	20038	31	3.5
Service Pack; W/49mm Black Insert.	20039	31	3.5
Service Pack; W/51mm Orange Insert.	20040	31	3.5

Application	Part No.	Torque in-lbs	Torque N.m.
BMW (cont'd)			
528xi			
2008			
OE Sensor: BMW - 36236781847			
Sensor; Includes Transmitter Only.	20083	31	3.5
Service Pack; Does Not Include Valve.	20023	31	3.5
Service Pack; W/43mm Silver Insert.	20037	31	3.5
Service Pack; W/48mm Green Insert.	20038	31	3.5
Service Pack; W/49mm Black Insert.	20039	31	3.5
Service Pack; W/51mm Orange Insert.	20040	31	3.5
530			
2001			
OE Sensor: BMW - 36118378682			
EZ-Sensor.	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
Sensor; Includes Transmitter Only.	20079	35	4
Service Pack; Does Not Include Valve.	20023	31	3.5
Service Pack; W/43mm Silver Insert.	20037	31	3.5
Service Pack; W/48mm Green Insert.	20038	31	3.5
Service Pack; W/49mm Black Insert.	20039	31	3.5
Service Pack; W/51mm Orange Insert.	20040	31	3.5
2002			
OE Sensor: BMW - 36118378682			
EZ-Sensor.	33000 A	11.5	1.3
	33100 A	11.5	1.3
	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
Sensor; Includes Transmitter Only.	20079	35	4
Sensor; Includes Transmitter Only; W/433 MHz Sensor.	20080	31	3.5
Service Pack; Does Not Include Valve.	20023	31	3.5
Service Pack; W/43mm Silver Insert.	20037	31	3.5
Service Pack; W/48mm Green Insert.	20038	31	3.5
Service Pack; W/49mm Black Insert.	20039	31	3.5
Service Pack; W/51mm Orange Insert.	20040	31	3.5
2003-2005			
OE Sensor: BMW - 36118378682			
EZ-Sensor.	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
Sensor; Includes Transmitter Only.	20080	31	3.5
Service Pack; Does Not Include Valve.	20023	31	3.5
Service Pack; W/43mm Silver Insert.	20037	31	3.5
Service Pack; W/48mm Green Insert.	20038	31	3.5
Service Pack; W/49mm Black Insert.	20039	31	3.5
Service Pack; W/51mm Orange Insert.	20040	31	3.5
2006-2007			
OE Sensor: BMW - 36236781847			
Sensor; Includes Transmitter Only.	20083	31	3.5
Service Pack; Does Not Include Valve.	20023	31	3.5
Service Pack; W/43mm Silver Insert.	20037	31	3.5
Service Pack; W/48mm Green Insert.	20038	31	3.5
Service Pack; W/49mm Black Insert.	20039	31	3.5
Service Pack; W/51mm Orange Insert.	20040	31	3.5

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
BMW (cont'd)			
535			
2008-2010			
OE Sensor: BMW - 36236781847			
Sensor; Includes Transmitter Only.	20083	31	3.5
Service Pack; Does Not Include Valve.	20023	31	3.5
Service Pack; W/43mm Silver Insert.	20037	31	3.5
Service Pack; W/48mm Green Insert.	20038	31	3.5
Service Pack; W/49mm Black Insert.	20039	31	3.5
Service Pack; W/51mm Orange Insert.	20040	31	3.5
2011			
OE Sensor: BMW - 36 10 6 790 054, 36236781847			
EZ-Sensor.	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
Sensor; Includes Transmitter Only.	20083	31	3.5
	28081	40	4.5
Service Pack; Does Not Include Valve.	20023	31	3.5
Service Pack; W/43mm Silver Insert.	20037	31	3.5
Service Pack; W/48mm Green Insert.	20038	31	3.5
Service Pack; W/49mm Black Insert.	20039	31	3.5
Service Pack; W/51mm Orange Insert.	20040	31	3.5
2012-2014			
OE Sensor: BMW - 36 10 6 790 054, 36 10 6 856 227			
EZ-Sensor.	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
Sensor; Includes Transmitter Only.	28081	40	4.5
Service Pack; Does Not Include Valve.	20023	31	3.5
Service Pack; W/43mm Silver Insert.	20037	31	3.5
Service Pack; W/48mm Green Insert.	20038	31	3.5
Service Pack; W/49mm Black Insert.	20039	31	3.5
Service Pack; W/51mm Orange Insert.	20040	31	3.5
2015-2016			
OE Sensor: BMW - 36 10 6 856 872			
EZ-Sensor.	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
Sensor.	28126	40	4.5
Service Pack; Does Not Include Valve.	20023	31	3.5
Service Pack; W/43mm Silver Insert.	20037	31	3.5
Service Pack; W/48mm Green Insert.	20038	31	3.5
Service Pack; W/49mm Black Insert.	20039	31	3.5
Service Pack; W/51mm Orange Insert.	20040	31	3.5
535d			
2014			
OE Sensor: BMW - 36 10 6 856 227			
EZ-Sensor.	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
Sensor; Includes Transmitter Only.	28081	40	4.5
Service Pack; Does Not Include Valve.	20023	31	3.5
Service Pack; W/43mm Silver Insert.	20037	31	3.5
Service Pack; W/48mm Green Insert.	20038	31	3.5
Service Pack; W/49mm Black Insert.	20039	31	3.5
Service Pack; W/51mm Orange Insert.	20040	31	3.5

Application	Part No.	Torque in-lbs	Torque N.m.
BMW (cont'd)			
535d (cont'd)			
2015-2016			
OE Sensor: BMW - 36 10 6 856 872			
EZ-Sensor.	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
Sensor.	28126	40	4.5
Service Pack; Does Not Include Valve.	20023	31	3.5
Service Pack; W/43mm Silver Insert.	20037	31	3.5
Service Pack; W/48mm Green Insert.	20038	31	3.5
Service Pack; W/49mm Black Insert.	20039	31	3.5
Service Pack; W/51mm Orange Insert.	20040	31	3.5
535d xDrive			
2014			
OE Sensor: BMW - 36 10 6 856 227			
EZ-Sensor.	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
Sensor; Includes Transmitter Only.	28081	40	4.5
Service Pack; Does Not Include Valve.	20023	31	3.5
Service Pack; W/43mm Silver Insert.	20037	31	3.5
Service Pack; W/48mm Green Insert.	20038	31	3.5
Service Pack; W/49mm Black Insert.	20039	31	3.5
Service Pack; W/51mm Orange Insert.	20040	31	3.5
2015-2016			
OE Sensor: BMW - 36 10 6 856 872			
EZ-Sensor.	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
Sensor.	28126	40	4.5
Service Pack; Does Not Include Valve.	20023	31	3.5
Service Pack; W/43mm Silver Insert.	20037	31	3.5
Service Pack; W/48mm Green Insert.	20038	31	3.5
Service Pack; W/49mm Black Insert.	20039	31	3.5
Service Pack; W/51mm Orange Insert.	20040	31	3.5
535xi			
2008			
OE Sensor: BMW - 36236781847			
Sensor; Includes Transmitter Only.	20083	31	3.5
Service Pack; Does Not Include Valve.	20023	31	3.5
Service Pack; W/43mm Silver Insert.	20037	31	3.5
Service Pack; W/48mm Green Insert.	20038	31	3.5
Service Pack; W/49mm Black Insert.	20039	31	3.5
Service Pack; W/51mm Orange Insert.	20040	31	3.5
540i			
1997-1998			
Service Pack; Does Not Include Valve.	20023	31	3.5
Service Pack; W/43mm Silver Insert.	20037	31	3.5
Service Pack; W/48mm Green Insert.	20038	31	3.5
Service Pack; W/49mm Black Insert.	20039	31	3.5
Service Pack; W/51mm Orange Insert.	20040	31	3.5

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
BMW (cont'd)			
540i (cont'd)			
1999-2000			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
2000			
EZ-Sensor	33000 A	11.5	1.3
2001			
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
2002			
OE Sensor: BMW - 36118378682			
EZ-Sensor	33000 A	11.5	1.3
	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Includes Transmitter Only; W/433 MHz			
Sensor	20080	31	3.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
2003			
OE Sensor: BMW - 36118378682			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Includes Transmitter Only	20080	31	3.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
2008-2011			
Sensor	20083		
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5

Application	Part No.	Torque in-lbs	Torque N.m.
BMW (cont'd)			
540i (cont'd)			
2012-2016			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
545i			
2004-2005			
OE Sensor: BMW - 36118378682			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Includes Transmitter Only	20080	31	3.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
550			
2006-2011			
OE Sensor: BMW - 36236781847			
Sensor; Includes Transmitter Only	20083	31	3.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
2012-2014			
OE Sensor: BMW - 36 10 6 790 054, 36 10 6 856 227			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Includes Transmitter Only	28081	40	4.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
2015-2016			
OE Sensor: BMW - 36 10 6 856 872			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28126	40	4.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
BMW (cont'd)			
640			
2012-2015			
OE Sensor: BMW - 36 10 6 790 054, 36 10 6 856 227			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Includes Transmitter Only	28081	40	4.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
2016			
OE Sensor: BMW - 36 10 6 798 872, 36 10 6 856 872			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28081	40	4.5
	28126	40	4.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
	20037		
Service Pack; W/48mm Green Insert	20038	31	3.5
	20038		
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
	20040		
645Ci			
2004-2005			
OE Sensor: BMW - 36118378682			
Sensor; Includes Transmitter Only	20080	31	3.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
650			
2006-2010			
OE Sensor: BMW - 36236781847			
Sensor; Includes Transmitter Only	20083	31	3.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
2012-2015			
OE Sensor: BMW - 36 10 6 790 054, 36 10 6 856 227			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Includes Transmitter Only	28081	40	4.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5

Application	Part No.	Torque in-lbs	Torque N.m.
BMW (cont'd)			
650 (cont'd)			
2016			
OE Sensor: BMW - 36 10 6 798 872			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28081	40	4.5
	28126	40	4.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
	20037		
Service Pack; W/48mm Green Insert	20038	31	3.5
	20038		
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
	20040		
650i Gran Coupe xDrive			
2016			
OE Sensor: BMW - 36 10 6 798 872			
Sensor	28126	40	4.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037		
Service Pack; W/48mm Green Insert	20038		
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040		
740i			
1997-1998			
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
1999-2001			
OE Sensor: BMW - 36118378682			
EZ-Sensor	33000 A	11.5	1.3
	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20080		
Sensor; Includes Transmitter Only	20079	35	4
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
2002-2003			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
BMW (cont'd)			
740i (cont'd)			
2011			
OE Sensor: BMW - 36236781847			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Includes Transmitter Only	28081	31	3.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
2012-2014			
OE Sensor: BMW - 36 10 6 790 054, 36 10 6 856 227			
Sensor; Includes Transmitter Only	28081	40	4.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
2015-2016			
OE Sensor: BMW - 36 10 6 856 227			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Includes Transmitter Only	28081	40	4.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
740iL			
1997-1998			
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
1999-2000			
OE Sensor: BMW - 36118378682			
EZ-Sensor	33000 A	11.5	1.3
	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20080		
Sensor; Includes Transmitter Only	20079	35	4
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5

Application	Part No.	Torque in-lbs	Torque N.m.
BMW (cont'd)			
740iL (cont'd)			
2001			
OE Sensor: BMW - 36118378682			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20080		
Sensor; Includes Transmitter Only	20079	35	4
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
2002			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
740Li			
2011			
OE Sensor: BMW - 36236781847			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Includes Transmitter Only	28081	31	3.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
2012-2016			
OE Sensor: BMW - 36 10 6 790 054, 36 10 6 856 227			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Includes Transmitter Only	28081	40	4.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
740Li xDrive			
2011-2012			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
BMW (cont'd)			
740Li xDrive (cont'd)			
2013-2016			
OE Sensor: BMW - 36 10 6 790 054, 36 10 6 856 227			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Includes Transmitter Only	28081	40	4.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
745			
2002			
OE Sensor: BMW - 36118378682			
EZ-Sensor	33100 A	11.5	1.3
	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Includes Transmitter Only; W/433 MHz			
Sensor	20080	31	3.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
2003			
OE Sensor: BMW - 36118378682			
EZ-Sensor	33100 A	11.5	1.3
	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Includes Transmitter Only	20080	31	3.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
2004-2005			
OE Sensor: BMW - 36118378682			
Sensor; Includes Transmitter Only	20080	31	3.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
750			
2006-2010			
OE Sensor: BMW - 36236781847			
Sensor; Includes Transmitter Only	20083	31	3.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5

Application	Part No.	Torque in-lbs	Torque N.m.
BMW (cont'd)			
750 (cont'd)			
2011			
OE Sensor: BMW - 36236781847			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Includes Transmitter Only	20083	31	3.5
	28081	31	3.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
2012-2016			
OE Sensor: BMW - 36 10 6 790 054, 36 10 6 856 227			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Includes Transmitter Only	28081	40	4.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
2015-2016			
OE Sensor: BMW - 36 10 6 856 227			
Sensor; Includes Transmitter Only	28126	40	4.5
750iL			
1997-1998			
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
1999-2000			
OE Sensor: BMW - 36118378682			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20080		
Sensor; Includes Transmitter Only	20079	35	4
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
2000			
EZ-Sensor	33000 A	11.5	1.3

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
BMW (cont'd)			
750iL (cont'd)			
2001			
OE Sensor: BMW - 36118378682			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20080		
Sensor; Includes Transmitter Only	20079	35	4
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
2002			
OE Sensor: BMW - 36118378682			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20080		
Sensor; Includes Transmitter Only	20079	35	4
2003			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
760i			
2004-2005			
OE Sensor: BMW - 36118378682			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Includes Transmitter Only	20080	31	3.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
2006			
OE Sensor: BMW - 36236781847			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Includes Transmitter Only	20083	31	3.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5

Application	Part No.	Torque in-lbs	Torque N.m.
BMW (cont'd)			
760Li			
2003			
OE Sensor: BMW - 36118378682			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Includes Transmitter Only	20080	31	3.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
2004-2008			
OE Sensor: BMW - 36236781847			
EZ-Sensor	33500 [A, DB]	11.5	1.3
Sensor; Includes Transmitter Only	20083	31	3.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
2009			
EZ-Sensor	33500 [A, DB]	11.5	1.3
2010			
OE Sensor: BMW - 36236781847			
EZ-Sensor	33500 [A, DB]	11.5	1.3
Sensor; Includes Transmitter Only	20083	31	3.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
2011			
OE Sensor: BMW - 36106856227			
EZ-Sensor	33500 [A, DB]	11.5	1.3
Sensor; Includes Transmitter Only	28081	31	3.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
2012-2014			
OE Sensor: BMW - 36 10 6 856 227, 36106856227			
EZ-Sensor	33500 [A, DB]	11.5	1.3
Sensor	28081	40	4.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
BMW (cont'd)			
760Li (cont'd)			
2015			
OE Sensor: BMW - 36106874830			
EZ-Sensor	33500 A, DB	11.5	1.3
Sensor	28126	40	4.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
2016			
OE Sensor: BMW - 36106874830			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28126	40	4.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
ActiveHybrid 3			
2013-2014			
OE Sensor: BMW - 36 10 6 856 227			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28081	40	4.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
2015			
OE Sensor: BMW - 36 10 6 856 227			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28081	40	4.5
ActiveHybrid 5			
2012-2014			
OE Sensor: BMW - 36 10 6 790 054, 36 10 6 856 227			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Includes Transmitter Only	28081	40	4.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5

Application	Part No.	Torque in-lbs	Torque N.m.
BMW (cont'd)			
ActiveHybrid 5 (cont'd)			
2015			
OE Sensor: BMW - 36 10 6 856 227			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28081	40	4.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
ActiveHybrid 7			
2013-2015			
OE Sensor: BMW - 36 10 6 790 054, 36 10 6 856 227			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Includes Transmitter Only	28081	40	4.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
Alpina B7			
2007-2008			
OE Sensor: BMW - 36236781847			
Sensor; Includes Transmitter Only	20083	31	3.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
2011-2015			
OE Sensor: BMW - 36118378682			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Includes Transmitter Only	28081	31	3.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
Alpina B7 xDrive			
2011			
OE Sensor: BMW - 36118378682			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Includes Transmitter Only	28081	31	3.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
BMW (cont'd)			
Alpina B7L			
2011			
OE Sensor: BMW - 36118378682			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Includes Transmitter Only	20080	31	3.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
Alpina B7L xDrive			
2011			
OE Sensor: BMW - 36118378682			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Includes Transmitter Only	28081	31	3.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
i3			
2013-2016			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
M			
2000-2001			
OE Sensor: BMW - 36118378682			
Sensor; Includes Transmitter Only; W/433 MHz Sensor	20080	31	3.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
2002			
OE Sensor: BMW - 36118378682			
EZ-Sensor	33100 A	11.5	1.3
	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Includes Transmitter Only; W/433 MHz Sensor	20080	31	3.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5

Application	Part No.	Torque in-lbs	Torque N.m.
BMW (cont'd)			
M (cont'd)			
2003			
OE Sensor: BMW - 36118378682			
EZ-Sensor	33100 A	11.5	1.3
	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Includes Transmitter Only	20080	31	3.5
Sensor; Includes Transmitter Only; W/433 MHz Sensor	20080	31	3.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
2004-2010			
OE Sensor: BMW - 36236781847			
Sensor; Includes Transmitter Only	20083	31	3.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
2010			
OE Sensor: BMW - 36236798726			
Sensor; Includes Transmitter Only	20083	40	4.5
2011-2012			
OE Sensor: BMW - 36 10 6 856 227, 36236781847, 36236798726			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Includes Transmitter Only	20083	40	4.5
	20083	31	3.5
	28081	40	4.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
2013			
OE Sensor: BMW - 36 10 6 856 227, 36236798726			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Includes Transmitter Only	20083	40	4.5
	28081	40	4.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
BMW (cont'd)			
M (cont'd)			
2014			
OE Sensor: BMW - 36 10 6 856 227			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor; Programmable sensor. Programming tool reqired.	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Aluminum valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
	20018 C	11.5	1.3
Sensor; Includes Transmitter Only	28081	40	4.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
2015-2016			
OE Sensor: BMW - 36 10 6 798 872, 36 10 6 856 227, 36106874830			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28126	40	4.5
Sensor; Includes Transmitter Only	28126	40	4.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
2016			
OE Sensor: BMW - 36 10 6 798 872			
Sensor; Includes Transmitter Only	28126	35	4
X			
1999-2004			
OE Sensor: BMW - 36146752128			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Includes Transmitter Only	28082	35	4
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
2000-2004			
EZ-Sensor	33100 A	11.5	1.3
	33200 A	11.5	1.3
2005-2007			
OE Sensor: BMW - 36236781847			
Sensor; Includes Transmitter Only	20083	35	4
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4

Application	Part No.	Torque in-lbs	Torque N.m.
BMW (cont'd)			
X (cont'd)			
2008-2010			
OE Sensor: BMW - 36236781847			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Includes Transmitter Only	20083	35	4
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
2011			
OE Sensor: BMW - 36 10 6 790 054, 36106856227, 36236781847			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor; Programmable sensor. Programming tool reqired.	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Aluminum valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
	20018 C	11.5	1.3
Sensor	20081		
	28081		
Sensor; Includes Transmitter Only	20083	35	4
	28081	40	4.5
Service Pack; Does Not Include Valve	20023	35	4
	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	35	4
	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	35	4
	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	35	4
	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	35	4
	20040	31	3.5
2012-2014			
OE Sensor: BMW - 36 10 6 790 054, 36 10 6 856 227			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor; Programmable sensor. Programming tool reqired.	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Aluminum valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
	20018 C	11.5	1.3
Sensor; Includes Transmitter Only	28081	40	4.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
BMW (cont'd)			
X (cont'd)			
2015			
OE Sensor: BMW - 36 10 6 798 872, 36 10 6 856 227, 36106874830			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor; Programmable sensor. Programming tool reqired.	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Aluminum valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
	20018 C	11.5	1.3
Sensor	28126	35	4
Sensor; Includes Transmitter Only	28081	40	4.5
	28126	40	4.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
2016			
OE Sensor: BMW - 36 10 6 798 872, 36 10 6 856 872, 36106874830			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor; Programmable sensor. Programming tool reqired.	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Aluminum valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
	20018 C	11.5	1.3
Sensor	28081	40	4.5
	28126	35	4
Sensor; Includes Transmitter Only	28126	40	4.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
Z3			
2000-2002			
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
Z4			
2003-2010			
OE Sensor: BMW - 36236781847			
Sensor; Includes Transmitter Only	20083	31	3.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5

Application	Part No.	Torque in-lbs	Torque N.m.
BMW (cont'd)			
Z4 (cont'd)			
2011			
OE Sensor: BMW - 36236781847			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Includes Transmitter Only	20083	31	3.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
2012-2015			
OE Sensor: BMW - 36 10 6 790 054, 36 10 6 856 227			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Includes Transmitter Only	28081	40	4.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
2016			
OE Sensor: BMW - 36 10 6 856 872			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28081	40	4.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
Z8			
2000-2002			
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5
2003			
OE Sensor: BMW - 36118378682			
Sensor; Includes Transmitter Only; W/433 MHz			
Sensor	20080	31	3.5
Service Pack; Does Not Include Valve	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert	20040	31	3.5

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Bugatti			
Veyron 16.4			
2006			
Service Pack; Does Not Include Valve.	20023	35	4
Service Pack; W/43mm Silver Insert.	20037	35	4
Service Pack; W/48mm Green Insert.	20038	35	4
Service Pack; W/49mm Black Insert.	20039	35	4
Service Pack; W/51mm Orange Insert.	20040	35	4
Buick			
Allure			
2006			
Sensor.	INDIRECT [D]		
2007-2008			
OE Sensor: General Motors - 10394110, 15921013			
EZ-Sensor.	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 [C]	11.5	1.3
Sensor.	20158	62	7
Service Pack; W/Schrader Sensor.	20004	62	7
Service Pack; W/Siemens Sensor.	20030	80	9
2009			
OE Sensor: General Motors - 25920615			
EZ-Sensor.	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 [C]	11.5	1.3
Sensor.	20153	11.5	1.3
Service Pack.	20008 [C]	11.5	1.3
2010			
OE Sensor: General Motors - 12768826			
EZ-Sensor.	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 [C]	11.5	1.3
Sensor.	28206	11.5	1.3
Service Pack.	20008 [C]	11.5	1.3
2011			
EZ-Sensor.	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 [C]	11.5	1.3
Century			
1999-2005			
Sensor.	INDIRECT [D]		
Enclave			
2008			
OE Sensor: General Motors - 15921013			
EZ-Sensor.	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 [C]	11.5	1.3
Sensor.	20158	62	7
Service Pack; W/Schrader Sensor.	20004	62	7
Service Pack; W/Siemens Sensor.	20030	80	9

Application	Part No.	Torque in-lbs	Torque N.m.
Buick (cont'd)			
Enclave (cont'd)			
2009-2015			
OE Sensor: General Motors - 13598771, 20923680, 22853741, 25920615			
EZ-Sensor.	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 [C]	11.5	1.3
Sensor.	20153	11.5	1.3
Service Pack.	20008 [C]	11.5	1.3
2016			
OE Sensor: General Motors - 13598771			
EZ-Sensor.	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 [C]	11.5	1.3
Sensor.	20153	11.5	1.3
Service Pack.	20008 [C]	11.5	1.3
2017			
OE Sensor: General Motors - 13598771			
Sensor.	20153	11.5	1.3
Service Pack.	20008 [C]	11.5	1.3
Encore			
2013-2015			
OE Sensor: General Motors - 22854866			
EZ-Sensor.	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 [C]	11.5	1.3
Sensor.	28206	11.5	1.3
Service Pack.	20008 [C]	11.5	1.3
2016			
EZ-Sensor.	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 [C]	11.5	1.3
Sensor.	28206	11.5	1.3
Service Pack.	20008 [C]	11.5	1.3
2017			
Sensor.	28206	11.5	1.3
Service Pack.	20008 [C]	11.5	1.3
Envision			
2017			
OE Sensor: General Motors - 13598772			
Sensor.	28206	11.5	1.3
Service Pack.	20008 [C]	11.5	1.3
LaCrosse			
2006			
OE Sensor: General Motors - 15268606			
EZ-Sensor.	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 [C]	11.5	1.3
Sensor.	20158	62	7
Service Pack; W/Schrader Sensor.	20004	62	7

A-Programming Tool Required C-20018 and 20008 are interchangeable. D-Indirect TPMS system. No sensor in wheel DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Buick (cont'd)			
LaCrosse (cont'd)			
2007-2008			
OE Sensor: General Motors - 10394110, 15921013			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20158	62	7
Service Pack; W/Schrader Sensor	20004	62	7
Service Pack; W/Siemens Sensor	20030	80	9
2009			
OE Sensor: General Motors - 25920615			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20153	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
2010-2015			
OE Sensor: General Motors - 12768826, 20922900, 22854866			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28206	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
2016			
OE Sensor: General Motors - 13598772			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28206	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
2017			
OE Sensor: General Motors - 13598773			
Sensor; Exc. ZL1	20154	11.5	1.3
Service Pack; Exc. ZL1	20008 [C]	11.5	1.3
LeSabre			
2000-2005			
Sensor	INDIRECT [D]		
2007			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Lucerne			
2007-2011			
OE Sensor: General Motors - 15254101, 15922396, 25799331, 25920615			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20153	11.5	1.3
Service Pack	20008 [C]	11.5	1.3

Application	Part No.	Torque in-lbs	Torque N.m.
Buick (cont'd)			
Park Avenue			
1998-2005			
Sensor	INDIRECT [D]		
Rainier			
2006-2007			
OE Sensor: General Motors - 25774006			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; OEM Part No. 25774006	20116	62	7
Service Pack	20004	62	7
Regal			
1999-2004			
Sensor	INDIRECT [D]		
2011-2016			
OE Sensor: General Motors - 12768826, 13598772, 22854866			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28206	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
2017			
OE Sensor: General Motors - 13598772			
Sensor	28206	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
Rendezvous			
2003-2007			
Sensor	INDIRECT [D]		
Verano			
2012-2015			
OE Sensor: General Motors - 12768826, 13581558, 22854866			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28206	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
2016-2017			
OE Sensor: General Motors - 13598772			
Sensor	28206	11.5	1.3
Service Pack	20008 [C]	11.5	1.3

A-Programming Tool Required C-20018 and 20008 are interchangeable. D-Indirect TPMS system. No sensor in wheel DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Cadillac			
ATS			
2013			
OE Sensor: General Motors - 22959744 EZ-Sensor; For ATS-V, When installing EZ-Sensor the rubber valve MUST be removed and replaced with Schrader Aluminium valve kit 34000	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; exc V; Rubber Valve	20018 [C]	11.5	1.3
Sensor; exc V	28206	11.5	1.3
Service Pack; exc V	20008 [C]	11.5	1.3
2014			
OE Sensor: General Motors - 13581558, 20964159 EZ-Sensor; For ATS-V, When installing EZ-Sensor the rubber valve MUST be removed and replaced with Schrader Aluminium valve kit 34000	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; exc V; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; exc V; Rubber Valve	20018 [C]	11.5	1.3
Sensor; exc V	28206	11.5	1.3
Sensor; V	28423	62	7
Service Pack; exc V	20008 [C]	11.5	1.3
Service Pack; V	20004	62	7
2015			
OE Sensor: General Motors - 13581558, 20964159 EZ-Sensor; For ATS-V, When installing EZ-Sensor the rubber valve MUST be removed and replaced with Schrader Aluminium valve kit 34000	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; exc V; Rubber Valve	20018 [C]	11.5	1.3
Sensor; exc V	28206	11.5	1.3
Sensor; V	28423	62	7
Service Pack; exc V	20008 [C]	11.5	1.3
Service Pack; V	20004	62	7
2016			
OE Sensor: General Motors - 13598772 EZ-Sensor; For ATS-V, When installing EZ-Sensor the rubber valve MUST be removed and replaced with Schrader Aluminium valve kit 34000	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; exc V; Rubber Valve	20018 [C]	11.5	1.3
Sensor; exc V	28206	11.5	1.3
Service Pack; exc V	20008 [C]	11.5	1.3
2017			
OE Sensor: General Motors - 13598772 Sensor; exc V	28206	11.5	1.3
Service Pack; exc V	20008 [C]	11.5	1.3
CT6			
2016-2017			
OE Sensor: General Motors - 13598773 Sensor; Exc. ZL1	20154	11.5	1.3
Service Pack; Exc. ZL1	20008 [C]	11.5	1.3

Application	Part No.	Torque in-lbs	Torque N.m.
Cadillac (cont'd)			
CTS			
2004-2007			
OE Sensor: General Motors - 25774006 EZ-Sensor; For CTS-V, When installing EZ-Sensor the rubber valve MUST be removed and replaced with Schrader Aluminium valve kit 34000	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; exc V; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20116	62	7
Service Pack	20004	62	7
2008			
OE Sensor: General Motors - 25920615 EZ-Sensor; For CTS-V, When installing EZ-Sensor the rubber valve MUST be removed and replaced with Schrader Aluminium valve kit 34000	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; exc V; Rubber Valve	20018 [C]	11.5	1.3
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20153	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
2009-2011			
OE Sensor: General Motors - 15268606, 15922396, 25920615 EZ-Sensor; For CTS-V, When installing EZ-Sensor the rubber valve MUST be removed and replaced with Schrader Aluminium valve kit 34000	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; exc V; Rubber Valve	20018 [C]	11.5	1.3
Sensor; OEM Part No. 15268606; CTS V; W/315 MHz Sensor	20158	62	7
Sensor; OEM Part No. 25920615; Exc. CTS V	20153	11.5	1.3
Service Pack; OEM Part No. 15268606; CTS V; W/315 MHz Sensor	20004	62	7
Service Pack; OEM Part No. 25920615; Exc. CTS V	20008 [C]	11.5	1.3
2012			
OE Sensor: General Motors - 20923680, 20925924 EZ-Sensor; For CTS-V, When installing EZ-Sensor the rubber valve MUST be removed and replaced with Schrader Aluminium valve kit 34000	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; exc V; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; exc V; Rubber Valve	20018 [C]	11.5	1.3
Sensor; OEM Part No. 15268606; CTS V; W/315 MHz Sensor	20158	62	7
Sensor; OEM Part No. 25920615; Exc. CTS V	20153	11.5	1.3
Service Pack; OEM Part No. 15268606; CTS V; W/315 MHz Sensor	20004	62	7
Service Pack; OEM Part No. 25920615; Exc. CTS V	20008 [C]	11.5	1.3

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Cadillac (cont'd)			
CTS (cont'd)			
2013			
OE Sensor: General Motors - 20925924, 22853741			
EZ-Sensor; For CTS-V, When installing EZ-Sensor the rubber valve MUST be removed and replaced with Schrader Aluminium valve kit 34000	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; exc V; Rubber Valve	20018 [C]	11.5	1.3
Sensor; OEM Part No. 15268606; CTS V; W/315 MHz Sensor	20158	62	7
Sensor; OEM Part No. 25920615; Exc. CTS V	20153	11.5	1.3
Service Pack; OEM Part No. 15268606; CTS V; W/315 MHz Sensor	20004	62	7
Service Pack; OEM Part No. 25920615; Exc. CTS V	20008 [C]	11.5	1.3
2014-2015			
OE Sensor: General Motors - 13581558, 13581559, 20964159			
EZ-Sensor; For CTS-V, When installing EZ-Sensor the rubber valve MUST be removed and replaced with Schrader Aluminium valve kit 34000	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; exc V; Rubber Valve	20018 [C]	11.5	1.3
Sensor; exc V	28206	11.5	1.3
Sensor; V	28423	62	7
Service Pack; exc V	20008 [C]	11.5	1.3
Service Pack; V	20004	62	7
2016			
OE Sensor: General Motors - 13598772			
EZ-Sensor; For CTS-V, When installing EZ-Sensor the rubber valve MUST be removed and replaced with Schrader Aluminium valve kit 34000	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; exc V; Rubber Valve	20018 [C]	11.5	1.3
Sensor; exc V	28206	11.5	1.3
Service Pack; exc V	20008 [C]	11.5	1.3
2017			
OE Sensor: General Motors - 13598772			
Sensor; exc V	28206	11.5	1.3
Service Pack; exc V	20008 [C]	11.5	1.3
DeVille			
2001-2005			
OE Sensor: General Motors - 25773946			
EZ-Sensor; For CTS-V, When installing EZ-Sensor the rubber valve MUST be removed and replaced with Schrader Aluminium valve kit 34000	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; exc V; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20117 [B]	62	7
Service Pack	20003	62	7

Application	Part No.	Torque in-lbs	Torque N.m.
Cadillac (cont'd)			
DTS			
2006			
OE Sensor: General Motors - 15268606			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20158	62	7
Service Pack	20004	62	7
2007-2011			
OE Sensor: General Motors - 15254101, 15922396, 20923680, 25799331, 25920615			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20153	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
ELR			
2014			
OE Sensor: General Motors - 22854866			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28206	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
2015-2016			
OE Sensor: General Motors - 13598772			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28206	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
2017			
OE Sensor: General Motors - 13598772			
Sensor	28206	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
Escalade			
2004			
OE Sensor: General Motors - 15136883			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20115	62	7
Service Pack	20004	62	7
2005-2006			
OE Sensor: General Motors - 15114379			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20107	62	7
Service Pack	20004	62	7

A-Programming Tool Required B-Magnet may be Required to Activate Sensor C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Cadillac (cont'd)			
Escalade (cont'd)			
2007			
OE Sensor: General Motors - 15825475, 25799331			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Clamp-In Style Only; TRW Sensor; W/Aluminium Valve Stem	20158	62	7
Sensor; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem	20153	11.5	1.3
Service Pack; Clamp-In Style Only; TRW Sensor; W/Aluminium Valve Stem	20015	80	9
Service Pack; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem	20008 [C]	11.5	1.3
2008			
OE Sensor: General Motors - 25799331			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; OEM Part No. 25799331; OEM Part No. 15922396	20153	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
2009-2011			
OE Sensor: General Motors - 15922396, 20923680, 25920615			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20153	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
2011			
Service Pack	20008 [C]		
2012-2013			
OE Sensor: General Motors - 13586335, 20923680			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20153	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
2014-2015			
OE Sensor: General Motors - 13581558			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28206	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
2016			
OE Sensor: General Motors - 13581558			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28206	11.5	1.3
Service Pack	20008 [C]	11.5	1.3

Application	Part No.	Torque in-lbs	Torque N.m.
Cadillac (cont'd)			
Escalade (cont'd)			
2017			
OE Sensor: General Motors - 13581558			
Sensor	28206	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
Seville			
2001-2004			
OE Sensor: General Motors - 25773946 EZ-Sensor; For CTS-V, When installing EZ-Sensor the rubber valve MUST be removed and replaced with Schrader Aluminium valve kit 34000	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; exc V; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20117 [B]	62	7
Service Pack	20003	62	7
SRX			
2004-2006			
OE Sensor: General Motors - 25774006			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20116	62	7
Service Pack	20004	62	7
2007-2009			
OE Sensor: General Motors - 15922396, 25799331			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20153	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
2010-2015			
OE Sensor: General Motors - 12768826, 13581558, 20922900, 22854866			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28206	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
2016			
OE Sensor: General Motors - 13581558			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28206	11.5	1.3
Service Pack	20008 [C]	11.5	1.3

A-Programming Tool Required B-Magnet may be Required to Activate Sensor C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Cadillac (cont'd)			
STS			
2005			
OE Sensor: General Motors - 25758220			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; OEM Part No. 25758220	20076	62	7
Service Pack	20004	62	7
2006-2008			
OE Sensor: General Motors - 25758220			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20076	62	7
Service Pack	20004	62	7
2009			
OE Sensor: General Motors - 15922396 EZ-Sensor; For STS-V, When installing EZ-Sensor the rubber valve MUST be removed and replaced with Schrader Aluminium valve kit 34000	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; exc V; Rubber Valve	20018 [C]	11.5	1.3
Sensor; OEM Part No. 25920615; Exc. STS V	20153	11.5	1.3
Service Pack; OEM Part No. 25920615; Exc. STS V	20008 [C]	11.5	1.3
2010			
OE Sensor: General Motors - 15922396 EZ-Sensor; For STS-V, When installing EZ-Sensor the rubber valve MUST be removed and replaced with Schrader Aluminium valve kit 34000	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; OEM Part No. 15922396; OEM Part No. 25920615	20153	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
2011			
OE Sensor: General Motors - 20923680, 25920615			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20153	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
XLR			
2004			
OE Sensor: General Motors - 25758220			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; OEM Part No. 25758220	20076	62	7
Service Pack	20004	62	7

Application	Part No.	Torque in-lbs	Torque N.m.
Cadillac (cont'd)			
XLR (cont'd)			
2005-2009			
OE Sensor: General Motors - 25758220			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20076	62	7
Service Pack	20004	62	7
2010-2011			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
XTS			
2013-2015			
OE Sensor: General Motors - 22854866			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28206	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
2016			
OE Sensor: General Motors - 13598772			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28206	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
2017			
OE Sensor: General Motors - 22854866			
Sensor	28206	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
Chevrolet			
Avalanche			
2004-2006			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2007			
OE Sensor: General Motors - 15825475, 25799331			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Clamp-In Style Only; TRW Sensor; W/Aluminium Valve Stem	20158	62	7
Sensor; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem	20153	11.5	1.3
Service Pack; Clamp-In Style Only; TRW Sensor; W/Aluminium Valve Stem	20015	80	9
Service Pack; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem	20008 [C]	11.5	1.3

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Chevrolet (cont'd)			
Avalanche (cont'd)			
2008			
OE Sensor: General Motors - 25799331			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; OEM Part No. 25799331; OEM Part No. 15922396	20153	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
2009-2013			
OE Sensor: General Motors - 13586335, 15922396, 20923680, 25920615			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20153	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
Aveo			
2007			
OE Sensor: General Motors - 25799331			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Hatchback	20153	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
2008-2011			
OE Sensor: General Motors - 15922396, 20923680, 25920615			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20153	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
Aveo5			
2007			
OE Sensor: General Motors - 25799331			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Hatchback	20153	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
2008-2011			
OE Sensor: General Motors - 15922396, 20923680, 25920615			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20153	11.5	1.3
Service Pack	20008 [C]	11.5	1.3

Application	Part No.	Torque in-lbs	Torque N.m.
Chevrolet (cont'd)			
Camaro			
2010-2011			
OE Sensor: General Motors - 12768826, 20922900			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28206	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
2012			
OE Sensor: General Motors - 20922900, 20964159			
EZ-Sensor; Exc. ZL1	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve; Exc. ZL1	34000	62	7
EZ-Sensor Service Pack; Rubber Valve; Exc. ZL1	20018 [C]	11.5	1.3
Sensor; exc ZL1; OEM Part No. 20922900; OEM Part No. 22854866	28206	11.5	1.3
Sensor; ZL1	28423	62	7
Service Pack; Exc. ZL1	20008 [C]	11.5	1.3
Service Pack; ZL1	20004	62	7
2013-2015			
OE Sensor: General Motors - 20964159, 22854866			
EZ-Sensor; Exc. ZL1	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve; Exc. ZL1	34000	62	7
EZ-Sensor Service Pack; Rubber Valve; Exc. ZL1	20018 [C]	11.5	1.3
Sensor; Exc. ZL1	28206	11.5	1.3
Sensor; ZL1	28423	62	7
Service Pack; Exc. ZL1	20008 [C]	11.5	1.3
Service Pack; ZL1	20004	62	7
2016			
EZ-Sensor; Exc. ZL1	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve; Exc. ZL1	34000	62	7
EZ-Sensor Service Pack; Rubber Valve; Exc. ZL1	20018 [C]	11.5	1.3
Sensor; Exc. ZL1	20154	11.5	1.3
Service Pack; Exc. ZL1	20008 [C]	11.5	1.3
2017			
Sensor; Exc. ZL1	20154	11.5	1.3
Service Pack; Exc. ZL1	20008 [C]	11.5	1.3
Caprice			
2011-2013			
OE Sensor: General Motors - 15268606			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20158	62	7
Service Pack	20004	62	7

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Chevrolet (cont'd)			
Caprice (cont'd)			
2014			
OE Sensor: General Motors - 13581559			
EZ-Sensor; exc Police	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; exc Police; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; exc Police; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20228	71	8
Service Pack	20047	71	8
2015			
OE Sensor: General Motors - 13581559			
EZ-Sensor; exc Police	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; exc Police; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; exc Police; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20228	71	8
Service Pack	20047	71	8
2016			
OE Sensor: General Motors - 13598786			
EZ-Sensor; exc Police	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; exc Police; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; exc Police; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28423	71	8
Service Pack	20004	62	7
2017			
OE Sensor: General Motors - 13598772			
Sensor	28206	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
Captiva Sport			
2012-2013			
OE Sensor: General Motors - 20923680, 22853741			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20153	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
2014-2015			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3

Application	Part No.	Torque in-lbs	Torque N.m.
Chevrolet (cont'd)			
Cobalt			
2008			
OE Sensor: General Motors - 15921013, 15922396			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Clamp-In Style Only; W/Aluminium Valve Stem	20158	62	7
Sensor; Snap-In Style Only; W/Rubber Valve Stem	20153	11.5	1.3
Service Pack; Clamp-In Style Only; W/Aluminium Valve Stem	20004	80	9
Service Pack; Snap-In Style Only; W/Rubber Valve Stem	20008 [C]	11.5	1.3
2009			
OE Sensor: General Motors - 15922396			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Snap-In Style Only; W/Rubber Valve Stem	20153	11.5	1.3
Service Pack; Clamp-In Style Only; W/Aluminium Valve Stem	20004	80	9
Service Pack; Snap-In Style Only; W/Rubber Valve Stem	20008 [C]	11.5	1.3
2010			
OE Sensor: General Motors - 12768826			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28206	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
Colorado			
2007-2012			
OE Sensor: General Motors - 15122618			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20131	62	7
Service Pack	20006	62	7
2015			
OE Sensor: General Motors - 13581558			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28206	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
2016			
OE Sensor: General Motors - 13581558			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28206	11.5	1.3
Service Pack	20008 [C]	11.5	1.3

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Chevrolet (cont'd)			
Colorado (cont'd)			
2017			
OE Sensor: General Motors - 13598772			
Sensor	28206	11.5	1.3
Service Pack	20008 C	11.5	1.3
Corvette			
1997-2000			
OE Sensor: General Motors - 10438853			
Sensor	28006 B	62	7
Service Pack	20012	62	7
2001-2004			
OE Sensor: General Motors - 25773946 EZ-Sensor; exc Z06; When installing EZ-Sensor the rubber valve MUST be removed and replaced with Schrader Aluminium valve kit 34000	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20117 B	62	7
Service Pack	20003	62	7
2005-2009			
OE Sensor: General Motors - 25758220 EZ-Sensor; exc Z06; When installing EZ-Sensor the rubber valve MUST be removed and replaced with Schrader Aluminium valve kit 34000	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20076	62	7
Service Pack	20004	62	7
2010-2011			
OE Sensor: General Motors - 15268606 EZ-Sensor; When installing EZ-Sensor the rubber valve MUST be removed and replaced with Schrader Aluminium valve kit 34000	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20158	62	7
Service Pack	20004	62	7
2012			
OE Sensor: General Motors - 15268606 EZ-Sensor; Z06, Base; When installing EZ-Sensor the rubber valve MUST be removed and replaced with Schrader Aluminium valve kit 34000	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Z06; Base	20018 C	11.5	1.3
	34000	62	7
Sensor; Z06; Base	20158	62	7
Service Pack; Z06; Base	20004	62	7

Application	Part No.	Torque in-lbs	Torque N.m.
Chevrolet (cont'd)			
Corvette (cont'd)			
2013			
OE Sensor: General Motors - 15268606 EZ-Sensor; When installing EZ-Sensor the rubber valve MUST be removed and replaced with Schrader Aluminium valve kit 34000	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20158	62	7
Service Pack	20004	62	7
2014-2015			
OE Sensor: General Motors - 13581560 EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20223	71	8
Service Pack	20047	71	8
2016			
OE Sensor: General Motors - 13581560 EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20223	71	8
Service Pack	20047	71	8
Cruze			
2011-2015			
OE Sensor: General Motors - 12768826, 13581558, 22854866 EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28206	11.5	1.3
Service Pack	20008 C	11.5	1.3
2016			
OE Sensor: General Motors - 13598772 EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28206	11.5	1.3
Service Pack	20008 C	11.5	1.3
2017			
Sensor; Exc. ZL1	20154	11.5	1.3
Service Pack; Exc. ZL1	20008 C	11.5	1.3
Equinox			
2007-2009			
OE Sensor: General Motors - 10394110, 15921013 EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20158	62	7
Service Pack; W/Schrader Sensor	20004	62	7
Service Pack; W/Siemens Sensor	20030	80	9

A-Programming Tool Required B-Magnet may be Required to Activate Sensor C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Chevrolet (cont'd)			
Equinox (cont'd)			
2010-2014			
OE Sensor: General Motors - 12768826, 22854866			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28206	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
2015-2016			
OE Sensor: General Motors - 13598772			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28206	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
2017			
OE Sensor: General Motors - 13598772			
Sensor	28206	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
Express			
2008-2009			
OE Sensor: General Motors - 15921013			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20158	62	7
Service Pack; W/Schrader Sensor	20004	62	7
Service Pack; W/Siemens Sensor	20030	80	9
2010-2015			
OE Sensor: General Motors - 13586335, 22853741, 25920615			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20153	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
2016			
OE Sensor: General Motors - 13586335			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20153	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
2017			
OE Sensor: General Motors - 13586335			
Sensor	20153	11.5	1.3
Service Pack	20008 [C]	11.5	1.3

Application	Part No.	Torque in-lbs	Torque N.m.
Chevrolet (cont'd)			
HHR			
2008-2009			
OE Sensor: General Motors - 15268606, 15922396			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Clamp-In Style Only; W/Aluminium Valve Stem	20158	62	7
Sensor; Snap-In Style Only; W/Rubber Valve Stem	20153	11.5	1.3
Service Pack; Clamp-In Style Only; W/Aluminium Valve Stem	20004	80	9
Service Pack; Snap-In Style Only; W/Rubber Valve Stem	20008 [C]	11.5	1.3
2010			
OE Sensor: General Motors - 12768826			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28206	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
2011			
OE Sensor: General Motors - 25920615			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20153	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
Impala			
2000-2005			
Sensor	INDIRECT [D]		
2006			
OE Sensor: General Motors - 15268606			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; W/Alloy Wheels	20158	62	7
Service Pack; W/Alloy Wheels	20004	62	7
2007			
OE Sensor: General Motors - 15268606, 25799331			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Clamp-In Style Only; W/Aluminium Valve Stem	20158	62	7
Sensor; Snap-In Style Only; W/Rubber Valve Stem	20153	11.5	1.3
Service Pack; Clamp-In Style Only; W/Aluminium Valve Stem	20004	62	7
Service Pack; Snap-In Style Only; W/Rubber Valve Stem	20008 [C]	11.5	1.3

A-Programming Tool Required C-20018 and 20008 are interchangeable. D-Indirect TPMS system. No sensor in wheel DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Chevrolet (cont'd)			
Impala (cont'd)			
2008-2013			
OE Sensor: General Motors - 15922396, 22853741, 25920615			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20153	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
2014-2015			
OE Sensor: General Motors - 22854866			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28206	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
2016			
OE Sensor: General Motors - 13598772, 22854866			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28206	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
2017			
OE Sensor: General Motors - 13598772, 22854866			
Sensor	28206	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
Malibu			
2008			
OE Sensor: General Motors - 15921013, 15922396			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Clamp-In Style Only; W/Aluminium Valve Stem	20158	62	7
Sensor; Snap-In Style Only; W/Rubber Valve Stem	20153	11.5	1.3
Service Pack; Clamp-In Style Only; W/Aluminium Valve Stem	20004	80	9
Service Pack; Snap-In Style Only; W/Rubber Valve Stem	20008 [C]	11.5	1.3
2009			
OE Sensor: General Motors - 15922396			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20153	11.5	1.3
Service Pack	20008 [C]	11.5	1.3

Application	Part No.	Torque in-lbs	Torque N.m.
Chevrolet (cont'd)			
Malibu (cont'd)			
2010			
OE Sensor: General Motors - 12768826			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28206	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
2011-2012			
OE Sensor: General Motors - 25920615			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20153	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
2013-2015			
OE Sensor: General Motors - 22854866			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28206	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
2016			
OE Sensor: General Motors - 13598773			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20154	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
2017			
OE Sensor: General Motors - 13598773			
Sensor	20154	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
Monte Carlo			
2000-2005			
Sensor	INDIRECT [D]		
2006			
OE Sensor: General Motors - 15268606			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; W/Alloy Wheels	20158	62	7
Service Pack; W/Alloy Wheels	20004	62	7

A-Programming Tool Required C-20018 and 20008 are interchangeable. D-Indirect TPMS system. No sensor in wheel DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Chevrolet (cont'd)			
Monte Carlo (cont'd)			
2007			
OE Sensor: General Motors - 15268606, 25799331			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Clamp-In Style Only; W/Aluminium Valve Stem	20158	62	7
Sensor; Snap-In Style Only; W/Rubber Valve Stem	20153	11.5	1.3
Service Pack; Clamp-In Style Only; W/Aluminium Valve Stem	20004	62	7
Service Pack; Snap-In Style Only; W/Rubber Valve Stem	20008 [C]	11.5	1.3
Orlando			
2012-2014			
OE Sensor: General Motors - 12768826			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28206	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
2017			
OE Sensor: General Motors - 12768826			
Sensor	28206	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
Silverado Series			
2004			
OE Sensor: General Motors - 15136883			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20115	62	7
Service Pack	20004	62	7
2005-2006			
OE Sensor: General Motors - 15114379			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20107	62	7
Service Pack	20004	62	7

Application	Part No.	Torque in-lbs	Torque N.m.
Chevrolet (cont'd)			
Silverado Series (cont'd)			
2007			
OE Sensor: General Motors - 15114379, 15254101, 15825475			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Clamp-In Style Only; TRW Sensor; W/Aluminium Valve Stem; Exc. Classic	20158	62	7
Sensor; Classic	20107	62	7
Sensor; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem; Exc. Classic	20153	11.5	1.3
Service Pack; Clamp-In Style Only; TRW Sensor; W/Aluminium Valve Stem; Exc. Classic	20015	80	9
Service Pack; Classic	20004	62	7
Service Pack; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem; Exc. Classic	20008 [C]	11.5	1.3
2008-2012			
OE Sensor: General Motors - 15922396, 25920615			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20153	11.5	1.3
Sensor; W/Single Rear Wheels	20153	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
Service Pack; W/Single Rear Wheels	20008 [C]	11.5	1.3
2013			
OE Sensor: General Motors - 25920615			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; W/Single Rear Wheels	20153	11.5	1.3
Service Pack; W/Single Rear Wheels	20008 [C]	11.5	1.3
2014-2015			
OE Sensor: General Motors - 13581558			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; W/Single Rear Wheels	28206	11.5	1.3
Service Pack; W/Single Rear Wheels	20008 [C]	11.5	1.3
2016			
OE Sensor: General Motors - 13581558			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; W/Single Rear Wheels	28206	11.5	1.3
Service Pack; W/Single Rear Wheels	20008 [C]	11.5	1.3
2017			
OE Sensor: General Motors - 13581558			
Sensor; W/Single Rear Wheels	28206	11.5	1.3
Service Pack; W/Single Rear Wheels	20008 [C]	11.5	1.3

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Chevrolet (cont'd)			
Sonic			
2012-2015			
OE Sensor: General Motors - 12768826, 13581558			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28206	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
2016			
OE Sensor: General Motors - 13598772			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28206	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
2017			
OE Sensor: General Motors - 13598772			
Sensor	28206	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
Spark			
2013-2015			
OE Sensor: General Motors - 12768826, 22854866			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28206	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
2016			
OE Sensor: General Motors - 13598772			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28206	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
2017			
OE Sensor: General Motors - 13598772			
Sensor	28206	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
SS			
2014-2016			
OE Sensor: General Motors - 13598786, 20964159			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28423	62	7
Service Pack	20004	62	7
2017			
OE Sensor: General Motors - 13598786			
Sensor	28423	62	7
Service Pack	20004	62	7

Application	Part No.	Torque in-lbs	Torque N.m.
Chevrolet (cont'd)			
SSR			
2006			
OE Sensor: General Motors - 25774006			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; OEM Part No. 25774006	20116	62	7
Service Pack	20004	62	7
2007			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Suburban			
2004			
OE Sensor: General Motors - 15136883			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20115	62	7
Service Pack	20004	62	7
2005-2006			
OE Sensor: General Motors - 15114379			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20107	62	7
Service Pack	20004	62	7
2007			
OE Sensor: General Motors - 15825475, 25799331			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Clamp-In Style Only; TRW Sensor; W/Aluminium Valve Stem	20158	62	7
Sensor; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem	20153	11.5	1.3
Service Pack; Clamp-In Style Only; TRW Sensor; W/Aluminium Valve Stem	20015	80	9
Service Pack; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem	20008 [C]	11.5	1.3
2008-2014			
OE Sensor: General Motors - 13581558, 13586335, 15922396, 25920615			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20153	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
2014			
OE Sensor: General Motors - 13581558			
Sensor	28206	11.5	1.3

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Chevrolet (cont'd)			
Suburban (cont'd)			
2015			
OE Sensor: General Motors - 13581558			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28206	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
2016			
OE Sensor: General Motors - 13581558			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28206	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
2017			
OE Sensor: General Motors - 13581558			
Sensor	28206	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
Tahoe			
2004			
OE Sensor: General Motors - 15136883			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20115	62	7
Service Pack	20004	62	7
2005-2006			
OE Sensor: General Motors - 15114379			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20107	62	7
Service Pack	20004	62	7
2007			
OE Sensor: General Motors - 15825475, 25799331			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Clamp-In Style Only; TRW Sensor; W/Aluminium Valve Stem	20158	62	7
Sensor; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem	20153	11.5	1.3
Service Pack; Clamp-In Style Only; TRW Sensor; W/Aluminium Valve Stem	20015	80	9
Service Pack; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem	20008 [C]	11.5	1.3

Application	Part No.	Torque in-lbs	Torque N.m.
Chevrolet (cont'd)			
Tahoe (cont'd)			
2008-2013			
OE Sensor: General Motors - 13586335, 15922396, 20923680, 25920615			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20153	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
2014-2015			
OE Sensor: General Motors - 13581558			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28206	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
2016			
OE Sensor: General Motors - 13581558			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28206	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
2017			
OE Sensor: General Motors - 13581558			
Sensor	28206	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
Trailblazer			
2006-2009			
OE Sensor: General Motors - 25774006			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; OEM Part No. 25774006	20116	62	7
Service Pack	20004	62	7
Traverse			
2009-2015			
OE Sensor: General Motors - 22853741, 23445327, 25920615			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20153	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
2016			
OE Sensor: General Motors - 13598771			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20153	11.5	1.3
Service Pack	20008 [C]	11.5	1.3

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Chevrolet (cont'd)			
Traverse (cont'd)			
2017			
OE Sensor: General Motors - 13598771			
Sensor	20153	11.5	1.3
Service Pack	20008 C	11.5	1.3
Trax			
2013-2015			
OE Sensor: General Motors - 13581558, 22854866			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28206	11.5	1.3
Service Pack	20008 C	11.5	1.3
2016			
OE Sensor: General Motors - 13598772			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28206	11.5 in-lbs	1.3 N.r
Service Pack	20008 C	11.5	1.3
Service Pack; Rubber Valve	20018 C	11.5	1.3
2017			
OE Sensor: General Motors - 13598772			
Sensor	28206	11.5 in-lbs	1.3 N.r
Service Pack	20008 C	11.5	1.3
Uplander			
2008-2009			
OE Sensor: General Motors - 15268606			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20158	62	7
Service Pack	20004	62	7
Volt			
2010			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
2011-2015			
OE Sensor: General Motors - 12768826, 20922900, 22854866			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28206	11.5	1.3
Service Pack	20008 C	11.5	1.3

Application	Part No.	Torque in-lbs	Torque N.m.
Chevrolet (cont'd)			
Volt (cont'd)			
2016			
OE Sensor: General Motors - 13598772			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28206	11.5	1.3
Service Pack	20008 C	11.5	1.3
2017			
Sensor; Exc. ZL1	20154	11.5	1.3
Service Pack; Exc. ZL1	20008 C	11.5	1.3
Chrysler			
200			
2011			
OE Sensor: Chrysler - 68078861AA			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor; Caution: Ez-sensor will not support (Wai) Wheel Arch Initiators	33000 A	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28308 F	11.5	1.3
Service Pack; Fits Schrader Alum stem sensor. Does not include stem.	20013	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Rubber Valve	20018 C	11.5	1.3
2012			
OE Sensor: Chrysler - 68078861AA			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor; Caution: Ez-sensor will not support (Wai) Wheel Arch Initiators	33000 A	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Rubber Valve	28308 F	11.5	1.3
Service Pack; Fits Schrader Alum stem sensor. Does not include stem	20013	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Rubber Valve	20018 C	11.5	1.3
2013-2014			
OE Sensor: Chrysler - 68078861AA			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor; Caution: Ez-sensor will not support (Wai) Wheel Arch Initiators	33000 A	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28308 F	11.5	1.3
Service Pack; Rubber Valve	20018 C	11.5	1.3
2015-2016			
OE Sensor: Chrysler - 68193586AC			
Sensor	28586		
Service Pack	20043		

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200 F-Supercedes the 20066

Application	Part No.	Torque in-lbs	Torque N.m.
Chrysler (cont'd)			
300			
2005-2006			
OE Sensor: Chrysler - 56053030AB			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28308 F	11.5	1.3
Service Pack; Fits Schrader Alum stem sensor. Does not include stem.	20013	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Rubber Valve	20018 C	11.5	1.3
Service Pack; W/Siemens Sensor	20030	71	8
2007			
OE Sensor: Chrysler - 56053030AB, 68001696AA			
EZ-Sensor	33000 A	11.5	1.3
	33100 A	11.5	1.3
EZ-Sensor; Caution: Ez-sensor will not support (Wai) Wheel Arch Initiators	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Can also use 28155 until depleted	28434 E	11.5	1.3
Sensor; Use until depleted-superseded by 20066	28308 F	11.5	1.3
Service Pack; Fits Schrader Alum stem sensor. Does not include stem.	20013	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Rubber Valve	20018 C	11.5	1.3
Service Pack; W/Siemens Sensor	20030	71	8
2008			
OE Sensor: Chrysler - 68001698AB			
EZ-Sensor	33100 A	11.5	1.3
	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; W/Steel Wheels	20018 C	11.5	1.3
Sensor	28434 E	11.5	1.3
Service Pack; Fits Schrader Alum stem sensor. Does not include stem.	20013	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Rubber Valve	20018 C	11.5	1.3
Service Pack; W/Siemens Sensor	20030	71	8
2009-2010			
OE Sensor: Chrysler - 56029400AC			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28291	58	6.5
Service Pack; Does Not Include Stem	20016	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Rubber Valve	20018 C	11.5	1.3
2010			
OE Sensor: Chrysler - 56029398AB			
Sensor	20398	11.5	1.3

Application	Part No.	Torque in-lbs	Torque N.m.
Chrysler (cont'd)			
300 (cont'd)			
2011			
OE Sensor: Chrysler - 56029398AB			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20398	11.5	1.3
Service Pack; Rubber Valve	20018 C	11.5	1.3
2012			
OE Sensor: Chrysler - 56029398AB			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; W/Rubber Stem Snap-in Sensor	20398	11.5	1.3
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Rubber Valve	20018 C	11.5	1.3
Service Pack; W/Metal Stem Clamp-in Sensor; Does Not Include Stem	20016	58	6.5
Service Pack; W/Rubber Stem Snap-in Sensor	20018 C	11.5	1.3
2013-2015			
OE Sensor: Chrysler - 56029398AB			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20398	11.5	1.3
Service Pack; Rubber Valve	20018 C	11.5	1.3
2016			
OE Sensor: Chrysler - 56029398AB			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20398	11.5	1.3
Service Pack; Rubber Valve	20018 C	11.5	1.3
2017			
OE Sensor: Chrysler - 56029398AB			
Sensor	20398	11.5	1.3
Service Pack; Rubber Valve	20018 C	11.5	1.3
300M			
2002-2004			
OE Sensor: Chrysler - 52088990AC			
EZ-Sensor	33100 A	11.5	1.3
	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20028 B	35	4
Service Pack; W/Schrader Sensor	20003	35	4
Service Pack; W/Siemens Sensor	20030	35	4

A-Programming Tool Required B-Magnet may be Required to Activate Sensor C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200
E-Supercedes the 28155 F-Supercedes the 20066

Application	Part No.	Torque in-lbs	Torque N.m.
Chrysler (cont'd)			
Aspen			
2007-2011			
OE Sensor: Chrysler - 56029465AB, 56053036AA			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor; Use 33500 for Wheel Arc Initiator systems	33000 A	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28308 F	11.5	1.3
Service Pack; Fits Schrader Alum stem sensor. Does not include stem.	20013	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Rubber Valve	20018 C	11.5	1.3
Service Pack; W/Siemens Sensor	20030	71	8
2012-2015			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
Service Pack; Rubber Valve	20018 C	11.5	1.3
Concorde			
2002-2004			
OE Sensor: Chrysler - 52088990AC			
EZ-Sensor	33100 A	11.5	1.3
	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20028 B	35	4
Service Pack; W/Schrader Sensor	20003	35	4
Service Pack; W/Siemens Sensor	20030	35	4
Crossfire			
2004			
OE Sensor: Chrysler - 52088990AD			
EZ-Sensor	33100 A	11.5	1.3
	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20028 B	35	4
Service Pack; W/Schrader Sensor	20003	35	4
Service Pack; W/Siemens Sensor	20030	35	4

Application	Part No.	Torque in-lbs	Torque N.m.
Chrysler (cont'd)			
Crossfire (cont'd)			
2005			
OE Sensor: Chrysler - 5142340AA, 52088990AC			
EZ-Sensor	33100 A	11.5	1.3
	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor; W/315 MHz Sensor. Caution: Pressure by location vehicles not supported by			
EZ-Sensor	33000 A	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20028 B	35	4
	28308 F	11.5	1.3
Service Pack; exc Siemens OE Sensor; Service Pack contains cap, core, grommet, and nut	20003	35	4
Service Pack; Fits Schrader Alum stem sensor. Does not include stem.	20013	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Rubber Valve	20018 C	11.5	1.3
2006-2008			
OE Sensor: Chrysler - 5096808AA			
EZ-Sensor	33100 A	11.5	1.3
	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor; W/315 MHz Sensor. Caution: Pressure by location vehicles not supported by			
EZ-Sensor	33000 A	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20028 B	35	4
Service Pack; W/Schrader Sensor	20003	35	4
Service Pack; W/Siemens Sensor	20030	35	4
2009-2011			
EZ-Sensor	33100 A	11.5	1.3
	33500 A, DB	11.5	1.3
Intrepid			
2002-2004			
OE Sensor: Chrysler - 52088990AC			
EZ-Sensor	33100 A	11.5	1.3
	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20028 B	35	4
Service Pack; W/Schrader Sensor	20003	35	4
Service Pack; W/Siemens Sensor	20030	35	4
Pacifica			
2003			
EZ-Sensor	33100 A	11.5	1.3
	33500 A, DB	11.5	1.3

A-Programming Tool Required B-Magnet may be Required to Activate Sensor C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200
F-Supercedes the 20066

Application	Part No.	Torque in-lbs	Torque N.m.
Chrysler (cont'd)			
Pacifica (cont'd)			
2004			
OE Sensor: Chrysler - 5127335AB, 52088990AC			
EZ-Sensor	33100 [A]	11.5	1.3
	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; OEM Part No. 04727392AD	20335	71	8
Sensor; OEM Part No. 52088990AC	20028 [B]	35	4
Service Pack; W/Schrader Sensor	20003	35	4
Service Pack; W/Siemens Sensor	20030	71	8
2005			
OE Sensor: Chrysler - 5127335AB			
EZ-Sensor	33500 [A, DB]	11.5	1.3
Sensor	20335	71	8
Service Pack	20030	71	8
2006-2007			
OE Sensor: Chrysler - 56053030AB, 68001696AA			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor; Caution: Ez-sensor will not support			
(Wai) Wheel Arch Initiators	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28308 [F]	11.5	1.3
Service Pack; Fits Schrader Alum stem sensor.			
Does not include stem.	20013	58	6.5
Service Pack; Fits Schrader Sensor; Includes			
Stem Only	20020	58	6.5
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Service Pack; W/Siemens Sensor	20030	71	8
2008			
OE Sensor: Chrysler - 68001696AA			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor; Caution: Ez-sensor will not support			
(Wai) Wheel Arch Initiators	33000 [A]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28308 [F]	11.5	1.3
Service Pack; Fits Schrader Alum stem sensor.			
Does not include stem.	20013	58	6.5
Service Pack; Fits Schrader Sensor; Includes			
Stem Only	20020	58	6.5
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Service Pack; W/Siemens Sensor	20030	71	8
Prowler			
2001			
OE Sensor: Chrysler - 4815132AB			
Sensor	28004	35	4
Service Pack; W/Black Sensor Body	20012	35	4
Service Pack; W/Red Sensor Body	20003	35	4

Application	Part No.	Torque in-lbs	Torque N.m.
Chrysler (cont'd)			
Prowler (cont'd)			
2002			
OE Sensor: Chrysler - 52088990AC			
EZ-Sensor	33100 [A]	11.5	1.3
	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20028 [B]	35	4
Service Pack; W/Schrader Sensor	20003	35	4
Service Pack; W/Siemens Sensor	20030	35	4
PT Cruiser			
2008-2010			
OE Sensor: Chrysler - 68001696AA, 68001696AB			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor; Caution: Ez-sensor will not support			
(Wai) Wheel Arch Initiators	33000 [A]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28308 [F]	11.5	1.3
Service Pack; Fits Schrader Alum stem sensor.			
Does not include stem.	20013	58	6.5
Service Pack; Fits Schrader Sensor; Includes			
Stem Only	20020	58	6.5
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Service Pack; W/Siemens Sensor	20030	71	8
Sebring			
2007-2009			
OE Sensor: Chrysler - 68001696AA, 68001696AB			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor; Caution: Ez-sensor will not support			
(Wai) Wheel Arch Initiators	33000 [A]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28308 [F]	11.5	1.3
Service Pack; Fits Schrader Alum stem sensor.			
Does not include stem.	20013	58	6.5
Service Pack; Fits Schrader Sensor; Includes			
Stem Only	20020	58	6.5
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Service Pack; W/Siemens Sensor	20030	71	8
2008-2009			
EZ-Sensor	33100 [A]	11.5	1.3
2010			
OE Sensor: Chrysler - 68078861AA			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor; Caution: Ez-sensor will not support			
(Wai) Wheel Arch Initiators	33000 [A]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28308 [F]	11.5	1.3
Service Pack; Fits Schrader Alum stem sensor.			
Does not include stem.	20013	58	6.5
Service Pack; Fits Schrader Sensor; Includes			
Stem Only	20020	58	6.5
Service Pack; Rubber Valve	20018 [C]	11.5	1.3

A-Programming Tool Required B-Magnet may be Required to Activate Sensor C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200
F-Supercedes the 20066

Application	Part No.	Torque in-lbs	Torque N.m.
Chrysler (cont'd)			
Town & Country			
2002-2003			
OE Sensor: Chrysler - 52088990AC			
EZ-Sensor	33100 [A]	11.5	1.3
	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20028 [B]	35	4
Service Pack	20003	35	4
2004-2005			
OE Sensor: Chrysler - 5127335AB			
Sensor	20335	71	8
Service Pack	20030	71	8
2006-2007			
OE Sensor: Chrysler - 56053030AB, 68001696AA			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor; Caution: Ez-sensor will not support (Wai) Wheel Arch Initiators	33000 [A]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28308 [F]	11.5	1.3
Service Pack; Fits Schrader Alum stem sensor. Does not include stem.	20013	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Service Pack; W/Siemens Sensor	20030	71	8
2008			
OE Sensor: Chrysler - 68001696AA, 68001698AB			
EZ-Sensor	33100 [A]	11.5	1.3
	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor; Caution: Ez-sensor will not support (Wai) Wheel Arch Initiators	33000 [A]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Can also use 20066 until depleted	28308 [F]	11.5	1.3
Sensor; Can also use 28155 until depleted	28434 [E]	11.5	1.3
Service Pack; Fits Schrader Alum stem sensor. Does not include stem.	20013	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Service Pack; W/Siemens Sensor	20030	71	8
2009-2010			
OE Sensor: Chrysler - 68001698AB			
EZ-Sensor	33100 [A]	11.5	1.3
	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28434 [E]	11.5	1.3
Service Pack; Fits Schrader Alum stem sensor. Does not include stem.	20013	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Service Pack; W/Siemens Sensor	20030	71	8

Application	Part No.	Torque in-lbs	Torque N.m.
Chrysler (cont'd)			
Town & Country (cont'd)			
2011-2014			
OE Sensor: Chrysler - 56029398AB			
EZ-Sensor	33100 [A]	11.5	1.3
	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20398	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2015			
OE Sensor: Chrysler - 56029398AB, 68241067AB			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20398	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2016			
OE Sensor: Chrysler - 68241067AB			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20398	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2017			
OE Sensor: Chrysler - 68241067AB			
Sensor	20398	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Voyager			
2002-2003			
OE Sensor: Chrysler - 52088990AC			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20028 [B]	35	4
Service Pack	20003	35	4
Dodge			
Avenger			
2007			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3

A-Programming Tool Required B-Magnet may be Required to Activate Sensor C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200
E-Supercedes the 28155 F-Supercedes the 20066

Application	Part No.	Torque in-lbs	Torque N.m.
Dodge (cont'd)			
Avenger (cont'd)			
2008-2009			
OE Sensor: Chrysler - 68001696AA, 68001696AB			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor; Caution: Ez-sensor will not support (Wai) Wheel Arch Initiators	33000 A	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28308 F	11.5	1.3
Service Pack; Fits Schrader Alum stem sensor. Does not include stem.	20013	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Rubber Valve	20018 C	11.5	1.3
Service Pack; W/Siemens Sensor	20030	71	8
2010-2012			
OE Sensor: Chrysler - 68078861AA			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor; Caution: Ez-sensor will not support (Wai) Wheel Arch Initiators	33000 A	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28308 F	11.5	1.3
Service Pack; Fits Schrader Alum stem sensor. Does not include stem.	20013	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Rubber Valve	20018 C	11.5	1.3
2013-2014			
OE Sensor: Chrysler - 68078861AA			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor; Caution: Ez-sensor will not support (Wai) Wheel Arch Initiators	33000 A	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28308 F	11.5	1.3
Service Pack; Rubber Valve	20018 C	11.5	1.3
Caliber			
2007-2010			
OE Sensor: Chrysler - 68001696AB, 68078861AA			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor; Caution: Ez-sensor will not support (Wai) Wheel Arch Initiators	33000 A	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28308 F	11.5	1.3
Service Pack; Fits Schrader Alum stem sensor. Does not include stem.	20013	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Rubber Valve	20018 C	11.5	1.3
Service Pack; W/Siemens Sensor	20030	71	8

Application	Part No.	Torque in-lbs	Torque N.m.
Dodge (cont'd)			
Caliber (cont'd)			
2011-2012			
OE Sensor: Chrysler - 68078861AA			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor; Caution: Ez-sensor will not support (Wai) Wheel Arch Initiators	33000 A	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28308 F	11.5	1.3
Service Pack; Fits Schrader Alum stem sensor. Does not include stem.	20013	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Rubber Valve	20018 C	11.5	1.3
Caravan			
2002-2003			
OE Sensor: Chrysler - 52088990AC			
EZ-Sensor	33100 A	11.5	1.3
	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20028 B	35	4
Service Pack	20003	35	4
2004-2005			
OE Sensor: Chrysler - 5127335AB			
Sensor	20335	71	8
Service Pack	20030	71	8
2006-2007			
OE Sensor: Chrysler - 68001696AA			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor; Caution: Ez-sensor will not support (Wai) Wheel Arch Initiators	33000 A	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28308 F	11.5	1.3
Service Pack; Fits Schrader Alum stem sensor. Does not include stem.	20013	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Rubber Valve	20018 C	11.5	1.3
Service Pack; W/Siemens Sensor	20030	71	8
Challenger			
2008			
OE Sensor: Chrysler - 56029400AB, 56029481AB			
EZ-Sensor	33100 A	11.5	1.3
	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; OEM No. 56029400AB	28291	58	6.5
Sensor; OEM No. 56029481AB; 433 MHz Sensor; Rubber Valve	28434 E	11.5	1.3
Service Pack; Does Not Include Stem	20016	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Rubber Valve	20018 C	11.5	1.3

A-Programming Tool Required B-Magnet may be Required to Activate Sensor C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200
E-Supercedes the 28155 F-Supercedes the 20066

Application	Part No.	Torque in-lbs	Torque N.m.
Dodge (cont'd)			
Challenger (cont'd)			
2009			
OE Sensor: Chrysler - 56029400AC			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28291	58	6.5
Service Pack; Does Not Include Stem	20016	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
2010-2012			
OE Sensor: Chrysler - 56029398AA, 56029398AB, 56029400AC, 56029400AD			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; W/Metal Stem Clamp-in Sensor	28291	58	6.5
Sensor; W/Rubber Stem Snap-in Sensor	20398	11.5	1.3
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Rubber Valve	20018 C	11.5	1.3
Service Pack; W/Metal Stem Clamp-in Sensor; Does Not Include Stem	20016	58	6.5
2013-2015			
OE Sensor: Chrysler - 56029398AB			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; W/Rubber Stem Snap-in Sensor	20398	11.5	1.3
Service Pack; W/Rubber Stem Snap-in Sensor	20018 C	11.5	1.3
2016			
OE Sensor: Chrysler - 56029398AB			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; W/Rubber Stem Snap-in Sensor	20398	11.5	1.3
Service Pack; W/Rubber Stem Snap-in Sensor	20018 C	11.5	1.3
2017			
OE Sensor: Chrysler - 56029398AB			
Sensor; W/Rubber Stem Snap-in Sensor	20398	11.5	1.3
Service Pack; W/Rubber Stem Snap-in Sensor	20018 C	11.5	1.3
Charger			
2005			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3

Application	Part No.	Torque in-lbs	Torque N.m.
Dodge (cont'd)			
Charger (cont'd)			
2006-2007			
OE Sensor: Chrysler - 68001696AA			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor; Caution: Ez-sensor will not support (Wai) Wheel Arch Initiators	33000 A	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28308 F	11.5	1.3
Service Pack; Fits Schrader Alum stem sensor. Does not include stem.	20013	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Rubber Valve	20018 C	11.5	1.3
Service Pack; W/Siemens Sensor	20030	71	8
2008			
OE Sensor: Chrysler - 68001698AB			
EZ-Sensor	33100 A	11.5	1.3
	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28434 E	11.5	1.3
Service Pack; Fits Schrader Alum stem sensor. Does not include stem.	20013	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Rubber Valve	20018 C	11.5	1.3
Service Pack; W/Siemens Sensor	20030	71	8
2009			
OE Sensor: Chrysler - 56029400AC			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28291	58	6.5
Service Pack; Does Not Include Stem	20016	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
2010			
OE Sensor: Chrysler - 56029398AA, 56029400AC			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; W/Metal Stem Clamp-in Sensor	28291	58	6.5
Sensor; W/Rubber Stem Snap-in Sensor	20398	11.5	1.3
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Rubber Valve	20018 C	11.5	1.3
Service Pack; W/Metal Stem Clamp-in Sensor; Does Not Include Stem	20016	58	6.5
2011			
OE Sensor: Chrysler - 56029398AB			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; W/Rubber Stem Snap-in Sensor	20398	11.5	1.3
Service Pack; Rubber Valve	20018 C	11.5	1.3

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200 E-Supercedes the 28155 F-Supercedes the 20066

Application	Part No.	Torque in-lbs	Torque N.m.
Dodge (cont'd)			
Charger (cont'd)			
2012-2015			
OE Sensor: Chrysler - 56029398AB			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20398	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2016			
OE Sensor: Chrysler - 56029398AB			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20398	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2017			
OE Sensor: Chrysler - 56029398AB			
Sensor	20398	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Dakota			
2008-2010			
OE Sensor: Chrysler - 56029319AA, 56029319AB			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor; Caution: Ez-sensor will not support (Wai) Wheel Arch Initiators	33000 [A]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28461 [G]	11.5	1.3
Service Pack; Fits Schrader Alum stem sensor. Does not include stem.	20013	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2011			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Dart			
2013-2016			
OE Sensor: Chrysler - 68193586AA, 68193586AB, 68193586AC			
Sensor	28586		
Service Pack	20043		

Application	Part No.	Torque in-lbs	Torque N.m.
Dodge (cont'd)			
Durango			
2007			
OE Sensor: Chrysler - 56053036AA			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor; Caution: Ez-sensor will not support (Wai) Wheel Arch Initiators	33000 [A]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28308 [F]	11.5	1.3
Service Pack; Fits Schrader Alum stem sensor. Does not include stem.	20013	58	6.5
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Service Pack; W/Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; W/Siemens Sensor	20030	71	8
2008			
OE Sensor: Chrysler - 56053036AA			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor; Caution: Ez-sensor will not support (Wai) Wheel Arch Initiators	33000 [A]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28308 [F]	11.5	1.3
Service Pack; Fits Schrader Alum stem sensor. Does not include stem.	20013	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Service Pack; W/Siemens Sensor	20030	71	8
2009			
OE Sensor: Chrysler - 56029465AB			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor; Caution: Ez-sensor will not support (Wai) Wheel Arch Initiators	33000 [A]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28308 [F]	11.5	1.3
Service Pack; Fits Schrader Alum stem sensor. Does not include stem.	20013	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2011-2015			
OE Sensor: Chrysler - 56029398AB			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20398	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2016			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20398	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200 F-Supercedes the 20066 G-Supercedes the 28154

Application	Part No.	Torque in-lbs	Torque N.m.
Dodge (cont'd)			
Grand Caravan			
2002-2003			
OE Sensor: Chrysler - 52088990AC			
EZ-Sensor	33100 [A]	11.5	1.3
	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20028 [B]	35	4
Service Pack	20003	35	4
2004-2005			
OE Sensor: Chrysler - 5127335AB			
Sensor	20335	71	8
Service Pack	20030	71	8
2006-2007			
OE Sensor: Chrysler - 68001696AA			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor; Caution: Ez-sensor will not support (Wai) Wheel Arch Initiators	33000 [A]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28308 [F]	11.5	1.3
Service Pack; Fits Schrader Alum stem sensor. Does not include stem.	20013	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Service Pack; W/Siemens Sensor	20030	71	8
2008			
OE Sensor: Chrysler - 68001698AB			
EZ-Sensor	33100 [A]	11.5	1.3
	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28434 [E]	11.5	1.3
Service Pack; Fits Schrader Alum stem sensor. Does not include stem.	20013	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Service Pack; W/Siemens Sensor	20030	71	8
2009-2010			
OE Sensor: Chrysler - 68001698AB			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28434 [E]	11.5	1.3
Service Pack; Fits Schrader Alum stem sensor. Does not include stem.	20013	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Service Pack; W/Siemens Sensor	20030	71	8

Application	Part No.	Torque in-lbs	Torque N.m.
Dodge (cont'd)			
Grand Caravan (cont'd)			
2011-2015			
OE Sensor: Chrysler - 56029398AB			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20398	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2016			
OE Sensor: Chrysler - 68241067AB			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20398	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2017			
OE Sensor: Chrysler - 68241067AB			
Sensor	20398	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Intrepid			
2002-2004			
OE Sensor: Chrysler - 52088990AC			
EZ-Sensor	33100 [A]	11.5	1.3
	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20028 [B]	35	4
Service Pack	20003	35	4
Journey			
2009			
OE Sensor: Chrysler - 68001698AB			
EZ-Sensor	33100 [A]	11.5	1.3
	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28434 [E]	11.5	1.3
Service Pack; Fits Schrader Alum stem sensor. Does not include stem.	20013	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Service Pack; W/Siemens Sensor	20030	71	8

A-Programming Tool Required B-Magnet may be Required to Activate Sensor C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200
E-Supercedes the 28155 F-Supercedes the 20066

Application	Part No.	Torque in-lbs	Torque N.m.
Dodge (cont'd)			
Journey (cont'd)			
2010			
OE Sensor: Chrysler - 56029398AA, 68001698AB			
EZ-Sensor	33100 [A]	11.5	1.3
	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; OEM No. 56029398AA; Rubber Valve	20398	11.5	1.3
Sensor; Replaces clamp-in Sensor	28434 [E]	11.5	1.3
Service Pack; Fits Schrader Alum stem sensor. Does not include stem.	20013	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Service Pack; W/Siemens Sensor	20030	71	8
2011-2015			
OE Sensor: Chrysler - 56029398AA, 56029398AB			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20398	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2016			
OE Sensor: Chrysler - 68241067AB			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20398	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2017			
OE Sensor: Chrysler - 68241067AB			
Sensor	20398	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Magnum			
2005-2007			
OE Sensor: Chrysler - 68001696AA			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor; Caution: Ez-sensor will not support (Wai) Wheel Arch Initiators	33000 [A]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28308 [F]	11.5	1.3
Service Pack; Fits Schrader Alum stem sensor. Does not include stem.	20013	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Service Pack; W/Siemens Sensor	20030	71	8

Application	Part No.	Torque in-lbs	Torque N.m.
Dodge (cont'd)			
Magnum (cont'd)			
2008			
OE Sensor: Chrysler - 68001698AA			
EZ-Sensor	33100 [A]	11.5	1.3
	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28434 [E]	11.5	1.3
Service Pack; Fits Schrader Alum stem sensor. Does not include stem.	20013	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Service Pack; W/Siemens Sensor	20030	71	8
2009-2011			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Nitro			
2007-2008			
OE Sensor: Chrysler - 56053036AA			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor; Caution: Ez-sensor will not support (Wai) Wheel Arch Initiators	33000 [A]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28308 [F]	11.5	1.3
Service Pack; Fits Schrader Alum stem sensor. Does not include stem.	20013	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Service Pack; W/Siemens Sensor	20030	71	8
2009-2011			
OE Sensor: Chrysler - 56029465AB, 56029465AC			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor; Caution: Ez-sensor will not support (Wai) Wheel Arch Initiators	33000 [A]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28308 [F]	11.5	1.3
Service Pack; Fits Schrader Alum stem sensor. Does not include stem.	20013	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2012			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200 E-Supercedes the 28155 F-Supercedes the 20066

Application	Part No.	Torque in-lbs	Torque N.m.
Dodge (cont'd)			
Ram 4500			
2010			
OE Sensor: Chrysler - 56029359AB, 56029398AA			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; W/Rubber Stem Snap-in Sensor	20398	11.5	1.3
	28434 E	11.5	1.3
Service Pack; W/Rubber Stem Snap-in Sensor	20018 C	11.5	1.3
Ram 5500			
2010			
OE Sensor: Chrysler - 56029359AB, 56029398AA			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; W/Rubber Stem Snap-in Sensor	20398	11.5	1.3
	28434 E	11.5	1.3
Service Pack; W/Rubber Stem Snap-in Sensor	20018 C	11.5	1.3
Ram Series			
2008			
OE Sensor: Chrysler - 56029319AA			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor; Caution: Ez-sensor will not support (Wai) Wheel Arch Initiators	33000 A	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28461 G	11.5	1.3
Service Pack; Fits Schrader Alum stem sensor. Does not include stem.	20013	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Rubber Valve	20018 C	11.5	1.3
2009			
OE Sensor: Chrysler - 56029359AB			
EZ-Sensor	33000 A		
	33100 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor; Caution: Ez-sensor will not support (Wai) Wheel Arch Initiators	33200 A	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28434 E	11.5	1.3
	28461 G	11.5	1.3
Service Pack; Fits Schrader Alum stem sensor. Does not include stem.	20013	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Rubber Valve	20018 C	11.5	1.3

Application	Part No.	Torque in-lbs	Torque N.m.
Dodge (cont'd)			
Ram Series (cont'd)			
2010			
OE Sensor: Chrysler - 56029359AB, 56029398AA			
EZ-Sensor	33100 A	11.5	1.3
	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; W/Rubber Stem Snap-in Sensor	20398	11.5	1.3
	28434 E	11.5	1.3
Service Pack; Fits Schrader Alum stem sensor. Does not include stem.	20013	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Rubber Valve	20018 C	11.5	1.3
Service Pack; W/Rubber Stem Snap-in Sensor	20018 C	11.5	1.3
2011-2013			
EZ-Sensor	33100 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Service Pack; Rubber Valve	20018 C	11.5	1.3
Sprinter			
2007-2009			
OE Sensor: Chrysler - 68006771AA, 68038945AA			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor; Caution: Ez-sensor will not support (Wai) Wheel Arch Initiators	33000 A	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20089	53	6
Service Pack; Includes Valve	20036	53	6
Stratus			
2007			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Viper			
2003-2006			
OE Sensor: Chrysler - 52088990AC			
EZ-Sensor	33100 A	11.5	1.3
	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20028 B	35	4
Service Pack	20003	35	4
2007			
EZ-Sensor	33100 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3

A-Programming Tool Required B-Magnet may be Required to Activate Sensor C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200
E-Supercedes the 28155 G-Supercedes the 28154

Application	Part No.	Torque in-lbs	Torque N.m.
Dodge (cont'd)			
Viper (cont'd)			
2008-2010			
OE Sensor: Chrysler - 52088990AC			
EZ-Sensor	33100 A	11.5	1.3
	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20028 B	35	4
Service Pack	20003	35	4
2011			
EZ-Sensor	33100 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
2012-2013			
OE Sensor: Chrysler - 56029400AD			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; W/Metal Stem Clamp-in Sensor	28291	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; W/Metal Stem Clamp-in Sensor; Does Not Include Stem	20016	58	6.5
2014-2015			
OE Sensor: Chrysler - 56029400AD			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; W/Metal Stem Clamp-in Sensor	28291	58	6.5
Service Pack; W/Metal Stem Clamp-in Sensor; Does Not Include Stem	20016	58	6.5
2016			
OE Sensor: Chrysler - 56029400AD			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; W/Metal Stem Clamp-in Sensor	28291	58	6.5
Service Pack; W/Metal Stem Clamp-in Sensor; Does Not Include Stem	20016	58	6.5
2017			
OE Sensor: Chrysler - 56029400AD			
Sensor; W/Metal Stem Clamp-in Sensor	28291	58	6.5
Service Pack; W/Metal Stem Clamp-in Sensor; Does Not Include Stem	20016	58	6.5
Ferrari			
599 GTB			
2007-2010			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3

Application	Part No.	Torque in-lbs	Torque N.m.
Ferrari (cont'd)			
612 Scaglietti			
2004-2011			
OE Sensor: Ferrari - 224549			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Includes Transmitter Only	20077	35	4
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
Enzo			
2003-2004			
OE Sensor: Ferrari - 224551			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Includes Transmitter Only	20084	35	4
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
2005-2009			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
F430			
2005			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
2006-2007			
OE Sensor: Ferrari - 224549			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Includes Transmitter Only	20077	35	4
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
2008-2009			
OE Sensor: Ferrari - 224549			
Sensor; Includes Transmitter Only	20077	35	4
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4

A-Programming Tool Required B-Magnet may be Required to Activate Sensor C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Ferrari (cont'd)			
FF			
2011			
OE Sensor: Original Equipment Manufacturer - 4F0 907 275			
Sensor; Includes Transmitter Only.	20078	35	4
Fxx			
2003-2009			
EZ-Sensor.	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
LaFerrari			
2014			
OE Sensor: Original Equipment Manufacturer - 4F0 907 275			
Sensor; Includes Transmitter Only.	20078	35	4
Maranello			
1998-2006			
OE Sensor: Ferrari - 224549			
EZ-Sensor.	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
Sensor; Includes Transmitter Only.	20077	35	4
Service Pack; Does Not Include Valve.	20023	35	4
Service Pack; W/43mm Silver Insert.	20037	35	4
Service Pack; W/48mm Green Insert.	20038	35	4
Service Pack; W/49mm Black Insert.	20039	35	4
Service Pack; W/51mm Orange Insert.	20040	35	4
Fiat			
500			
2012-2015			
OE Sensor: Chrysler - 56029398AB, 68241067AB			
EZ-Sensor.	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
Sensor.	20398	11.5	1.3
Service Pack; Rubber Valve.	20018 C	11.5	1.3
2016			
OE Sensor: Chrysler - 68241067AB			
EZ-Sensor.	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
Sensor.	20398	11.5	1.3
Service Pack; Rubber Valve.	20018 C	11.5	1.3
2017			
OE Sensor: Chrysler - 68241067AB			
Sensor.	20398	11.5	1.3
Service Pack; Rubber Valve.	20018 C	11.5	1.3

Application	Part No.	Torque in-lbs	Torque N.m.
Ford			
C-Max			
2012-2015			
OE Sensor: Ford Motor Company - DE8T-1A180-AA, DE8T-1A180AA			
EZ-Sensor.	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
Sensor.	20315	11.5	1.3
Service Pack; Rubber Valve.	20018 C	11.5	1.3
2016			
OE Sensor: Ford Motor Company - DE8T-1A180AA			
EZ-Sensor.	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
Sensor.	20315	11.5	1.3
Service Pack; Rubber Valve.	20018 C	11.5	1.3
2017			
OE Sensor: Ford Motor Company - DE8T-1A180AA			
Sensor.	20315	11.5	1.3
Service Pack; Rubber Valve.	20018 C	11.5	1.3
Crown Victoria			
2006-2011			
OE Sensor: Ford Motor Company - 6F2Z1A189A			
EZ-Sensor.	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
Sensor.	28385	27	3
Sensor Clip.	22100		
Sensor Cradle.	22101		
Universal Band.	22102		
Edge			
2007-2008			
OE Sensor: Ford Motor Company - 6F2Z1A189A, 7L1Z1A189A			
EZ-Sensor.	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
Sensor; W/Chrome Plated Almnm. Wheels.	28385	27	3
Sensor; W/O Chrome Plated Almnm. Wheels.	28390	27	3
Sensor Clip.	22100		
Sensor Cradle.	22101		
Universal Band.	22102		
2009-2010			
OE Sensor: Ford Motor Company - 7L1Z1A189A			
EZ-Sensor.	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
Sensor.	28390	27	3
Sensor Clip.	22100		
Sensor Cradle.	22101		
Universal Band.	22102		

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Ford (cont'd)			
Edge (cont'd)			
2011-2014			
OE Sensor: Ford Motor Company - 9L3Z1A189A, CM5T 1A180 AA, DE8T-1A180-AA			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20315	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2015-2016			
OE Sensor: Ford Motor Company - F2GT-1A180-AB			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20280	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2017			
OE Sensor: Ford Motor Company - F2GT-1A180-AB			
Sensor	20280	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Escape			
2005			
OE Sensor: Ford Motor Company - 6F2Z1A189A			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Oct. 3, 2005 & Newer	28385	27	3
Sensor Clip	22100		
Sensor Cradle	22101		
Universal Band	22102		
2006-2008			
OE Sensor: Ford Motor Company - 6F2Z1A189A			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28385	27	3
Sensor Clip	22100		
Sensor Cradle	22101		
Universal Band	22102		
2009-2010			
OE Sensor: Ford Motor Company - 9L3Z1A189A			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20315	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2011			
OE Sensor: Ford Motor Company - 9L3Z1A189A			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20315	11.5	1.3

Application	Part No.	Torque in-lbs	Torque N.m.
Ford (cont'd)			
Escape (cont'd)			
2012-2015			
OE Sensor: Ford Motor Company - CM5T 1A180 AA, DE8T-1A180-AA, DE8T1A180AA			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20315	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2016			
OE Sensor: Ford Motor Company - DE8T1A180AA			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20315	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2017			
OE Sensor: Ford Motor Company - DE8T1A180AA			
Sensor	20315	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
E-Series Van			
2007			
OE Sensor: Ford Motor Company - 6F2Z1A189A, 8C2Z1A189A			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28385	27	3
	28395	27	3
Sensor Clip	22100		
Sensor Cradle	22101		
Universal Band	22102		
2008-2009			
OE Sensor: Ford Motor Company - 8C2Z1A189A; Original Equipment Manufacturer - 8C2Z1A189A			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28395	27	3
Sensor Clip	22100		
Sensor Cradle	22101		
Universal Band	22102		

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Ford (cont'd)			
E-Series Van (cont'd)			
2010			
OE Sensor: Ford Motor Company - 8C2Z1A189A, 9L3Z1A189A			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor; W/Alloy Wheels	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
EZ-Sensor Service Pack; W/Alloy Wheels; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; W/Alloy Wheels; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20315	11.5	1.3
	28395	27	3
Sensor; W/Alloy Wheels	28395	27	3
Sensor; W/Steel Wheels	20315	11.5	1.3
Sensor Clip	22100		
Sensor Clip; W/Alloy Wheels	22100		
Sensor Cradle	22101		
Sensor Cradle; W/Alloy Wheels	22101		
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Service Pack; W/Steel Wheels	20018 [C]	11.5	1.3
Universal Band	22102		
Universal Band; W/Alloy Wheels	22102		
2011-2013			
OE Sensor: Ford Motor Company - 9L3Z1A189A, DE8T1A180AA			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20315	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2013			
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2014-2015			
OE Sensor: Ford Motor Company - 9L3Z1A189A, DE8T-1A180-AA, DE8T1A180AA			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20315	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2016			
OE Sensor: Ford Motor Company - DE8T1A180AA			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20315	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2017			
OE Sensor: Ford Motor Company - DE8T1A180AA			
Sensor	20315	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3

Application	Part No.	Torque in-lbs	Torque N.m.
Ford (cont'd)			
Expedition			
2003-2004			
OE Sensor: Ford Motor Company - 4L2Z 1A150 BA			
EZ-Sensor	33100 [A]	11.5	1.3
	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20096 [B]	44	5
Service Pack	20002	44	5
2005-2006			
OE Sensor: Ford Motor Company - 5L1Z 1A150 AA			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20135 [B]	44	5
Service Pack	20002	44	5
2007-2010			
OE Sensor: Ford Motor Company - 7L1Z1A189A			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28390	27	3
Sensor Clip	22100		
Sensor Cradle	22101		
Universal Band	22102		
2011-2015			
OE Sensor: Ford Motor Company - 9L3Z1A189A, CM5T 1A180 AA, DE8T-1A180-AA, DE8T1A180AA			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20315	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2016			
OE Sensor: Ford Motor Company - DE8T1A180AA			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20315	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2017			
OE Sensor: Ford Motor Company - DE8T1A180AA			
Sensor	20315	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Explorer			
2002-2003			
OE Sensor: Ford Motor Company - 4L2Z 1A150 BA			
EZ-Sensor	33100 [A]	11.5	1.3
	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Exc. Sport	20096 [B]	44	5
Service Pack; Exc. Sport	20002	44	5

A-Programming Tool Required B-Magnet may be Required to Activate Sensor C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Ford (cont'd)			
Explorer (cont'd)			
2004-2005			
OE Sensor: Ford Motor Company - 4L2Z 1A150 BA			
EZ-Sensor	33100 [A]	11.5	1.3
	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20096 [B]	44	5
Service Pack	20002	44	5
2006-2010			
OE Sensor: Ford Motor Company - 6F2Z1A189A			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28385	27	3
Sensor Clip	22100		
Sensor Cradle	22101		
Universal Band	22102		
2011-2014			
OE Sensor: Ford Motor Company - 9L3Z1A189A, CM5T 1A180 AA, DE8T-1A180-AA			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20315	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2015			
OE Sensor: Ford Motor Company - DE8T-1A180-AA			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20315	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2016			
OE Sensor: Ford Motor Company - F2GT-1A180-AB			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20280	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2017			
OE Sensor: Ford Motor Company - F2GT-1A180-AB			
Sensor	20280	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3

Application	Part No.	Torque in-lbs	Torque N.m.
Ford (cont'd)			
Explorer Sport Trac			
2007-2010			
OE Sensor: Ford Motor Company - 6F2Z1A189A			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28385	27	3
Sensor Clip	22100		
Sensor Cradle	22101		
Universal Band	22102		
F-150			
2007			
OE Sensor: Ford Motor Company - 6F2Z1A189A			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28385	27	3
Sensor Clip	22100		
Sensor Cradle	22101		
Universal Band	22102		
2008			
OE Sensor: Ford Motor Company - 6F2Z1A189A, 8C2Z1A189A			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; W/H.D. Payload Pkg.	28395	27	3
Sensor; W/O H.D. Payload Pkg.	28385	27	3
Sensor Clip	22100		
Sensor Cradle	22101		
Universal Band	22102		
2009-2014			
OE Sensor: Ford Motor Company - 9L3Z1A189A, CM5T 1A180 AA, DE8T-1A180-AA			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20315	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2015-2016			
OE Sensor: Ford Motor Company - F2GT-1A180-AA, F2GT-1A180-AB			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20280	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2017			
OE Sensor: Ford Motor Company - F2GT-1A180-AA			
Sensor	20280	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3

A-Programming Tool Required B-Magnet may be Required to Activate Sensor C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Ford (cont'd)			
F-250 Super Duty			
2008-2010			
OE Sensor: Ford Motor Company - 8C2Z1A189A			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28395	27	3
Sensor Clip	22100		
Sensor Cradle	22101		
Universal Band	22102		
2011-2015			
OE Sensor: Ford Motor Company - 9L3Z1A189A, CM5T 1A180 AA, DE8T-1A180-A, DE8T1A180AA			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20315	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2016			
OE Sensor: Ford Motor Company - DE8T1A180AA			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20315	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
F-350 Super Duty			
2008-2010			
OE Sensor: Ford Motor Company - 8C2Z1A189A			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28395	27	3
Sensor Clip	22100		
Sensor Cradle	22101		
Universal Band	22102		
2011-2015			
OE Sensor: Ford Motor Company - 9L3Z1A189A, CM5T 1A180 AA, DE8T-1A180-A, DE8T1A180AA			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20315	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2016			
OE Sensor: Ford Motor Company - DE8T1A180AA			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20315	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3

Application	Part No.	Torque in-lbs	Torque N.m.
Ford (cont'd)			
F-450 Super Duty			
2008			
OE Sensor: Ford Motor Company - 8C2Z1A189A			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28395	27	3
Sensor Clip	22100		
Sensor Cradle	22101		
Universal Band	22102		
2009			
OE Sensor: Ford Motor Company - 8C2Z1A189A			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28395	27	3
Sensor Clip	22100		
Sensor Cradle	22101		
Universal Band	22102		
2010			
OE Sensor: Ford Motor Company - 8C2Z1A189A			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28395	27	3
Sensor Clip	22100		
Sensor Cradle	22101		
Universal Band	22102		
2014			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20315		
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2015-2016			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
Sensor	20315		
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
F-550 Super Duty			
2010			
OE Sensor: Ford Motor Company - 8C2Z1A189A			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28395	27	3
Sensor Clip	22100		
Sensor Cradle	22101		
Universal Band	22102		

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Ford (cont'd)			
Fiesta			
2011-2015			
OE Sensor: Ford Motor Company - 9L3Z1A189A, CM5T 1A180 AA, DE8T-1A180-AA, DE8T1A180AA			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20315	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2016			
OE Sensor: Ford Motor Company - DE8T1A180AA			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20315	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2017			
OE Sensor: Ford Motor Company - DE8T1A180AA			
Sensor	20315	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Five Hundred			
2006-2007			
OE Sensor: Ford Motor Company - 7L1Z1A189A			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28390	27	3
Sensor Clip	22100		
Sensor Cradle	22101		
Universal Band	22102		
Flex			
2009-2010			
OE Sensor: Ford Motor Company - 7L1Z1A189A			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28390	27	3
Sensor Clip	22100		
Sensor Cradle	22101		
Universal Band	22102		
2011-2015			
OE Sensor: Ford Motor Company - 9L3Z1A189A, CM5T 1A180 AA, DE8T-1A-180-AA, DE8T-1A180-AA			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20315	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3

Application	Part No.	Torque in-lbs	Torque N.m.
Ford (cont'd)			
Flex (cont'd)			
2016			
OE Sensor: Ford Motor Company - DE8T-1A-180-AA			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20315	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Focus			
2007			
OE Sensor: Ford Motor Company - 6F2Z1A189A			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28385	27	3
Sensor Clip	22100		
Sensor Cradle	22101		
Universal Band	22102		
2008-2009			
OE Sensor: Ford Motor Company - 7L1Z1A189A			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28390	27	3
Sensor Clip	22100		
Sensor Cradle	22101		
Universal Band	22102		
2010			
OE Sensor: Ford Motor Company - 9L3Z1A189A			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20315	13	1.5
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2011			
OE Sensor: Ford Motor Company - 9L3Z1A189A			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20315	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2012-2015			
OE Sensor: Ford Motor Company - CM5T 1A180 AA, DE8T-1A180-AA, DE8T1A180AA			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20315	13	1.5
Service Pack; Rubber Valve	20018 [C]	11.5	1.3

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Ford (cont'd)			
Focus (cont'd)			
2016			
OE Sensor: Ford Motor Company - DE8T1A180AA			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20315	13	1.5
Service Pack; Rubber Valve	20018 C	11.5	1.3
2017			
OE Sensor: Ford Motor Company - DE8T1A180AA			
Sensor	20315	13	1.5
Service Pack; Rubber Valve	20018 C	11.5	1.3
Freestar			
2004-2005			
OE Sensor: Ford Motor Company - 5L1Z 1A150 AA			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; W/Aluminium Valve Stem	20135 B	44	5
Service Pack; W/Aluminium Valve Stem	20002	44	5
2006-2007			
OE Sensor: Ford Motor Company - 6F2Z1A189A			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28385	27	3
Sensor Clip	22100		
Sensor Cradle	22101		
Universal Band	22102		
Freestyle			
2005-2007			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Fusion			
2007-2009			
OE Sensor: Ford Motor Company - 6F2Z1A189A			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28385	27	3
Sensor Clip	22100		
Sensor Cradle	22101		
Universal Band	22102		
2010-2015			
OE Sensor: Ford Motor Company - 9L3Z1A189A, CM5T 1A180 AA, DE8T-1A180-AA, DE8T1A180AA			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20315	11.5	1.3
Service Pack; Rubber Valve	20018 C	11.5	1.3

Application	Part No.	Torque in-lbs	Torque N.m.
Ford (cont'd)			
Fusion (cont'd)			
2016			
OE Sensor: Ford Motor Company - DE8T1A180AA			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20315	11.5	1.3
Service Pack; Rubber Valve	20018 C	11.5	1.3
Mustang			
2007-2009			
OE Sensor: Ford Motor Company - 6F2Z1A189A			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28385	27	3
Sensor Clip	22100		
Sensor Cradle	22101		
Universal Band	22102		
2010-2011			
OE Sensor: Ford Motor Company - 9L3Z1A189A			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20315	11.5	1.3
Service Pack; Rubber Valve	20018 C	11.5	1.3
2012			
OE Sensor: Ford Motor Company - CM5T 1A180 AA			
EZ-Sensor; exc Shelby GT500	33000 A	11.5	1.3
EZ-Sensor; Shelby GT500; MUST use Aluminium stem kit 34000 before Sensor installation	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; exc Shelby GT500; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; exc Shelby GT500; Rubber Valve	20018 C	11.5	1.3
EZ-Sensor Service Pack; Shelby GT500; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Shelby GT500; Rubber Valve	20018 C	11.5	1.3
Sensor; exc Shelby GT500	20315	11.5	1.3
Service Pack; exc Shelby GT500	20018 C	11.5	1.3
2013			
OE Sensor: Ford Motor Company - 9L3Z1A189A			
EZ-Sensor	33100 A	11.5	1.3
EZ-Sensor; exc Shelby GT500	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; exc Shelby GT500; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; exc Shelby GT500; Rubber Valve	20018 C	11.5	1.3
Sensor; exc Shelby GT500	20315	11.5	1.3
Service Pack; exc Shelby GT500	20018 C	11.5	1.3

A-Programming Tool Required B-Magnet may be Required to Activate Sensor C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Ford (cont'd)			
Mustang (cont'd)			
2014			
OE Sensor: Ford Motor Company - CM5T 1A180 AA, DE8T-1A180-A			
EZ-Sensor	33100 [A]	11.5	1.3
EZ-Sensor; exc Shelby GT500	33000 [A]	11.5	1.3
EZ-Sensor; Shelby GT500; MUST use Aluminium stem kit 34000 before Sensor installation	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; exc Shelby GT500; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; exc Shelby GT500; Rubber Valve	20018 [C]	11.5	1.3
EZ-Sensor Service Pack; Shelby GT500; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Shelby GT500; Rubber Valve	20018 [C]	11.5	1.3
Sensor; exc Shelby GT500	20315	11.5	1.3
Service Pack; exc Shelby GT500	20018 [C]	11.5	1.3
2015-2016			
OE Sensor: Ford Motor Company - F2GT-1A180-AB			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20280	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2017			
OE Sensor: Ford Motor Company - F2GT-1A180-AB			
Sensor	20280	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Police Interceptor Sedan			
2011-2013			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2013			
EZ-Sensor	33000 [A]	11.5	1.3
Police Interceptor Utility			
2015-2016			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Ranger			
2007-2011			
OE Sensor: Ford Motor Company - 6F2Z1A189A			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28385	27	3
Sensor Clip	22100		
Sensor Cradle	22101		
Universal Band	22102		

Application	Part No.	Torque in-lbs	Torque N.m.
Ford (cont'd)			
Taurus			
2008-2009			
OE Sensor: Ford Motor Company - 7L1Z1A189A			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28390	27	3
Sensor Clip	22100		
Sensor Cradle	22101		
Universal Band	22102		
2010			
OE Sensor: Ford Motor Company - 7L1Z1A189A, 9L3Z1A189A			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor; Apr. & Older	33000 [A]	11.5	1.3
EZ-Sensor Service Pack; Apr. & Older; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Apr. & Older; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Apr. & Older	28390	27	3
Sensor; May & Newer	20315	11.5	1.3
Sensor Clip; Apr. & Older	22100		
Sensor Cradle; Apr. & Older	22101		
Service Pack; May & Newer	20018 [C]	11.5	1.3
Universal Band; Apr. & Older	22102		
2011-2015			
OE Sensor: Ford Motor Company - 9L3Z1A189A, CM5T 1A180 AA, DE8T-1A180-AA, DE8T1A180AA			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20315	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2016			
OE Sensor: Ford Motor Company - DE8T1A180AA			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20315	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2017			
OE Sensor: Ford Motor Company - DE8T1A180AA			
Sensor	20315	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Transit			
2014-2015			
OE Sensor: Ford Motor Company - DE8T-1A180-AA, DE8T1A180AA			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20315	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Ford (cont'd)			
Transit (cont'd)			
2016			
OE Sensor: Ford Motor Company - DE8T1A180AA			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20315	11.5	1.3
Service Pack; Rubber Valve	20018 C	11.5	1.3
2017			
OE Sensor: Ford Motor Company - DE8T1A180AA			
Sensor	20315	11.5	1.3
Service Pack; Rubber Valve	20018 C	11.5	1.3
Transit Connect			
2010-2015			
OE Sensor: Ford Motor Company - 9L3Z1A189A, CM5T 1A180 AA, DE8T-1A180-AA, DE8T1A180AA			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20315	11.5	1.3
Service Pack; Rubber Valve	20018 C	11.5	1.3
2016			
OE Sensor: Ford Motor Company - DE8T1A180AA			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20315	11.5	1.3
Service Pack; Rubber Valve	20018 C	11.5	1.3
2017			
OE Sensor: Ford Motor Company - DE8T1A180AA			
Sensor	20315	11.5	1.3
Service Pack; Rubber Valve	20018 C	11.5	1.3
Freightliner			
Sprinter			
2007-2008			
OE Sensor: Chrysler - 68006771AA			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20089	53	6
Service Pack; Includes Valve	20036	53	6
2009-2012			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
2013			
OE Sensor: Chrysler - 68006771AA			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20089	53	6
Service Pack; Includes Valve	20036	53	6
Freightliner (cont'd)			
Sprinter (cont'd)			
2014-2016			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
GMC			
Acadia			
2007-2008			
OE Sensor: General Motors - 10394110, 15921013			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20158	62	7
Service Pack; W/Schrader Sensor	20004	62	7
Service Pack; W/Siemens Sensor	20030	80	9
2009-2015			
OE Sensor: General Motors - 22853741, 23445327, 25920615			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20153	11.5	1.3
Service Pack	20008 C	11.5	1.3
2016			
OE Sensor: General Motors - 13598771			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20153	11.5	1.3
Service Pack	20008 C	11.5	1.3
2017			
OE Sensor: General Motors - 13598771			
Sensor	20153	11.5	1.3
Service Pack	20008 C	11.5	1.3
Canyon			
2007-2012			
OE Sensor: General Motors - 15122618			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20131	62	7
Service Pack	20006	62	7
2015-2016			
OE Sensor: General Motors - 13581558			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28206	11.5	1.3
Service Pack	20008 C	11.5	1.3
2017			
OE Sensor: General Motors - 13581558			
Sensor	28206	11.5	1.3
Service Pack	20008 C	11.5	1.3

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
GMC (cont'd)			
Envoy			
2006			
OE Sensor: General Motors - 25774006			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20116	62	7
Service Pack	20004	62	7
2007-2009			
OE Sensor: General Motors - 25774006			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20116	62	7
Service Pack	20004	62	7
Savana Series			
2008-2009			
OE Sensor: General Motors - 15921013			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20158	62	7
Service Pack; W/Schrader Sensor	20004	62	7
Service Pack; W/Siemens Sensor	20030	80	9
2010-2015			
OE Sensor: General Motors - 13586335, 20923680, 22853741, 25920615			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20153	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
2016			
OE Sensor: General Motors - 13586335			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20153	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
2017			
OE Sensor: General Motors - 13586335			
Sensor	20153	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
Sierra Series			
2004			
OE Sensor: General Motors - 15136883			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20115	62	7
Service Pack	20004	62	7

Application	Part No.	Torque in-lbs	Torque N.m.
GMC (cont'd)			
Sierra Series (cont'd)			
2005-2006			
OE Sensor: General Motors - 15114379			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20107	62	7
Service Pack	20004	62	7
2007			
OE Sensor: General Motors - 15114379, 15254101, 15825475			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Clamp-In Style Only; TRW Sensor; W/Aluminium Valve Stem; Exc. Classic	20158	62	7
Sensor; Classic	20107	62	7
Sensor; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem; Exc. Classic	20153	11.5	1.3
Service Pack; Clamp-In Style Only; TRW Sensor; W/Aluminium Valve Stem; Exc. Classic	20015	80	9
Service Pack; Classic	20004	62	7
Service Pack; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem; Exc. Classic	20008 [C]	11.5	1.3
2008-2012			
OE Sensor: General Motors - 15922396, 25920615			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20153	11.5	1.3
Sensor; W/Single Rear Wheels	20153	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
Service Pack; W/Single Rear Wheels	20008 [C]	11.5	1.3
2013			
OE Sensor: General Motors - 13586335			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; W/Single Rear Wheels	20153	11.5	1.3
Service Pack; W/Single Rear Wheels	20008 [C]	11.5	1.3
2014			
OE Sensor: General Motors - 13581558			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; W/Single Rear Wheels	28206	11.5	1.3
Service Pack; W/Single Rear Wheels	20008 [C]	11.5	1.3

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
GMC (cont'd)			
Sierra Series (cont'd)			
2015			
OE Sensor: General Motors - 13581558			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; W/Single Rear Wheels	28206	11.5	1.3
Service Pack	20008 C	11.5	1.3
Service Pack; W/Single Rear Wheels	20008 C	11.5	1.3
2016			
OE Sensor: General Motors - 13581558			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; W/Single Rear Wheels	28206	11.5	1.3
Service Pack	20008 C	11.5	1.3
Service Pack; W/Single Rear Wheels	20008 C	11.5	1.3
2017			
OE Sensor: General Motors - 13581558			
Sensor; W/Single Rear Wheels	28206	11.5	1.3
Service Pack	20008 C	11.5	1.3
Service Pack; W/Single Rear Wheels	20008 C	11.5	1.3
Terrain			
2010-2014			
OE Sensor: General Motors - 12768826, 22854866			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28206	11.5	1.3
Service Pack	20008 C	11.5	1.3
2015			
OE Sensor: General Motors - 13598772			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28206	11.5	1.3
Service Pack; Rubber Valve	20008 C	11.5	1.3
2016			
OE Sensor: General Motors - 13598772			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28206	11.5	1.3
Service Pack; Rubber Valve	20008 C	11.5	1.3
2017			
OE Sensor: General Motors - 13598772			
Sensor	28206	11.5	1.3
Service Pack; Rubber Valve	20008 C	11.5	1.3

Application	Part No.	Torque in-lbs	Torque N.m.
GMC (cont'd)			
Yukon			
2004			
OE Sensor: General Motors - 15136883			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20115	62	7
Service Pack	20004	62	7
2005-2006			
OE Sensor: General Motors - 15114379			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20107	62	7
Service Pack	20004	62	7
2007			
OE Sensor: General Motors - 15254101, 15825475			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Clamp-In Style Only; TRW Sensor; W/Aluminium Valve Stem	20158	62	7
Sensor; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem	20153	11.5	1.3
Service Pack; Clamp-In Style Only; TRW Sensor; W/Aluminium Valve Stem	20015	62	7
Service Pack; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem	20008 C	11.5	1.3
2008-2013			
OE Sensor: General Motors - 13586335, 15922396, 20923680, 25920615			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20153	11.5	1.3
Service Pack	20008 C	11.5	1.3
2014-2015			
OE Sensor: General Motors - 13581558			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28206	11.5	1.3
Service Pack	20008 C	11.5	1.3
2016			
OE Sensor: General Motors - 13581558			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28206	11.5	1.3
Service Pack	20008 C	11.5	1.3

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
GMC (cont'd)			
Yukon (cont'd)			
2017			
OE Sensor: General Motors - 13581558			
Sensor	28206	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
Honda			
Accord			
2008-2012			
OE Sensor: Honda - 42753SWA306, 42753SWA316			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20099	35	4
Service Pack	20032	35	4
2013-2016			
Sensor	INDIRECT [D]		
Accord Crosstour			
2010-2015			
OE Sensor: Honda - 42753-TP6-A82, 42753TP6A82			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20100	35	4
Civic			
2008-2014			
OE Sensor: Honda - 42753SNAA83, 42753TR0A81, 42753TR3A81			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28720	35	4
Service Pack	20019	35	4
Crosstour			
2010-2015			
OE Sensor: Honda - 42753TP6A82			
Sensor	20100	71	8
CR-V			
2007-2011			
OE Sensor: Honda - 42753SWA306, 42753SWA316			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20099	35	4
Service Pack	20032	35	4
2012-2013			
OE Sensor: Honda - 42753-TP6-A82			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20100	35	4

Application	Part No.	Torque in-lbs	Torque N.m.
Honda (cont'd)			
CR-V (cont'd)			
2014-2015			
Sensor	INDIRECT [D]		
CR-Z			
2011-2014			
OE Sensor: Honda - 42753SNAA83, 42753SNAA84			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28720	35	4
Service Pack	20019	35	4
2015			
OE Sensor: Honda - 42753TR3A81			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28720	35	4
Service Pack	20019	35	4
Element			
2007-2008			
Service Pack; Includes Valve	20036	35	4
2009-2011			
OE Sensor: Honda - 42753SNAA83			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28720	35	4
Service Pack	20019	35	4
Fit			
2008			
OE Sensor: Honda - 42753SWA306			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20099	35	4
Service Pack	20032	35	4
2009-2014			
OE Sensor: Honda - 42753SNAA83, 42753TR3A81			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28720	35	4
Service Pack	20019	35	4
2015-2016			
Sensor	INDIRECT [D]		

A-Programming Tool Required C-20018 and 20008 are interchangeable. D-Indirect TPMS system. No sensor in wheel DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Honda (cont'd)			
Insight			
2010-2014			
OE Sensor: Honda - 42753SNAA83			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28720	35	4
Service Pack	20019	35	4
Odyssey			
2005-2007			
OE Sensor: Honda - 06421S3VA04			
Sensor; Touring	28981	35	4
Service Pack; Touring; Includes Valve	20036	35	4
2008			
OE Sensor: Honda - 42753-AHJ-A53, 42753-SHJ-A82			
Sensor	28983	35	4
Sensor; Touring	28981	35	4
Service Pack; Includes Valve	20036	31-40	3.5-4.5
Service Pack; Touring; Includes Valve	20036	35	4
2009-2010			
OE Sensor: Honda - 42753-SHJ-A82			
Sensor	28983	35	4
Service Pack; Includes Valve	20036	31-40	3.5-4.5
2011-2016			
OE Sensor: Honda - 42753-TR3-A81, 42753-TR3-A83			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28720	35	4
Service Pack	20019	35	4
Pilot			
2005			
OE Sensor: Honda - 06421S3VA02, 06421S9VA01			
Sensor; LX; W/Long Stem Valve	28982	35	4
Sensor; W/Short Stem Valve	28981	35	4
Service Pack; EX; Includes Valve	20036	35	4
Service Pack; LX; W/Long Stem Valve; Includes Valve	20035	35	4
Service Pack; LX; W/Short Stem Valve; Includes Valve	20036	35	4
2006-2008			
OE Sensor: Honda - 06421S3VA02, 06421S3VA04			
Sensor	28981	35	4
Service Pack; Includes Valve	20036	35	4
2009			
OE Sensor: Honda - 42753STKA03			
Sensor; W/Alloy Wheels	20098	35	4
Service Pack; W/Alloy Wheels	20032	35	4
2010-2011			
OE Sensor: Honda - 42753STKA04			
Sensor; Exc. LX	20098	35	4
Service Pack; Exc. LX	20032	35	4

Application	Part No.	Torque in-lbs	Torque N.m.
Honda (cont'd)			
Pilot (cont'd)			
2012-2015			
OE Sensor: Honda - 42753STKA04			
Sensor; W/Alloy Wheels	20098	35	4
Service Pack; W/Alloy Wheels	20032	35	4
Ridgeline			
2006			
OE Sensor: Honda - 06421S3VA02, 06421S9VA01			
Sensor; RT	28982	35	4
Sensor; RTL, RTS	28981	35	4
Service Pack; RT; Includes Valve	20035	35	4
Service Pack; RTL, RTS; Includes Valve	20036	35	4
2007-2008			
OE Sensor: Honda - 06421S3VA04, 06421S9VA03			
Sensor; RT	28982	35	4
Sensor; RTL, RTS, RTX	28981	35	4
Service Pack; RT; Includes Valve	20035	35	4
Service Pack; RTL, RTS, RTX; Includes Valve	20036	35	4
2009			
OE Sensor: Honda - 06421S3VA04			
Sensor	28981	35	4
Service Pack; Includes Valve	20036	35	4
2010			
OE Sensor: Honda - 06421S3VA04, 42753SHJA53			
Sensor; W/Alloy Wheels	28981	35	4
Sensor; W/Steel Wheels	28981	35	4
Service Pack; RT; Includes Valve	20036	35	4
2011-2014			
OE Sensor: Honda - 06421S3VA04, 42753SHJA53, 42753SHJA54			
Sensor	28981	35	4
Service Pack; RT; Includes Valve	20036	35	4
S2000			
2008-2009			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Service Pack	20032	35	4
Hummer			
H2			
2008-2009			
OE Sensor: General Motors - 15922396			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20153	11.5	1.3
Service Pack	20008 [C]	11.5	1.3

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Hummer (cont'd)			
H3			
2006-2010			
OE Sensor: General Motors - 15122618			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20131	62	7
Service Pack	20006	62	7
H3T			
2006-2008			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2009-2010			
OE Sensor: General Motors - 15122618			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20131	62	7
Service Pack	20006	62	7
Hyundai			
Accent			
2006-2007			
OE Sensor: Hyundai - 52933-1F000			
Sensor	28983	35	4
Service Pack; Includes Valve	20036	31-40	3.5-4.5
2008-2011			
OE Sensor: Hyundai - 529332F000			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28849	35	4
Service Pack	20022	35	4
2012-2014			
OE Sensor: Hyundai - 529332M000			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20092	31-40	3.5-4.5
Azera			
2006			
OE Sensor: Hyundai - 529332G200			
Sensor; Includes Transmitter Only	20086	31-40	3.5-4.5
Service Pack; Includes Valve	20036	31-40	3.5-4.5

Application	Part No.	Torque in-lbs	Torque N.m.
Hyundai (cont'd)			
Azera (cont'd)			
2007-2012			
OE Sensor: Hyundai - 529332G200			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Includes Transmitter Only	20086	31-40	3.5-4.5
Service Pack; Includes Valve	20036	31-40	3.5-4.5
2013			
OE Sensor: Hyundai - 529332G201			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20086	31-40	3.5-4.5
Service Pack; Includes Valve	20036	31-40	3.5-4.5
Elantra			
2007-2009			
OE Sensor: Hyundai - 529332G200			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Includes Transmitter Only	20086	31-40	3.5-4.5
Service Pack; Includes Valve	20036	31-40	3.5-4.5
2010			
OE Sensor: Hyundai - 529332G200, 529332M000			
EZ-Sensor; exc Touring	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; exc Touring; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; exc Touring; Rubber Valve	20018 [C]	11.5	1.3
Sensor; exc Touring; Includes Transmitter Only	20086	31-40	3.5-4.5
Sensor; Touring; Includes Transmitter Only	20092	31-40	3.5-4.5
Service Pack	20019	35	4
Service Pack; exc Touring; Includes Valve	20036	31-40	3.5-4.5
2011			
OE Sensor: Hyundai - 529332M000, 529333X200			
Sensor; exc Touring; Includes Transmitter Only	20086	31-40	3.5-4.5
Sensor; Touring; Includes Transmitter Only	20092	31-40	3.5-4.5
Service Pack	20019	35	4
Service Pack; exc Touring; Includes Valve	20036	31-40	3.5-4.5
2012			
OE Sensor: Hyundai - 529332M000, 529333X200			
Sensor; exc Touring; W/Transmitter Only	20086	31-40	3.5-4.5
Sensor; Touring; W/Transmitter Only	20092	31-40	3.5-4.5
Service Pack	20019	35	4
Service Pack; exc Touring; Includes Valve	20036	31-40	3.5-4.5
2013			
OE Sensor: Hyundai - 529333X200			
Sensor; W/Transmitter Only	20086	31-40	3.5-4.5
Service Pack	20019	35	4
Service Pack; Includes Valve	20036	31-40	3.5-4.5

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Hyundai (cont'd)			
Elantra (cont'd)			
2014			
OE Sensor: Hyundai - 52933-3N000 Sensor	20092	31-40	3.5-4.5
2015-2016			
EZ-Sensor; exc Touring	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; exc Touring; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; exc Touring; Rubber Valve	20018 C	11.5	1.3
Elantra Coupe			
2013			
OE Sensor: Hyundai - 529333X200 Sensor; W/Transmitter Only	20086	31-40	3.5-4.5
Service Pack; Includes Valve	20036	31-40	3.5-4.5
Elantra GT			
2013-2016			
OE Sensor: Hyundai - 52933-3N000 Sensor	20092	31-40	3.5-4.5
Entourage			
2007-2009			
OE Sensor: Hyundai - 529334D200 Sensor; Includes Transmitter Only	20085	31-40	3.5-4.5
Service Pack; Includes Valve	20036	31-40	3.5-4.5
Equus			
2011-2013			
OE Sensor: Hyundai - 529332F000, 529332F001 Sensor	28849	35	4
Service Pack	20022	35	4
2014-2015			
OE Sensor: Hyundai - 529332M001 EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20092	31-40	3.5-4.5
2016			
OE Sensor: Hyundai - 529332M001 EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20092	31-40	3.5-4.5
Genesis			
2009-2014			
OE Sensor: Hyundai - 529332F000 Sensor	28849	35	4
Service Pack	20022	35	4

Application	Part No.	Torque in-lbs	Torque N.m.
Hyundai (cont'd)			
Genesis Coupe			
2010-2012			
OE Sensor: Hyundai - 529332M000 EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20092	31-40	3.5-4.5
2013			
OE Sensor: Hyundai - 52933-A5000 Sensor	20092	31-40	3.5-4.5
2014-2015			
OE Sensor: Hyundai - 529332M000 EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20092	31-40	3.5-4.5
2016			
OE Sensor: Hyundai - 529332M000 Sensor	20092	31-40	3.5-4.5
Santa Fe			
2007			
OE Sensor: Hyundai - 529334D200 Sensor; Includes Transmitter Only	20085	31-40	3.5-4.5
Service Pack; Includes Valve	20036	31-40	3.5-4.5
2008			
OE Sensor: Hyundai - 529332G200, 529334D200 EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Includes Transmitter Only	20085	31-40	3.5-4.5
	20086	31-40	3.5-4.5
Service Pack; Includes Valve	20036	31-40	3.5-4.5
2009			
OE Sensor: Hyundai - 529332G200 EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Includes Transmitter Only	20086	31-40	3.5-4.5
Service Pack; Includes Valve	20036	31-40	3.5-4.5
2010-2012			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
2013			
OE Sensor: Hyundai - 529332M001 EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20092	31-40	3.5-4.5
Service Pack	20022	35	4

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Hyundai (cont'd)			
Santa Fe (cont'd)			
2014-2017			
OE Sensor: Hyundai - 529332M000, 529333N000			
Sensor	20092	31-40	3.5-4.5
Santa Fe XL			
2013			
OE Sensor: Hyundai - 52933A5000			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28849	35	4
Service Pack	20022	35	4
Sonata			
2007			
OE Sensor: Hyundai - 529331FA00			
Sensor	28983	35	4
Service Pack; Includes Valve	20036	31-40	3.5-4.5
2008			
OE Sensor: Hyundai - 52933-1F000, 52933-2F000			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28849	35	4
	28983	35	4
Service Pack; Includes Valve	20036	31-40	3.5-4.5
2009-2010			
OE Sensor: Hyundai - 529332F000			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28849	35	4
Service Pack	20022	35	4
2011-2013			
OE Sensor: Hyundai - 529332M000, 529332M001			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20092	31-40	3.5-4.5
2014			
OE Sensor: Hyundai - 529332M550			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20092	31-40	3.5-4.5
2015-2016			
OE Sensor: Hyundai - 52933-C1100			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20281	11.5	1.3
Service Pack; Rubber Valve	20046	11.5	1.3

Application	Part No.	Torque in-lbs	Torque N.m.
Hyundai (cont'd)			
Tiburon			
2007-2008			
OE Sensor: Hyundai - 529331FA00			
Sensor	28983	35	4
Service Pack; Includes Valve	20036	31-40	3.5-4.5
Tucson			
2006-2009			
OE Sensor: Hyundai - 529331FA00			
Sensor	28983	35	4
Service Pack; Includes Valve	20036	31-40	3.5-4.5
2010-2013			
OE Sensor: Hyundai - 529332F000			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28849	35	4
Service Pack	20022	35	4
2014			
OE Sensor: Hyundai - 529332S500			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28500		
2015-2016			
OE Sensor: Hyundai - 52933-C1100			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20281	11.5	1.3
Service Pack; Rubber Valve	20046	11.5	1.3
Veloster			
2012-2015			
OE Sensor: Hyundai - 529332V000			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28505	11.5	1.3
Service Pack	20008 C	11.5	1.3
2016			
OE Sensor: Hyundai - 529332V000			
Sensor	28505	11.5	1.3
Service Pack	20008 C	11.5	1.3
Veracruz			
2006-2007			
OE Sensor: Hyundai - 529334D200			
Sensor; Includes Transmitter Only	20085	31-40	3.5-4.5
Service Pack; Includes Valve	20036	31-40	3.5-4.5

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Hyundai (cont'd)			
Veracruz (cont'd)			
2008			
OE Sensor: Hyundai - 529332G200, 529334D200			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20086		
Sensor; Includes Transmitter Only	20085	31-40	3.5-4.5
Service Pack; Includes Valve	20036	31-40	3.5-4.5
2009-2012			
OE Sensor: Hyundai - 529332G200			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Includes Transmitter Only	20086	31-40	3.5-4.5
Service Pack; Includes Valve	20036	31-40	3.5-4.5
Infiniti			
EX35			
2008-2010			
OE Sensor: Nissan - 40700-JK00B			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28210	66	7.5
Service Pack	20014	66	7.5
2011-2012			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2013			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
EX37			
2011-2012			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
FX35			
2003-2006			
OE Sensor: Nissan - 40700-CD001			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20064	66	7.5
Service Pack	20007	66	7.5

Application	Part No.	Torque in-lbs	Torque N.m.
Infiniti (cont'd)			
FX35 (cont'd)			
2007			
OE Sensor: Nissan - 40700-CD001, 40700-JA01B			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Jul. & Newer	28204	66	7.5
Sensor; Jun. & Older	20064	66	7.5
Service Pack; Jul. & Newer	20014	66	7.5
Service Pack; Jun. & Older	20007	66	7.5
2008			
OE Sensor: Nissan - 40700-JA01B			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28204	66	7.5
Service Pack	20014	66	7.5
2009-2010			
OE Sensor: Nissan - 40700-JK00B			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28210	66	7.5
Service Pack	20014	66	7.5
2011-2012			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2013			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
FX37			
2013			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
FX45			
2003-2006			
OE Sensor: Nissan - 40700-CD001			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20064	66	7.5
Service Pack	20007	66	7.5

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Infiniti (cont'd)			
FX45 (cont'd)			
2007			
OE Sensor: Nissan - 40700-CD001, 40700-JA01B			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Jul. & Newer	28204	66	7.5
Sensor; Jun. & Older	20064	66	7.5
Service Pack; Jul. & Newer	20014	66	7.5
Service Pack; Jun. & Older	20007	66	7.5
2008			
OE Sensor: Nissan - 40700-JA01B			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28204	66	7.5
Service Pack	20014	66	7.5
FX50			
2009-2010			
OE Sensor: Nissan - 40700-JK00B			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28210	66	7.5
Service Pack	20014	66	7.5
2011-2013			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
G25			
2011-2013			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
G35			
2003			
OE Sensor: Nissan - 40700-CD001			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Jun. & Newer	20064	61-72	6.8-8.2
Service Pack; Jun. & Newer	20007	61-72	6.8-8.2
2004-2006			
OE Sensor: Nissan - 40700-CD001			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20064	61-72	6.8-8.2
Service Pack	20007	61-72	6.8-8.2

Application	Part No.	Torque in-lbs	Torque N.m.
Infiniti (cont'd)			
G35 (cont'd)			
2007			
OE Sensor: Nissan - 40700-JA01B, 40700-JK00B			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Coupe	28204	66	7.5
Sensor; Sedan	28210	66	7.5
Service Pack	20014	66	7.5
2008			
OE Sensor: Nissan - 40700-JK00B			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28210	66	7.5
Service Pack	20014	66	7.5
G37			
2008-2010			
OE Sensor: Nissan - 40700-JK00B			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28210	66	7.5
Service Pack	20014	66	7.5
2011-2013			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
M35			
2006-2007			
OE Sensor: Nissan - 40700-CD001			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20064	66	7.5
Service Pack	20007	66	7.5
2008-2010			
OE Sensor: Nissan - 40700-JA00C, 40700-JA01C			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28204	66	7.5
Service Pack	20014	66	7.5
2011-2012			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Infiniti (cont'd)			
M35h			
2011			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
2012			
OE Sensor: Nissan - 40700-JA01C			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28204	66	7.5
Service Pack	20014	66	7.5
M37			
2011-2012			
OE Sensor: Nissan - 40700-JA01C			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28204	66	7.5
Service Pack	20014	66	7.5
2013			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
M45			
2003-2004			
OE Sensor: Nissan - 40700-CD001			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20064	66	7.5
Service Pack	20007	66	7.5
2006-2007			
OE Sensor: Nissan - 40700-CD001			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20064	66	7.5
Service Pack	20007	66	7.5
2008-2009			
OE Sensor: Nissan - 40700-JA00C, 40700-JA01C			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28204	66	7.5
Service Pack	20014	66	7.5

Application	Part No.	Torque in-lbs	Torque N.m.
Infiniti (cont'd)			
M45 (cont'd)			
2010			
OE Sensor: Nissan - 40700-JA01C			
EZ-Sensor	33000 A	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28204	66	7.5
Service Pack	20014	66	7.5
2011			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
M56			
2011-2012			
OE Sensor: Nissan - 40700-JA01C			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28204	66	7.5
Service Pack	20014	66	7.5
2013			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Q45			
2002			
Service Pack	20007	66	7.5
2003-2005			
OE Sensor: Nissan - 40700-CD001			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20064	66	7.5
Service Pack	20007	66	7.5
2006			
OE Sensor: Nissan - 40700-CD001, 40700-JA01B			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Aug. & Newer	28204	66	7.5
Sensor; Jul. & Older	20064	66	7.5
Service Pack; Aug. & Newer	20014	66	7.5
Service Pack; Jul. & Older	20007	66	7.5
Q70			
2014-2016			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Infiniti (cont'd)			
QX4			
2003			
OE Sensor: Nissan - 40700-CD001			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20064	66	7.5
Service Pack	20007	66	7.5
QX50			
2013-2016			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
QX56			
2004			
OE Sensor: Nissan - 40700-CK002			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20069	49	5.5
Service Pack	20005	49	5.5
2005-2006			
OE Sensor: Nissan - 40700-CK001, 40700-CK002			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; W/Alloy Wheels	20161	49	5.5
Sensor; W/Steel Wheels	20069	49	5.5
Service Pack; W/Alloy Wheels	20007	49	5.5
Service Pack; W/Steel Wheels	20005	49	5.5
2007			
OE Sensor: Nissan - 40700-CK001, 40700-JA02B			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Apr. 1 & Newer	28204	49	5.5
Sensor; Mar. & Older	20161	49	5.5
Service Pack; Apr. 1 & Newer	20014	49	5.5
Service Pack; Mar. & Older	20007	49	5.5
2008-2010			
OE Sensor: Nissan - 40700-JA01B, 40700-JA02B			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28204	49	5.5
Service Pack	20014	49	5.5
2011-2013			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3

Application	Part No.	Torque in-lbs	Torque N.m.
Infiniti (cont'd)			
QX70			
2014-2016			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
QX80			
2014-2016			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Isuzu			
Ascender			
2006-2008			
OE Sensor: Isuzu - 8257740060			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; exc Touring; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20116	62	7
Service Pack	20004	62	7
2009-2011			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; exc Touring; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
i-290			
2007-2008			
OE Sensor: General Motors - 15122618			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20131	62	7
Service Pack	20006	62	7
2009			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
i-370			
2007-2008			
OE Sensor: General Motors - 15122618			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20131	62	7
Service Pack	20006	62	7
2009			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Isuzu (cont'd)			
Rodeo			
2004			
OE Sensor: Isuzu - 8973271890			
EZ-Sensor	33100 [A]	11.5	1.3
	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20028 [B]	62	7
Service Pack	20003	62	7
Jaguar			
Jaguar			
2004-2012			
OE Sensor: Jaguar - C2C25519, C2C40476, C2C40725, C2S40710, C2Z15016, C2Z15017, XR855949, XR855950			
Sensor; W/315 MHz Sensor	20090	71	8
Sensor; W/433 MHz Sensor	20091	71	8
Service Pack	20030	71	8
Jeep			
Cherokee			
2014			
OE Sensor: Chrysler - 682397208AA			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
Sensor	28984	35	4
Service Pack	20635	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2015			
OE Sensor: Chrysler - 68239720AC			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
Sensor	28984	35	4
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
	20635	11.5	1.3
2016-2017			
OE Sensor: Chrysler - 68239720AC			
Sensor	28984	35	4
Service Pack; Rubber Valve	20635	11.5	1.3
Commander			
2006-2007			
OE Sensor: Chrysler - 56053030AB, 56053036AA			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor; Caution: Ez-sensor will not support (Wai) Wheel Arch Initiators	33000 [A]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28308 [F]	11.5	1.3
Service Pack; Fits Schrader Alum stem sensor. Does not include stem.	20013	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Service Pack; W/Siemens Sensor	20030	71	8

Application	Part No.	Torque in-lbs	Torque N.m.
Jeep (cont'd)			
Commander (cont'd)			
2008-2010			
OE Sensor: Chrysler - 56029359AA, 56029359AB			
EZ-Sensor	33100 [A]	11.5	1.3
	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28434 [E]	11.5	1.3
Service Pack; Fits Schrader Alum stem sensor. Does not include stem.	20013	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2011			
EZ-Sensor	33100 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
Compass			
2007-2010			
OE Sensor: Chrysler - 68001696AA, 68001696AB			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor; Caution: Ez-sensor will not support (Wai) Wheel Arch Initiators	33000 [A]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28308 [F]	11.5	1.3
Service Pack; Fits Schrader Alum stem sensor. Does not include stem.	20013	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Service Pack; W/Siemens Sensor	20030	71	8
2011			
OE Sensor: Chrysler - 68001696AB			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor; Caution: Ez-sensor will not support (Wai) Wheel Arch Initiators	33000 [A]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28308 [F]	11.5	1.3
Service Pack; Fits Schrader Alum stem sensor. Does not include stem.	20013	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2012-2015			
OE Sensor: Chrysler - 56029481AB, 68001696AB			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor; Caution: Ez-sensor will not support (Wai) Wheel Arch Initiators	33000 [A]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28308 [F]	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3

A-Programming Tool Required B-Magnet may be Required to Activate Sensor C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200
E-Supercedes the 28155 F-Supercedes the 20066

Application	Part No.	Torque in-lbs	Torque N.m.
Jeep (cont'd)			
Compass (cont'd)			
2016			
OE Sensor: Chrysler - 56029479AB			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28308 F	11.5	1.3
Service Pack; Rubber Valve	20018 C	11.5	1.3
2017			
OE Sensor: Chrysler - 56029479AB			
Sensor	28308 F	11.5	1.3
Service Pack; Rubber Valve	20018 C	11.5	1.3
Grand Cherokee			
2002-2004			
OE Sensor: Chrysler - 52088990AC			
EZ-Sensor	33100 A	11.5	1.3
	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20028 B	64	7
Service Pack	20003	64	7
2005-2007			
OE Sensor: Chrysler - 56053030AB, 68001696AA			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor; Caution: Ez-sensor will not support (Wai) Wheel Arch Initiators	33000 A	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28308 F	11.5	1.3
Service Pack; Fits Schrader Alum stem sensor. Does not include stem.	20013	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Rubber Valve	20018 C	11.5	1.3
Service Pack; W/Siemens Sensor	20030	71	8
2008-2010			
OE Sensor: Chrysler - 56029359AB			
EZ-Sensor	33100 A	11.5	1.3
	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28434 E	11.5	1.3
Service Pack; Fits Schrader Alum stem sensor. Does not include stem.	20013	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Rubber Valve	20018 C	11.5	1.3
2011-2015			
OE Sensor: Chrysler - 56029398AA, 56029398AB			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20398	11.5	1.3
Service Pack; Rubber Valve	20018 C	11.5	1.3

Application	Part No.	Torque in-lbs	Torque N.m.
Jeep (cont'd)			
Liberty			
2002-2004			
OE Sensor: Chrysler - 52088990AC			
EZ-Sensor	33100 A	11.5	1.3
	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20028 B	64	7
Service Pack	20003	64	7
2005-2008			
OE Sensor: Chrysler - 56053036AA, 68001696AB			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor; Caution: Ez-sensor will not support (Wai) Wheel Arch Initiators	33000 A	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28308 F	11.5	1.3
Service Pack; Fits Schrader Alum stem sensor. Does not include stem.	20013	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Rubber Valve	20018 C	11.5	1.3
Service Pack; W/Siemens Sensor	20030	71	8
2009			
OE Sensor: Chrysler - 56029359AB, 56029465AB			
EZ-Sensor	33100 A	11.5	1.3
	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor; Caution: Ez-sensor will not support (Wai) Wheel Arch Initiators	33000 A	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; W/315 MHz Snap-in Sensor	28308 F	11.5	1.3
Sensor; W/433 MHz Clamp-in Sensor	28434 E	11.5	1.3
Service Pack; Fits Schrader Alum stem sensor. Does not include stem.	20013	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Rubber Valve	20018 C	11.5	1.3
2010-2012			
OE Sensor: Chrysler - 56029465AB			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor; Caution: Ez-sensor will not support (Wai) Wheel Arch Initiators	33000 A	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28308 F	11.5	1.3
Service Pack; Fits Schrader Alum stem sensor. Does not include stem.	20013	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Rubber Valve	20018 C	11.5	1.3

A-Programming Tool Required B-Magnet may be Required to Activate Sensor C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200
E-Supercedes the 28155 F-Supercedes the 20066

Application	Part No.	Torque in-lbs	Torque N.m.
Jeep (cont'd)			
Patriot			
2007-2010			
OE Sensor: Chrysler - 68001696AA, 68001696AB			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor; Caution: Ez-sensor will not support (Wai) Wheel Arch Initiators	33000 A	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28308 F	11.5	1.3
Service Pack; Fits Schrader Alum stem sensor. Does not include stem.	20013	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Rubber Valve	20018 C	11.5	1.3
Service Pack; W/Siemens Sensor	20030	71	8
2011-2012			
OE Sensor: Chrysler - 68078861AA			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor; Caution: Ez-sensor will not support (Wai) Wheel Arch Initiators	33000 A	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28308 F	11.5	1.3
Service Pack; Fits Schrader Alum stem sensor. Does not include stem.	20013	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Rubber Valve	20018 C	11.5	1.3
2013-2015			
OE Sensor: Chrysler - 56029479AB, 56029481AB			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor; Caution: Ez-sensor will not support (Wai) Wheel Arch Initiators	33000 A	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; W/315 MHz	28308 F	11.5	1.3
Service Pack; Rubber Valve	20018 C	11.5	1.3
2016			
OE Sensor: Chrysler - 56029481AB			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; W/315 MHz	28308 F	11.5	1.3
Service Pack; Rubber Valve	20018 C	11.5	1.3
2017			
OE Sensor: Chrysler - 56029481AB			
Sensor; W/315 MHz	28308 F	11.5	1.3
Service Pack; Rubber Valve	20018 C	11.5	1.3
Renegade			
2015-2016			
OE Sensor: Chrysler - 68193586AC			
Sensor	28586		
Service Pack	20043		

Application	Part No.	Torque in-lbs	Torque N.m.
Jeep (cont'd)			
Wrangler			
2007-2008			
OE Sensor: Chrysler - 56053036AA			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor; Caution: Ez-sensor will not support (Wai) Wheel Arch Initiators	33000 A	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28308 F	11.5	1.3
Service Pack; Fits Schrader Alum stem sensor. Does not include stem.	20013	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Rubber Valve	20018 C	11.5	1.3
Service Pack; W/Siemens Sensor	20030	71	8
2009			
OE Sensor: Chrysler - 56029359AB			
EZ-Sensor	33100 A	11.5	1.3
	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28434 E	11.5	1.3
Service Pack; Fits Schrader Alum stem sensor. Does not include stem.	20013	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Rubber Valve	20018 C	11.5	1.3
2010			
OE Sensor: Chrysler - 56029359AB			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28434 E	11.5	1.3
Service Pack; Fits Schrader Alum stem sensor. Does not include stem.	20013	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Rubber Valve	20018 C	11.5	1.3
2011			
OE Sensor: Chrysler - 56029479AA			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor; Caution: Ez-sensor will not support (Wai) Wheel Arch Initiators	33000 A	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28308 F	11.5	1.3
Service Pack; Fits Schrader Alum stem sensor. Does not include stem.	20013	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Rubber Valve	20018 C	11.5	1.3

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200 E-Supercedes the 28155 F-Supercedes the 20066

Application	Part No.	Torque in-lbs	Torque N.m.
Jeep (cont'd)			
Wrangler (cont'd)			
2012			
OE Sensor: Chrysler - 56029479AA			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor; Caution: Ez-sensor will not support (Wai) Wheel Arch Initiators	33000 A	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28308 F	11.5	1.3
Service Pack; Rubber Valve	20018 C	11.5	1.3
2013-2015			
OE Sensor: Chrysler - 56029398AB, 68241067AB			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20398	11.5	1.3
Service Pack; Rubber Valve	20018 C	11.5	1.3
2016			
OE Sensor: Chrysler - 68241067AB			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20398	11.5	1.3
Service Pack; Rubber Valve	20018 C	11.5	1.3
2017			
OE Sensor: Chrysler - 68241067AB			
Sensor	20398	11.5	1.3
Service Pack; Rubber Valve	20018 C	11.5	1.3
Kia			
Amanti			
2007-2009			
OE Sensor: Kia - 529331FA00			
Sensor	28983	35	4
Service Pack; Includes Valve	20036	35	4
Borrego			
2009-2011			
OE Sensor: Hyundai - 529332F000			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28849	35	4
Service Pack	20022	35	4
Cadenza			
2014-2015			
OE Sensor: Hyundai - 529332M550, 52933A5000; Kia - 529332M550			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20092	31-40	3.5-4.5

Application	Part No.	Torque in-lbs	Torque N.m.
Kia (cont'd)			
Cadenza (cont'd)			
2016			
OE Sensor: Kia - 529332M550			
Sensor	20092	31-40	3.5-4.5
Forte			
2010-2013			
OE Sensor: Hyundai - 529332M000; Kia - 529332M000			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20092	31-40	3.5-4.5
2014-2015			
OE Sensor: Kia - 52933-A7000			
Sensor	28070		
2016			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Forte Koup			
2010-2013			
OE Sensor: Hyundai - 529332M000; Kia - 529332M000			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20092	31-40	3.5-4.5
2014			
Sensor	20092	31-40	3.5-4.5
Forte5			
2012-2013			
OE Sensor: Hyundai - 529332M000			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20092	31-40	3.5-4.5
Magentis			
2008			
OE Sensor: Hyundai - 52933-2G200			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Includes Transmitter Only	20086	31-40	3.5-4.5
Service Pack; Includes Valve	20036	31-40	3.5-4.5
2009			
OE Sensor: Hyundai - 52933-2G200			
Sensor; Includes Transmitter Only	20086	31-40	3.5-4.5
Service Pack; Includes Valve	20036	31-40	3.5-4.5

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200 F-Supercedes the 20066

Application	Part No.	Torque in-lbs	Torque N.m.
Kia (cont'd)			
Magentis (cont'd)			
2010			
OE Sensor: Hyundai - 52933-2G200			
EZ-Sensor	33500 A, DB	11.5	1.3
Sensor; Includes Transmitter Only	20086	31-40	3.5-4.5
Service Pack; Includes Valve	20036	31-40	3.5-4.5
Optima			
2006-2010			
OE Sensor: Hyundai - 529332G200			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Includes Transmitter Only	20086	31-40	3.5-4.5
Service Pack; Includes Valve	20036	31-40	3.5-4.5
2011-2015			
OE Sensor: Kia - 52933-2M000, 529332M000			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20092	31-40	3.5-4.5
Rio			
2007-2011			
OE Sensor: Hyundai - 529332F000			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28849	35	4
Service Pack	20022	35	4
2015-2017			
OE Sensor: Kia - 52933-3X200			
Sensor	20086	31-40	3.5-4.5
Rio5			
2007-2011			
OE Sensor: Hyundai - 529332F000			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28849	35	4
Service Pack	20022	35	4
2012			
OE Sensor: Hyundai - 529332M000			
Sensor	20092	31-40	3.5-4.5
2015-2016			
OE Sensor: Kia - 52933-3X200			
Sensor	20086	31-40	3.5-4.5

Application	Part No.	Torque in-lbs	Torque N.m.
Kia (cont'd)			
Rondo			
2007-2011			
OE Sensor: Hyundai - 529332G200			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Includes Transmitter Only	20086	31-40	3.5-4.5
Service Pack; Includes Valve	20036	31-40	3.5-4.5
Sedona			
2006-2008			
OE Sensor: Hyundai - 529334D200			
Sensor; Includes Transmitter Only	20085	31-40	3.5-4.5
Service Pack; Includes Valve	20036	31-40	3.5-4.5
2009-2012			
OE Sensor: Hyundai - 529332G200			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Includes Transmitter Only	20086	31-40	3.5-4.5
Service Pack; Includes Valve	20036	31-40	3.5-4.5
2013-2014			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
2015-2016			
OE Sensor: Kia - 52933-B2100			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20218	11.5	1.3
Service Pack; Rubber Valve	20046	11.5	1.3
2017			
OE Sensor: Kia - 52933-B2100			
Sensor	20218	11.5	1.3
Service Pack; Rubber Valve	20046	11.5	1.3
Sorento			
2007-2009			
OE Sensor: Kia - 529331FA00			
Sensor	28983	35	4
Service Pack; Includes Valve	20036	35	4
2011-2014			
OE Sensor: Kia - 529332M000; Original Equipment Manufacturer - 529332M00			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20092	31-40	3.5-4.5
2015			
OE Sensor: Kia - 52933-2M550			
Sensor	20092	31-40	3.5-4.5

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Kia (cont'd)			
Soul			
2010-2013			
OE Sensor: Kia - 529332M000, 529332M001			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20092	31-40	3.5-4.5
2014			
OE Sensor: Kia - 52933-B2100			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20218	11.5	1.3
Service Pack	20046	11.5	1.3
2015-2016			
OE Sensor: Kia - 52933-B2100			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20218	11.5	1.3
Service Pack; Rubber Valve	20046	11.5	1.3
Spectra			
2006			
OE Sensor: Hyundai - 529332F000			
Sensor	28849	35	4
Service Pack	20022	35	4
2007-2009			
OE Sensor: Hyundai - 529332F000			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28849	35	4
Service Pack	20022	35	4
2010-2011			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Spectra5			
2006			
OE Sensor: Hyundai - 529332F000			
Sensor	28849	35	4
Service Pack	20022	35	4
2007-2009			
OE Sensor: Hyundai - 529332F000			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28849	35	4
Service Pack	20022	35	4

Application	Part No.	Torque in-lbs	Torque N.m.
Kia (cont'd)			
Sportage			
2005			
OE Sensor: Hyundai - 529331FA00			
Sensor; Jun. 15, 2005 & Newer	28983	35	4
Service Pack; Jun. 15, 2005 & Newer; Includes Valve	20036	31-40	3.5-4.5
2006-2008			
OE Sensor: Hyundai - 529331FA00; Kia - 529331FA00			
Sensor	28983	35	4
Service Pack; Includes Valve	20036	31-40	3.5-4.5
2009-2012			
OE Sensor: Kia - 529332F000			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28849	35	4
Service Pack	20022	35	4
2013			
OE Sensor: Kia - 529332F000			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28849	35	4
Service Pack	20022	35	4
2014-2015			
OE Sensor: Hyundai - 529332S500			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28500		
2016			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Lamborghini			
Aventador			
2011			
OE Sensor: Volkswagen - 4F0 907 275			
Sensor; Includes Transmitter Only	20078	35	4
Land Rover			
LR2			
2008-2015			
OE Sensor: Land Rover - LR021936, LR032833, LR066378			
Sensor	20090	71	8
Service Pack	20030	71	8

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Land Rover (cont'd)			
LR3			
2002-2005			
OE Sensor: Land Rover - YBD000060			
EZ-Sensor	33100 [A]	11.5	1.3
	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Includes Transmitter Only	28082	58	6.5
Service Pack; Does Not Include Valve	20023	58	6.5
Service Pack; W/43mm Silver Insert	20037	58	6.5
Service Pack; W/48mm Green Insert	20038	58	6.5
Service Pack; W/49mm Black Insert	20039	58	6.5
Service Pack; W/51mm Orange Insert	20040	58	6.5
2006-2009			
OE Sensor: Land Rover - LR010532, LR010533, LR018860, LR018861, LR0500461, RQH500471			
Sensor; W/315 MHz Sensor	20090	71	8
Sensor; W/433 MHz Sensor	20091	71	8
Service Pack	20030	71	8
LR4			
2010-2011			
OE Sensor: Land Rover - LR018860, LR018861			
Sensor; W/315 MHz Sensor	20090	71	8
Sensor; W/433 MHz Sensor	20091	71	8
Service Pack	20030	71	8
2012-2014			
OE Sensor: Land Rover - LR021936, LR032833			
Sensor	20090	71	8
Service Pack	20030	71	8
Range Rover			
2002			
OE Sensor: Land Rover - YBD000061			
Sensor; Includes Transmitter Only	28082	58	6.5
Service Pack; Does Not Include Valve	20023	58	6.5
Service Pack; W/43mm Silver Insert	20037	58	6.5
Service Pack; W/48mm Green Insert	20038	58	6.5
Service Pack; W/49mm Black Insert	20039	58	6.5
Service Pack; W/51mm Orange Insert	20040	58	6.5
2003-2005			
OE Sensor: Land Rover - YBD000061			
EZ-Sensor	33100 [A]	11.5	1.3
	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Includes Transmitter Only	28082	58	6.5
Service Pack; Does Not Include Valve	20023	58	6.5
Service Pack; W/43mm Silver Insert	20037	58	6.5
Service Pack; W/48mm Green Insert	20038	58	6.5
Service Pack; W/49mm Black Insert	20039	58	6.5
Service Pack; W/51mm Orange Insert	20040	58	6.5

Application	Part No.	Torque in-lbs	Torque N.m.
Land Rover (cont'd)			
Range Rover (cont'd)			
2006-2011			
OE Sensor: Land Rover - LR010532, LR010533, LR018860, LR018861, LR0500461, RQH500471			
Sensor; W/315 MHz Sensor	20090	71	8
Sensor; W/433 MHz Sensor	20091	71	8
Service Pack	20030	71	8
2012-2014			
OE Sensor: Land Rover - LR0031713, LR021936			
Sensor	20090	71	8
Service Pack	20030	71	8
Range Rover Evoque			
2012-2015			
OE Sensor: Land Rover - LR0031713, LR021936			
Sensor	20090	71	8
Service Pack	20030	71	8
Range Rover Sport			
2006-2011			
OE Sensor: Land Rover - LR010532, LR010533, LR018860, LR018861, LR0500461, RQH500471			
Sensor; W/315 MHz Sensor	20090	71	8
Sensor; W/433 MHz Sensor	20091	71	8
Service Pack	20030	71	8
2012-2014			
OE Sensor: Land Rover - LR021936, LR031713			
Sensor	20090	71	8
Service Pack	20030	71	8
Lexus			
CT200h			
2011			
OE Sensor: Toyota - 4260733021			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28370	35	4
Service Pack	20032	35	4
2012-2015			
OE Sensor: Toyota - 4260733021			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28370	35	4
Service Pack	20032	35	4
2016			
OE Sensor: Toyota - 4260733021			
Sensor	28370	35	4
Service Pack	20032	35	4

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Lexus (cont'd)			
ES300h			
2013			
OE Sensor: Toyota - 4260733021			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28370	35	4
Service Pack	20032	35	4
2014-2016			
OE Sensor: Toyota - 4260730060, 4260733021			
Sensor	28370	35	4
Service Pack	20032	35	4
ES350			
2007-2013			
OE Sensor: Toyota - 4260733021			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28370	35	4
Service Pack	20032	35	4
2014-2016			
OE Sensor: Toyota - 4260730060, 4260733021			
Sensor	28370	35	4
Service Pack	20032	35	4
GS300			
2006			
OE Sensor: Toyota - 4260730030			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28335	35	4
Service Pack	20031	35	4
2007-2011			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
GS350			
2007-2011			
OE Sensor: Toyota - 4260733021			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28370	35	4
Service Pack	20032	35	4

Application	Part No.	Torque in-lbs	Torque N.m.
Lexus (cont'd)			
GS350 (cont'd)			
2013			
OE Sensor: Toyota - 42607-30060			
EZ-Sensor	33200 [A]	11.5	1.3
EZ-Sensor; For use with 433 MHz sensor 42607-30070	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; 315 MHz	28370	35	4
Service Pack	20032	62	7
2014-2016			
OE Sensor: Toyota - 42607-30060, 4260730060			
EZ-Sensor; For use with 433 MHz sensor 42607-30070	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; 315 MHz	28370	35	4
Service Pack	20032	35	4
GS430			
2005			
OE Sensor: Toyota - 4260730030			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28335	35	4
Service Pack	20031	35	4
2006			
OE Sensor: Toyota - 4260730030, 4260733021			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Jul. & Newer	28370	35	4
Sensor; Jun. & Older	28335	35	4
Service Pack; Jul. & Newer	20032	35	4
Service Pack; Jun. & Older	20031	35	4
2007			
OE Sensor: Toyota - 4260733021			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28370	35	4
Service Pack	20032	35	4
GS450h			
2007-2011			
OE Sensor: Toyota - 4260733021			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28370	35	4
Service Pack	20032	35	4

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Lexus (cont'd)			
GS450h (cont'd)			
2013-2016			
OE Sensor: Toyota - 4260730060, 4260730600, 4260733021			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28370	35	4
Service Pack	20032	35	4
GS460			
2008-2011			
OE Sensor: Toyota - 4260733021			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28370	35	4
Service Pack	20032	35	4
2012-2016			
OE Sensor: Toyota - 4260730600, 4260733021			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28370	35	4
Service Pack	20032	35	4
2016			
EZ-Sensor	33000 [A]	11.5	1.3
GX460			
2010-2015			
OE Sensor: Toyota - 4260733021, 4260733022			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28370	35	4
Service Pack	20032	35	4
2016			
OE Sensor: Toyota - 4260733022			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28370	35	4
Service Pack	20032	35	4
GX470			
2004-2005			
OE Sensor: Toyota - 4260735010			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28345	35	4
Service Pack	20031	35	4

Application	Part No.	Torque in-lbs	Torque N.m.
Lexus (cont'd)			
GX470 (cont'd)			
2006			
OE Sensor: Toyota - 4260730030, 4260733011, 4260735010			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Feb. & Newer; W/O Valve Cap	28335	35	4
Sensor; Feb. & Newer; W/Valve Cap	28365	35	4
Sensor; Jan. 31 & Older	28345	35	4
Service Pack; Feb. & Newer	20032	35	4
Service Pack; Jan. 31 & Older	20031	35	4
2007-2009			
OE Sensor: Toyota - 4260733021			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28370	35	4
Service Pack	20032	35	4
HS250h			
2010-2012			
OE Sensor: Toyota - 4260775010			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28345	35	4
Service Pack	20032	35	4
IS F			
2008-2015			
OE Sensor: Toyota - 4260733021			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28370	35	4
Service Pack	20032	35	4
2016			
OE Sensor: Toyota - 4260733021			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28370	35	4
Service Pack	20032	35	4
IS250			
2006			
OE Sensor: Toyota - 4260730030, 4260733021			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Apr. 1 & Newer	28370	35	4
Sensor; Mar. & Older	28335	35	4
Service Pack; Apr. 1 & Newer	20032	35	4
Service Pack; Mar. & Older	20031	35	4

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Lexus (cont'd)			
IS250 (cont'd)			
2007			
OE Sensor: Toyota - 4260733021			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; C; Rubber Valve	20018 [C]	11.5	1.3
EZ-Sensor Service Pack; exc C; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28370	35	4
Service Pack	20032	35	4
2008-2015			
OE Sensor: Toyota - 4260733021			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28370	35	4
Service Pack	20032	35	4
2016			
OE Sensor: Toyota - 4260730060			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28370	35	4
Service Pack	20032	35	4
IS350			
2006			
OE Sensor: Toyota - 4260730030, 4260733021			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Apr. 1 & Newer	28370	35	4
Sensor; Mar. & Older	28335	35	4
Service Pack; Apr. 1 & Newer	20032	35	4
Service Pack; Mar. & Older	20031	35	4
2007-2015			
OE Sensor: Toyota - 4260733021			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28370	35	4
Service Pack	20032	35	4
2016			
OE Sensor: Toyota - 4260733021			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28370	35	4
Service Pack	20032	35	4

Application	Part No.	Torque in-lbs	Torque N.m.
Lexus (cont'd)			
LFA			
2012			
OE Sensor: Toyota - 4260733021			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28370	35	4
Service Pack	20032	35	4
2013-2015			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2016			
OE Sensor: Toyota - 4260733021			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28370	35	4
Service Pack	20032	35	4
LS430			
2004-2006			
Sensor	INDIRECT [D]		
LS460			
2007-2016			
OE Sensor: Toyota - 4260733021			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28370	35	4
Service Pack	20032	35	4
LS600h			
2008-2016			
OE Sensor: Toyota - 4260730600, 4260733021			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28370	35	4
Service Pack	20032	35	4
LX470			
2005			
OE Sensor: Toyota - 4260733011			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28365	35	4
Service Pack	20031	35	4

A-Programming Tool Required C-20018 and 20008 are interchangeable. D-Indirect TPMS system. No sensor in wheel DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Lexus (cont'd)			
LX470 (cont'd)			
2006			
OE Sensor: Toyota - 4260733011, 4260733021			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Aug. & Newer	28370	35	4
Sensor; Jul. & Older	28365	35	4
Service Pack; Aug. & Newer	20032	35	4
Service Pack; Jul. & Older	20031	35	4
2007			
OE Sensor: Toyota - 4260733021			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28370	35	4
Service Pack	20032	35	4
LX570			
2008-2011			
OE Sensor: Toyota - 4260733021			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28370	35	4
Service Pack	20032	35	4
2013-2014			
OE Sensor: Toyota - 4260733021			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28370	35	4
Service Pack	20032	35	4
2015			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2016			
OE Sensor: Toyota - 4260733021			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28370	35	4
Service Pack	20032	35	4
RX330			
2004-2005			
Sensor	INDIRECT [D]		

Application	Part No.	Torque in-lbs	Torque N.m.
Lexus (cont'd)			
RX330 (cont'd)			
2006			
OE Sensor: Toyota - 4260733021			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Models made in Japan; Feb. & Newer	28370	35	4
Service Pack; Feb. & Newer	20032	35	4
Service Pack; Jan. 31 & Older	20031	35	4
RX350			
2007-2010			
OE Sensor: Toyota - 4260733021			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Models made in Japan	28370	35	4
Service Pack	20032	35	4
2011-2012			
OE Sensor: Toyota - 426070E011, 4260733021			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28370	35	4
Service Pack	20032	35	4
2013			
OE Sensor: Toyota - 426070E011			
EZ-Sensor; exc F Sport	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; exc F Sport; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; exc F Sport; Rubber Valve	20018 [C]	11.5	1.3
Sensor; exc F Sport	28370	35	4
Service Pack; exc F Sport	20032	35	4
2014-2015			
OE Sensor: Toyota - 4260733021			
EZ-Sensor; exc F Sport	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; exc F Sport; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; exc F Sport; Rubber Valve	20018 [C]	11.5	1.3
Sensor; F Sport; Vehicle Made for Canada	28370	35	4
Service Pack	20032	35	4
RX400h			
2006			
OE Sensor: Toyota - 4260733021			
Sensor	28370	35	4
Service Pack	20032	35	4

A-Programming Tool Required C-20018 and 20008 are interchangeable. D-Indirect TPMS system. No sensor in wheel DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Lexus (cont'd)			
RX400h (cont'd)			
2007-2008			
OE Sensor: Toyota - 4260733021			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Models made in Japan	28370	35	4
Service Pack	20032	35	4
2009-2012			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
RX450h			
2010-2013			
OE Sensor: Toyota - 4260733021			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28370	35	4
Service Pack	20032	35	4
2014-2015			
OE Sensor: Toyota - 4260733021			
Sensor	28370	35	4
Service Pack	20032	35	4
SC430			
2002-2005			
OE Sensor: Toyota - 4260724010, 4260724020, 4260724030, 4260724040			
Sensor; W/Blue I.D. Mark	28315	27	3
Sensor; W/Gold I.D. Mark	28325	27	3
Sensor; W/Red I.D. Mark	28320	27	3
Sensor; W/White I.D. Mark	28310	27	3
2006			
OE Sensor: Toyota - 4260724010, 4260724020, 4260724030, 4260724040, 4260733021			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Aug. & Newer	28370	27	3
Sensor; W/Blue I.D. Mark; Jul. & Older	28315	27	3
Sensor; W/Gold I.D. Mark; Jul. & Older	28325	27	3
Sensor; W/Red I.D. Mark; Jul. & Older	28320	27	3
Sensor; W/White I.D. Mark; Jul. & Older	28310	27	3
Service Pack; Aug. & Newer	20032	27	3
2007-2010			
OE Sensor: Toyota - 4260733021			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28370	27	3
Service Pack	20032	27	3

Application	Part No.	Torque in-lbs	Torque N.m.
Lincoln			
Aviator			
2003-2005			
OE Sensor: Ford Motor Company - 4L2Z 1A150 BA			
EZ-Sensor	33100 [A]	11.5	1.3
	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20096 [B]	44	5
Service Pack	20002	44	5
Continental			
2017			
OE Sensor: Ford Motor Company - F2GT-1A180-AB			
Sensor	20280	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Mark LT			
2007-2008			
OE Sensor: Ford Motor Company - 6F2Z1A189A			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28385	27	3
Sensor Clip	22100		
Sensor Cradle	22101		
Universal Band	22102		
2013-2014			
OE Sensor: Ford Motor Company - DE8T1A180AA			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20315	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2015-2016			
OE Sensor: Ford Motor Company - F2GT-1A180-AB			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20280	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
MKC			
2015			
OE Sensor: Ford Motor Company - 9L3Z1A189A			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20315	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3

A-Programming Tool Required B-Magnet may be Required to Activate Sensor C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Lincoln (cont'd)			
MKC (cont'd)			
2016			
OE Sensor: Ford Motor Company - 9L3Z1A189A			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20315	11.5	1.3
Service Pack; Rubber Valve	20018 C	11.5	1.3
2017			
OE Sensor: Ford Motor Company - 9L3Z1A189A			
Sensor	20315	11.5	1.3
Service Pack; Rubber Valve	20018 C	11.5	1.3
MKS			
2009-2010			
OE Sensor: Ford Motor Company - 7L1Z1A189A			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28390	27	3
Sensor Clip	22100		
Sensor Cradle	22101		
Universal Band	22102		
2011-2015			
OE Sensor: Ford Motor Company - 9L3Z1A189A, CM5T 1A180 AA, DE8T-1A180-AA, DE8T1A180AA			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20315	11.5	1.3
Service Pack; Rubber Valve	20018 C	11.5	1.3
2016			
OE Sensor: Ford Motor Company - F2GT-1A180-AB			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20280	11.5	1.3
Service Pack; Rubber Valve	20018 C	11.5	1.3
MKT			
2010			
OE Sensor: Ford Motor Company - 7L1Z1A189A			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28390	27	3
Sensor Clip	22100		
Sensor Cradle	22101		
Universal Band	22102		

Application	Part No.	Torque in-lbs	Torque N.m.
Lincoln (cont'd)			
MKT (cont'd)			
2011-2016			
OE Sensor: Ford Motor Company - 9L3Z1A189A, CM5T 1A180 AA, DE8T-10A-180-AA, DE8T-1A180-AA, DE8T1A180AA			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20315	11.5	1.3
Service Pack; Rubber Valve	20018 C	11.5	1.3
2017			
OE Sensor: Ford Motor Company - DE8T-10A-180-AA			
Sensor	20315	11.5	1.3
Service Pack; Rubber Valve	20018 C	11.5	1.3
MKX			
2007-2008			
OE Sensor: Ford Motor Company - 6F2Z1A189A, 7L1Z1A189A			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; W/Chrome Plated Almnm. Wheels	28385	27	3
Sensor; W/O Chrome Plated Almnm. Wheels	28390	27	3
Sensor Clip	22100		
Sensor Cradle	22101		
Universal Band	22102		
2009-2010			
OE Sensor: Ford Motor Company - 7L1Z1A189A			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28390	27	3
Sensor Clip	22100		
Sensor Cradle	22101		
Universal Band	22102		
2011-2014			
OE Sensor: Ford Motor Company - 9L3Z1A189A, CM5T 1A180 AA, DE8T-1A180-AA			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20315	11.5	1.3
Service Pack; Rubber Valve	20018 C	11.5	1.3
2015-2016			
OE Sensor: Ford Motor Company - F2GT-1A180-AB			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20280	11.5	1.3
Service Pack; Rubber Valve	20018 C	11.5	1.3
2017			
OE Sensor: Ford Motor Company - F2GT-1A180-AB			
Sensor	20280	11.5	1.3
Service Pack; Rubber Valve	20018 C	11.5	1.3

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Lincoln (cont'd)			
MKZ			
2007-2009			
OE Sensor: Ford Motor Company - 6F2Z1A189A			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28385	27	3
Sensor Clip	22100		
Sensor Cradle	22101		
Universal Band	22102		
2010-2015			
OE Sensor: Ford Motor Company - 9L3Z1A189A, CM5T 1A180 AA, CM5T-1A180-AA, DE8T-1A180-AA, DE8T1A180AA			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20315	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2016			
OE Sensor: Ford Motor Company - DE8T1A180AA			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20315	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Navigator			
2003-2004			
OE Sensor: Ford Motor Company - 4L2Z 1A150 BA			
EZ-Sensor	33100 [A]	11.5	1.3
	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20096 [B]	44	5
Service Pack	20002	44	5
2005-2006			
OE Sensor: Ford Motor Company - 5L1Z 1A150 AA			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20135 [B]	44	5
Service Pack	20002	44	5
2007-2010			
OE Sensor: Ford Motor Company - 7L1Z1A189A			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28390	27	3
Sensor Clip	22100		
Sensor Cradle	22101		
Universal Band	22102		

Application	Part No.	Torque in-lbs	Torque N.m.
Lincoln (cont'd)			
Navigator (cont'd)			
2011-2015			
OE Sensor: Ford Motor Company - 9L3Z1A189A, CM5T 1A180 AA, DE8T-1A180-AA, DE8T1A180AA			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20315	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2016			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20315	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2017			
Sensor	20315	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Town Car			
2006-2010			
OE Sensor: Ford Motor Company - 6F2Z1A189A			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28385	27	3
Sensor Clip	22100		
Sensor Cradle	22101		
Universal Band	22102		
2011			
OE Sensor: Ford Motor Company - 9L3Z1A189A			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20315	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Zephyr			
2006			
OE Sensor: Ford Motor Company - 6F2Z1A189A			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28385	27	3
Sensor Clip	22100		
Sensor Cradle	22101		
Universal Band	22102		

A-Programming Tool Required B-Magnet may be Required to Activate Sensor C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Lotus			
Elise			
2008-2015			
OE Sensor: Original Equipment Manufacturer - 12825085, 13227143			
Sensor	20159	88	10
Service Pack	20009	88	10
Evora			
2010-2013			
OE Sensor: Original Equipment Manufacturer - 12825085, 13227143			
Sensor	20159	88	10
Service Pack	20009	88	10
2014			
Service Pack	20009	88	10
2015			
OE Sensor: Original Equipment Manufacturer - 12825085			
Sensor	20159	88	10
Service Pack	20009	88	10
Exige			
2008-2015			
OE Sensor: Original Equipment Manufacturer - 12825085, 13227143			
Sensor	20159	88	10
Service Pack	20009	88	10
Maserati			
Coupe			
2004-2006			
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
Ghibli			
2014-2016			
OE Sensor: Original Equipment Manufacturer - 670002790			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20284	71	8
Service Pack	20047	71	8
GranTurismo			
2014			
OE Sensor: Original Equipment Manufacturer - 282189			
Sensor; Does Not Include Valve	20078	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
2015			
OE Sensor: Original Equipment Manufacturer - 282189			
Sensor; Includes Transmitter Only	20078	35	4

Application	Part No.	Torque in-lbs	Torque N.m.
Maserati (cont'd)			
Quattroporte			
2004-2008			
OE Sensor: Chrysler - 185189			
EZ-Sensor	33100 A	11.5	1.3
	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Includes Transmitter Only	20077	35	4
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
2014-2016			
OE Sensor: Original Equipment Manufacturer - 670002790			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20284	71	8
Service Pack	20047	71	8
Spyder			
2004-2006			
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
Maybach			
57,62			
2002			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
2003-2011			
OE Sensor: Volkswagen - 4D0907275D			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Includes Transmitter Only	20079	35	4
2012			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Mazda			
2			
2011-2013			
OE Sensor: Mazda - BBM237140B, GN3A37140B			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20093	71	8

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Mazda (cont'd)			
3			
2004			
OE Sensor: Mazda - GN3A37140B			
Sensor	20093	71	8
2005-2012			
OE Sensor: Mazda - GN3A37140B			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20093	71	8
2013			
OE Sensor: Mazda - BBM2-37-140B			
Sensor	20093	71	8
2014-2015			
Sensor	INDIRECT D		
5			
2006-2010			
OE Sensor: Mazda - GN3A37140B			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20093	71	8
2011			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
2012-2013			
OE Sensor: Mazda - BBM2-37-140B, GN3A37140B			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20093	71	8
2014-2015			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
6			
2005-2007			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
2008-2013			
OE Sensor: Mazda - BBM2-37-140B, GN3A37140B			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20093	71	8
2014-2016			
Sensor	INDIRECT D		

Application	Part No.	Torque in-lbs	Torque N.m.
Mazda (cont'd)			
B2300			
2007-2009			
OE Sensor: Ford Motor Company - 6F2Z1A189A; Mazda - 6F2Z1A189A			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28385	27	3
Sensor Clip	22100		
Sensor Cradle	22101		
Universal Band	22102		
B3000			
2007-2008			
OE Sensor: Mazda - 6F2Z1A189A			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28385	27	3
Sensor Clip	22100		
Sensor Cradle	22101		
Universal Band	22102		
B4000			
2007-2009			
OE Sensor: Ford Motor Company - ZZDA-37-140; Mazda - 6F2Z1A189A			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28385	27	3
Sensor Clip	22100		
Sensor Cradle	22101		
Universal Band	22102		
CX-5			
2013-2016			
Sensor	INDIRECT D		
CX-7			
2007-2011			
OE Sensor: Mazda - GN3A37140B			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20093	71	8
2012			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
CX-9			
2007-2012			
OE Sensor: Mazda - GN3A37140B			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20093	71	8

A-Programming Tool Required C-20018 and 20008 are interchangeable. D-Indirect TPMS system. No sensor in wheel DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Mazda (cont'd)			
CX-9 (cont'd)			
2013			
OE Sensor: Mazda - BBM2-37-140B			
Sensor	20093	71	8
MX-5 Miata			
2006-2015			
OE Sensor: Mazda - GN3A37140B, GS1D37140			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20093	71	8
2016			
Sensor	INDIRECT D		
RX-8			
2004			
OE Sensor: Mazda - GN3A37140B			
Sensor	20093	71	8
2005-2011			
OE Sensor: Mazda - GN3A37140B			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20093	71	8
Tribute			
2006			
OE Sensor: Mazda - ZZC137140			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28385	27	3
Sensor Clip	22100		
Sensor Cradle	22101		
Universal Band	22102		
2008			
OE Sensor: Mazda - ZZC137140			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28385	27	3
Sensor Clip	22100		
Sensor Cradle	22101		
Universal Band	22102		
2009-2011			
OE Sensor: Mazda - ZZDA37140			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20315	11.5	1.3
Service Pack; Rubber Valve	20018 C	11.5	1.3

Application	Part No.	Torque in-lbs	Torque N.m.
Mercedes-Benz			
550,63AMG			
2006			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
2007-2009			
OE Sensor: Mercedes-Benz - 0025409017			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Does Not Include Stem	20016	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
B200			
2014			
OE Sensor: Mercedes-Benz - A0009050030			
Sensor	20213	80	9
Service Pack	20049	80	9
2015-2016			
OE Sensor: Mercedes-Benz - A0009050030			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20213	80	9
Service Pack	20049	80	9
2017			
OE Sensor: Mercedes-Benz - A0009050030			
Sensor	20213	80	9
Service Pack	20049	80	9
B250			
2015			
OE Sensor: Mercedes-Benz - A0009050030			
Sensor	20213	80	9
Service Pack	20049	80	9
2016			
OE Sensor: Mercedes-Benz - A0009050030			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20213	80	9
Service Pack	20049	80	9
2017			
OE Sensor: Mercedes-Benz - A0009050030			
Sensor	20213	80	9
Service Pack	20049	80	9

A-Programming Tool Required C-20018 and 20008 are interchangeable. D-Indirect TPMS system. No sensor in wheel DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Mercedes-Benz (cont'd)			
C Series			
2000			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor; Programmable Sensor. Programming tool required.	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
	20018 C	11.5	1.3
2001-2006			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor; Programmable Sensor. Programming tool required.	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluiminum valve.	34000	62	7
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
	20018 C	11.5	1.3
Service Pack; Does Not Include Valve.	20023	35	4
Service Pack; W/43mm Silver Insert.	20037	35	4
Service Pack; W/48mm Green Insert.	20038	35	4
Service Pack; W/49mm Black Insert.	20039	35	4
Service Pack; W/51mm Orange Insert.	20040	35	4
2007			
OE Sensor: Mercedes-Benz - 0025406817, 0025409017			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
Sensor	20094	53	6
Sensor; Jun. & Newer.	28214	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only.	20020	58	6.5
Service Pack; Includes Valve.	20036	53	6
Service Pack; Jun. & Newer; Does Not Include Stem.	20016	58	6.5
2008-2009			
OE Sensor: Mercedes-Benz - 0025406817, 0025407917, 0025409017			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
Sensor	20094	53	6
	28214	58	6.5
Service Pack; Does Not Include Stem.	20016	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only.	20020	58	6.5
Service Pack; Includes Valve.	20036	53	6
2010-2012			
OE Sensor: Mercedes-Benz - 0009054100, 0035400217			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Does Not Include Stem.	20016	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only.	20020	58	6.5

Application	Part No.	Torque in-lbs	Torque N.m.
Mercedes-Benz (cont'd)			
C Series (cont'd)			
2013			
OE Sensor: Mercedes-Benz - 0009057200			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only.	20020	58	6.5
Service Pack; W/O Valve.	20016	58	6.5
2014-2015			
OE Sensor: Mercedes-Benz - A0009050030			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
Sensor	20213	80	9
Service Pack.	20049	80	9
2016-2017			
OE Sensor: Mercedes-Benz - A0009050030			
Sensor	20213	80	9
Service Pack.	20049	80	9
C250			
2012			
OE Sensor: Mercedes-Benz - 0009054100			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Does Not Include Stem.	20016	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only.	20020	58	6.5
2013			
OE Sensor: Mercedes-Benz - 0009057200			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only.	20020	58	6.5
Service Pack; W/O Valve.	20016	58	6.5
2014-2017			
OE Sensor: Mercedes-Benz - A0009050030			
Sensor	20213	80	9
Service Pack.	20049	80	9
C280			
2007			
OE Sensor: Mercedes-Benz - 0025408617			
Sensor; Mar. & Newer.	28214	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only.	20020	58	6.5
Service Pack; Mar. & Newer; Does Not Include Stem.	20016	58	6.5

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Mercedes-Benz (cont'd)			
CL			
2000-2006			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
2008-2009			
OE Sensor: Mercedes-Benz - 0025407917			
Sensor	20094	53	6
Service Pack; Includes Valve	20036	53	6
2010-2012			
EZ-Sensor	33000 [A]	11.5	1.3
	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2013-2015			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
CLA250			
2014-2016			
OE Sensor: Mercedes-Benz - A0009050030			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20213	80	9
Service Pack	20049	80	9
2017			
OE Sensor: Mercedes-Benz - A0009050030			
Sensor	20213	80	9
Service Pack	20049	80	9
CLA45 AMG			
2014-2016			
OE Sensor: Mercedes-Benz - A0009050030			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20213	80	9
Service Pack	20049	80	9
2017			
OE Sensor: Mercedes-Benz - A0009050030			
Sensor	20213	80	9
Service Pack	20049	80	9

Application	Part No.	Torque in-lbs	Torque N.m.
Mercedes-Benz (cont'd)			
CLK			
2006			
OE Sensor: Mercedes-Benz - 0025409017			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Does Not Include Stem	20016	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
2007-2009			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
CLK350			
2006-2009			
OE Sensor: Mercedes-Benz - 0025409017			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Does Not Include Stem	20016	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
CLS			
2006			
OE Sensor: Mercedes-Benz - 0025407917			
Sensor	20094	53	6
Service Pack; Includes Valve	20036	53	6
CLS550			
2007-2011			
OE Sensor: Mercedes-Benz - 0025407917			
Sensor	20094	53	6
Service Pack; Includes Valve	20036	53	6
2012			
OE Sensor: Mercedes-Benz - 0009054100			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Does Not Include Stem	20016	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
2013			
OE Sensor: Mercedes-Benz - 0009057200			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; W/O Valve	20016	58	6.5

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Mercedes-Benz (cont'd)			
CLS550 (cont'd)			
2014-2016			
OE Sensor: Mercedes-Benz - A0009050030			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20213	80	9
Service Pack	20049	80	9
CLS63 AMG S			
2014-2016			
OE Sensor: Mercedes-Benz - A0009050030			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20213	80	9
Service Pack	20049	80	9
E250			
2014-2016			
OE Sensor: Mercedes-Benz - A0009050030			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20213	80	9
Service Pack	20049	80	9
2017			
OE Sensor: Mercedes-Benz - A0009050030			
Sensor	20213	80	9
Service Pack	20049	80	9
E320			
2001-2005			
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
2006-2009			
OE Sensor: Mercedes-Benz - 0025406817, 0025407917			
Sensor	20094	53	6
Service Pack; Includes Valve	20036	53	6
E350			
2006-2009			
OE Sensor: Mercedes-Benz - 0025406817, 0025407917, 0025408017			
Sensor; W/315 MHz Sensor	20094	53	6
Sensor; W/433 MHz Sensor	20095	53	6
Service Pack; Includes Valve	20036	53	6

Application	Part No.	Torque in-lbs	Torque N.m.
Mercedes-Benz (cont'd)			
E350 (cont'd)			
2010-2012			
OE Sensor: Mercedes-Benz - 0009054100, 0035400217			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Does Not Include Stem	20016	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
2013			
OE Sensor: Mercedes-Benz - 0009057200			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; W/O Valve	20016	58	6.5
2014-2016			
OE Sensor: Mercedes-Benz - A0009050030			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20213	80	9
Service Pack	20049	80	9
2017			
OE Sensor: Mercedes-Benz - A0009050030			
Sensor	20213	80	9
Service Pack	20049	80	9
E400			
2010-2013			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2014-2016			
OE Sensor: Mercedes-Benz - A0009050030			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20213	80	9
Service Pack	20049	80	9
2017			
OE Sensor: Mercedes-Benz - A0009050030			
Sensor	20213	80	9
Service Pack	20049	80	9

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Mercedes-Benz (cont'd)			
E430			
2001-2002			
Service Pack; Does Not Include Valve.	20023	35	4
Service Pack; W/43mm Silver Insert.	20037	35	4
Service Pack; W/48mm Green Insert.	20038	35	4
Service Pack; W/49mm Black Insert.	20039	35	4
Service Pack; W/51mm Orange Insert.	20040	35	4
E500			
2003-2005			
Service Pack; Does Not Include Valve.	20023	35	4
Service Pack; W/43mm Silver Insert.	20037	35	4
Service Pack; W/48mm Green Insert.	20038	35	4
Service Pack; W/49mm Black Insert.	20039	35	4
Service Pack; W/51mm Orange Insert.	20040	35	4
2006			
OE Sensor: Mercedes-Benz - 0025406817 Sensor.	20094	53	6
Service Pack; Includes Valve.	20036	53	6
E55 AMG			
1999			
Service Pack; Does Not Include Valve; Jul. & Newer.	20023	35	4
Service Pack; W/43mm Silver Insert.	20037	35	4
Service Pack; W/48mm Green Insert; Jul. & Newer.	20038	35	4
Service Pack; W/49mm Black Insert; Jul. & Newer.	20039	35	4
Service Pack; W/51mm Orange Insert; Jul. & Newer.	20040	35	4
2000-2005			
Service Pack; Does Not Include Valve.	20023	35	4
Service Pack; W/43mm Silver Insert.	20037	35	4
Service Pack; W/48mm Green Insert.	20038	35	4
Service Pack; W/49mm Black Insert.	20039	35	4
Service Pack; W/51mm Orange Insert.	20040	35	4
2006			
OE Sensor: Mercedes-Benz - 0025406817 Sensor.	20094	53	6
Service Pack; Includes Valve.	20036	53	6
E550			
2007-2009			
OE Sensor: Mercedes-Benz - 0025407917, 0025408017 Sensor; W/315 MHz Sensor.	20094	53	6
Sensor; W/433 MHz Sensor.	20095	53	6
Service Pack; Includes Valve.	20036	53	6
2010-2011			
OE Sensor: Mercedes-Benz - 0009054100, 0035400217 EZ-Sensor.	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 [C]	11.5	1.3
Sensor.	28214	58	6.5
Service Pack; Does Not Include Stem.	20016	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only.	20020	58	6.5

Application	Part No.	Torque in-lbs	Torque N.m.
Mercedes-Benz (cont'd)			
E550 (cont'd)			
2012-2013			
OE Sensor: Mercedes-Benz - 0009054100, 0009057200 EZ-Sensor.	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 [C]	11.5	1.3
Sensor.	28214	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only.	20020	58	6.5
Service Pack; W/O Valve.	20016	58	6.5
2014-2016			
OE Sensor: Mercedes-Benz - A0009050030 EZ-Sensor.	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 [C]	11.5	1.3
Sensor.	20213	80	9
Service Pack.	20049	80	9
2017			
OE Sensor: Mercedes-Benz - A0009050030 Sensor.	20213	80	9
Service Pack.	20049	80	9
E63 AMG			
2007-2009			
OE Sensor: Mercedes-Benz - 0025406817, 0025407917 Sensor.	20094	53	6
Service Pack; Includes Valve.	20036	53	6
2010-2011			
OE Sensor: Mercedes-Benz - 0009054100, 0035400217 EZ-Sensor.	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 [C]	11.5	1.3
Sensor.	28214	58	6.5
Service Pack; Does Not Include Stem.	20016	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only.	20020	58	6.5
2012-2013			
OE Sensor: Mercedes-Benz - 0009054100, 0009057200 EZ-Sensor.	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 [C]	11.5	1.3
Sensor.	28214	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only.	20020	58	6.5
Service Pack; W/O Valve.	20016	58	6.5
2014-2016			
OE Sensor: Mercedes-Benz - A0009050030 EZ-Sensor.	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 [C]	11.5	1.3
Sensor.	20213	80	9
Service Pack.	20049	80	9

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Mercedes-Benz (cont'd)			
E63 AMG (cont'd)			
2017			
OE Sensor: Mercedes-Benz - A0009050030			
Sensor	20213	80	9
Service Pack	20049	80	9
E63 AMG S			
2010-2013			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
2014-2016			
OE Sensor: Mercedes-Benz - A0009050030			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20213	80	9
Service Pack	20049	80	9
2017			
OE Sensor: Mercedes-Benz - A0009050030			
Sensor	20213	80	9
Service Pack	20049	80	9
G500			
2007			
OE Sensor: Mercedes-Benz - 0025408617			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Mar. & Newer	28214	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Mar. & Newer; Does Not Include Stem	20016	58	6.5
2008			
OE Sensor: Mercedes-Benz - 0025409017			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Does Not Include Stem	20016	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
G55 AMG			
2007			
OE Sensor: Mercedes-Benz - 0025408617			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Mar. & Newer	28214	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Mar. & Newer; Does Not Include Stem	20016	58	6.5

Application	Part No.	Torque in-lbs	Torque N.m.
Mercedes-Benz (cont'd)			
G55 AMG (cont'd)			
2008-2010			
OE Sensor: Mercedes-Benz - 0025409017			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Does Not Include Stem	20016	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
2011			
OE Sensor: Mercedes-Benz - 0025409017			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Mar. & Newer; Does Not Include Stem	20016	58	6.5
G550			
2009-2010			
OE Sensor: Mercedes-Benz - 0025409017			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Does Not Include Stem	20016	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
2011			
OE Sensor: Mercedes-Benz - 0025409017			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Mar. & Newer; Does Not Include Stem	20016	58	6.5
2012-2013			
OE Sensor: Mercedes-Benz - 0009057200, 0025409017			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; W/O Valve	20016	58	6.5

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Mercedes-Benz (cont'd)			
G550 (cont'd)			
2014-2016			
OE Sensor: Mercedes-Benz - A0009050030			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20213	80	9
Service Pack	20049	80	9
2017			
OE Sensor: Mercedes-Benz - A0009050030			
Sensor	20213	80	9
Service Pack	20049	80	9
G63 AMG			
2014-2016			
OE Sensor: Mercedes-Benz - A0009050030			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20213	80	9
Service Pack	20049	80	9
2017			
OE Sensor: Mercedes-Benz - A0009050030			
Sensor	20213	80	9
Service Pack	20049	80	9
GL			
2007-2009			
OE Sensor: Mercedes-Benz - 0025408017			
Sensor	20095	53	6
Service Pack; Includes Valve	20036	53	6
2010			
OE Sensor: Mercedes-Benz - 0035400217			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Does Not Include Stem	20016	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
2011			
OE Sensor: Mercedes-Benz - 0009054100			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Mar. & Newer; Does Not Include Stem	20016	58	6.5

Application	Part No.	Torque in-lbs	Torque N.m.
Mercedes-Benz (cont'd)			
GL (cont'd)			
2012-2013			
OE Sensor: Mercedes-Benz - 0009054100, 0009057200			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; W/O Valve	20016	58	6.5
2014-2016			
OE Sensor: Mercedes-Benz - A0009050030			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20213	80	9
Service Pack	20049	80	9
2017			
OE Sensor: Mercedes-Benz - A0009050030			
Sensor	20213	80	9
Service Pack	20049	80	9
GL320			
2007-2009			
OE Sensor: Mercedes-Benz - 0025408017			
Sensor	20095	53	6
Service Pack; Includes Valve	20036	53	6
GL350			
2010			
OE Sensor: Mercedes-Benz - 0035400217			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Does Not Include Stem	20016	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
2011			
OE Sensor: Mercedes-Benz - 0009054100			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Mar. & Newer; Does Not Include Stem	20016	58	6.5

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Mercedes-Benz (cont'd)			
GL350 (cont'd)			
2012-2013			
OE Sensor: Mercedes-Benz - 0009054100, 0009057200			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; W/O Valve	20016	58	6.5
2014-2015			
OE Sensor: Mercedes-Benz - A0009050030			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20213	80	9
Service Pack	20049	80	9
2016			
OE Sensor: Mercedes-Benz - A0009050030			
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20213	80	9
Service Pack	20049	80	9
2017			
Service Pack	20049	80	9
GL63 AMG			
2013			
OE Sensor: Mercedes-Benz - 0009057200			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; W/O Valve	20016	58	6.5
2014-2016			
OE Sensor: Mercedes-Benz - A0009050030			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20213	80	9
Service Pack	20049	80	9
2017			
OE Sensor: Mercedes-Benz - A0009050030			
Sensor	20213	80	9
Service Pack	20049	80	9

Application	Part No.	Torque in-lbs	Torque N.m.
Mercedes-Benz (cont'd)			
GLK250			
2014-2016			
OE Sensor: Mercedes-Benz - A0009050030			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20213	80	9
Service Pack	20049	80	9
2017			
OE Sensor: Mercedes-Benz - A0009050030			
Sensor	20213	80	9
Service Pack	20049	80	9
GLK350			
2010			
OE Sensor: Mercedes-Benz - 0035400217			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Does Not Include Stem	20016	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
2011			
OE Sensor: Mercedes-Benz - 0009054100			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Mar. & Newer; Does Not Include Stem	20016	58	6.5
2012			
OE Sensor: Mercedes-Benz - 0009054100			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Does Not Include Stem	20016	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
2013			
OE Sensor: Mercedes-Benz - 0009057200			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; W/O Valve	20016	58	6.5

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Mercedes-Benz (cont'd)			
GLK350 (cont'd)			
2014-2016			
OE Sensor: Mercedes-Benz - A0009050030			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20213	80	9
Service Pack	20049	80	9
2017			
OE Sensor: Mercedes-Benz - A0009050030			
Sensor	20213	80	9
Service Pack	20049	80	9
ML320			
2007-2009			
OE Sensor: Mercedes-Benz - 0025406917, 0025408017			
Sensor	20095	53	6
Service Pack; Includes Valve	20036	53	6
ML350			
2006-2009			
OE Sensor: Mercedes-Benz - 0025406917, 0025408017			
Sensor	20095	53	6
Service Pack; Includes Valve	20036	53	6
2010			
OE Sensor: Mercedes-Benz - 0035400217			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Does Not Include Stem	20016	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
2011			
OE Sensor: Mercedes-Benz - 0009054100			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Mar. & Newer; Does Not Include Stem	20016	58	6.5
2012			
OE Sensor: Mercedes-Benz - 0009054100			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Does Not Include Stem	20016	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5

Application	Part No.	Torque in-lbs	Torque N.m.
Mercedes-Benz (cont'd)			
ML350 (cont'd)			
2013			
OE Sensor: Mercedes-Benz - 0009057200			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; W/O Valve	20016	58	6.5
2014			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2015			
OE Sensor: Mercedes-Benz - 000 905 00 30			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20213	80	9
Service Pack	20049	80	9
2016			
OE Sensor: Mercedes-Benz - A0009050030			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20213	80	9
Service Pack	20049	80	9
2017			
OE Sensor: Mercedes-Benz - A0009050030			
Sensor	20213	80	9
Service Pack	20049	80	9
ML450			
2010			
OE Sensor: Mercedes-Benz - 0035400217			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Does Not Include Stem	20016	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
2011			
OE Sensor: Mercedes-Benz - 0009054100			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Mar. & Newer; Does Not Include Stem	20016	58	6.5

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Mercedes-Benz (cont'd)			
ML500			
2006-2007			
OE Sensor: Mercedes-Benz - 0025406917			
Sensor	20095	53	6
Service Pack; Includes Valve	20036	53	6
ML550			
2008-2009			
OE Sensor: Mercedes-Benz - 0025406917, 0025408017			
Sensor	20095	53	6
Service Pack; Includes Valve	20036	53	6
2010			
OE Sensor: Mercedes-Benz - 0035400217			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Does Not Include Stem	20016	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
2011-2012			
OE Sensor: Mercedes-Benz - 0009054100			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Mar. & Newer; Does Not Include Stem	20016	58	6.5
2013-2014			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
2015-2016			
OE Sensor: Mercedes-Benz - A0009050030			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20213	80	9
Service Pack	20049	80	9
2017			
OE Sensor: Mercedes-Benz - A0009050030			
Sensor	20213	80	9
Service Pack	20049	80	9
ML63 AMG			
2007-2009			
OE Sensor: Mercedes-Benz - 0025406917, 0025408017			
Sensor	20095	53	6
Service Pack; Includes Valve	20036	53	6

Application	Part No.	Torque in-lbs	Torque N.m.
Mercedes-Benz (cont'd)			
ML63 AMG (cont'd)			
2010			
OE Sensor: Mercedes-Benz - 0035400217			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Does Not Include Stem	20016	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
2011			
OE Sensor: Mercedes-Benz - 0009054100			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Mar. & Newer; Does Not Include Stem	20016	58	6.5
2012-2013			
OE Sensor: Mercedes-Benz - 0009054100, 0009057200			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; W/O Valve	20016	58	6.5
2014-2016			
OE Sensor: Mercedes-Benz - A0009050030			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20213	80	9
Service Pack	20049	80	9
2017			
OE Sensor: Mercedes-Benz - A0009050030			
Sensor	20213	80	9
Service Pack	20049	80	9
R320			
2007-2009			
OE Sensor: Mercedes-Benz - 0025406917, 0025408017			
Sensor	20095	53	6
Service Pack; Includes Valve	20036	53	6
R350			
2006-2009			
OE Sensor: Mercedes-Benz - 0025406917, 0025408017			
Sensor	20095	53	6
Service Pack; Includes Valve	20036	53	6

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Mercedes-Benz (cont'd)			
R350 (cont'd)			
2010			
OE Sensor: Mercedes-Benz - 0035400217			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Does Not Include Stem	20016	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
2011			
OE Sensor: Mercedes-Benz - 0009054100			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; Mar. & Newer; Does Not Include Stem	20016	58	6.5
2012			
OE Sensor: Mercedes-Benz - 0009054100			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Does Not Include Stem	20016	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
2013			
OE Sensor: Mercedes-Benz - 0009057200			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; W/O Valve	20016	58	6.5
R500			
2006-2007			
OE Sensor: Mercedes-Benz - 0025406917			
Sensor	20095	53	6
Service Pack; Includes Valve	20036	53	6
R63 AMG			
2007			
OE Sensor: Mercedes-Benz - 0025406917			
Sensor	20095	53	6
Service Pack; Includes Valve	20036	53	6

Application	Part No.	Torque in-lbs	Torque N.m.
Mercedes-Benz (cont'd)			
S Series			
2006			
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
2010			
OE Sensor: Mercedes-Benz - 0025407917			
Sensor	20094	53	6
Service Pack; Includes Valve	20036	53	6
2011			
OE Sensor: Mercedes-Benz - 0009054100			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Does Not Include Stem	20016	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
2012			
OE Sensor: Mercedes-Benz - 0009054100			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; W/O Valve	20016	58	6.5
2013			
OE Sensor: Mercedes-Benz - 0009057200, A0009050030			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20213	80	9
	28214	58	6.5
Service Pack	20049	80	9
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; W/O Valve	20016	58	6.5
2014-2016			
OE Sensor: Mercedes-Benz - A0009050030			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20213	80	9
Service Pack	20049	80	9
2017			
OE Sensor: Mercedes-Benz - A0009050030			
Sensor	20213	80	9
Service Pack	20049	80	9

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Mercedes-Benz (cont'd)			
S430			
2000-2006			
EZ-Sensor	33000 [A]	11.5	1.3
	33100 [A]	11.5	1.3
	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
S500			
2000			
OE Sensor: Mercedes-Benz - 0008223406			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Includes Transmitter Only	20079	35	4
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
2001			
OE Sensor: Mercedes-Benz - 0008223406			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor; Programmable sensor, Rubber Valve	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Includes Transmitter Only	20079	35	4
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
2002-2006			
OE Sensor: Mercedes-Benz - 0008223406			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Includes Transmitter Only	20079	35	4
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4

Application	Part No.	Torque in-lbs	Torque N.m.
Mercedes-Benz (cont'd)			
S55 AMG			
2001-2006			
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
S550			
2007-2010			
OE Sensor: Mercedes-Benz - 0025406817, 0025407917			
Sensor	20094	53	6
Service Pack; Includes Valve	20036	53	6
2011			
OE Sensor: Mercedes-Benz - 0009054100			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Does Not Include Stem	20016	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
2012-2013			
OE Sensor: Mercedes-Benz - 0009054100, 0009057200			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; W/O Valve	20016	58	6.5
2014-2016			
OE Sensor: Mercedes-Benz - A0009050030			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20213	80	9
Service Pack	20049	80	9
2017			
OE Sensor: Mercedes-Benz - A0009050030			
Sensor	20213	80	9
Service Pack	20049	80	9
S600			
2001-2006			
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
2007-2010			
OE Sensor: Mercedes-Benz - 0025406817, 0025407917			
Sensor	20094	53	6
Service Pack; Includes Valve	20036	53	6

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Mercedes-Benz (cont'd)			
S600 (cont'd)			
2011			
OE Sensor: Mercedes-Benz - 0009054100			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Does Not Include Stem	20016	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
2012-2013			
OE Sensor: Mercedes-Benz - 0009054100, 0009057200			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; W/O Valve	20016	58	6.5
2014-2016			
OE Sensor: Mercedes-Benz - A0009050030			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20213	80	9
Service Pack	20049	80	9
2017			
OE Sensor: Mercedes-Benz - A0009050030			
Sensor	20213	80	9
Service Pack	20049	80	9
S63 AMG			
2008-2010			
OE Sensor: Mercedes-Benz - 0025406817, 0025407917			
Sensor	20094	53	6
Service Pack; Includes Valve	20036	53	6
2011			
OE Sensor: Mercedes-Benz - 0009054100			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Does Not Include Stem	20016	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
2012-2013			
OE Sensor: Mercedes-Benz - 0009054100, 0009057200			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; W/O Valve	20016	58	6.5

Application	Part No.	Torque in-lbs	Torque N.m.
Mercedes-Benz (cont'd)			
S63 AMG (cont'd)			
2014-2016			
OE Sensor: Mercedes-Benz - A0009050030			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20213	80	9
Service Pack	20049	80	9
2017			
OE Sensor: Mercedes-Benz - A0009050030			
Sensor	20213	80	9
Service Pack	20049	80	9
S65 AMG			
2006			
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
2007-2010			
OE Sensor: Mercedes-Benz - 0025406817, 0025407917			
Sensor	20094	53	6
Service Pack; Includes Valve	20036	53	6
2011			
OE Sensor: Mercedes-Benz - 0009054100			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Does Not Include Stem	20016	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
2012-2013			
OE Sensor: Mercedes-Benz - 0009054100, 0009057200			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; W/O Valve	20016	58	6.5
SL500			
2000-2005			
EZ-Sensor; Programmable sensor, Rubber Valve	33500 [A, DB]	11.5	1.3
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
2006			
OE Sensor: Mercedes-Benz - 0025406817			
Sensor	20094	53	6
Service Pack; Includes Valve	20036	53	6

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Mercedes-Benz (cont'd)			
SL55 AMG			
2003			
EZ-Sensor; Programmable sensor, Rubber Valve.	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminum valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
Service Pack; Does Not Include Valve.	20023	35	4
Service Pack; W/43mm Silver Insert.	20037	35	4
Service Pack; W/48mm Green Insert.	20038	35	4
Service Pack; W/49mm Black Insert.	20039	35	4
Service Pack; W/51mm Orange Insert.	20040	35	4
2004			
EZ-Sensor; Programmable sensor, Rubber Valve.	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminum valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
Service Pack; W/43mm Silver Insert.	20037	35	4
Service Pack; W/48mm Green Insert.	20038	35	4
Service Pack; W/49mm Black Insert.	20039	35	4
Service Pack; W/51mm Orange Insert.	20040	35	4
2005			
EZ-Sensor; Programmable sensor, Rubber Valve.	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminum valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
Service Pack; Does Not Include Valve.	20023	35	4
Service Pack; W/43mm Silver Insert.	20037	35	4
Service Pack; W/48mm Green Insert.	20038	35	4
Service Pack; W/49mm Black Insert.	20039	35	4
Service Pack; W/51mm Orange Insert.	20040	35	4
2006-2008			
OE Sensor: Mercedes-Benz - 002 540 6817			
Sensor.	20094	53	6
Service Pack; Includes Valve.	20036	53	6
SL550			
2007-2009			
OE Sensor: Mercedes-Benz - 0025406817			
Sensor.	20094	53	6
Service Pack; Includes Valve.	20036	53	6
2012			
OE Sensor: Mercedes-Benz - 0009054100			
EZ-Sensor.	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
Sensor.	28214	58	6.5
Service Pack; Does Not Include Stem.	20016	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only.	20020	58	6.5
2013			
OE Sensor: Mercedes-Benz - 0009057200			
EZ-Sensor.	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
Sensor.	28214	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only.	20020	58	6.5
Service Pack; W/O Valve.	20016	58	6.5

Application	Part No.	Torque in-lbs	Torque N.m.
Mercedes-Benz (cont'd)			
SL550 (cont'd)			
2014-2016			
OE Sensor: Mercedes-Benz - A0009050030			
EZ-Sensor.	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
Sensor.	20213	80	9
Service Pack.	20049	80	9
SL600			
2000			
EZ-Sensor; Programmable sensor, Rubber Valve.	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminum valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
2001-2002			
EZ-Sensor; Programmable sensor, Rubber Valve.	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminum valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
Service Pack; Does Not Include Valve.	20023	35	4
Service Pack; W/43mm Silver Insert.	20037	35	4
Service Pack; W/48mm Green Insert.	20038	35	4
Service Pack; W/49mm Black Insert.	20039	35	4
Service Pack; W/51mm Orange Insert.	20040	35	4
2003			
EZ-Sensor; Programmable sensor, Rubber Valve.	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminum valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
2004-2005			
EZ-Sensor; Programmable sensor, Rubber Valve.	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminum valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
Service Pack; Does Not Include Valve.	20023	35	4
Service Pack; W/43mm Silver Insert.	20037	35	4
Service Pack; W/48mm Green Insert.	20038	35	4
Service Pack; W/49mm Black Insert.	20039	35	4
Service Pack; W/51mm Orange Insert.	20040	35	4
2006-2009			
OE Sensor: Mercedes-Benz - 0025406817			
Sensor.	20094	53	6
Service Pack; Includes Valve.	20036	53	6
SL63 AMG			
2009			
OE Sensor: Mercedes-Benz - 0025406817			
Sensor.	20094	53	6
Service Pack; Includes Valve.	20036	53	6
2011			
OE Sensor: Mercedes-Benz - 0025407917			
Sensor.	20094	53	6

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Mercedes-Benz (cont'd)			
SL63 AMG (cont'd)			
2012			
OE Sensor: Mercedes-Benz - 0009054100			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Does Not Include Stem	20016	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
2013			
OE Sensor: Mercedes-Benz - 0009057200			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; W/O Valve	20016	58	6.5
2014-2015			
OE Sensor: Mercedes-Benz - A0009050030			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20213	80	9
Service Pack	20049	80	9
2016			
OE Sensor: Mercedes-Benz - A0009050030			
EZ-Sensor	33200 A	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20213	80	9
Service Pack	20049	80	9
SL65 AMG			
2005			
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
2006-2009			
OE Sensor: Mercedes-Benz - 0025406817			
Sensor	20094	53	6
Service Pack; Includes Valve	20036	53	6
2011			
OE Sensor: Mercedes-Benz - 0025407917			
Sensor	20094	53	6
2014-2016			
OE Sensor: Mercedes-Benz - A0009050030			
Sensor	20213	80	9
Service Pack	20049	80	9

Application	Part No.	Torque in-lbs	Torque N.m.
Mercedes-Benz (cont'd)			
SLK250			
2012			
OE Sensor: Mercedes-Benz - 0009054100			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Does Not Include Stem	20016	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
2013			
OE Sensor: Mercedes-Benz - 0009057200			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; W/O Valve	20016	58	6.5
2014-2016			
OE Sensor: Mercedes-Benz - A0009050030			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20213	80	9
Service Pack	20049	80	9
2017			
OE Sensor: Mercedes-Benz - A0009050030			
Sensor	20213	80	9
Service Pack	20049	80	9
SLK280			
2007			
OE Sensor: Mercedes-Benz - 0045421518			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; May & Newer	28214	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; May & Newer; Does Not Include Stem	20016	58	6.5
2008			
OE Sensor: Mercedes-Benz - 0025409017			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Does Not Include Stem	20016	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Mercedes-Benz (cont'd)			
SLK300			
2009-2011			
OE Sensor: Mercedes-Benz - 0025409017, 0035400217			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Does Not Include Stem	20016	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
SLK350			
2007			
OE Sensor: Mercedes-Benz - 0045421518			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; May & Newer	28214	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; May & Newer; Does Not Include Stem	20016	58	6.5
2008-2012			
OE Sensor: Mercedes-Benz - 0009054100, 0025409017, 0035400217			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Does Not Include Stem	20016	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
2013			
OE Sensor: Mercedes-Benz - 0009057200			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; W/O Valve	20016	58	6.5
2014-2016			
OE Sensor: Mercedes-Benz - A0009050030			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20213	80	9
Service Pack	20049	80	9
2017			
OE Sensor: Mercedes-Benz - A0009050030			
Sensor	20213	80	9
Service Pack	20049	80	9

Application	Part No.	Torque in-lbs	Torque N.m.
Mercedes-Benz (cont'd)			
SLK55 AMG			
2007			
OE Sensor: Mercedes-Benz - 0045421518			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; May & Newer	28214	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; May & Newer; Does Not Include Stem	20016	58	6.5
2008-2010			
OE Sensor: Mercedes-Benz - 0025409017, 0035400217			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Does Not Include Stem	20016	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
2014			
OE Sensor: Mercedes-Benz - A0009050030			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20213	80	9
Service Pack	20049	80	9
2015-2017			
OE Sensor: Mercedes-Benz - A0009050030			
Sensor	20213	80	9
Service Pack	20049	80	9
SLR McLaren			
2004-2006			
EZ-Sensor	33200 A	11.5	1.3
EZ-Sensor; Programmable sensor, Rubber Valve	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminum valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
2007			
EZ-Sensor	33200 A	11.5	1.3
EZ-Sensor; Programmable sensor, Rubber Valve	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminum valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Service Pack; Does Not Include Valve	20023	53	6
Service Pack; W/43mm Silver Insert	20037	53	6
Service Pack; W/48mm Green Insert	20038	53	6
Service Pack; W/49mm Black Insert	20039	53	6
Service Pack; W/51mm Orange Insert	20040	53	6

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Mercedes-Benz (cont'd)			
SLR McLaren (cont'd)			
2008-2009			
OE Sensor: Mercedes-Benz - 0025407917			
Sensor	20094	53	6
Service Pack; Includes Valve	20036	53	6
SLS AMG			
2011-2012			
OE Sensor: Mercedes-Benz - 0009054100			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Does Not Include Stem	20016	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
2013			
OE Sensor: Mercedes-Benz - 0009057200			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; W/O Valve	20016	58	6.5
2014-2015			
OE Sensor: Mercedes-Benz - A0009050030			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20213	80	9
Service Pack	20049	80	9
2016			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sprinter 2500			
2010			
OE Sensor: Mercedes-Benz - 68006771AA			
EZ-Sensor	33000 A		
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20089	53	6
Service Pack; Includes Valve	20036	31-40	3.5-4.5
2011-2012			
OE Sensor: Mercedes-Benz - 68006771AA			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20089	53	6
Service Pack; Includes Valve	20036	31-40	3.5-4.5

Application	Part No.	Torque in-lbs	Torque N.m.
Mercedes-Benz (cont'd)			
Sprinter 2500 (cont'd)			
2013			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
2014-2016			
OE Sensor: Mercedes-Benz - A0009050030			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20213	80	9
Service Pack; Does Not Include Stem	20016	58	6.5
2017			
OE Sensor: Mercedes-Benz - A0009050030			
Sensor	20213	80	9
Service Pack; Does Not Include Stem	20016	58	6.5
Sprinter 3500			
2010-2012			
OE Sensor: Mercedes-Benz - 68006771AA			
EZ-Sensor	33000 A	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20089	53	6
Service Pack; Includes Valve	20036	53	6
2012			
EZ-Sensor	33500 A, DB	11.5	1.3
2013			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
2014-2016			
OE Sensor: Mercedes-Benz - A0009050030			
EZ-Sensor	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20213	80	9
Service Pack; Does Not Include Stem	20016	58	6.5
2017			
OE Sensor: Mercedes-Benz - A0009050030			
Sensor	20213	80	9
Service Pack; Does Not Include Stem	20016	58	6.5

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Mercury			
Grand Marquis			
2006-2011			
OE Sensor: Ford Motor Company - 6F2Z1A189A			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28385	27	3
Sensor Clip	22100		
Sensor Cradle	22101		
Universal Band	22102		
Mariner			
2005			
OE Sensor: Ford Motor Company - 6F2Z1A189A			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Oct. 3, 2005 & Newer	28385	27	3
Sensor Clip	22100		
Sensor Cradle	22101		
Universal Band	22102		
2006-2008			
OE Sensor: Ford Motor Company - 6F2Z1A189A			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28385	27	3
Sensor Clip	22100		
Sensor Cradle	22101		
Universal Band	22102		
2009-2011			
OE Sensor: Ford Motor Company - 9L3Z1A189A			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20315	13	1.5
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Milan			
2007-2009			
OE Sensor: Ford Motor Company - 6F2Z1A189A			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28385	27	3
Sensor Clip	22100		
Sensor Cradle	22101		
Universal Band	22102		

Application	Part No.	Torque in-lbs	Torque N.m.
Mercury (cont'd)			
Milan (cont'd)			
2010-2011			
OE Sensor: Ford Motor Company - 9L3Z1A189A			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20315	13	1.5
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Montego			
2006-2007			
OE Sensor: Ford Motor Company - 7L1Z1A189A			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28390	27	3
Sensor Clip	22100		
Sensor Cradle	22101		
Universal Band	22102		
Monterey			
2004-2005			
OE Sensor: Ford Motor Company - 5L1Z 1A150 AA			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20135 [B]	44	5
Service Pack	20002	44	5
2006-2007			
OE Sensor: Ford Motor Company - 6F2Z1A189A			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28385	27	3
Sensor Clip	22100		
Sensor Cradle	22101		
Universal Band	22102		
Mountaineer			
2002-2005			
OE Sensor: Ford Motor Company - 4L2Z 1A150 BA			
EZ-Sensor	33100 [A]	11.5	1.3
	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20096 [B]	44	5
Service Pack	20002	44	5

A-Programming Tool Required B-Magnet may be Required to Activate Sensor C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Mercury (cont'd)			
Mountaineer (cont'd)			
2006-2010			
OE Sensor: Ford Motor Company - 6F2Z1A189A			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28385	27	3
Sensor Clip	22100		
Sensor Cradle	22101		
Universal Band	22102		
Sable			
2008-2009			
OE Sensor: Ford Motor Company - 7L1Z1A189A			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28390	27	3
Sensor Clip	22100		
Sensor Cradle	22101		
Universal Band	22102		
Mini			
Cooper			
2008-2009			
OE Sensor: BMW - 36236781847			
Sensor; Includes Transmitter Only	20083	35	4
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
2009			
OE Sensor: BMW - 36 10 6 790 054			
Sensor; Includes Transmitter Only	28081	40	4.5
2010-2013			
OE Sensor: BMW - 36 10 6 790 054			
Sensor; Includes Transmitter Only	28081	40	4.5
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4

Application	Part No.	Torque in-lbs	Torque N.m.
Mini (cont'd)			
Cooper (cont'd)			
2014			
OE Sensor: BMW - 36 10 6 790 054, 36 10 6 798 872			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
	20018 [C]	11.5	1.3
Sensor; Includes Transmitter Only	28126	40	4.5
Sensor; Transmiter only	28081	40	4.5
Sensor; Transmitter only	28126	40	4.5
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
2015-2016			
OE Sensor: BMW - 36 10 6 798 872			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
	20018 [C]	11.5	1.3
Sensor	28126	40	4.5
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
Mitsubishi			
Eclipse			
2006-2007			
OE Sensor: Mitsubishi - 4250A030, MN103081			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; W/Alloy Wheels	20034 [B]	45-53	5-6
Sensor; W/Steel Wheels	28129	45-53	5-6
Service Pack; W/Alloy Wheels	20003	45-53	5-6
Service Pack; W/Steel Wheels	20010	45-53	5-6
2008-2010			
OE Sensor: Mitsubishi - MN103081			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20034 [B]	45-53	5-6
Service Pack	20003	45-53	5-6
2011			
OE Sensor: Mitsubishi - 4250B877			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20034 [B]	49	5.5
Service Pack	20003	45-53	5-6

A-Programming Tool Required B-Magnet may be Required to Activate Sensor C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Mitsubishi (cont'd)			
Eclipse (cont'd)			
2012			
OE Sensor: Mitsubishi - 42508875			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; W/Steel Wheels	28129	45-53	5-6
Service Pack	20003	45-53	5-6
Endeavor			
2004-2005			
OE Sensor: Mitsubishi - MN103033			
EZ-Sensor	33100 A	11.5	1.3
	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20028 B	45-53	5-6
Service Pack	20003	45-53	5-6
2006			
OE Sensor: Mitsubishi - MN103033, MN103081			
EZ-Sensor	33100 A	11.5	1.3
	33200 A	11.5	1.3
EZ-Sensor; Sept. 1 & Newer	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Aug. & Older	20028 B	45-53	5-6
Sensor; Sept. 1 & Newer	20034 B	45-53	5-6
Service Pack	20003	45-53	5-6
2007			
OE Sensor: Mitsubishi - MN103081			
EZ-Sensor	33100 A	11.5	1.3
	33200 A	11.5	1.3
EZ-Sensor; W/315 MHz Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20034 B	45-53	5-6
Service Pack	20003	45-53	5-6
2008			
OE Sensor: Mitsubishi - MN103081			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20034 B	45-53	5-6
Service Pack	20003	45-53	5-6
2010			
OE Sensor: Mitsubishi - MN103081			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20034 B	45-53	5-6
Service Pack	20003	45-53	5-6

Application	Part No.	Torque in-lbs	Torque N.m.
Mitsubishi (cont'd)			
Endeavor (cont'd)			
2011			
OE Sensor: Mitsubishi - 4250B875, 4250B877			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; W/Alloy Wheels	20034 B	49	5.5
Sensor; W/Steel Wheels	28129	45-53	5-6
Service Pack; W/Alloy Wheels	20003	45-53	5-6
Service Pack; W/Steel Wheels	20010	45-53	5-6
2012			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Galant			
2004-2006			
OE Sensor: Mitsubishi - MN103033			
EZ-Sensor	33100 A	11.5	1.3
	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20028 B	45-53	5-6
Service Pack	20003	45-53	5-6
2007-2009			
OE Sensor: Mitsubishi - 4250A030, MN103081			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; W/Alloy Wheels	20034 B	45-53	5-6
Sensor; W/Steel Wheels	28129	45-53	5-6
Service Pack; W/Alloy Wheels	20003	45-53	5-6
Service Pack; W/Steel Wheels	20010	45-53	5-6
2010-2012			
OE Sensor: Mitsubishi - 4250B875, 4250B877			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; W/Alloy Wheels	20034 B	49	5.5
Sensor; W/Steel Wheels	28129	45-53	5-6
Service Pack; W/Alloy Wheels	20003	45-53	5-6
Service Pack; W/Steel Wheels	20010	45-53	5-6
2013			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3

A-Programming Tool Required B-Magnet may be Required to Activate Sensor C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Mitsubishi (cont'd)			
i-MiEV			
2012-2016			
OE Sensor: Mercedes-Benz - 4250B668			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28096	71	8
Service Pack	20030	71	8
2017			
OE Sensor: Mercedes-Benz - 4250B668			
Sensor	28096	71	8
Service Pack	20030	71	8
Lancer			
2008-2010			
OE Sensor: Mitsubishi - 4250A225			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor; Caution: Ez-sensor will not support (Wai) Wheel Arch Initiators	33000 A	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28096	71	8
Service Pack	20030	71	8
2011			
OE Sensor: Mitsubishi - 4250A225			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28096	71	8
Service Pack	20030	71	8
2012			
OE Sensor: Mitsubishi - 4250A225			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28096	71	8
Service Pack	20030	71	8
Service Pack; Rubber Valve	20018 C	11.5	1.3
2013-2014			
OE Sensor: Mitsubishi - 4250B8975, 4250B975			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28096	71	8
Service Pack	20030	71	8
2015-2016			
OE Sensor: Mitsubishi - 4250B8975			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28096	71	8
Service Pack	20030	71	8

Application	Part No.	Torque in-lbs	Torque N.m.
Mitsubishi (cont'd)			
Mirage			
2014			
OE Sensor: Mitsubishi - 4250B8975			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28096	71	8
Service Pack	20030	71	8
Montero			
2003-2006			
OE Sensor: Mitsubishi - MN103081			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20034 B	45-53	5-6
Service Pack	20003	45-53	5-6
Montero Sport			
2003-2004			
OE Sensor: Mitsubishi - MN103081			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20034 B	45-53	5-6
Service Pack	20003	45-53	5-6
Outlander			
2007-2010			
OE Sensor: Mitsubishi - 4250A225			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor; Caution: Ez-sensor will not support (Wai) Wheel Arch Initiators	33000 A	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28096	71	8
Service Pack	20030	71	8
2011-2015			
OE Sensor: Mitsubishi - 4250A225, 4250B8975			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28096	71	8
Service Pack	20030	71	8
2016			
OE Sensor: Mitsubishi - 4250B8975			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28096	71	8
Service Pack	20030	71	8

A-Programming Tool Required B-Magnet may be Required to Activate Sensor C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Mitsubishi (cont'd)			
Outlander Sport			
2011-2015			
OE Sensor: Mitsubishi - 4250A225, 4250B8975			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28096	71	8
Service Pack	20030	71	8
Raider			
2008-2009			
OE Sensor: Chrysler - 56029319AA, 56029319AB			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor; Caution: Ez-sensor will not support (Wai) Wheel Arch Initiators	33000 [A]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28461 [G]	11.5	1.3
Service Pack; Fits Schrader Alum stem sensor. Does not include stem.	20013	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
RVR			
2011-2014			
OE Sensor: Mitsubishi - 4250B8975			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28096	71	8
Service Pack	20030	71	8
2015			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Nissan			
350Z			
2003-2006			
OE Sensor: Nissan - 40700-CD001			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20064	49	5.5
Service Pack	20007	49	5.5
2007-2009			
OE Sensor: Nissan - 40700-JA01B, 40700-JA01C			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28204	71	8
Service Pack	20014	71	8

Application	Part No.	Torque in-lbs	Torque N.m.
Nissan (cont'd)			
370Z			
2009-2010			
OE Sensor: Nissan - 40700-JK00B			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28210	71	8
Service Pack	20014	71	8
2010			
Service Pack	20032	50-60	5.6 - 7.
2011-2013			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Service Pack	20032	50-60	5.6 - 7.
2014-2016			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Altima			
2006			
OE Sensor: Nissan - 40700-JA01B			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Oct. 1 & Newer	28204	71	8
Service Pack; Oct. 1 & Newer	20014	71	8
2007-2010			
OE Sensor: Nissan - 40700-JA01B, 40700-JA02B			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28204	71	8
Service Pack	20014	71	8
2011-2012			
OE Sensor: Nissan - 40700-1AA0D, 40700-JA01B			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28204	49	5.5
Service Pack	20014	71	8
2013-2015			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200 G-Supercedes the 28154

Application	Part No.	Torque in-lbs	Torque N.m.
Nissan (cont'd)			
Armada			
2005-2006			
OE Sensor: Nissan - 40700-CK001, 40700-CK002			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; W/Alloy Wheels	20161	49	5.5
Sensor; W/Steel Wheels	20069	49	5.5
Service Pack; W/Alloy Wheels	20007	49	5.5
Service Pack; W/Steel Wheels	20005	49	5.5
2007			
OE Sensor: Nissan - 40700-CK001			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20161	49	5.5
Service Pack	20007	49	5.5
2008			
OE Sensor: Nissan - 40700-CK001, 40700-JA02B			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; LE	28204	49	5.5
Sensor; SE	20161	49	5.5
Service Pack; LE	20014	49	5.5
Service Pack; SE	20007	49	5.5
2009-2011			
OE Sensor: Nissan - 40700-JA01B			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28204	49	5.5
Service Pack	20014	49	5.5
2012-2015			
OE Sensor: Nissan - 40700-1AA0D, 407001AA0D			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28204	49	5.5
Service Pack	20014	71	8
2016			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28204	49	5.5
Service Pack	20014	71	8

Application	Part No.	Torque in-lbs	Torque N.m.
Nissan (cont'd)			
Cube			
2009-2010			
OE Sensor: Nissan - 40700-JA01C			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28204	71	8
Service Pack	20014	71	8
2011-2012			
OE Sensor: Nissan - 40700-1AA0B, 40700-1AA0D			
EZ-Sensor; Ikey	33000 [A]	11.5	1.3
EZ-Sensor; non-Ikey	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Ikey; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Ikey; Rubber Valve	20018 [C]	11.5	1.3
EZ-Sensor Service Pack; non-Ikey; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; non-Ikey; Rubber Valve	20018 [C]	11.5	1.3
Sensor; non-Ikey	28204	49	5.5
Service Pack; non-Ikey	20014	49	5.5
2013			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2014			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Frontier			
2003-2004			
OE Sensor: Nissan - 40700-CD001			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20064	36-60	4.1-6.8
Service Pack	20007	36-60	4.1-6.8
2005-2007			
OE Sensor: Nissan - 40700-CK001, 40700-CK002			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; W/Alloy Wheels	20161	49	5.5
Sensor; W/Steel Wheels	20069	49	5.5
Service Pack; W/Alloy Wheels	20007	49	5.5
Service Pack; W/Steel Wheels	20005	49	5.5

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Nissan (cont'd)			
Frontier (cont'd)			
2008			
OE Sensor: Nissan - 40700-CK001, 40700-JA01B			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; W/Alloy Wheels	20161	49	5.5
Sensor; W/Steel Wheels	28204	49	5.5
Service Pack; W/Alloy Wheels	20007	49	5.5
Service Pack; W/Steel Wheels	20014	49	5.5
2009-2011			
OE Sensor: Nissan - 40700-1AA0B, 40700-JA01B			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28204	49	5.5
Service Pack	20014	49	5.5
2012-2015			
OE Sensor: Nissan - 40700-1AA0D, 407001AA0D			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28204	49	5.5
Service Pack	20014	71	8
2016			
OE Sensor: Nissan - 407001AA0D			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28204	49	5.5
Service Pack	20014	71	8
GT-R			
2009			
OE Sensor: Nissan - 40700-JA01C			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28204	71	8
Service Pack	20014	71	8
2010			
OE Sensor: Nissan - 40700-JA01C EZ-Sensor; When installing EZ-Sensor the rubber valve MUST be removed and replaced with Schrader Aluminium valve kit 34000	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28204	71	8
Service Pack	20014	71	8

Application	Part No.	Torque in-lbs	Torque N.m.
Nissan (cont'd)			
GT-R (cont'd)			
2011-2016			
OE Sensor: Nissan - 40700-1AA0B, 40700-1AA0D, 40700-JA01B, 407001AA0B EZ-Sensor; When installing EZ-Sensor the rubber valve MUST be removed and replaced with Schrader Aluminium valve kit 34000	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28204	49	5.5
Service Pack	20014	71	8
2017			
Sensor	28204	49	5.5
Service Pack	20014	71	8
Juke			
2011			
OE Sensor: Nissan - 40700-1AA0B			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28204	49	5.5
Service Pack	20014	49	5.5
2012			
OE Sensor: Nissan - 40700-1AA0D			
EZ-Sensor	33000 [A]	11.5	1.3
EZ-Sensor; non-Ikey	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28204	49	5.5
Service Pack	20014	49	5.5
2013-2015			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Leaf			
2011-2013			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Maxima			
2006			
OE Sensor: Nissan - 40700-CK001			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Jun. & Newer	20161	49	5.5
Service Pack; Jun. & Newer	20007	49	5.5

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Nissan (cont'd)			
Maxima (cont'd)			
2007			
OE Sensor: Nissan - 40700-CK001, 40700-JA01B			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Apr. 1 & Newer	28204	68	7.7
Sensor; Mar. & Older	20161	49	5.5
Service Pack; Apr. 1 & Newer	20014	68	7.7
Service Pack; Mar. & Older	20007	49	5.5
2008-2010			
OE Sensor: Nissan - 40700-JA01B, 40700-JA02B			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28204	68	7.7
Service Pack	20014	68	7.7
2011-2012			
OE Sensor: Nissan - 40700-1AA0D, 40700-JA01B			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28204	49	5.5
Service Pack	20014	71	8
2013			
EZ-Sensor	33100 [A]	11.5	1.3
	33200 [A]	11.5	1.3
EZ-Sensor; exc GCC	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; exc GCC; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; exc GCC; Rubber Valve	20018 [C]	11.5	1.3
2014-2015			
EZ-Sensor; exc GCC	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; exc GCC; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; exc GCC; Rubber Valve	20018 [C]	11.5	1.3
Murano			
2003-2006			
OE Sensor: Nissan - 40700-CD001			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20064	66	7.5
Service Pack	20007	66	7.5

Application	Part No.	Torque in-lbs	Torque N.m.
Nissan (cont'd)			
Murano (cont'd)			
2007			
OE Sensor: Nissan - 40700-JA01B			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28204	71	8
Service Pack	20014	71	8
2009			
OE Sensor: Nissan - 40700-JA01B			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28204	68	7.7
Service Pack	20014	68	7.7
2010			
OE Sensor: Nissan - 40700-1AA0B			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28204	35	4
Service Pack	20014	49	5.5
2011			
OE Sensor: Nissan - 40700-1AA0B			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28204	49	5.5
Service Pack	20014	49	5.5
2012-2014			
OE Sensor: Nissan - 40700-1AA0D			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28204	49	5.5
Service Pack	20014	71	8
NV			
2012			
OE Sensor: Nissan - 40700-1PA0A			
Sensor	28342	68	7.7
Service Pack	20014	71	8
2013-2015			
OE Sensor: Nissan - 40700-1A00D, 40700-1PA0A, 407001PA0A			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28342	68	7.7
Service Pack	20014	71	8
2014-2015			
Sensor	28204	49	5.5

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Nissan (cont'd)			
NV (cont'd)			
2016			
OE Sensor: Nissan - 407001PA0A			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28204	49	5.5
	28342	68	7.7
Service Pack	20014	71	8
Pathfinder			
2003			
OE Sensor: Nissan - 40700-CD001			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20064	49	5.5
Service Pack	20007	49	5.5
2004			
OE Sensor: Nissan - 40700-CD001, 40700-CK002			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Armada	20069	49	5.5
Sensor; Exc. Armada; Aug. & Newer	20069	49	5.5
Sensor; Exc. Armada; Jul. & Older	20064	49	5.5
Service Pack; Armada	20005	49	5.5
Service Pack; Exc. Armada; Aug. & Newer	20005	49	5.5
Service Pack; Exc. Armada; Jul. & Older	20007	49	5.5
2005-2006			
OE Sensor: Nissan - 40700-CK001			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20161	49	5.5
Service Pack	20007	49	5.5
2007			
OE Sensor: Nissan - 40700-JA01A, 40700-JA01B			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; OEM Part No. 40700JA01A	28167	49	5.5
Sensor; OEM Part No. 40700JA01B	28204	49	5.5
Service Pack	20014	49	5.5
2008-2011			
OE Sensor: Nissan - 40700-1AA0B, 40700-JA01B, 40700-JA02B			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28204	49	5.5
Service Pack	20014	49	5.5

Application	Part No.	Torque in-lbs	Torque N.m.
Nissan (cont'd)			
Pathfinder (cont'd)			
2012			
OE Sensor: Nissan - 40700-1AA0D			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28204	49	5.5
Service Pack	20014	71	8
Quest			
2004			
OE Sensor: Nissan - 40700-CK002			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20069	78	8.8
Service Pack	20005	78	8.8
2005-2006			
OE Sensor: Nissan - 40700-CK001, 40700-CK002			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; W/Alloy Wheels	20161	78	8.8
Sensor; W/Steel Wheels	20069	78	8.8
Service Pack; W/Alloy Wheels	20007	78	8.8
Service Pack; W/Steel Wheels	20005	78	8.8
2007-2009			
OE Sensor: Nissan - 40700-JA01B, 40700-JA02B			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28204	49	5.5
Service Pack	20014	49	5.5
2011-2016			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Rogue			
2008-2009			
OE Sensor: Nissan - 40700-JA01B, 40700-JA01C			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28204	68	7.7
Service Pack	20014	68	7.7

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Nissan (cont'd)			
Rogue (cont'd)			
2011			
OE Sensor: Nissan - 40700-1AA0B			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28204	49	5.5
Service Pack	20014	49	5.5
2012			
OE Sensor: Nissan - 40700-1AA0D			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28204	49	5.5
Service Pack	20014	71	8
2013			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2014-2016			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sentra			
2007			
OE Sensor: Nissan - 40700-CK001, 40700-JA01B			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; W/Alloy Wheels	20161	78	8.8
Sensor; W/Steel Wheels	28204	71	8
Service Pack; W/Alloy Wheels	20007	78	8.8
Service Pack; W/Steel Wheels	20014	71	8
2008			
OE Sensor: Nissan - 40700-JA01B			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28204	71	8
Service Pack	20014	71	8
2009-2010			
OE Sensor: Nissan - 40700-JA01B			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28204	68	7.7
Service Pack	20014	68	7.7

Application	Part No.	Torque in-lbs	Torque N.m.
Nissan (cont'd)			
Sentra (cont'd)			
2011-2013			
OE Sensor: Nissan - 40700-1AA0B, 40700-1AA0D			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28204	49	5.5
Service Pack	20014	71	8
Titan			
2004			
OE Sensor: Nissan - 40700-CK002			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20069	49	5.5
Service Pack	20005	49	5.5
2005			
OE Sensor: Nissan - 40700-CK001, 40700-CK002			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Apr. 1 & Newer	20161	49	5.5
Sensor; Mar. & Older	20069	49	5.5
Service Pack; Apr. 1 & Newer	20007	49	5.5
Service Pack; Mar. & Older	20005	49	5.5
2006			
OE Sensor: Nissan - 40700-CK001			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20161	49	5.5
Service Pack	20007	49	5.5
2007			
OE Sensor: Nissan - 40700-CK001, 40700-JA02B			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Apr. 1 & Newer	28204	49	5.5
Sensor; Mar. & Older	20161	49	5.5
Service Pack; Apr. 1 & Newer	20014	49	5.5
Service Pack; Mar. & Older	20007	49	5.5
2008-2011			
OE Sensor: Nissan - 40700-1AA0B, 40700-JA02B			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28204	49	5.5
Service Pack	20014	49	5.5

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Nissan (cont'd)			
Titan (cont'd)			
2012-2015			
OE Sensor: Nissan - 40700-1AA0D			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28204	49	5.5
Service Pack	20014	71	8
2016			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Versa			
2007			
OE Sensor: Nissan - 40700-JA01A, 40700-JA01B			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; OEM Part No. 40700JA01A	28167	71	8
Sensor; OEM Part No. 40700JA01B	28204	71	8
Service Pack	20014	71	8
2008-2010			
OE Sensor: Nissan - 40700-JA01B			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28204	71	8
Service Pack	20014	71	8
2011-2012			
OE Sensor: Nissan - 40700-1AA0D, 40700-JA01B			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28204	49	5.5
Service Pack	20014	71	8
Xterra			
2003-2004			
OE Sensor: Nissan - 40700-CD001			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20064	36-60	4.1-6.8
Service Pack	20007	36-60	4.1-6.8
2005			
OE Sensor: Nissan - 40700-CK001			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20161	36-60	4.1-6.8
Service Pack	20007	36-60	4.1-6.8

Application	Part No.	Torque in-lbs	Torque N.m.
Nissan (cont'd)			
Xterra (cont'd)			
2006			
OE Sensor: Nissan - 40700-CK001, 40700-CK002			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Exc. Submodel X	20161	49	5.5
Sensor; Submodel X	20069	49	5.5
Service Pack; Exc. Submodel X	20007	49	5.5
Service Pack; Submodel X	20005	49	5.5
2007			
OE Sensor: Nissan - 40700-JA01A, 40700-JA01B			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; OEM Part No. 40700JA01A	28167	49	5.5
Sensor; OEM Part No. 40700JA01B	28204	49	5.5
Service Pack	20014	49	5.5
2008-2011			
OE Sensor: Nissan - 40700-1AA0B, 40700-JA01B			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28204	49	5.5
Service Pack	20014	49	5.5
2012-2015			
OE Sensor: Nissan - 40700-1AA0D			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28204	49	5.5
Service Pack	20014	71	8
2016			
Sensor	28204	49	5.5
Service Pack	20014	71	8
Oldsmobile			
Alero			
1999-2000			
Sensor	INDIRECT [D]		
Aurora			
2001-2003			
Sensor	INDIRECT [D]		
Plymouth			
Prowler			
1997			
OE Sensor: Chrysler - 4815132			
Sensor	28004	35	4
Service Pack; W/Black Sensor Body	20012	35	4
Service Pack; W/Red Sensor Body	20003	35	4

A-Programming Tool Required C-20018 and 20008 are interchangeable. D-Indirect TPMS system. No sensor in wheel DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Plymouth (cont'd)			
Prowler (cont'd)			
1999-2001			
OE Sensor: Chrysler - 4815132, 4815132AB			
Sensor	28004	35	4
Service Pack; W/Black Sensor Body	20012	35	4
Service Pack; W/Red Sensor Body	20003	35	4
Pontiac			
Aztek			
2003-2005			
Sensor	INDIRECT [D]		
Bonneville			
2000-2005			
Sensor	INDIRECT [D]		
G Series			
2008			
OE Sensor: General Motors - 15921013, 15922396			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20153	62	7
	20158	62	7
Service Pack	20008 [C]	11.5	1.3
Service Pack; W/Schrader Sensor	20004	62	7
Service Pack; W/Siemens Sensor	20030	80	9
2009-2010			
OE Sensor: General Motors - 15922396, 25920615			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20153	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
Grand Am			
1999-2002			
Sensor	INDIRECT [D]		
Grand Prix			
2004-2006			
Sensor	INDIRECT [D]		
2007			
OE Sensor: General Motors - 10394110			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20158	62	7
Service Pack; W/Schrader Sensor	20004	62	7
Service Pack; W/Siemens Sensor	20030	80	9

Application	Part No.	Torque in-lbs	Torque N.m.
Pontiac (cont'd)			
Grand Prix (cont'd)			
2008			
OE Sensor: General Motors - 15921013, 15922396			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Clamp-In Style Only; W/Aluminium Valve Stem	20158	62	7
Sensor; Snap-In Style Only; W/Rubber Valve Stem	20153	11.5	1.3
Service Pack; Clamp-In Style Only; W/Aluminium Valve Stem	20004	62	7
Service Pack; Snap-In Style Only; W/Rubber Valve Stem	20008 [C]	11.5	1.3
Montana			
2008			
OE Sensor: General Motors - 15268606			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20158	62	7
Service Pack; W/Schrader Sensor	20004	62	7
Service Pack; W/Siemens Sensor	20030	80	9
2009			
Sensor	20131	62	7
Service Pack	20006	62	7
Solstice			
2008-2009			
OE Sensor: General Motors - 15921013			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20158	62	7
Service Pack; W/Schrader Sensor	20004	62	7
Service Pack; W/Siemens Sensor	20030	80	9
2010			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Torrent			
2007-2009			
OE Sensor: General Motors - 10394110, 15921013			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20158	62	7
Service Pack; W/Schrader Sensor	20004	62	7
Service Pack; W/Siemens Sensor	20030	80	9
Vibe			
2005-2007			
Sensor	INDIRECT [D]		

A-Programming Tool Required C-20018 and 20008 are interchangeable. D-Indirect TPMS system. No sensor in wheel DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Pontiac (cont'd)			
Vibe (cont'd)			
2008-2010			
OE Sensor: General Motors - 88974915			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28360	35	4
Service Pack	20032	35	4
Wave			
2008			
OE Sensor: General Motors - 15922396			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20153	11.5	1.3
Service Pack	20008 C	11.5	1.3
2009			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Porsche			
911			
2005-2006			
OE Sensor: Porsche - 99760602120			
EZ-Sensor	33100 A	11.5	1.3
	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Includes Transmitter Only	28087	31-40	3.5-4.5
Service Pack; Does Not Include Valve	20023	31-40	3.5-4.5
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
2007-2009			
OE Sensor: Porsche - 997 606 021 00, 99760602120			
EZ-Sensor	33100 A	11.5	1.3
	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Includes Transmiter Only	20077	35	4
Sensor; Includes Transmitter Only	28087	31-40	3.5-4.5
Service Pack; Does Not Include Valve	20023	31-40	3.5-4.5
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4

Application	Part No.	Torque in-lbs	Torque N.m.
Porsche (cont'd)			
911 (cont'd)			
2010			
OE Sensor: Porsche - 958 361 661 00, 99760602120			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor; Excluding GT3	33100 A	11.5	1.3
	33200 A	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Includes Transmitter Only	20103	35	4
	28087	31-40	3.5-4.5
Service Pack; Does Not Include Valve	20023	31-40	3.5-4.5
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
2011			
OE Sensor: Porsche - 95536105300			
EZ-Sensor	33100 A	11.5	1.3
	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; Includes Transmitter Only	20077	35	4
Service Pack; Does Not Include Valve	20023	35	4
	20023	31-40	3.5-4.5
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
2012			
OE Sensor: Porsche - 99760602120			
EZ-Sensor	33100 A	11.5	1.3
	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20103	35	4
Sensor; Includes Transmitter Only	28087	31-40	3.5-4.5
Service Pack	20009	88	10
Service Pack; Does Not Include Valve	20023	31-40	3.5-4.5
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
2013-2014			
EZ-Sensor	33100 A	11.5	1.3
	33200 A	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20103	35	4
Service Pack; Does Not Include Valve	20023	31-40	3.5-4.5
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Porsche (cont'd)			
911 (cont'd)			
2015-2016			
Sensor	20103	35	4
Service Pack; Does Not Include Valve	20023	31-40	3.5-4.5
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
918 Spyder			
2015-2016			
Sensor	20103	35	4
Service Pack; Does Not Include Valve	20023	31-40	3.5-4.5
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
Boxster			
2005-2007			
OE Sensor: Porsche - 99760602120			
EZ-Sensor	33100 [A]	11.5	1.3
	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Includes Transmitter Only	28087	31-40	3.5-4.5
Service Pack; Does Not Include Valve	20023	31-40	3.5-4.5
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
2008-2010			
OE Sensor: Porsche - 99760602120			
EZ-Sensor	33100 [A]	11.5	1.3
	33200 [A]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Includes Transmitter Only	28087	31-40	3.5-4.5
Service Pack; Does Not Include Valve	20023	31-40	3.5-4.5
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
2011			
OE Sensor: Porsche - 95536105300			
EZ-Sensor	33100 [A]	11.5	1.3
	33200 [A]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Includes Transmitter Only	20077	35	4
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4

Application	Part No.	Torque in-lbs	Torque N.m.
Porsche (cont'd)			
Boxster (cont'd)			
2012-2013			
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
2014-2016			
Sensor	20103	35	4
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
Carrera GT			
2004-2005			
OE Sensor: Porsche - 99760602120			
EZ-Sensor	33100 [A]	11.5	1.3
	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Includes Transmitter Only	28087	31-40	3.5-4.5
Service Pack; Does Not Include Valve	20023	31-40	3.5-4.5
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
2006-2011			
EZ-Sensor	33100 [A]	11.5	1.3
	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Cayenne			
2002			
EZ-Sensor	33100 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
2003-2006			
OE Sensor: Porsche - 99760602120			
EZ-Sensor	33100 [A]	11.5	1.3
	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Includes Transmitter Only	28087	31-40	3.5-4.5
Service Pack; Does Not Include Valve	20023	31-40	3.5-4.5
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Porsche (cont'd)			
Cayenne (cont'd)			
2008-2010			
Service Pack; Does Not Include Valve.	20023	31-40	3.5-4.5
Service Pack; W/43mm Silver Insert.	20037	35	4
Service Pack; W/48mm Green Insert.	20038	35	4
Service Pack; W/49mm Black Insert.	20039	35	4
Service Pack; W/51mm Orange Insert.	20040	35	4
2011-2013			
OE Sensor: Porsche - 95836166100			
Sensor; Includes Transmitter Only.	20103	35	4
Service Pack; Does Not Include Valve.	20023	31-40	3.5-4.5
Service Pack; W/43mm Silver Insert.	20037	35	4
Service Pack; W/48mm Green Insert.	20038	35	4
Service Pack; W/49mm Black Insert.	20039	35	4
Service Pack; W/51mm Orange Insert.	20040	35	4
2014-2016			
OE Sensor: Porsche - 95836166100			
Sensor.	20103	35	4
Service Pack; Does Not Include Valve.	20023	31-40	3.5-4.5
Service Pack; W/43mm Silver Insert.	20037	35	4
Service Pack; W/48mm Green Insert.	20038	35	4
Service Pack; W/49mm Black Insert.	20039	35	4
Service Pack; W/51mm Orange Insert.	20040	35	4
Cayman			
2005-2007			
OE Sensor: Porsche - 99760602101			
EZ-Sensor.	33100 [A]	11.5	1.3
	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 [C]	11.5	1.3
Sensor; Includes Transmitter Only.	20077	31-40	3.5-4.5
Service Pack; Does Not Include Valve.	20023	31-40	3.5-4.5
Service Pack; W/43mm Silver Insert.	20037	35	4
Service Pack; W/48mm Green Insert.	20038	35	4
Service Pack; W/49mm Black Insert.	20039	35	4
Service Pack; W/51mm Orange Insert.	20040	35	4
2008			
OE Sensor: Porsche - 99760602101			
EZ-Sensor.	33100 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 [C]	11.5	1.3
Sensor; Includes Transmitter Only.	20077	31-40	3.5-4.5
Service Pack; Does Not Include Valve.	20023	31-40	3.5-4.5
Service Pack; W/43mm Silver Insert.	20037	35	4
Service Pack; W/48mm Green Insert.	20038	35	4
Service Pack; W/49mm Black Insert.	20039	35	4
Service Pack; W/51mm Orange Insert.	20040	35	4
2009-2010			
OE Sensor: Porsche - 99760602120			
Sensor; Includes Transmitter Only.	28087	31-40	3.5-4.5
Service Pack; Does Not Include Valve.	20023	31-40	3.5-4.5
Service Pack; W/43mm Silver Insert.	20037	35	4
Service Pack; W/48mm Green Insert.	20038	35	4
Service Pack; W/49mm Black Insert.	20039	35	4
Service Pack; W/51mm Orange Insert.	20040	35	4

Application	Part No.	Torque in-lbs	Torque N.m.
Porsche (cont'd)			
Cayman (cont'd)			
2011			
OE Sensor: Porsche - 95536105300, 99760602120			
Sensor; Includes Transmitter Only.	20077	35	4
	28087	31-40	3.5-4.5
Service Pack; Does Not Include Valve.	20023	35	4
Service Pack; W/43mm Silver Insert.	20037	35	4
Service Pack; W/48mm Green Insert.	20038	35	4
Service Pack; W/49mm Black Insert.	20039	35	4
Service Pack; W/51mm Orange Insert.	20040	35	4
2012-2016			
Sensor.	20103		
Service Pack; Does Not Include Valve.	20023	35	4
Service Pack; W/43mm Silver Insert.	20037	35	4
Service Pack; W/48mm Green Insert.	20038	35	4
Service Pack; W/49mm Black Insert.	20039	35	4
Service Pack; W/51mm Orange Insert.	20040	35	4
Macan			
2014-2015			
EZ-Sensor.	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 [C]	11.5	1.3
2016			
OE Sensor: Porsche - 95836166100			
EZ-Sensor.	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 [C]	11.5	1.3
Sensor.	20103	35	4
Service Pack; Does Not Include Valve.	20023	31-40	3.5-4.5
Service Pack; W/43mm Silver Insert.	20037	35	4
Service Pack; W/48mm Green Insert.	20038	35	4
Service Pack; W/49mm Black Insert.	20039	35	4
Service Pack; W/51mm Orange Insert.	20040	35	4
2017			
OE Sensor: Porsche - 95836166100			
Sensor.	20103	35	4
Service Pack; Does Not Include Valve.	20023	31-40	3.5-4.5
Service Pack; W/43mm Silver Insert.	20037	35	4
Service Pack; W/48mm Green Insert.	20038	35	4
Service Pack; W/49mm Black Insert.	20039	35	4
Service Pack; W/51mm Orange Insert.	20040	35	4
Panamera			
2010			
OE Sensor: Porsche - 99760602120			
Sensor; Includes Transmitter Only.	28087	31-40	3.5-4.5
Service Pack; Does Not Include Valve.	20023	31-40	3.5-4.5
Service Pack; W/43mm Silver Insert.	20037	35	4
Service Pack; W/48mm Green Insert.	20038	35	4
Service Pack; W/49mm Black Insert.	20039	35	4
Service Pack; W/51mm Orange Insert.	20040	35	4

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Porsche (cont'd)			
Panamera (cont'd)			
2011			
OE Sensor: Porsche - 99760602120			
Sensor; Includes Transmitter Only.	28087	31-40	3.5-4.5
Service Pack; W/43mm Silver Insert.	20037	35	4
Service Pack; W/48mm Green Insert.	20038	35	4
Service Pack; W/49mm Black Insert.	20039	35	4
Service Pack; W/51mm Orange Insert.	20040	35	4
2014			
OE Sensor: Porsche - 95836166100			
EZ-Sensor.	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
Sensor.	20103	35	4
Service Pack; Does Not Include Valve.	20023	31-40	3.5-4.5
Service Pack; W/43mm Silver Insert.	20037	35	4
Service Pack; W/48mm Green Insert.	20038	35	4
Service Pack; W/49mm Black Insert.	20039	35	4
Service Pack; W/51mm Orange Insert.	20040	35	4
2015			
OE Sensor: Porsche - 95836166100			
EZ-Sensor.	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
Sensor.	20103	35	4
2016			
OE Sensor: Porsche - 95836166100			
Sensor.	20103	35	4
Ram			
4500			
2012			
OE Sensor: Chrysler - 56029398AB			
EZ-Sensor.	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
Sensor.	20398	11.5	1.3
Service Pack; Rubber Valve.	20018 C	11.5	1.3
5500			
2012			
OE Sensor: Chrysler - 56029398AB			
Sensor.	20398	11.5	1.3
Service Pack; Rubber Valve.	20018 C	11.5	1.3
C/V			
2012			
OE Sensor: Chrysler - 68241067AB			
EZ-Sensor.	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
Sensor; Rubber Valve.	20398	11.5	1.3
Service Pack; Rubber Valve.	20018 C	11.5	1.3

Application	Part No.	Torque in-lbs	Torque N.m.
Ram (cont'd)			
C/V (cont'd)			
2013-2015			
OE Sensor: Chrysler - 68241067AB			
EZ-Sensor.	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
Sensor.	20398	11.5	1.3
Service Pack; Rubber Valve.	20018 C	11.5	1.3
ProMaster			
2014-2015			
OE Sensor: Chrysler - 5154876AA			
EZ-Sensor.	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; exc Hybrid; Rubber Valve.	20018 C	11.5	1.3
Sensor.	20398	11.5	1.3
Service Pack; Rubber Valve.	20018 C	11.5	1.3
2016			
OE Sensor: Chrysler - 5154876AA			
EZ-Sensor.	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; exc Hybrid; Rubber Valve.	20018 C	11.5	1.3
Sensor.	20398	11.5	1.3
Service Pack; Rubber Valve.	20018 C	11.5	1.3
2017			
OE Sensor: Chrysler - 5154876AA			
Sensor.	20398	11.5	1.3
Service Pack; Rubber Valve.	20018 C	11.5	1.3
Ram Series			
2011			
OE Sensor: Chrysler - 56029398AB			
EZ-Sensor.	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
Sensor; W/Rubber Stem Snap-in Sensor.	20398	11.5	1.3
Service Pack; W/Rubber Stem Snap-in Sensor. . . .	20018 C	11.5	1.3
2012-2013			
OE Sensor: Chrysler - 56029398AB			
EZ-Sensor.	33200 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
Sensor.	20398	11.5	1.3
Service Pack; Rubber Valve.	20018 C	11.5	1.3
2014-2015			
OE Sensor: Chrysler - 68157568AA, 68239720AA, 68249197AA			
EZ-Sensor.	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
Sensor.	28984	35	4
Service Pack.	20635	11.5	1.3
Service Pack; Rubber Valve.	20018 C	11.5	1.3

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Ram (cont'd)			
Ram Series (cont'd)			
2016-2017			
OE Sensor: Chrysler - 68249197AA			
Sensor	28984	35	4
Service Pack	20635	11.5	1.3
Rolls Royce			
Ghost			
2011-2016			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
Sensor	28081		
Service Pack; Does Not Include Valve	20023	31-40	3.5-4.5
Service Pack; Rubber Valve	20018 C	11.5	1.3
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
Phantom			
2007-2011			
Service Pack; Does Not Include Valve	20023	31-40	3.5-4.5
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
2012-2016			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
Sensor	28081		
Service Pack; Does Not Include Valve	20023	31-40	3.5-4.5
Service Pack; Rubber Valve	20018 C	11.5	1.3
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
Silver Dawn			
2016			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
Sensor	28081		
Service Pack; Does Not Include Valve	20023	31-40	3.5-4.5
Service Pack; Rubber Valve	20018 C	11.5	1.3
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4

Application	Part No.	Torque in-lbs	Torque N.m.
Rolls Royce (cont'd)			
Wraith			
2014-2016			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
Sensor	28081		
Service Pack; Does Not Include Valve	20023	31-40	3.5-4.5
Service Pack; Rubber Valve	20018 C	11.5	1.3
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
Saab			
9-3			
2003-2007			
OE Sensor: Saab - 13172567, 24437708			
Sensor	28078	62	7
Service Pack	20009	62	7
2008-2011			
OE Sensor: Saab - 13227143			
Sensor	20159	88	10
Service Pack	20009	88	10
9-3X			
2010-2011			
OE Sensor: Saab - 13227143			
Sensor	20159	88	10
Service Pack	20009	88	10
9-4X			
2011			
OE Sensor: General Motors - 20922900			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28206	11.5	1.3
Service Pack	20008 C	11.5	1.3
9-5			
2003-2007			
OE Sensor: Saab - 13172567, 24437708			
Sensor	28078	62	7
Service Pack	20009	62	7
2008-2009			
OE Sensor: Saab - 13227143			
Sensor	20159	88	10
Service Pack	20009	88	10
2010-2011			
OE Sensor: Saab - 13227143			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20159	88	10
Service Pack	20009	88	10

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Saab (cont'd)			
9-5 (cont'd)			
2012			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
9-7x			
2005-2009			
OE Sensor: General Motors - 25774006			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20116	62	7
Service Pack	20004	62	7
Saturn			
Astra			
2008-2009			
OE Sensor: General Motors - 13172567; Saab - 13172567			
Sensor	28078	80	9
Service Pack	20009	80	9
Aura			
2007			
OE Sensor: General Motors - 10394110			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20158	62	7
Service Pack; W/Schrader Sensor	20004	62	7
Service Pack; W/Siemens Sensor	20030	62	7
2008-2009			
OE Sensor: General Motors - 15922396, 25920615			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20153	11.5	1.3
Service Pack	20008 C	11.5	1.3
2010			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Outlook			
2007-2008			
OE Sensor: General Motors - 10394110, 15921013			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20158	62	7
Service Pack; W/Schrader Sensor	20004	62	7
Service Pack; W/Siemens Sensor	20030	62	7

Application	Part No.	Torque in-lbs	Torque N.m.
Saturn (cont'd)			
Outlook (cont'd)			
2009-2010			
OE Sensor: General Motors - 25920615			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20153	11.5	1.3
Service Pack	20008 C	11.5	1.3
Sky			
2008-2010			
OE Sensor: General Motors - 15921013			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20158	62	7
Service Pack; W/Schrader Sensor	20004	62	7
Service Pack; W/Siemens Sensor	20030	80	9
Vue			
2007-2010			
OE Sensor: General Motors - 15922396, 25920615			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	20153	11.5	1.3
Service Pack	20008 C	11.5	1.3
Scion			
FR-S			
2013			
OE Sensor: Toyota - 4260706020			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28360	35	4
Service Pack	20032	35	4
2014-2016			
OE Sensor: Toyota - 4260706020			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28360	35	4
Service Pack	20032	35	4
iM			
2015-2016			
OE Sensor: Toyota - 4260706020			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28360	35	4
Service Pack	20032	35	4

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Scion (cont'd)			
iQ			
2012-2014			
OE Sensor: Toyota - 4260733011			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28365	35	4
Service Pack	20032	35	4
2015			
OE Sensor: Toyota - 4260733011			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28365	35	4
Service Pack	20032	35	4
tC			
2006			
OE Sensor: Toyota - 4260733011			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; May & Newer	28365	35	4
Service Pack; May & Newer	20032	35	4
2007-2014			
OE Sensor: Toyota - 4260733011			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28365	35	4
Service Pack	20032	35	4
2015-2016			
OE Sensor: Toyota - 4260733011			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28365	35	4
Service Pack	20032	35	4
xB			
2008-2014			
OE Sensor: Toyota - 4260733011			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28365	35	4
Service Pack	20032	35	4
2015-2016			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28365	35	4
Service Pack	20032	35	4

Application	Part No.	Torque in-lbs	Torque N.m.
Scion (cont'd)			
xD			
2008-2014			
OE Sensor: Toyota - 4260733011			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28365	35	4
Service Pack	20032	35	4
2015			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Smart			
Fortwo			
2008-2012			
OE Sensor: Mercedes-Benz - 0025409017, 0045421518			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Does Not Include Stem	20016	53	6
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	53	6
2013			
OE Sensor: Mercedes-Benz - 0009057200			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28214	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; W/O Valve	20016	58	6.5
2014			
OE Sensor: Mercedes-Benz - A0009050030			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20213		
Service Pack	20049	80	9
2015-2016			
OE Sensor: Mercedes-Benz - A0009050030			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20213	80	9
Service Pack	20049	80	9
2017			
OE Sensor: Mercedes-Benz - A0009050030			
Sensor	20213	80	9
Service Pack	20049	80	9

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Subaru			
B9 Tribeca			
2006-2007			
OE Sensor: Subaru - 28103AG00A			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20081	66	7.5
Service Pack	20011	66	7.5
2008-2011			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
BRZ			
2013-2014			
OE Sensor: Subaru - 4260706020			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28360	35	4
Service Pack	20032	35	4
2015-2016			
OE Sensor: Subaru - 4260706020			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28360	35	4
Service Pack	20032	35	4
Forester			
2008-2015			
OE Sensor: Subaru - 28103AG01B, 28103AG01C, 28103SA001, 28103SG000, 28103SG010			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28203	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
2016			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28203	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
Impreza			
2008-2015			
OE Sensor: Subaru - 28103AG01A, 28103AG01B, 28103AG01C, 28103SA002, 28103SG000			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28203	11.5	1.3
Service Pack	20008 [C]	11.5	1.3

Application	Part No.	Torque in-lbs	Torque N.m.
Subaru (cont'd)			
Impreza (cont'd)			
2016			
Sensor	28203	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
Legacy			
2004-2007			
OE Sensor: Subaru - 28103AG00A			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20081	66	7.5
Service Pack	20011	66	7.5
2008			
OE Sensor: Subaru - 28103AG00A, 28103AG01A			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; W/16" Or 17" Wheels	20081	66	7.5
Sensor; W/18" Wheels	28203	11.5	1.3
Service Pack; W/16" Or 17" Wheels	20011	66	7.5
Service Pack; W/18" Wheels	20008 [C]	11.5	1.3
2009-2015			
OE Sensor: Subaru - 28103AG01B, 28103AG01C, 28103AJ00A			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28203	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
2016			
OE Sensor: Subaru - 28103AJ00A			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28203	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
Outback			
2004-2007			
OE Sensor: Subaru - 28103AG00A			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20081	66	7.5
Service Pack	20011	66	7.5
2008-2015			
OE Sensor: Subaru - 28103AG01A, 28103AG01B, 28103AG01C, 28103AJ00A			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28203	11.5	1.3
Service Pack	20008 [C]	11.5	1.3

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Subaru (cont'd)			
Outback (cont'd)			
2016-2017			
OE Sensor: Subaru - 28103AJ00A			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28203	11.5	1.3
Service Pack	20008 C	11.5	1.3
Tribeca			
2008			
OE Sensor: Subaru - 28103AG00A, 28103AG01A			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; W/Metal Stem Clamp-in Sensor	20081	66	7.5
Sensor; W/Rubber Stem Snap-in Sensor	28203	11.5	1.3
Service Pack	20008 C	11.5	1.3
Service Pack; W/Metal Stem Clamp-in Sensor	20011	66	7.5
2009			
OE Sensor: Subaru - 28103AG00A, 28103AG01B			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; W/Metal Stem Clamp-in Sensor	20081	66	7.5
Sensor; W/Rubber Stem Snap-in Sensor	28203	11.5	1.3
Service Pack; Rubber Valve	20008 C	11.5	1.3
Service Pack; W/Metal Stem Clamp-in Sensor	20011	66	7.5
2010			
OE Sensor: Subaru - 28103AG00A, 28103AG01C			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; W/Metal Stem Clamp-in Sensor	20081	66	7.5
Sensor; W/Rubber Stem Snap-in Sensor	28203	11.5	1.3
Service Pack	20008 C	11.5	1.3
Service Pack; W/Metal Stem Clamp-in Sensor	20011	66	7.5
2011			
OE Sensor: Subaru - 28103AG00A, 28103AG01C			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor; W/Metal Stem Clamp-in Sensor	20081	66	7.5
Sensor; W/Rubber Stem Snap-in Sensor	28203	11.5	1.3
Service Pack; Rubber Valve	20008 C	11.5	1.3
Service Pack; W/Metal Stem Clamp-in Sensor	20011	66	7.5
2012-2014			
OE Sensor: Subaru - 28103AG01C			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28203	11.5	1.3
Service Pack	20008 C	11.5	1.3

Application	Part No.	Torque in-lbs	Torque N.m.
Subaru (cont'd)			
WRX			
2013-2015			
OE Sensor: Subaru - 28103SA002, 28103SG000			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28203	11.5	1.3
Service Pack	20008 C	11.5	1.3
2016			
OE Sensor: Subaru - 28103AJ00A			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28203	11.5	1.3
Service Pack	20008 C	11.5	1.3
XV Crosstrek			
2013-2015			
OE Sensor: Subaru - 28103AG01C, 28103SG000			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28203	11.5	1.3
Service Pack	20008 C	11.5	1.3
2016			
OE Sensor: Subaru - 28103AJ00A			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28203	11.5	1.3
Service Pack	20008 C	11.5	1.3
Suzuki			
Equator			
2009-2012			
OE Sensor: Suzuki - 4321182Z10			
EZ-Sensor	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3
Sensor	28204	49	5.5
Service Pack	20014	49	5.5
2013			
EZ-Sensor	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 C	11.5	1.3

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Suzuki (cont'd)			
Forenza			
2007-2008			
OE Sensor: Suzuki - 4313085Z00			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20153	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
Grand Vitara			
2007-2013			
OE Sensor: Suzuki - 4313054J20, 4313054J21, 4313054J22			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20087	80	9
Service Pack	20009	80	9
Kizashi			
2010-2012			
OE Sensor: Original Equipment Manufacturer - 43130-57L00			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28308 [F]	11.5	1.3
Service Pack; Fits Schrader Alum stem sensor. Does not include stem.	20013	58	6.5
Service Pack; Fits Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; W/Siemens Sensor	20030	71	8
Reno			
2007-2008			
OE Sensor: Suzuki - 4313085Z00			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20153	11.5	1.3
Service Pack	20008 [C]	11.5	1.3
SX4			
2007-2013			
OE Sensor: Suzuki - 4313054J20, 4313054J21, 4313054J22			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20087	80	9
Service Pack	20009	80	9

Application	Part No.	Torque in-lbs	Torque N.m.
Suzuki (cont'd)			
SX4 Crossover			
2012			
OE Sensor: Suzuki - 4313054J21			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20087	80	9
Service Pack	20009	80	9
Verona			
2005-2006			
OE Sensor: Suzuki - 4313086Z20			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20082	80	9
Service Pack	20009	80	9
XL-7			
2005-2006			
OE Sensor: Suzuki - 4313054J20			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20087	80	9
Service Pack	20009	80	9
2007-2009			
OE Sensor: Suzuki - 4313078J10			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20158	62	7
Service Pack; W/Schrader Sensor	20004	62	7
Service Pack; W/Siemens Sensor	20030	62	7
2010-2011			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Toyota			
4Runner			
2003-2005			
OE Sensor: Toyota - 4260735010			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28345	35	4
Service Pack	20031	35	4

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200 F-Supercedes the 20066

Application	Part No.	Torque in-lbs	Torque N.m.
Toyota (cont'd)			
4Runner (cont'd)			
2006			
OE Sensor: Toyota - 4260730030, 4260733011, 4260733021, 4260735010			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; OEM Part No. 4260730030	28335	35	4
Sensor; OEM Part No. 4260733011	28365	35	4
Sensor; OEM Part No. 4260733021	28370	35	4
Sensor; OEM Part No. 4260735010	28345	35	4
Service Pack; Jun. & Newer	20032	35	4
Service Pack; May & Older	20031	35	4
2007			
OE Sensor: Toyota - 4260733011, 4260733021			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; W/O Valve Cap	28370	35	4
Sensor; W/Valve Cap	28365	35	4
Service Pack	20032	35	4
2008			
OE Sensor: Toyota - 4260733011, 4260733021			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; W/O Valve Cap; OEM Part No. 4260733021	28370	35	4
Sensor; W/Valve Cap; OEM Part No. 4260733011	28365	35	4
Service Pack	20032	35	4
2009			
OE Sensor: Toyota - 4260733011, 4260733021			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; W/O Valve Cap	28370	35	4
Sensor; W/Valve Cap	28365	35	4
Service Pack	20032	35	4
2010-2016			
OE Sensor: Toyota - 4260733021			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28370	35	4
Service Pack	20032	35	4

Application	Part No.	Torque in-lbs	Torque N.m.
Toyota (cont'd)			
Avalon			
2006			
OE Sensor: Toyota - 4260706011			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Aug. & Newer	28360	35	4
Service Pack; Aug. & Newer	20032	35	4
2007-2014			
OE Sensor: Toyota - 4260706011, 4260706020			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28360	35	4
Service Pack	20032	35	4
2015-2016			
OE Sensor: Toyota - 4260706020			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28360	35	4
Service Pack	20032	35	4
Camry			
2007-2011			
OE Sensor: Toyota - 42607-06011, 42607-33011			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Models made in Japan; OEM Part No. 4260733011	28365	35	4
Sensor; Models made in USA; OEM Part No. 4260706011	28360	35	4
Service Pack	20032	35	4
2012-2014			
OE Sensor: Toyota - 42607-06011			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28360	35	4
Service Pack	20032	35	4
2015			
OE Sensor: Toyota - 42607-06020			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Lo Line Sensor	28360	35	4
Service Pack	20032	35	4
2016			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Toyota (cont'd)			
Corolla			
2007			
OE Sensor: Toyota - 4260706011, 4260733011			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Models made in Japan; OEM Part No. 4260733011; Jun. & Newer	28365	35	4
Sensor; Models made in USA; OEM Part No. 4260706011; Jun. & Newer	28360	35	4
Service Pack; Jun. & Newer	20032	35	4
2008			
OE Sensor: Toyota - 4260706011, 4260733011			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Models made in Japan; OEM Part No. 4260733011	28365	35	4
Sensor; Models made in USA; OEM Part No. 4260706011	28360	35	4
Service Pack	20032	35	4
2009-2012			
OE Sensor: Toyota - 4260702010, 4260706011, 4260733011, 4260733021			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Models made in Japan; OEM Part No. 4260733011	28365	35	4
Sensor; Models made in Japan; OEM Part No. 4260733021	28370	35	4
Sensor; Models made in USA; W/15" Wheels	28365	35	4
Sensor; Models made in USA; W/16" Or 17" Wheels	28360	35	4
Service Pack	20032	35	4
2013			
OE Sensor: Toyota - 4260706011, 4260733011			
EZ-Sensor	33000 [A]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Models made in Japan	28365	35	4
Sensor; Models made in USA; W/16" Or 17" Wheels	28360	35	4
Service Pack	20032	35	4
2014			
OE Sensor: Toyota - 4260706011			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Models made in USA; W/16" Or 17" Wheels	28360	35	4
Service Pack	20032	35	4

Application	Part No.	Torque in-lbs	Torque N.m.
Toyota (cont'd)			
Corolla (cont'd)			
2015-2016			
OE Sensor: Toyota - 4260706011			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Models made in USA; W/16" Or 17" Wheels	28360	35	4
Service Pack	20032	35	4
FJ Cruiser			
2008-2014			
OE Sensor: Toyota - 4260733011			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28365	35	4
Service Pack	20032	35	4
2015			
OE Sensor: Toyota - 4260706011			
Sensor; Models made in USA; W/16" Or 17" Wheels	28360	35	4
Service Pack	20032	35	4
Highlander			
2007			
OE Sensor: Toyota - 4260733011			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; May & Newer	28365	35	4
Service Pack; May & Newer	20032	35	4
2008-2010			
OE Sensor: Toyota - 4260733011			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28365	35	4
Service Pack	20032	35	4
2011-2015			
OE Sensor: Toyota - 4260706011			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28360	35	4
Service Pack	20032	35	4
2016			
OE Sensor: Toyota - 4260706011			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28360	35	4
Service Pack	20032	35	4

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Toyota (cont'd)			
Land Cruiser			
2005			
OE Sensor: Toyota - 4260733011			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; May & Newer	28365	35	4
Service Pack; May & Newer	20031	35	4
2006			
OE Sensor: Toyota - 4260733011			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28365	35	4
Service Pack; Apr. 1 & Newer	20032	35	4
Service Pack; Mar. & Older	20031	35	4
2007-2011			
OE Sensor: Toyota - 4260733011			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28365	35	4
Service Pack	20032	35	4
2013-2014			
OE Sensor: Toyota - 4260733011			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28365	35	4
Service Pack	20032	35	4
2015			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28365	35	4
Service Pack	20032	35	4
2016			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Matrix			
2007			
OE Sensor: Toyota - 4260706011, 4260733011			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Models made in Japan; OEM Part No. 4260733011; Jun. & Newer	28365	35	4
Sensor; Models made in USA; OEM Part No. 4260706011; Jun. & Newer	28360	35	4
Service Pack; Jun. & Newer	20032	35	4

Application	Part No.	Torque in-lbs	Torque N.m.
Toyota (cont'd)			
Matrix (cont'd)			
2008-2013			
OE Sensor: Toyota - 4260706011, 4260733011			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Models made in Japan; OEM Part No. 4260733011	28365	35	4
Sensor; Models made in USA; OEM Part No. 4260706011	28360	35	4
Service Pack	20032	35	4
Prius			
2005-2013			
OE Sensor: Toyota - 4260733011			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28365	35	4
Service Pack	20032	35	4
2013			
Sensor	28360	35	4
2014-2016			
OE Sensor: Toyota - 4260733011			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28365	35	4
Service Pack	20032	35	4
RAV4			
2006			
OE Sensor: Toyota - 4260733011			
EZ-Sensor; exc Electric	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; exc Electric; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; exc Electric; Rubber Valve	20018 [C]	11.5	1.3
Sensor; exc Electric	28365	35	4
Service Pack; exc Electric	20032	35	4
2007-2011			
OE Sensor: Toyota - 4260733021			
EZ-Sensor; exc Electric	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; exc Electric; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; exc Electric; Rubber Valve	20018 [C]	11.5	1.3
Sensor; exc Electric	28370	35	4
Service Pack; exc Electric	20032	35	4

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Toyota (cont'd)			
RAV4 (cont'd)			
2012			
OE Sensor: Toyota - 4260706011, 4260733021			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Electric	28360	35	4
Sensor; exc Electric	28370	35	4
Service Pack	20032	35	4
2013			
OE Sensor: Toyota - 4260733021			
Sensor; exc Electric	28370	35	4
Service Pack; exc Electric	20032	35	4
Sequoia			
2004-2007			
OE Sensor: Toyota - 426070C010, 426070C020			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; W/Alloy Wheels	28305	35	4
Sensor; W/Steel Wheels; W/20 Deg. Angled Valve Sensor	28305	35	4
Sensor; W/Steel Wheels; W/40 Deg. Angled Valve Sensor	28300	35	4
Service Pack	20031	35	4
2008-2013			
OE Sensor: Toyota - 4260708010, 426070C050			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28670	35	4
Service Pack	20022	35	4
2014-2016			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sienna			
2005			
Sensor	INDIRECT [D]		
2006-2014			
OE Sensor: Toyota - 4260708010, 426070C030, 426070C050			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28670	35	4
Service Pack	20022	35	4
2015-2016			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3

Application	Part No.	Torque in-lbs	Torque N.m.
Toyota (cont'd)			
Solara			
2006			
OE Sensor: Toyota - 4260706011			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; May & Newer	28360	35	4
Service Pack; May & Newer	20032	35	4
2007-2008			
OE Sensor: Toyota - 4260706011			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28360	35	4
Service Pack	20032	35	4
2009-2011			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Tacoma			
2005			
OE Sensor: Toyota - 4260704010, 426070C010, 426070C020, 42607AD020			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; W/20 Deg. Angled Valve Sensor; Dec. 1 & Newer	28355	35	4
Sensor; W/20 Deg. Angled Valve Sensor; Nov. 30 & Older	28305	35	4
Sensor; W/40 Deg. Angled Valve Sensor; Dec. 1 & Newer	28380	35	4
Sensor; W/40 Deg. Angled Valve Sensor; Nov. 30 & Older	28300	35	4
Service Pack	20031	35	4
2006			
OE Sensor: Toyota - 4260704010, 4260706011, 42607AD020			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor; Aug. & Newer	28360	35	4
Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor; Jul. & Older	28355	35	4
Sensor; W/Steel Wheels; W/40 Deg. Angled Valve Sensor	28380	35	4
Service Pack; Aug. & Newer	20032	35	4
Service Pack; Jul. & Older	20031	35	4

A-Programming Tool Required C-20018 and 20008 are interchangeable. D-Indirect TPMS system. No sensor in wheel DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Toyota (cont'd)			
Tacoma (cont'd)			
2007-2013			
OE Sensor: Toyota - 4260704010, 4260706011			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor	28360	35	4
Sensor; W/Steel Wheels; W/40 Deg. Angled Valve Sensor	28380	35	4
Service Pack	20032	35	4
2014			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor	28360	35	4
Service Pack	20032	35	4
2015			
OE Sensor: Toyota - 4260704010, 4260706011			
Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor	28360	35	4
Sensor; W/Steel Wheels; W/20 Deg. Angled Valve Sensor	28380	35	4
Service Pack	20032	35	4
Tundra			
2005			
OE Sensor: Toyota - 426070C010, 426070C020			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor	28305	35	4
Sensor; W/Steel Wheels; W/40 Deg. Angled Valve Sensor	28300	35	4
Service Pack	20031	35	4
2006			
OE Sensor: Toyota - 4260708010, 426070C010, 426070C020			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor	28305	35	4
Sensor; W/Alloy Wheels; W/TRW Sensor	28670	35	4
Sensor; W/Steel Wheels; W/40 Deg. Angled Valve Sensor	28300	35	4
Service Pack; Nov. 1 & Newer	20022	35	4
Service Pack; Oct. 31 & Older	20031	35	4

Application	Part No.	Torque in-lbs	Torque N.m.
Toyota (cont'd)			
Tundra (cont'd)			
2007			
OE Sensor: Toyota - 426070C050			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; W/Alloy Wheels; W/TRW Sensor	28670	35	4
Service Pack; W/Alloy Wheels; W/TRW Sensor	20022	35	4
2008-2011			
OE Sensor: Toyota - 4260708010, 426070C050			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; W/Alloy Wheels; W/TRW Sensor	28670	35	4
Service Pack	20022	35	4
2012			
OE Sensor: Toyota - 4260708010			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28670	35	4
Service Pack	20022	35	4
2013			
OE Sensor: Toyota - 4260708010			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; W/Alloy Wheels; W/TRW Sensor	28670	35	4
Service Pack	20022	35	4
2014			
OE Sensor: Toyota - 426070C030, 426070C040			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; W/Alloy Wheels	28670	35	4
Sensor; W/Steel Wheels	28380	35	4
Service Pack	20022	35	4
2015			
OE Sensor: Toyota - 4260708010, 426070C060			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; W/Alloy Wheels	28670	35	4
Sensor; W/Steel Wheels	28380	35	4
Service Pack	20022	35	4

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Toyota (cont'd)			
Venza			
2009-2014			
OE Sensor: Toyota - 42607-06011			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28360	35	4
Service Pack	20032	35	4
2015-2016			
OE Sensor: Toyota - 42607-06011			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28360	35	4
Service Pack	20032	35	4
Yaris			
2007			
OE Sensor: Toyota - 4260733011			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Aug. & Newer	28365	35	4
Service Pack; Aug. & Newer	20032	35	4
2008-2012			
OE Sensor: Toyota - 4260733011			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28365	35	4
Service Pack	20032	35	4
2013			
OE Sensor: Toyota - 4260706011			
EZ-Sensor	33000 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	28360	35	4
Service Pack	20032	35	4
2014			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2015			
Sensor	INDIRECT [D]		
Volkswagen			
Beetle			
2008-2010			
OE Sensor: Volkswagen - 1K0907253D			
Sensor	20088	71	8
Service Pack	20017	71	8

Application	Part No.	Torque in-lbs	Torque N.m.
Volkswagen (cont'd)			
Beetle (cont'd)			
2013-2014			
Sensor	INDIRECT [D]		
CC			
2009-2011			
OE Sensor: Volkswagen - 1K0907253D			
Sensor	20088	71	8
Service Pack	20017	71	8
2012-2014			
OE Sensor: Volkswagen - 3AA-907-275			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminum valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20088	71	8
Service Pack	20017	71	8
2015-2016			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminum valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Eos			
2007-2016			
OE Sensor: Volkswagen - 1K0907253D			
Sensor	20088	71	8
Service Pack	20017	71	8
Golf			
2006			
Sensor	20088	71	8
Service Pack	20017	71	8
2010			
OE Sensor: Volkswagen - 1K0907253D			
Sensor	20088	71	8
Service Pack	20017	71	8
2013-2015			
Sensor	INDIRECT [D]		
GTI			
2006-2007			
OE Sensor: Volkswagen - 1K0907253D			
Sensor; W/16" Or 17" Wheels	20088	71	8
Service Pack; W/16" Or 17" Wheels	20017	71	8
2008-2010			
OE Sensor: Volkswagen - 1K0907253D			
Sensor	20088	71	8
Service Pack	20017	71	8
2013-2015			
Sensor	INDIRECT [D]		
Jetta			
2006-2007			
OE Sensor: Volkswagen - 1K0907253D			
Sensor	20088	71	8
Service Pack	20017	71	8

A-Programming Tool Required C-20018 and 20008 are interchangeable. D-Indirect TPMS system. No sensor in wheel DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Volkswagen (cont'd)			
Jetta (cont'd)			
2008-2009			
OE Sensor: Volkswagen - 1K0907253D			
Sensor	20088	71	8
Sensor; exc GLI	20088	71	8
Service Pack	20017	71	8
2010			
OE Sensor: Volkswagen - 1K0907253D			
Sensor	20088	71	8
Service Pack	20017	71	8
2013-2015			
Sensor	INDIRECT [D]		
Passat			
2006-2008			
OE Sensor: Volkswagen - 1K0907253D			
Sensor; W/16" Or 17" Wheels	20088	71	8
Service Pack; W/16" Or 17" Wheels	20017	71	8
2009-2010			
OE Sensor: Volkswagen - 1K0907253D			
Sensor	20088	71	8
Service Pack	20017	71	8
2013-2015			
Sensor	INDIRECT [D]		
Phaeton			
2002-2003			
EZ-Sensor	33100 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
2004-2006			
OE Sensor: Volkswagen - 4D0907275C, 4F0907275B			
EZ-Sensor	33100 [A]	11.5	1.3
	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Includes Transmitter Only; W/315 MHz			
Sensor	20077	35	4
Sensor; Includes Transmitter Only; W/433 MHz			
Sensor	20078	35	4
Service Pack; Does Not Include Valve; W/315 MHz Sensor	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
R32			
2008			
OE Sensor: Volkswagen - 1K0907253D			
Sensor	20088	71	8
Service Pack	20017	71	8
Rabbit			
2006-2007			
OE Sensor: Volkswagen - 1K0907253D			
Sensor; W/15" Wheels	20088	71	8
Service Pack; W/15" Wheels	20017	71	8

Application	Part No.	Torque in-lbs	Torque N.m.
Volkswagen (cont'd)			
Rabbit (cont'd)			
2008-2009			
OE Sensor: Volkswagen - 1K0907253D			
Sensor	20088	71	8
Service Pack	20017	71	8
Routan			
2009-2010			
OE Sensor: Volkswagen - 7B0-907-253, 7B0-907-253A			
Sensor	28434 [E]	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2011-2013			
OE Sensor: Chrysler - 56029398AB; Volkswagen - 7B0-907-253B, 7B0-907-253C			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminum valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20398	11.5	1.3
Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2012-2013			
EZ-Sensor	33200 [A]	11.5	1.3
2014			
EZ-Sensor	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminum valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Service Pack	20398	11.5	1.3
2015			
Service Pack	INDIRECT [D]		
Tiguan			
2009-2010			
OE Sensor: Volkswagen - 1K0907253D			
Sensor	20088	71	8
Service Pack	20017	71	8
2011-2012			
OE Sensor: Volkswagen - 1K0907253D			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminum valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	20088	71	8
Service Pack	20017	71	8
2013			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminum valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
2014-2015			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminum valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor	INDIRECT [D]		
2016			
EZ-Sensor	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminum valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3

A-Programming Tool Required C-20018 and 20008 are interchangeable. D-Indirect TPMS system. No sensor in wheel DB-Replaces 33000,33100 & 33200
E-Supercedes the 28155

Application	Part No.	Torque in-lbs	Torque N.m.
Volkswagen (cont'd)			
Touareg			
2001-2003			
EZ-Sensor	33100 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
2004-2006			
OE Sensor: Volkswagen - 4F0907275B			
EZ-Sensor	33100 [A]	11.5	1.3
	33200 [A]	11.5	1.3
	33500 [A, DB]	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve	34000	62	7
EZ-Sensor Service Pack; Rubber Valve	20018 [C]	11.5	1.3
Sensor; Includes Transmitter Only; W/433 MHz Sensor	20078	35	4
Service Pack; Does Not Include Valve	20023	62	7
Service Pack; W/43mm Silver Insert	20037	62	7
Service Pack; W/48mm Green Insert	20038	62	7
Service Pack; W/49mm Black Insert	20039	62	7
Service Pack; W/51mm Orange Insert	20040	62	7
2007			
Service Pack; Does Not Include Valve	20023	62	7
Service Pack; W/43mm Silver Insert	20037	62	7
Service Pack; W/48mm Green Insert	20038	62	7
Service Pack; W/49mm Black Insert	20039	62	7
Service Pack; W/51mm Orange Insert	20040	62	7
2008-2009			
OE Sensor: Volkswagen - 4F0907275B			
Sensor; Includes Transmitter Only	20078	35	4
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
2010			
OE Sensor: Volkswagen - 4F0907275D			
Sensor; Includes Transmitter Only	20103	35	4
Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
2011-2013			
OE Sensor: Volkswagen - 7P0907275, 7P0907275A			
Sensor; W/315 MHz Sensor; Includes Transmitter Only	20077	35	4
Sensor; W/433 MHz Sensor; Includes Transmitter Only	20103	35	4
Service Pack; Does Not Include Valve; W/315 MHz Sensor	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4

Application	Part No.	Torque in-lbs	Torque N.m.
Volkswagen (cont'd)			
Touareg (cont'd)			
2014-2016			
OE Sensor: Volkswagen - 7P0907275			
Sensor; W/433 MHz Sensor; Includes Transmitter Only	20103	35	4
Service Pack; Does Not Include Valve; W/315 MHz Sensor	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert	20040	35	4
Volvo			
C30,C70,S40			
2007-2013			
OE Sensor: Volvo - 312802970, 313020960			
Sensor	20097	71	8
S60,S80			
2004-2005			
OE Sensor: Volvo - 86517000			
Sensor	20156	44	5
Sensor; W/315 MHz Sensor	20156	44	5
Service Pack	20010	44	5
Service Pack; W/315 MHz Sensor	20010	44	5
2006-2009			
OE Sensor: Volvo - 307489910, 312009230, 86517000			
Sensor	20156	44	5
Service Pack	20010	44	5
2007-2009			
OE Sensor: Volvo - 312802970			
Sensor	20097	71	8
2010-2014			
OE Sensor: Volvo - 313020960			
Sensor	20097	71	8
V50			
2005-2011			
OE Sensor: Volvo - 312802970, 313020960			
Sensor	20097	71	8
V70			
2004-2007			
OE Sensor: Volvo - 307489910, 86517000			
Sensor; W/315 MHz Sensor	20156	44	5
Service Pack; W/315 MHz Sensor	20010	44	5
2008-2010			
OE Sensor: Volvo - 312802970, 313020960			
Sensor	20097	71	8
XC60			
2010-2014			
OE Sensor: Volvo - 313020960			
Sensor	20097	71	8
2015			
Sensor	INDIRECT [D]		

A-Programming Tool Required C-20018 and 20008 are interchangeable. D-Indirect TPMS system. No sensor in wheel DB-Replaces 33000,33100 & 33200

Application	Part No.	Torque in-lbs	Torque N.m.
Volvo (cont'd)			
XC70			
2004-2007			
OE Sensor: Volvo - 307489910, 86517000			
Sensor; W/315 MHz Sensor.	20156	44	5
Service Pack; W/315 MHz Sensor.	20010	44	5
2008-2014			
OE Sensor: Volvo - 312802970, 313020960			
Sensor.	20097	71	8
XC90			
2004			
OE Sensor: Volvo - 86517000			
Sensor.	20156	44	5
Service Pack.	20010	44	5
2005-2007			
OE Sensor: Volvo - 307489910, 86517000			
Sensor; W/315 MHz Sensor.	20156	44	5
Service Pack; W/315 MHz Sensor.	20010	44	5
2008-2011			
OE Sensor: Volvo - 31200923			
Sensor; W/315 MHz Sensor.	20156	44	5
Service Pack.	20010	44	5
2012-2014			
OE Sensor: Volvo - 31200923			
Sensor.	28362	11.5	1.3
Service Pack.	20008 C	11.5	1.3
2015			
EZ-Sensor.	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminum valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
Sensor.	28362	11.5	1.3
Service Pack.	20008 C	11.5	1.3
2016			
EZ-Sensor.	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminum valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
VPG			
MV-1			
2011			
OE Sensor: Ford Motor Company - 9L3Z1A189A			
Sensor.	20315	11.5	1.3
Service Pack; Rubber Valve.	20018 C	11.5	1.3
2012			
OE Sensor: Ford Motor Company - 9L3Z1A189A			
EZ-Sensor.	33000 A	11.5	1.3
	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
Sensor.	20315	11.5	1.3
Service Pack; Rubber Valve.	20018 C	11.5	1.3
VPG (cont'd)			
MV-1 (cont'd)			
2013-2016			
OE Sensor: Ford Motor Company - 9L3Z1A189A			
EZ-Sensor.	33500 A, DB	11.5	1.3
EZ-Sensor Service Pack; Aluminium Valve.	34000	62	7
EZ-Sensor Service Pack; Rubber Valve.	20018 C	11.5	1.3
Sensor.	20315	11.5	1.3
Service Pack; Rubber Valve.	20018 C	11.5	1.3

A-Programming Tool Required C-20018 and 20008 are interchangeable. DB-Replaces 33000,33100 & 33200

Numerical Listing

Sensor
20028 (433 MHz)

Chrysler; 300M; 2002-2004
Chrysler; Concorde; 2002-2004
Chrysler; Crossfire; 2004
Chrysler; Crossfire; 2005
Chrysler; Crossfire; 2006-2008
Chrysler; Intrepid; 2002-2004
Chrysler; Pacifica; 2004; OEM Part No. 52088990AC
Chrysler; Prowler; 2002
Chrysler; Town & Country; 2002-2003
Chrysler; Voyager; 2002-2003
Dodge; Caravan; 2002-2003
Dodge; Grand Caravan; 2002-2003
Dodge; Intrepid; 2002-2004
Dodge; Viper; 2003-2006
Dodge; Viper; 2008-2010
Isuzu; Rodeo; 2004
Jeep; Grand Cherokee; 2002-2004
Jeep; Liberty; 2002-2004
Mitsubishi; Endeavor; 2004-2005
Mitsubishi; Endeavor; 2006; Aug. & Older
Mitsubishi; Galant; 2004-2006

20034 (315 MHz)

Mitsubishi; Eclipse; 2006-2007; W/Alloy Wheels
Mitsubishi; Eclipse; 2008-2010
Mitsubishi; Eclipse; 2011
Mitsubishi; Endeavor; 2006; Sept. 1 & Newer
Mitsubishi; Endeavor; 2007
Mitsubishi; Endeavor; 2008
Mitsubishi; Endeavor; 2010
Mitsubishi; Endeavor; 2011; W/Alloy Wheels
Mitsubishi; Galant; 2007-2009; W/Alloy Wheels
Mitsubishi; Galant; 2010-2012; W/Alloy Wheels
Mitsubishi; Montero; 2003-2006
Mitsubishi; Montero Sport; 2003-2004

Sensor
20064 (315 MHz)

Infiniti; FX35; 2003-2006
Infiniti; FX35; 2007; Jun. & Older
Infiniti; FX45; 2003-2006
Infiniti; FX45; 2007; Jun. & Older
Infiniti; G35; 2003; Jun. & Newer
Infiniti; G35; 2004-2006
Infiniti; M35; 2006-2007
Infiniti; M45; 2003-2004
Infiniti; M45; 2006-2007
Infiniti; Q45; 2003-2005
Infiniti; Q45; 2006; Jul. & Older
Infiniti; QX4; 2003
Nissan; 350Z; 2003-2006
Nissan; Frontier; 2003-2004
Nissan; Murano; 2003-2006
Nissan; Pathfinder; 2003
Nissan; Pathfinder; 2004; Exc. Armada; Jul. & Older
Nissan; Xterra; 2003-2004

20069 (315 MHz)

Infiniti; QX56; 2004
Infiniti; QX56; 2005-2006; W/Steel Wheels
Nissan; Armada; 2005-2006; W/Steel Wheels
Nissan; Frontier; 2005-2007; W/Steel Wheels
Nissan; Pathfinder; 2004; Armada
Nissan; Pathfinder; 2004; Exc. Armada; Aug. & Newer
Nissan; Quest; 2004
Nissan; Quest; 2005-2006; W/Steel Wheels
Nissan; Titan; 2004
Nissan; Titan; 2005; Mar. & Older
Nissan; Xterra; 2006; Submodel X

20076 (315 MHz)

Cadillac; STS; 2005; OEM Part No. 25758220
Cadillac; STS; 2006-2008
Cadillac; XLR; 2004; OEM Part No. 25758220
Cadillac; XLR; 2005-2009
Chevrolet; Corvette; 2005-2009

Numerical Listing

Sensor
20077 (433 MHz)

Audi; A6; 2011; Includes Transmitter Only
Audi; A6 Quattro; 2011; Includes Transmitter Only
Audi; A8; 2006-2011; Includes Transmitter Only
Audi; A8 Quattro; 2003; Includes Transmitter Only; Chassis No. 4E3000001 & After
Audi; A8 Quattro; 2004-2011; Includes Transmitter Only
Audi; Q7; 2011; Includes Transmitter Only
Audi; RS6; 2003; Includes Transmitter Only
Audi; S6; 2011; Includes Transmitter Only
Audi; S8; 2003; Includes Transmitter Only; Chassis No. 4E3000001 & After
Audi; S8; 2004-2006; Includes Transmitter Only; Chassis No. 4E3000001 & After
Audi; S8; 2007-2008; Includes Transmitter Only
Audi; S8; 2009; Includes Transmitter Only; Chassis No. 4E3000001 & After
Audi; S8; 2015; Includes Transmitter Only; Chassis No. 4E3000001 & After
Bentley; Continental; 2003-2005; Includes Transmitter Only
Ferrari; 612 Scaglietti; 2004-2011; Includes Transmitter Only
Ferrari; F430; 2006-2007; Includes Transmitter Only
Ferrari; F430; 2008-2009; Includes Transmitter Only
Ferrari; Maranello; 1998-2006; Includes Transmitter Only
Maserati; Quattroporte; 2004-2008; Includes Transmitter Only
Porsche; 911; 2007-2009; Includes Transmiter Only
Porsche; 911; 2011; Includes Transmitter Only
Porsche; Boxster; 2011; Includes Transmitter Only
Porsche; Cayman; 2005-2007; Includes Transmitter Only
Porsche; Cayman; 2008; Includes Transmitter Only
Porsche; Cayman; 2011; Includes Transmitter Only
Volkswagen; Phaeton; 2004-2006; Includes Transmitter Only; W/315 MHz Sensor
Volkswagen; Touareg; 2011-2013; W/315 MHz Sensor; Includes Transmitter Only

20078 (433 MHz)

Audi; A3, A4,A5 & Quattro; 2002-2007; Includes Transmitter Only
Audi; A3, A4,A5 & Quattro; 2008; Includes Transmitter Only
Audi; A6; 2006-2008; Includes Transmitter Only
Audi; A6 Quattro; 2006-2008; Includes Transmitter Only
Audi; Q7; 2007-2009; Includes Transmitter Only
Audi; R8; 2008-2009; Includes Transmitter Only
Audi; RS4; 2007-2008; Includes Transmitter Only
Audi; S4; 2004-2009; Includes Transmitter Only
Audi; S6; 2007-2009; Includes Transmitter Only
Bentley; Arnage; 2008; Includes Transmitter Only
Bentley; Brooklands; 2008; Includes Transmitter Only
Bentley; Continental; 2006-2010; Includes Transmitter Only
Bentley; Mulsanne; 2009; Includes Transmitter Only
Ferrari; FF; 2011; Includes Transmitter Only
Ferrari; LaFerrari; 2014; Includes Transmitter Only
Lamborghini; Aventador; 2011; Includes Transmitter Only
Maserati; GranTurismo; 2014; Does Not Include Valve
Maserati; GranTurismo; 2015; Includes Transmitter Only
Volkswagen; Phaeton; 2004-2006; Includes Transmitter Only; W/433 MHz Sensor
Volkswagen; Touareg; 2004-2006; Includes Transmitter Only; W/433 MHz Sensor
Volkswagen; Touareg; 2008-2009; Includes Transmitter Only

Sensor
20079 (315 MHz)

Audi; A6; 2002-2004; Includes Transmitter Only
Audi; A8; 2000; Includes Transmitter Only
Audi; A8; 2001-2003; Includes Transmitter Only
Audi; A8 Quattro; 2000-2002; Includes Transmitter Only
Audi; A8 Quattro; 2003; Includes Transmitter Only; Chassis No. 4D3004999 & Before
Audi; Allroad Quattro; 2001-2005; Includes Transmitter Only
Audi; S4; 2002; Includes Transmitter Only
Audi; S4; 2003; Includes Transmitter Only
Audi; S8; 2000; Includes Transmitter Only
Audi; S8; 2001-2002; Includes Transmitter Only
Audi; S8; 2003; Includes Transmitter Only; Chassis No. 4D3004999 & Before
BMW; 325; 2001-2002; Includes Transmitter Only; W/433 MHz Sensor
BMW; 325; 2003-2006; Includes Transmitter Only
BMW; 525i; 2002; Includes Transmitter Only
BMW; 530; 2001; Includes Transmitter Only
BMW; 530; 2002; Includes Transmitter Only
BMW; 740i; 1999-2001; Includes Transmitter Only
BMW; 740iL; 1999-2000; Includes Transmitter Only
BMW; 740iL; 2001; Includes Transmitter Only
BMW; 750iL; 1999-2000; Includes Transmitter Only
BMW; 750iL; 2001; Includes Transmitter Only
BMW; 750iL; 2002; Includes Transmitter Only
Maybach; 57,62; 2003-2011; Includes Transmitter Only
Mercedes-Benz; S500; 2000; Includes Transmitter Only
Mercedes-Benz; S500; 2001; Includes Transmitter Only
Mercedes-Benz; S500; 2002-2006; Includes Transmitter Only

Numerical Listing

Sensor
20080 (433 MHz)

BMW; 320i; 2001-2002; Includes Transmitter Only; W/433 MHz Sensor
BMW; 320i; 2003-2005; Includes Transmitter Only
BMW; 323Ci; 2000; Includes Transmitter Only
BMW; 323i; 2000; Includes Transmitter Only
BMW; 323i; 2003; Includes Transmitter Only
BMW; 323i; 2006; Includes Transmitter Only
BMW; 328Ci; 2000; Includes Transmitter Only
BMW; 328i; 2000; Includes Transmitter Only; W/433 MHz Sensor
BMW; 330; 2001-2002; Includes Transmitter Only; W/433 MHz Sensor
BMW; 330; 2003-2006; Includes Transmitter Only
BMW; 525i; 2002; Includes Transmitter Only; W/433 MHz Sensor
BMW; 525i; 2003-2005; Includes Transmitter Only
BMW; 530; 2002; Includes Transmitter Only; W/433 MHz Sensor
BMW; 530; 2003-2005; Includes Transmitter Only
BMW; 540i; 2002; Includes Transmitter Only; W/433 MHz Sensor
BMW; 540i; 2003; Includes Transmitter Only
BMW; 545i; 2004-2005; Includes Transmitter Only
BMW; 645Ci; 2004-2005; Includes Transmitter Only
BMW; 740i; 1999-2001
BMW; 740iL; 1999-2000
BMW; 740iL; 2001
BMW; 745; 2002; Includes Transmitter Only; W/433 MHz Sensor
BMW; 745; 2003; Includes Transmitter Only
BMW; 745; 2004-2005; Includes Transmitter Only
BMW; 750iL; 1999-2000
BMW; 750iL; 2001
BMW; 750iL; 2002
BMW; 760i; 2004-2005; Includes Transmitter Only
BMW; 760Li; 2003; Includes Transmitter Only
BMW; Alpina B7L; 2011; Includes Transmitter Only
BMW; M; 2000-2001; Includes Transmitter Only; W/433 MHz Sensor
BMW; M; 2002; Includes Transmitter Only; W/433 MHz Sensor
BMW; M; 2003; Includes Transmitter Only
BMW; M; 2003; Includes Transmitter Only; W/433 MHz Sensor
BMW; Z8; 2003; Includes Transmitter Only; W/433 MHz Sensor

20081 (315 MHz)

BMW; X; 2011
Subaru; B9 Tribeca; 2006-2007
Subaru; Legacy; 2004-2007
Subaru; Legacy; 2008; W/16" Or 17" Wheels
Subaru; Outback; 2004-2007
Subaru; Tribeca; 2008; W/Metal Stem Clamp-in Sensor
Subaru; Tribeca; 2009; W/Metal Stem Clamp-in Sensor
Subaru; Tribeca; 2010; W/Metal Stem Clamp-in Sensor
Subaru; Tribeca; 2011; W/Metal Stem Clamp-in Sensor

Sensor
20082 (315 MHz)

Suzuki; Verona; 2005-2006

20083 (315 MHz)

BMW; 1 Series; 2008; Includes Transmitter Only
BMW; 1 Series; 2009-2010; Includes Transmitter Only
BMW; 323i; 2007-2010; Includes Transmitter Only
BMW; 325; 2007; Includes Transmitter Only
BMW; 328i; 2007-2008; Includes Transmitter Only
BMW; 328xi; 2007-2008; Includes Transmitter Only
BMW; 335d; 2009; Includes Transmitter Only
BMW; 335i; 2007-2008; Includes Transmitter Only
BMW; 335xi; 2007-2008; Includes Transmitter Only
BMW; 525i; 2006-2007; Includes Transmitter Only
BMW; 525xi; 2006-2007; Includes Transmitter Only
BMW; 528; 2008; Includes Transmitter Only
BMW; 528; 2009-2011; Includes Transmitter Only
BMW; 528xi; 2008; Includes Transmitter Only
BMW; 530; 2006-2007; Includes Transmitter Only
BMW; 535; 2008-2010; Includes Transmitter Only
BMW; 535; 2011; Includes Transmitter Only
BMW; 535xi; 2008; Includes Transmitter Only
BMW; 540i; 2008-2011
BMW; 550; 2006-2011; Includes Transmitter Only
BMW; 650; 2006-2010; Includes Transmitter Only
BMW; 750; 2006-2010; Includes Transmitter Only
BMW; 750; 2011; Includes Transmitter Only
BMW; 760i; 2006; Includes Transmitter Only
BMW; 760Li; 2004-2008; Includes Transmitter Only
BMW; 760Li; 2010; Includes Transmitter Only
BMW; Alpina B7; 2007-2008; Includes Transmitter Only
BMW; M; 2004-2010; Includes Transmitter Only
BMW; M; 2011-2012; Includes Transmitter Only
BMW; M; 2013; Includes Transmitter Only
BMW; X; 2005-2007; Includes Transmitter Only
BMW; X; 2008-2010; Includes Transmitter Only
BMW; X; 2011; Includes Transmitter Only
BMW; Z4; 2003-2010; Includes Transmitter Only
BMW; Z4; 2011; Includes Transmitter Only
Mini; Cooper; 2008-2009; Includes Transmitter Only

Numerical Listing

Sensor
20084 (433 MHz)

Ferrari; Enzo; 2003-2004; Includes Transmitter Only

20085 (315 MHz)

Hyundai; Entourage; 2007-2009; Includes Transmitter Only
Hyundai; Santa Fe; 2007; Includes Transmitter Only
Hyundai; Santa Fe; 2008; Includes Transmitter Only
Hyundai; Veracruz; 2006-2007; Includes Transmitter Only
Hyundai; Veracruz; 2008; Includes Transmitter Only
Kia; Sedona; 2006-2008; Includes Transmitter Only

20086 (315 MHz)

Hyundai; Azera; 2006; Includes Transmitter Only
Hyundai; Azera; 2007-2012; Includes Transmitter Only
Hyundai; Azera; 2013
Hyundai; Elantra; 2007-2009; Includes Transmitter Only
Hyundai; Elantra; 2010; exc Touring; Includes Transmitter Only
Hyundai; Elantra; 2011; exc Touring; Includes Transmitter Only
Hyundai; Elantra; 2012; exc Touring; W/Transmitter Only
Hyundai; Elantra; 2013; W/Transmitter Only
Hyundai; Elantra Coupe; 2013; W/Transmitter Only
Hyundai; Santa Fe; 2008; Includes Transmitter Only
Hyundai; Santa Fe; 2009; Includes Transmitter Only
Hyundai; Veracruz; 2008
Hyundai; Veracruz; 2009-2012; Includes Transmitter Only
Kia; Magentis; 2008; Includes Transmitter Only
Kia; Magentis; 2009; Includes Transmitter Only
Kia; Magentis; 2010; Includes Transmitter Only
Kia; Optima; 2006-2010; Includes Transmitter Only
Kia; Rio; 2015-2017
Kia; Rio5; 2015-2016
Kia; Rondo; 2007-2011; Includes Transmitter Only
Kia; Sedona; 2009-2012; Includes Transmitter Only

Sensor
20087 (315 MHz)

Suzuki; Grand Vitara; 2007-2013
Suzuki; SX4; 2007-2013
Suzuki; SX4 Crossover; 2012
Suzuki; XL-7; 2005-2006

20088 (315 MHz)

Audi; A3, A4,A5 & Quattro; 2008
Audi; A3, A4,A5 & Quattro; 2009-2012
Audi; Q5; 2009-2012
Audi; S4; 2010-2011
Audi; S5; 2008-2012
Audi; TT; 2008-2009
Audi; TT Quattro; 2008-2009
Volkswagen; Beetle; 2008-2010
Volkswagen; CC; 2009-2011
Volkswagen; CC; 2012-2014
Volkswagen; Eos; 2007-2016
Volkswagen; Golf; 2006
Volkswagen; Golf; 2010
Volkswagen; GTI; 2006-2007; W/16" Or 17" Wheels
Volkswagen; GTI; 2008-2010
Volkswagen; Jetta; 2006-2007
Volkswagen; Jetta; 2008
Volkswagen; Jetta; 2008; exc GLI
Volkswagen; Jetta; 2009
Volkswagen; Jetta; 2009; exc GLI
Volkswagen; Jetta; 2010
Volkswagen; Passat; 2006-2008; W/16" Or 17" Wheels
Volkswagen; Passat; 2009-2010
Volkswagen; R32; 2008
Volkswagen; Rabbit; 2006-2007; W/15" Wheels
Volkswagen; Rabbit; 2008-2009
Volkswagen; Tiguan; 2009-2010
Volkswagen; Tiguan; 2011-2012

Numerical Listing

Sensor
20089 (315 MHz)

Dodge; Sprinter; 2007-2009
Freightliner; Sprinter; 2007-2008
Freightliner; Sprinter; 2013
Mercedes-Benz; Sprinter 2500; 2010
Mercedes-Benz; Sprinter 2500; 2011-2012
Mercedes-Benz; Sprinter 3500; 2010-2012

20090 (315 MHz)

Jaguar; Jaguar; 2004-2012; W/315 MHz Sensor
Land Rover; LR2; 2008-2015
Land Rover; LR3; 2006-2009; W/315 MHz Sensor
Land Rover; LR4; 2010-2011; W/315 MHz Sensor
Land Rover; LR4; 2012-2014
Land Rover; Range Rover; 2006-2011; W/315 MHz Sensor
Land Rover; Range Rover; 2012-2014
Land Rover; Range Rover Evoque; 2012-2015
Land Rover; Range Rover Sport; 2006-2011; W/315 MHz Sensor
Land Rover; Range Rover Sport; 2012-2014

20091 (433 MHz)

Jaguar; Jaguar; 2004-2012; W/433 MHz Sensor
Land Rover; LR3; 2006-2009; W/433 MHz Sensor
Land Rover; LR4; 2010-2011; W/433 MHz Sensor
Land Rover; Range Rover; 2006-2011; W/433 MHz Sensor
Land Rover; Range Rover Sport; 2006-2011; W/433 MHz Sensor

Sensor
20092 (315 MHz)

Hyundai; Accent; 2012-2014
Hyundai; Elantra; 2010; Touring; Includes Transmitter Only
Hyundai; Elantra; 2011; Touring; Includes Transmitter Only
Hyundai; Elantra; 2012; Touring; W/Transmitter Only
Hyundai; Elantra; 2014
Hyundai; Elantra GT; 2013-2016
Hyundai; Equus; 2014-2015
Hyundai; Equus; 2016
Hyundai; Genesis Coupe; 2010-2012
Hyundai; Genesis Coupe; 2013
Hyundai; Genesis Coupe; 2014-2015
Hyundai; Genesis Coupe; 2016
Hyundai; Santa Fe; 2013
Hyundai; Santa Fe; 2014-2017
Hyundai; Sonata; 2011-2013
Hyundai; Sonata; 2014
Kia; Cadenza; 2014-2015
Kia; Cadenza; 2016
Kia; Forte; 2010-2013
Kia; Forte Koup; 2010-2013
Kia; Forte Koup; 2014
Kia; Forte5; 2012-2013
Kia; Optima; 2011-2015
Kia; Rio5; 2012
Kia; Sorento; 2011-2014
Kia; Sorento; 2015
Kia; Soul; 2010-2013

20093 (315 MHz)

Mazda; 2; 2011-2013
Mazda; 3; 2004
Mazda; 3; 2005-2012
Mazda; 3; 2013
Mazda; 5; 2006-2010
Mazda; 5; 2012-2013
Mazda; 6; 2008-2013
Mazda; CX-7; 2007-2011
Mazda; CX-9; 2007-2012
Mazda; CX-9; 2013
Mazda; MX-5 Miata; 2006-2015
Mazda; RX-8; 2004
Mazda; RX-8; 2005-2011

Numerical Listing

Sensor
20094 (433 MHz)

Mercedes-Benz; C Series; 2007
Mercedes-Benz; C Series; 2008-2009
Mercedes-Benz; CL; 2008-2009
Mercedes-Benz; CLS; 2006
Mercedes-Benz; CLS550; 2007-2011
Mercedes-Benz; E320; 2006-2009
Mercedes-Benz; E350; 2006-2009; W/315 MHz Sensor
Mercedes-Benz; E500; 2006
Mercedes-Benz; E55 AMG; 2006
Mercedes-Benz; E550; 2007-2009; W/315 MHz Sensor
Mercedes-Benz; E63 AMG; 2007-2009
Mercedes-Benz; S Series; 2010
Mercedes-Benz; S550; 2007-2010
Mercedes-Benz; S600; 2007-2010
Mercedes-Benz; S63 AMG; 2008-2010
Mercedes-Benz; S65 AMG; 2007-2010
Mercedes-Benz; SL500; 2006
Mercedes-Benz; SL55 AMG; 2006-2008
Mercedes-Benz; SL550; 2007-2009
Mercedes-Benz; SL600; 2006-2009
Mercedes-Benz; SL63 AMG; 2009
Mercedes-Benz; SL63 AMG; 2011
Mercedes-Benz; SL65 AMG; 2006-2009
Mercedes-Benz; SL65 AMG; 2011
Mercedes-Benz; SLR McLaren; 2008-2009

20095 (433 MHz)

Mercedes-Benz; E350; 2006-2009; W/433 MHz Sensor
Mercedes-Benz; E550; 2007-2009; W/433 MHz Sensor
Mercedes-Benz; GL; 2007-2009
Mercedes-Benz; GL320; 2007-2009
Mercedes-Benz; ML320; 2007-2009
Mercedes-Benz; ML350; 2006-2009
Mercedes-Benz; ML500; 2006-2007
Mercedes-Benz; ML550; 2008-2009
Mercedes-Benz; ML63 AMG; 2007-2009
Mercedes-Benz; R320; 2007-2009
Mercedes-Benz; R350; 2006-2009
Mercedes-Benz; R500; 2006-2007
Mercedes-Benz; R63 AMG; 2007

Sensor
20096 (433 MHz)

Ford; Expedition; 2003-2004
Ford; Explorer; 2002-2003; Exc. Sport
Ford; Explorer; 2004-2005
Lincoln; Aviator; 2003-2005
Lincoln; Navigator; 2003-2004
Mercury; Mountaineer; 2002-2005

20097 (433 MHz)

Volvo; C30,C70,S40; 2007-2013
Volvo; S60,S80; 2007-2009
Volvo; S60,S80; 2010-2014
Volvo; V50; 2005-2011
Volvo; V70; 2008-2010
Volvo; XC60; 2010-2014
Volvo; XC70; 2008-2014

20098 (315 MHz)

Acura; MDX, RDX; 2007-2013
Acura; TSX; 2007-2014
Honda; Pilot; 2009; W/Alloy Wheels
Honda; Pilot; 2010-2011; Exc. LX
Honda; Pilot; 2012-2015; W/Alloy Wheels

20099 (315 MHz)

Honda; Accord; 2008-2012
Honda; CR-V; 2007-2011
Honda; Fit; 2008

Numerical Listing

Sensor

20100 (315 MHz)

Honda; Accord Crosstour; 2010-2015
Honda; Crosstour; 2010-2015
Honda; CR-V; 2012-2013

20103 (433 MHz)

Audi; A6; 2009; Includes Transmitter Only; Quattro
Audi; A6; 2010; Includes Transmitter Only
Audi; A6 Quattro; 2010; Includes Transmitter Only
Audi; Q7; 2010; Includes Transmitter Only
Audi; Q7; 2012; Includes Transmitter Only
Audi; R8; 2010; Includes Transmitter Only
Audi; R8; 2011
Audi; R8; 2012; Includes Transmitter Only
Audi; R8; 2014-2015; Includes Transmitter Only
Audi; RS7; 2014-2016
Audi; S6; 2010; Includes Transmitter Only
Bentley; Azure; 2007-2009; Includes Transmitter Only
Bentley; Continental; 2012-2014; Includes Transmitter Only
Bentley; Continental; 2015-2016; Includes Transmitter Only
Bentley; Mulsanne; 2011-2015; Includes Transmitter Only
Bentley; Mulsanne; 2016; Includes Transmitter Only
Porsche; 911; 2010; Includes Transmitter Only
Porsche; 911; 2012
Porsche; 911; 2013-2014
Porsche; 911; 2015-2016
Porsche; 918 Spyder; 2015-2016
Porsche; Boxster; 2014-2016
Porsche; Cayenne; 2011-2013; Includes Transmitter Only
Porsche; Cayenne; 2014-2016
Porsche; Cayman; 2012-2016
Porsche; Macan; 2016
Porsche; Macan; 2017
Porsche; Panamera; 2014
Porsche; Panamera; 2015
Porsche; Panamera; 2016
Volkswagen; Touareg; 2010; Includes Transmitter Only
Volkswagen; Touareg; 2011-2013; W/433 MHz Sensor; Includes Transmitter Only
Volkswagen; Touareg; 2014-2016; W/433 MHz Sensor; Includes Transmitter Only

Sensor

20107 (315 MHz)

Cadillac; Escalade; 2005-2006
Chevrolet; Silverado Series; 2005-2006
Chevrolet; Silverado Series; 2007; Classic
Chevrolet; Suburban; 2005-2006
Chevrolet; Tahoe; 2005-2006
GMC; Sierra Series; 2005-2006
GMC; Sierra Series; 2007; Classic
GMC; Yukon; 2005-2006

20115 (315 MHz)

Cadillac; Escalade; 2004
Chevrolet; Silverado Series; 2004
Chevrolet; Suburban; 2004
Chevrolet; Tahoe; 2004
GMC; Sierra Series; 2004
GMC; Yukon; 2004

20116 (315 MHz)

Buick; Rainier; 2006-2007; OEM Part No. 25774006
Cadillac; CTS; 2004-2007
Cadillac; SRX; 2004-2006
Chevrolet; SSR; 2006; OEM Part No. 25774006
Chevrolet; Trailblazer; 2006-2009; OEM Part No. 25774006
GMC; Envoy; 2006
GMC; Envoy; 2007-2009
Isuzu; Ascender; 2006-2008
Saab; 9-7x; 2005-2009

Numerical Listing

Sensor

20117 (315 MHz)

Cadillac; DeVille; 2001-2005
Cadillac; Seville; 2001-2004
Chevrolet; Corvette; 2001-2004

20131 (315 MHz)

Chevrolet; Colorado; 2007-2012
GMC; Canyon; 2007-2012
Hummer; H3; 2006-2010
Hummer; H3T; 2009-2010
Isuzu; i-290; 2007-2008
Isuzu; i-370; 2007-2008
Pontiac; Montana; 2009

20135 (315 MHz)

Ford; Expedition; 2005-2006
Ford; Freestar; 2004-2005; W/Aluminium Valve Stem
Lincoln; Navigator; 2005-2006
Mercury; Monterey; 2004-2005

Sensor

20153 (315 MHz)

Buick; Allure; 2009
Buick; Enclave; 2009-2015
Buick; Enclave; 2016
Buick; Enclave; 2017
Buick; LaCrosse; 2009
Buick; Lucerne; 2007-2011
Cadillac; CTS; 2008
Cadillac; CTS; 2009-2011; OEM Part No. 25920615; Exc. CTS V
Cadillac; CTS; 2012; OEM Part No. 25920615; Exc. CTS V
Cadillac; CTS; 2013; OEM Part No. 25920615; Exc. CTS V
Cadillac; DTS; 2007-2011
Cadillac; Escalade; 2007; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem
Cadillac; Escalade; 2008; OEM Part No. 25799331; OEM Part No. 15922396
Cadillac; Escalade; 2009-2011
Cadillac; Escalade; 2012-2013
Cadillac; SRX; 2007-2009
Cadillac; STS; 2009; OEM Part No. 25920615; Exc. STS V
Cadillac; STS; 2010; OEM Part No. 15922396; OEM Part No. 25920615
Cadillac; STS; 2011
Chevrolet; Avalanche; 2007; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem
Chevrolet; Avalanche; 2008; OEM Part No. 25799331; OEM Part No. 15922396
Chevrolet; Avalanche; 2009-2013
Chevrolet; Aveo; 2007; Hatchback
Chevrolet; Aveo; 2008-2011
Chevrolet; Aveo5; 2007; Hatchback
Chevrolet; Aveo5; 2008-2011
Chevrolet; Captiva Sport; 2012-2013
Chevrolet; Cobalt; 2008; Snap-In Style Only; W/Rubber Valve Stem
Chevrolet; Cobalt; 2009; Snap-In Style Only; W/Rubber Valve Stem
Chevrolet; Express; 2010-2015
Chevrolet; Express; 2016
Chevrolet; Express; 2017
Chevrolet; HHR; 2008-2009; Snap-In Style Only; W/Rubber Valve Stem
Chevrolet; HHR; 2011
Chevrolet; Impala; 2007; Snap-In Style Only; W/Rubber Valve Stem
Chevrolet; Impala; 2008-2013
Chevrolet; Malibu; 2008; Snap-In Style Only; W/Rubber Valve Stem
Chevrolet; Malibu; 2009
Chevrolet; Malibu; 2011-2012
Chevrolet; Monte Carlo; 2007; Snap-In Style Only; W/Rubber Valve Stem
Chevrolet; Silverado Series; 2007; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem; Exc. Classic
Chevrolet; Silverado Series; 2008
Chevrolet; Silverado Series; 2008; W/Single Rear Wheels
Chevrolet; Silverado Series; 2009
Chevrolet; Silverado Series; 2009; W/Single Rear Wheels
Chevrolet; Silverado Series; 2010
Chevrolet; Silverado Series; 2010; W/Single Rear Wheels
Chevrolet; Silverado Series; 2011
Chevrolet; Silverado Series; 2011; W/Single Rear Wheels
Chevrolet; Silverado Series; 2012
Chevrolet; Silverado Series; 2012; W/Single Rear Wheels
Chevrolet; Silverado Series; 2013; W/Single Rear Wheels
Chevrolet; Suburban; 2007; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem
Chevrolet; Suburban; 2008-2014
Chevrolet; Tahoe; 2007; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem

Numerical Listing

Chevrolet; Tahoe; 2008-2013
Chevrolet; Traverse; 2009-2015
Chevrolet; Traverse; 2016
Chevrolet; Traverse; 2017
GMC; Acadia; 2009-2015
GMC; Acadia; 2016
GMC; Acadia; 2017
GMC; Savana Series; 2010-2015
GMC; Savana Series; 2016
GMC; Savana Series; 2017
GMC; Sierra Series; 2007; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem; Exc. Classic
GMC; Sierra Series; 2008
GMC; Sierra Series; 2008; W/Single Rear Wheels
GMC; Sierra Series; 2009
GMC; Sierra Series; 2009; W/Single Rear Wheels
GMC; Sierra Series; 2010
GMC; Sierra Series; 2010; W/Single Rear Wheels
GMC; Sierra Series; 2011
GMC; Sierra Series; 2011; W/Single Rear Wheels
GMC; Sierra Series; 2012
GMC; Sierra Series; 2012; W/Single Rear Wheels
GMC; Sierra Series; 2013; W/Single Rear Wheels
GMC; Yukon; 2007; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem
GMC; Yukon; 2008-2013
Hummer; H2; 2008-2009
Pontiac; G Series; 2008
Pontiac; G Series; 2009-2010
Pontiac; Grand Prix; 2008; Snap-In Style Only; W/Rubber Valve Stem
Pontiac; Wave; 2008
Saturn; Aura; 2008-2009
Saturn; Outlook; 2009-2010
Saturn; Vue; 2007-2010
Suzuki; Forenza; 2007-2008
Suzuki; Reno; 2007-2008

20154 (433)

Buick; LaCrosse; 2017; Exc. ZL1
Cadillac; CT6; 2016-2017; Exc. ZL1
Chevrolet; Camaro; 2016; Exc. ZL1
Chevrolet; Camaro; 2017; Exc. ZL1
Chevrolet; Cruze; 2017; Exc. ZL1
Chevrolet; Malibu; 2016
Chevrolet; Malibu; 2017
Chevrolet; Volt; 2017; Exc. ZL1

Sensor

20156 (315 MHz)

Volvo; S60,S80; 2004
Volvo; S60,S80; 2004; W/315 MHz Sensor
Volvo; S60,S80; 2005
Volvo; S60,S80; 2005; W/315 MHz Sensor
Volvo; S60,S80; 2006-2009
Volvo; V70; 2004-2007; W/315 MHz Sensor
Volvo; XC70; 2004-2007; W/315 MHz Sensor
Volvo; XC90; 2004
Volvo; XC90; 2005-2007; W/315 MHz Sensor
Volvo; XC90; 2008-2011; W/315 MHz Sensor

Numerical Listing

Sensor
20158 (315 MHz)

Buick; Allure; 2007-2008
Buick; Enclave; 2008
Buick; LaCrosse; 2006
Buick; LaCrosse; 2007-2008
Cadillac; CTS; 2009-2011; OEM Part No. 15268606; CTS V; W/315 MHz Sensor
Cadillac; CTS; 2012; OEM Part No. 15268606; CTS V; W/315 MHz Sensor
Cadillac; CTS; 2013; OEM Part No. 15268606; CTS V; W/315 MHz Sensor
Cadillac; DTS; 2006
Cadillac; Escalade; 2007; Clamp-In Style Only; TRW Sensor; W/Aluminium Valve Stem
Chevrolet; Avalanche; 2007; Clamp-In Style Only; TRW Sensor; W/Aluminium Valve Stem
Chevrolet; Caprice; 2011-2013
Chevrolet; Cobalt; 2008; Clamp-In Style Only; W/Aluminium Valve Stem
Chevrolet; Corvette; 2010-2011
Chevrolet; Corvette; 2012; Z06; Base
Chevrolet; Corvette; 2013
Chevrolet; Equinox; 2007-2009
Chevrolet; Express; 2008-2009
Chevrolet; HHR; 2008-2009; Clamp-In Style Only; W/Aluminium Valve Stem
Chevrolet; Impala; 2006; W/Alloy Wheels
Chevrolet; Impala; 2007; Clamp-In Style Only; W/Aluminium Valve Stem
Chevrolet; Malibu; 2008; Clamp-In Style Only; W/Aluminium Valve Stem
Chevrolet; Monte Carlo; 2006; W/Alloy Wheels
Chevrolet; Monte Carlo; 2007; Clamp-In Style Only; W/Aluminium Valve Stem
Chevrolet; Silverado Series; 2007; Clamp-In Style Only; TRW Sensor; W/Aluminium Valve Stem; Exc. Classic
Chevrolet; Suburban; 2007; Clamp-In Style Only; TRW Sensor; W/Aluminium Valve Stem
Chevrolet; Tahoe; 2007; Clamp-In Style Only; TRW Sensor; W/Aluminium Valve Stem
Chevrolet; Uplander; 2008-2009
GMC; Acadia; 2007-2008
GMC; Savana Series; 2008-2009
GMC; Sierra Series; 2007; Clamp-In Style Only; TRW Sensor; W/Aluminium Valve Stem; Exc. Classic
GMC; Yukon; 2007; Clamp-In Style Only; TRW Sensor; W/Aluminium Valve Stem
Pontiac; G Series; 2008
Pontiac; Grand Prix; 2007
Pontiac; Grand Prix; 2008; Clamp-In Style Only; W/Aluminium Valve Stem
Pontiac; Montana; 2008
Pontiac; Solstice; 2008-2009
Pontiac; Torrent; 2007-2009
Saturn; Aura; 2007
Saturn; Outlook; 2007-2008
Saturn; Sky; 2008-2010
Suzuki; XL-7; 2007-2009

Sensor
20159 (433 MHz)

Lotus; Elise; 2008-2015
Lotus; Evora; 2010-2013
Lotus; Evora; 2015
Lotus; Exige; 2008-2015
Saab; 9-3; 2008-2011
Saab; 9-3X; 2010-2011
Saab; 9-5; 2008-2009
Saab; 9-5; 2010-2011

20161 (315 MHz)

Infiniti; QX56; 2005-2006; W/Alloy Wheels
Infiniti; QX56; 2007; Mar. & Older
Nissan; Armada; 2005-2006; W/Alloy Wheels
Nissan; Armada; 2007
Nissan; Armada; 2008; SE
Nissan; Frontier; 2005-2007; W/Alloy Wheels
Nissan; Frontier; 2008; W/Alloy Wheels
Nissan; Maxima; 2006; Jun. & Newer
Nissan; Maxima; 2007; Mar. & Older
Nissan; Pathfinder; 2005-2006
Nissan; Quest; 2005-2006; W/Alloy Wheels
Nissan; Sentra; 2007; W/Alloy Wheels
Nissan; Titan; 2005; Apr. 1 & Newer
Nissan; Titan; 2006
Nissan; Titan; 2007; Mar. & Older
Nissan; Xterra; 2005
Nissan; Xterra; 2006; Exc. Submodel X

Numerical Listing

Sensor

20213 (433 MHz)

Mercedes-Benz; B200; 2014
Mercedes-Benz; B200; 2015-2016
Mercedes-Benz; B200; 2017
Mercedes-Benz; B250; 2015
Mercedes-Benz; B250; 2016
Mercedes-Benz; B250; 2017
Mercedes-Benz; C Series; 2014-2015
Mercedes-Benz; C Series; 2016-2017
Mercedes-Benz; C250; 2014-2017
Mercedes-Benz; CLA250; 2014-2016
Mercedes-Benz; CLA250; 2017
Mercedes-Benz; CLA45 AMG; 2014-2016
Mercedes-Benz; CLA45 AMG; 2017
Mercedes-Benz; CLS550; 2014-2016
Mercedes-Benz; CLS63 AMG S; 2014-2016
Mercedes-Benz; E250; 2014-2016
Mercedes-Benz; E250; 2017
Mercedes-Benz; E350; 2014-2016
Mercedes-Benz; E350; 2017
Mercedes-Benz; E400; 2014-2016
Mercedes-Benz; E400; 2017
Mercedes-Benz; E550; 2014-2016
Mercedes-Benz; E550; 2017
Mercedes-Benz; E63 AMG; 2014-2016
Mercedes-Benz; E63 AMG; 2017
Mercedes-Benz; E63 AMG S; 2014-2016
Mercedes-Benz; E63 AMG S; 2017
Mercedes-Benz; G550; 2014-2016
Mercedes-Benz; G550; 2017
Mercedes-Benz; G63 AMG; 2014-2016
Mercedes-Benz; G63 AMG; 2017
Mercedes-Benz; GL; 2014-2016
Mercedes-Benz; GL; 2017
Mercedes-Benz; GL350; 2014-2015
Mercedes-Benz; GL350; 2016
Mercedes-Benz; GL63 AMG; 2014-2016
Mercedes-Benz; GL63 AMG; 2017
Mercedes-Benz; GLK250; 2014-2016
Mercedes-Benz; GLK250; 2017
Mercedes-Benz; GLK350; 2014-2016
Mercedes-Benz; GLK350; 2017
Mercedes-Benz; ML350; 2015
Mercedes-Benz; ML350; 2016
Mercedes-Benz; ML350; 2017
Mercedes-Benz; ML550; 2015-2016
Mercedes-Benz; ML550; 2017
Mercedes-Benz; ML63 AMG; 2014-2016
Mercedes-Benz; ML63 AMG; 2017
Mercedes-Benz; S Series; 2013
Mercedes-Benz; S Series; 2014-2016
Mercedes-Benz; S Series; 2017
Mercedes-Benz; S550; 2014-2016
Mercedes-Benz; S550; 2017
Mercedes-Benz; S600; 2014-2016
Mercedes-Benz; S600; 2017
Mercedes-Benz; S63 AMG; 2014-2016
Mercedes-Benz; S63 AMG; 2017
Mercedes-Benz; SL550; 2014-2016
Mercedes-Benz; SL63 AMG; 2014-2015
Mercedes-Benz; SL63 AMG; 2016
Mercedes-Benz; SL65 AMG; 2014-2016
Mercedes-Benz; SLK250; 2014-2016
Mercedes-Benz; SLK250; 2017
Mercedes-Benz; SLK350; 2014-2016
Mercedes-Benz; SLK350; 2017
Mercedes-Benz; SLK55 AMG; 2014
Mercedes-Benz; SLK55 AMG; 2015-2017
Mercedes-Benz; SLS AMG; 2014-2015
Mercedes-Benz; Sprinter 2500; 2014-2016
Mercedes-Benz; Sprinter 2500; 2017
Mercedes-Benz; Sprinter 3500; 2014-2016
Mercedes-Benz; Sprinter 3500; 2017
Smart; Fortwo; 2014
Smart; Fortwo; 2015-2016
Smart; Fortwo; 2017

20218 (433 MHz)

Kia; Sedona; 2015-2016
Kia; Sedona; 2017
Kia; Soul; 2014
Kia; Soul; 2015-2016

20223 (433 MHz WAL)

Chevrolet; Corvette; 2014-2015
Chevrolet; Corvette; 2016

20228 (314.9 MHz)

Chevrolet; Caprice; 2014
Chevrolet; Caprice; 2015

Numerical Listing

Sensor
20280 (315 MHz)

Ford; Edge; 2015-2016
Ford; Edge; 2017
Ford; Explorer; 2016
Ford; Explorer; 2017
Ford; F-150; 2015-2016
Ford; F-150; 2017
Ford; Mustang; 2015-2016
Ford; Mustang; 2017
Lincoln; Continental; 2017
Lincoln; Mark LT; 2015-2016
Lincoln; MKS; 2016
Lincoln; MKX; 2015-2016
Lincoln; MKX; 2017

20281 (433 MHz)

Hyundai; Sonata; 2015-2016
Hyundai; Tucson; 2015-2016

20284 (433 MHz)

Maserati; Ghibli; 2014-2016
Maserati; Quattroporte; 2014-2016

Sensor
20315 (315 MHz)

Ford; C-Max; 2012-2015
Ford; C-Max; 2016
Ford; C-Max; 2017
Ford; Edge; 2011-2014
Ford; Escape; 2009-2010
Ford; Escape; 2011
Ford; Escape; 2012-2015
Ford; Escape; 2016
Ford; Escape; 2017
Ford; E-Series Van; 2010
Ford; E-Series Van; 2010; W/Steel Wheels
Ford; E-Series Van; 2011-2013
Ford; E-Series Van; 2014-2015
Ford; E-Series Van; 2016
Ford; E-Series Van; 2017
Ford; Expedition; 2011-2015
Ford; Expedition; 2016
Ford; Expedition; 2017
Ford; Explorer; 2011-2014
Ford; Explorer; 2015
Ford; F-150; 2009-2014
Ford; F-250 Super Duty; 2011-2015
Ford; F-250 Super Duty; 2016
Ford; F-350 Super Duty; 2011-2015
Ford; F-350 Super Duty; 2016
Ford; F-450 Super Duty; 2014
Ford; F-450 Super Duty; 2015-2016
Ford; Fiesta; 2011-2015
Ford; Fiesta; 2016
Ford; Fiesta; 2017
Ford; Flex; 2011-2015
Ford; Flex; 2016
Ford; Focus; 2010
Ford; Focus; 2011
Ford; Focus; 2012-2015
Ford; Focus; 2016
Ford; Focus; 2017
Ford; Fusion; 2010-2015
Ford; Fusion; 2016
Ford; Mustang; 2010-2011
Ford; Mustang; 2012; exc Shelby GT500
Ford; Mustang; 2013; exc Shelby GT500
Ford; Mustang; 2014; exc Shelby GT500
Ford; Taurus; 2010; May & Newer
Ford; Taurus; 2011-2015
Ford; Taurus; 2016
Ford; Taurus; 2017
Ford; Transit; 2014-2015
Ford; Transit; 2016
Ford; Transit; 2017
Ford; Transit Connect; 2010-2015
Ford; Transit Connect; 2016
Ford; Transit Connect; 2017
Lincoln; Mark LT; 2013-2014
Lincoln; MKC; 2015
Lincoln; MKC; 2016
Lincoln; MKC; 2017
Lincoln; MKS; 2011-2015
Lincoln; MKT; 2011-2016
Lincoln; MKT; 2017

Numerical Listing

Lincoln; MKX; 2011-2014
Lincoln; MKZ; 2010-2015
Lincoln; MKZ; 2016
Lincoln; Navigator; 2011-2015
Lincoln; Navigator; 2016
Lincoln; Navigator; 2017
Lincoln; Town Car; 2011
Mazda; Tribute; 2009-2011
Mercury; Mariner; 2009-2011
Mercury; Milan; 2010-2011
VPG; MV-1; 2011
VPG; MV-1; 2012
VPG; MV-1; 2013-2016

20335 (315 MHz)

Chrysler; Pacifica; 2004; OEM Part No. 04727392AD
Chrysler; Pacifica; 2005
Chrysler; Town & Country; 2004-2005
Dodge; Caravan; 2004-2005
Dodge; Grand Caravan; 2004-2005

Sensor

20398 (433 MHz)

Alfa Romeo; 4C; 2012-2016
Chrysler; 300; 2010
Chrysler; 300; 2011
Chrysler; 300; 2012; W/Rubber Stem Snap-in Sensor
Chrysler; 300; 2013-2015
Chrysler; 300; 2016
Chrysler; 300; 2017
Chrysler; Town & Country; 2011-2014
Chrysler; Town & Country; 2015
Chrysler; Town & Country; 2016
Chrysler; Town & Country; 2017
Dodge; Challenger; 2010-2012; W/Rubber Stem Snap-in Sensor
Dodge; Challenger; 2013-2015; W/Rubber Stem Snap-in Sensor
Dodge; Challenger; 2016; W/Rubber Stem Snap-in Sensor
Dodge; Challenger; 2017; W/Rubber Stem Snap-in Sensor
Dodge; Charger; 2010; W/Rubber Stem Snap-in Sensor
Dodge; Charger; 2011; W/Rubber Stem Snap-in Sensor
Dodge; Charger; 2012-2015
Dodge; Charger; 2016
Dodge; Charger; 2017
Dodge; Durango; 2011-2015
Dodge; Durango; 2016
Dodge; Grand Caravan; 2011-2015
Dodge; Grand Caravan; 2016
Dodge; Grand Caravan; 2017
Dodge; Journey; 2010; OEM No. 56029398AA; Rubber Valve
Dodge; Journey; 2011-2015
Dodge; Journey; 2016
Dodge; Journey; 2017
Dodge; Ram 4500; 2010; W/Rubber Stem Snap-in Sensor
Dodge; Ram 5500; 2010; W/Rubber Stem Snap-in Sensor
Dodge; Ram Series; 2010; W/Rubber Stem Snap-in Sensor
Fiat; 500; 2012-2015
Fiat; 500; 2016
Fiat; 500; 2017
Jeep; Grand Cherokee; 2011-2015
Jeep; Wrangler; 2013-2015
Jeep; Wrangler; 2016
Jeep; Wrangler; 2017
Ram; 4500; 2012
Ram; 5500; 2012
Ram; C/V; 2012; Rubber Valve
Ram; C/V; 2013-2015
Ram; ProMaster; 2014-2015
Ram; ProMaster; 2016
Ram; ProMaster; 2017
Ram; Ram Series; 2011; W/Rubber Stem Snap-in Sensor
Ram; Ram Series; 2012-2013
Volkswagen; Routan; 2011-2013
Volkswagen; Routan; 2014

Numerical Listing

Sensor
20720 (433 MHz)

Acura; TL; 2009-2013
Acura; ZDX; 2010-2013

28004 (315 MHz)

Chrysler; Prowler; 2001
Plymouth; Prowler; 1997
Plymouth; Prowler; 1999-2001

28006 (315 MHz)

Chevrolet; Corvette; 1997-2000

28070 (315 MHz)

Kia; Forte; 2014-2015

28078 (433 MHz)

Saab; 9-3; 2003-2007
Saab; 9-5; 2003-2007
Saturn; Astra; 2008-2009

Sensor
28081 (433 MHz)

BMW; 1 Series; 2008; Includes Transmitter Only
BMW; 1 Series; 2011-2013; Includes Transmitter Only
BMW; 328i; 2009; Includes Transmitter Only
BMW; 328i; 2010-2013; Includes Transmitter Only
BMW; 328i xDrive; 2009; Includes Transmitter Only
BMW; 328i xDrive; 2010-2013; Includes Transmitter Only
BMW; 335d; 2010-2011; Includes Transmitter Only
BMW; 335i; 2009; Includes Transmitter Only
BMW; 335i; 2010-2012; Includes Transmitter Only
BMW; 335i xDrive; 2009; Includes Transmitter Only
BMW; 335i xDrive; 2010-2012; Includes Transmitter Only
BMW; 335is; 2012-2013; Includes Transmitter Only
BMW; 528; 2012-2014; Includes Transmitter Only
BMW; 528; 2015-2016
BMW; 535; 2011; Includes Transmitter Only
BMW; 535; 2012-2014; Includes Transmitter Only
BMW; 535d; 2014; Includes Transmitter Only
BMW; 535d xDrive; 2014; Includes Transmitter Only
BMW; 550; 2012-2014; Includes Transmitter Only
BMW; 640; 2012-2015; Includes Transmitter Only
BMW; 640; 2016
BMW; 650; 2012-2015; Includes Transmitter Only
BMW; 650; 2016
BMW; 740i; 2011; Includes Transmitter Only
BMW; 740i; 2012-2014; Includes Transmitter Only
BMW; 740i; 2015-2016; Includes Transmitter Only
BMW; 740Li; 2011; Includes Transmitter Only
BMW; 740Li; 2012-2016; Includes Transmitter Only
BMW; 740Li xDrive; 2013-2016; Includes Transmitter Only
BMW; 750; 2011; Includes Transmitter Only
BMW; 750; 2012-2016; Includes Transmitter Only
BMW; 760Li; 2011; Includes Transmitter Only
BMW; 760Li; 2012-2014
BMW; ActiveHybrid 3; 2013-2014
BMW; ActiveHybrid 3; 2015
BMW; ActiveHybrid 5; 2012-2014; Includes Transmitter Only
BMW; ActiveHybrid 5; 2015
BMW; ActiveHybrid 7; 2013-2015; Includes Transmitter Only
BMW; Alpina B7; 2011-2015; Includes Transmitter Only
BMW; Alpina B7 xDrive; 2011; Includes Transmitter Only
BMW; Alpina B7L xDrive; 2011; Includes Transmitter Only
BMW; M; 2011-2012; Includes Transmitter Only
BMW; M; 2013; Includes Transmitter Only
BMW; M; 2014; Includes Transmitter Only
BMW; X; 2011
BMW; X; 2011; Includes Transmitter Only
BMW; X; 2012-2014; Includes Transmitter Only
BMW; X; 2015; Includes Transmitter Only
BMW; X; 2016
BMW; Z4; 2012-2015; Includes Transmitter Only
BMW; Z4; 2016
Mini; Cooper; 2009; Includes Transmitter Only
Mini; Cooper; 2010-2013; Includes Transmitter Only
Mini; Cooper; 2014; Transmiter only
Rolls Royce; Ghost; 2011-2016
Rolls Royce; Phantom; 2012-2016
Rolls Royce; Silver Dawn; 2016
Rolls Royce; Wraith; 2014-2016

Numerical Listing

Sensor
28082 (433 MHz)

BMW; X; 1999-2004; Includes Transmitter Only
Land Rover; LR3; 2002-2005; Includes Transmitter Only
Land Rover; Range Rover; 2002; Includes Transmitter Only
Land Rover; Range Rover; 2003-2005; Includes Transmitter Only

28087 (433 MHz)

Porsche; 911; 2005-2006; Includes Transmitter Only
Porsche; 911; 2007-2009; Includes Transmitter Only
Porsche; 911; 2010; Includes Transmitter Only
Porsche; 911; 2012; Includes Transmitter Only
Porsche; Boxster; 2005-2007; Includes Transmitter Only
Porsche; Boxster; 2008-2010; Includes Transmitter Only
Porsche; Carrera GT; 2004-2005; Includes Transmitter Only
Porsche; Cayenne; 2003-2006; Includes Transmitter Only
Porsche; Cayman; 2009-2010; Includes Transmitter Only
Porsche; Cayman; 2011; Includes Transmitter Only
Porsche; Panamera; 2010; Includes Transmitter Only
Porsche; Panamera; 2011; Includes Transmitter Only

28096 (315 MHz)

Mitsubishi; i-MiEV; 2012-2016
Mitsubishi; i-MiEV; 2017
Mitsubishi; Lancer; 2008-2010
Mitsubishi; Lancer; 2011
Mitsubishi; Lancer; 2012
Mitsubishi; Lancer; 2013-2014
Mitsubishi; Lancer; 2015-2016
Mitsubishi; Mirage; 2014
Mitsubishi; Outlander; 2007-2010
Mitsubishi; Outlander; 2011-2015
Mitsubishi; Outlander; 2016
Mitsubishi; Outlander Sport; 2011-2015
Mitsubishi; RVR; 2011-2014

Sensor
28126 (433 MHz)

BMW; 228i; 2014
BMW; 228i; 2015
BMW; 320i; 2014
BMW; 320i xDrive; 2014
BMW; 328d; 2014
BMW; 328d xDrive; 2014
BMW; 328i; 2014-2016; Includes Transmitter Only
BMW; 328i GT xDrive; 2014-2016; Includes Transmitter Only
BMW; 328i xDrive; 2014-2015; Includes Transmitter Only
BMW; 335i; 2013-2014; Includes Transmitter Only
BMW; 335i GT xDrive; 2014-2015; Includes Transmitter Only
BMW; 335i xDrive; 2013-2015; Includes Transmitter Only
BMW; 428i; 2014; Includes Transmitter Only
BMW; 428i; 2015
BMW; 428i; 2016
BMW; 428i xDrive; 2014
BMW; 428i xDrive; 2015
BMW; 435i; 2014
BMW; 435i; 2015
BMW; 435i; 2016
BMW; 435i xDrive; 2014
BMW; 435i xDrive; 2015
BMW; 528; 2015-2016
BMW; 535; 2015-2016
BMW; 535d; 2015-2016
BMW; 535d xDrive; 2015-2016
BMW; 550; 2015-2016
BMW; 640; 2016
BMW; 650; 2016
BMW; 650i Gran Coupe xDrive; 2016
BMW; 750; 2015-2016; Includes Transmitter Only
BMW; 760Li; 2015
BMW; 760Li; 2016
BMW; M; 2015
BMW; M; 2015; Includes Transmitter Only
BMW; M; 2016
BMW; M; 2016; Includes Transmitter Only
BMW; X; 2015
BMW; X; 2015; Includes Transmitter Only
BMW; X; 2016
BMW; X; 2016; Includes Transmitter Only
Mini; Cooper; 2014; Includes Transmitter Only
Mini; Cooper; 2014; Transmitter only
Mini; Cooper; 2015-2016

28128 (315 MHz)



Acura; MDX, RDX; 2013-2015
Acura; RLX; 2016

Numerical Listing

Sensor
28129 (315 MHz)

Mitsubishi; Eclipse; 2006-2007; W/Steel Wheels
Mitsubishi; Eclipse; 2012; W/Steel Wheels
Mitsubishi; Endeavor; 2011; W/Steel Wheels
Mitsubishi; Galant; 2007-2009; W/Steel Wheels
Mitsubishi; Galant; 2010-2012; W/Steel Wheels

28167 (315 MHz)

Nissan; Pathfinder; 2007; OEM Part No. 40700JA01A
Nissan; Versa; 2007; OEM Part No. 40700JA01A
Nissan; Xterra; 2007; OEM Part No. 40700JA01A

28203 (315 MHz)

Subaru; Forester; 2008-2015
Subaru; Forester; 2016
Subaru; Impreza; 2008-2015
Subaru; Impreza; 2016
Subaru; Legacy; 2008; W/18" Wheels
Subaru; Legacy; 2009-2015
Subaru; Legacy; 2016
Subaru; Outback; 2008-2015
Subaru; Outback; 2016-2017
Subaru; Tribeca; 2008; W/Rubber Stem Snap-in Sensor
Subaru; Tribeca; 2009; W/Rubber Stem Snap-in Sensor
Subaru; Tribeca; 2010; W/Rubber Stem Snap-in Sensor
Subaru; Tribeca; 2011; W/Rubber Stem Snap-in Sensor
Subaru; Tribeca; 2012-2014
Subaru; WRX; 2013-2015
Subaru; WRX; 2016
Subaru; XV Crosstrek; 2013-2015
Subaru; XV Crosstrek; 2016

Sensor
28204 (315 MHz)

Infiniti; FX35; 2007; Jul. & Newer
Infiniti; FX35; 2008
Infiniti; FX45; 2007; Jul. & Newer
Infiniti; FX45; 2008
Infiniti; G35; 2007; Coupe
Infiniti; M35; 2008-2010
Infiniti; M35h; 2012
Infiniti; M37; 2011-2012
Infiniti; M45; 2008-2009
Infiniti; M45; 2010
Infiniti; M56; 2011-2012
Infiniti; Q45; 2006; Aug. & Newer
Infiniti; QX56; 2007; Apr. 1 & Newer
Infiniti; QX56; 2008-2010
Nissan; 350Z; 2007-2009
Nissan; Altima; 2006; Oct. 1 & Newer
Nissan; Altima; 2007-2010
Nissan; Altima; 2011-2012
Nissan; Armada; 2008; LE
Nissan; Armada; 2009-2011
Nissan; Armada; 2012-2015
Nissan; Armada; 2016
Nissan; Cube; 2009-2010
Nissan; Cube; 2011-2012; non-Ikey
Nissan; Frontier; 2008; W/Steel Wheels
Nissan; Frontier; 2009-2011
Nissan; Frontier; 2012-2015
Nissan; Frontier; 2016
Nissan; GT-R; 2009
Nissan; GT-R; 2010
Nissan; GT-R; 2011-2016
Nissan; GT-R; 2017
Nissan; Juke; 2011
Nissan; Juke; 2012
Nissan; Maxima; 2007; Apr. 1 & Newer
Nissan; Maxima; 2008-2010
Nissan; Maxima; 2011-2012
Nissan; Murano; 2007
Nissan; Murano; 2009
Nissan; Murano; 2010
Nissan; Murano; 2011
Nissan; Murano; 2012-2014
Nissan; NV; 2014-2015
Nissan; NV; 2016
Nissan; Pathfinder; 2007; OEM Part No. 40700JA01B
Nissan; Pathfinder; 2008-2011
Nissan; Pathfinder; 2012
Nissan; Quest; 2007-2009
Nissan; Rogue; 2008-2009
Nissan; Rogue; 2011
Nissan; Rogue; 2012
Nissan; Sentra; 2007; W/Steel Wheels
Nissan; Sentra; 2008
Nissan; Sentra; 2009-2010
Nissan; Sentra; 2011-2013
Nissan; Titan; 2007; Apr. 1 & Newer
Nissan; Titan; 2008-2011
Nissan; Titan; 2012-2015
Nissan; Versa; 2007; OEM Part No. 40700JA01B
Nissan; Versa; 2008-2010

Numerical Listing

Nissan; Versa; 2011-2012
Nissan; Xterra; 2007; OEM Part No. 40700JA01B
Nissan; Xterra; 2008-2011
Nissan; Xterra; 2012-2015
Nissan; Xterra; 2016
Suzuki; Equator; 2009-2012

Sensor

28206 (314.9 MHz)

Buick; Allure; 2010
Buick; Encore; 2013-2015
Buick; Encore; 2016
Buick; Encore; 2017
Buick; Envision; 2017
Buick; LaCrosse; 2010-2015
Buick; LaCrosse; 2016
Buick; Regal; 2011-2016
Buick; Regal; 2017
Buick; Verano; 2012-2015
Buick; Verano; 2016-2017
Cadillac; ATS; 2013; exc V
Cadillac; ATS; 2014; exc V
Cadillac; ATS; 2015; exc V
Cadillac; ATS; 2016; exc V
Cadillac; ATS; 2017; exc V
Cadillac; CTS; 2014-2015; exc V
Cadillac; CTS; 2016; exc V
Cadillac; CTS; 2017; exc V
Cadillac; ELR; 2014
Cadillac; ELR; 2015-2016
Cadillac; ELR; 2017
Cadillac; Escalade; 2014-2015
Cadillac; Escalade; 2016
Cadillac; Escalade; 2017
Cadillac; SRX; 2010-2015
Cadillac; SRX; 2016
Cadillac; XTS; 2013-2015
Cadillac; XTS; 2016
Cadillac; XTS; 2017
Chevrolet; Camaro; 2010-2011
Chevrolet; Camaro; 2012; exc ZL1; OEM Part No. 20922900; OEM Part No. 22854866
Chevrolet; Camaro; 2013-2015; Exc. ZL1
Chevrolet; Caprice; 2017
Chevrolet; Cobalt; 2010
Chevrolet; Colorado; 2015
Chevrolet; Colorado; 2016
Chevrolet; Colorado; 2017
Chevrolet; Cruze; 2011-2015
Chevrolet; Cruze; 2016
Chevrolet; Equinox; 2010-2014
Chevrolet; Equinox; 2015-2016
Chevrolet; Equinox; 2017
Chevrolet; HHR; 2010
Chevrolet; Impala; 2014-2015
Chevrolet; Impala; 2016
Chevrolet; Impala; 2017
Chevrolet; Malibu; 2010
Chevrolet; Malibu; 2013-2015
Chevrolet; Orlando; 2012-2014
Chevrolet; Orlando; 2017
Chevrolet; Silverado Series; 2014-2015; W/Single Rear Wheels
Chevrolet; Silverado Series; 2016; W/Single Rear Wheels
Chevrolet; Silverado Series; 2017; W/Single Rear Wheels
Chevrolet; Sonic; 2012-2015
Chevrolet; Sonic; 2016
Chevrolet; Sonic; 2017
Chevrolet; Spark; 2013-2015
Chevrolet; Spark; 2016

Numerical Listing

Chevrolet; Spark; 2017
Chevrolet; Suburban; 2014
Chevrolet; Suburban; 2015
Chevrolet; Suburban; 2016
Chevrolet; Suburban; 2017
Chevrolet; Tahoe; 2014-2015
Chevrolet; Tahoe; 2016
Chevrolet; Tahoe; 2017
Chevrolet; Trax; 2013-2015
Chevrolet; Trax; 2016
Chevrolet; Trax; 2017
Chevrolet; Volt; 2011-2015
Chevrolet; Volt; 2016
GMC; Canyon; 2015-2016
GMC; Canyon; 2017
GMC; Sierra Series; 2014; W/Single Rear Wheels
GMC; Sierra Series; 2015; W/Single Rear Wheels
GMC; Sierra Series; 2016; W/Single Rear Wheels
GMC; Sierra Series; 2017; W/Single Rear Wheels
GMC; Terrain; 2010-2014
GMC; Terrain; 2015
GMC; Terrain; 2016
GMC; Terrain; 2017
GMC; Yukon; 2014-2015
GMC; Yukon; 2016
GMC; Yukon; 2017
Saab; 9-4X; 2011

28210 (315 MHz)

Infiniti; EX35; 2008-2010
Infiniti; FX35; 2009-2010
Infiniti; FX50; 2009-2010
Infiniti; G35; 2007; Sedan
Infiniti; G35; 2008
Infiniti; G37; 2008-2010
Nissan; 370Z; 2009-2010

Sensor

28214 (433 MHz)

Mercedes-Benz; 550,63AMG; 2007-2009
Mercedes-Benz; C Series; 2007; Jun. & Newer
Mercedes-Benz; C Series; 2008-2009
Mercedes-Benz; C Series; 2010-2012
Mercedes-Benz; C Series; 2013
Mercedes-Benz; C250; 2012
Mercedes-Benz; C250; 2013
Mercedes-Benz; C280; 2007; Mar. & Newer
Mercedes-Benz; CLK; 2006
Mercedes-Benz; CLK350; 2006-2009
Mercedes-Benz; CLS550; 2012
Mercedes-Benz; CLS550; 2013
Mercedes-Benz; E350; 2010-2012
Mercedes-Benz; E350; 2013
Mercedes-Benz; E550; 2010-2011
Mercedes-Benz; E550; 2012-2013
Mercedes-Benz; E63 AMG; 2010-2011
Mercedes-Benz; E63 AMG; 2012-2013
Mercedes-Benz; G500; 2007; Mar. & Newer
Mercedes-Benz; G500; 2008
Mercedes-Benz; G55 AMG; 2007; Mar. & Newer
Mercedes-Benz; G55 AMG; 2008-2010
Mercedes-Benz; G55 AMG; 2011
Mercedes-Benz; G550; 2009-2010
Mercedes-Benz; G550; 2011
Mercedes-Benz; G550; 2012-2013
Mercedes-Benz; GL; 2010
Mercedes-Benz; GL; 2011
Mercedes-Benz; GL; 2012-2013
Mercedes-Benz; GL350; 2010
Mercedes-Benz; GL350; 2011
Mercedes-Benz; GL350; 2012-2013
Mercedes-Benz; GL63 AMG; 2013
Mercedes-Benz; GLK350; 2010
Mercedes-Benz; GLK350; 2011
Mercedes-Benz; GLK350; 2012
Mercedes-Benz; GLK350; 2013
Mercedes-Benz; ML350; 2010
Mercedes-Benz; ML350; 2011
Mercedes-Benz; ML350; 2012
Mercedes-Benz; ML350; 2013
Mercedes-Benz; ML450; 2010
Mercedes-Benz; ML450; 2011
Mercedes-Benz; ML550; 2010
Mercedes-Benz; ML550; 2011-2012
Mercedes-Benz; ML63 AMG; 2010
Mercedes-Benz; ML63 AMG; 2011
Mercedes-Benz; ML63 AMG; 2012-2013
Mercedes-Benz; R350; 2010
Mercedes-Benz; R350; 2011
Mercedes-Benz; R350; 2012
Mercedes-Benz; R350; 2013
Mercedes-Benz; S Series; 2011
Mercedes-Benz; S Series; 2012
Mercedes-Benz; S Series; 2013
Mercedes-Benz; S550; 2011
Mercedes-Benz; S550; 2012-2013
Mercedes-Benz; S600; 2011
Mercedes-Benz; S600; 2012-2013
Mercedes-Benz; S63 AMG; 2011

Numerical Listing

Mercedes-Benz; S63 AMG; 2012-2013
Mercedes-Benz; S65 AMG; 2011
Mercedes-Benz; S65 AMG; 2012-2013
Mercedes-Benz; SL550; 2012
Mercedes-Benz; SL550; 2013
Mercedes-Benz; SL63 AMG; 2012
Mercedes-Benz; SL63 AMG; 2013
Mercedes-Benz; SLK250; 2012
Mercedes-Benz; SLK250; 2013
Mercedes-Benz; SLK280; 2007; May & Newer
Mercedes-Benz; SLK280; 2008
Mercedes-Benz; SLK300; 2009-2011
Mercedes-Benz; SLK350; 2007; May & Newer
Mercedes-Benz; SLK350; 2008-2012
Mercedes-Benz; SLK350; 2013
Mercedes-Benz; SLK55 AMG; 2007; May & Newer
Mercedes-Benz; SLK55 AMG; 2008-2010
Mercedes-Benz; SLS AMG; 2011-2012
Mercedes-Benz; SLS AMG; 2013
Smart; Fortwo; 2008-2012
Smart; Fortwo; 2013

28291 (433 MHz)

Chrysler; 300; 2009-2010
Dodge; Challenger; 2008; OEM No. 56029400AB
Dodge; Challenger; 2009
Dodge; Challenger; 2010-2012; W/Metal Stem Clamp-in Sensor
Dodge; Charger; 2009
Dodge; Charger; 2010; W/Metal Stem Clamp-in Sensor
Dodge; Viper; 2012-2013; W/Metal Stem Clamp-in Sensor
Dodge; Viper; 2014-2015; W/Metal Stem Clamp-in Sensor
Dodge; Viper; 2016; W/Metal Stem Clamp-in Sensor
Dodge; Viper; 2017; W/Metal Stem Clamp-in Sensor

28300 (315 MHz)

Toyota; Sequoia; 2004-2007; W/Steel Wheels; W/40 Deg. Angled Valve Sensor
Toyota; Tacoma; 2005; W/40 Deg. Angled Valve Sensor; Nov. 30 & Older
Toyota; Tundra; 2005; W/Steel Wheels; W/40 Deg. Angled Valve Sensor
Toyota; Tundra; 2006; W/Steel Wheels; W/40 Deg. Angled Valve Sensor

Sensor

28305 (315 MHz)

Toyota; Sequoia; 2004; W/Alloy Wheels
Toyota; Sequoia; 2004; W/Steel Wheels; W/20 Deg. Angled Valve Sensor
Toyota; Sequoia; 2005; W/Alloy Wheels
Toyota; Sequoia; 2005; W/Steel Wheels; W/20 Deg. Angled Valve Sensor
Toyota; Sequoia; 2006; W/Alloy Wheels
Toyota; Sequoia; 2006; W/Steel Wheels; W/20 Deg. Angled Valve Sensor
Toyota; Sequoia; 2007; W/Alloy Wheels
Toyota; Sequoia; 2007; W/Steel Wheels; W/20 Deg. Angled Valve Sensor
Toyota; Tacoma; 2005; W/20 Deg. Angled Valve Sensor; Nov. 30 & Older
Toyota; Tundra; 2005; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor
Toyota; Tundra; 2006; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor

Numerical Listing

Sensor
28308 (315 MHz)

Chrysler; 200; 2011
Chrysler; 200; 2012; Rubber Valve
Chrysler; 200; 2013-2014
Chrysler; 300; 2005-2006
Chrysler; 300; 2007; Use until depleted-superseded by 20066
Chrysler; Aspen; 2007-2011
Chrysler; Crossfire; 2005
Chrysler; Pacifica; 2006-2007
Chrysler; Pacifica; 2008
Chrysler; PT Cruiser; 2008-2010
Chrysler; Sebring; 2007-2009
Chrysler; Sebring; 2010
Chrysler; Town & Country; 2006-2007
Chrysler; Town & Country; 2008; Can also use 20066 until depleted
Dodge; Avenger; 2008-2009
Dodge; Avenger; 2010-2012
Dodge; Avenger; 2013-2014
Dodge; Caliber; 2007-2010
Dodge; Caliber; 2011-2012
Dodge; Caravan; 2006-2007
Dodge; Charger; 2006-2007
Dodge; Durango; 2007
Dodge; Durango; 2008
Dodge; Durango; 2009
Dodge; Grand Caravan; 2006-2007
Dodge; Magnum; 2005-2007
Dodge; Nitro; 2007-2008
Dodge; Nitro; 2009-2011
Jeep; Commander; 2006-2007
Jeep; Compass; 2007-2010
Jeep; Compass; 2011
Jeep; Compass; 2012-2015
Jeep; Compass; 2016
Jeep; Compass; 2017
Jeep; Grand Cherokee; 2005-2007
Jeep; Liberty; 2005-2008
Jeep; Liberty; 2009; W/315 MHz Snap-in Sensor
Jeep; Liberty; 2010-2012
Jeep; Patriot; 2007-2010
Jeep; Patriot; 2011-2012
Jeep; Patriot; 2013-2015; W/315 MHz
Jeep; Patriot; 2016; W/315 MHz
Jeep; Patriot; 2017; W/315 MHz
Jeep; Wrangler; 2007-2008
Jeep; Wrangler; 2011
Jeep; Wrangler; 2012
Suzuki; Kizashi; 2010-2012

Sensor
28310 (315 MHz)

Lexus; SC430; 2002-2005; W/White I.D. Mark
Lexus; SC430; 2006; W/White I.D. Mark; Jul. & Older

28315 (315 MHz)

Lexus; SC430; 2002-2005; W/Blue I.D. Mark
Lexus; SC430; 2006; W/Blue I.D. Mark; Jul. & Older

28320 (315 MHz)

Lexus; SC430; 2002-2005; W/Red I.D. Mark
Lexus; SC430; 2006; W/Red I.D. Mark; Jul. & Older

28325 (315 MHz)

Lexus; SC430; 2002-2005; W/Gold I.D. Mark
Lexus; SC430; 2006; W/Gold I.D. Mark; Jul. & Older

Numerical Listing

Sensor

28335 (315 MHz)

Lexus; GS300; 2006
Lexus; GS430; 2005
Lexus; GS430; 2006; Jun. & Older
Lexus; GX470; 2006; Feb. & Newer; W/O Valve Cap
Lexus; IS250; 2006; Mar. & Older
Lexus; IS350; 2006; Mar. & Older
Toyota; 4Runner; 2006; OEM Part No. 4260730030

28342 (315 MHz)

Nissan; NV; 2012
Nissan; NV; 2013-2015
Nissan; NV; 2016

28345 (315 MHz)

Lexus; GX470; 2004-2005
Lexus; GX470; 2006; Jan. 31 & Older
Lexus; HS250h; 2010-2012
Toyota; 4Runner; 2003-2005
Toyota; 4Runner; 2006; OEM Part No. 4260735010

28355 (315 MHz)

Toyota; Tacoma; 2005; W/20 Deg. Angled Valve Sensor; Dec. 1 & Newer
Toyota; Tacoma; 2006; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor; Jul. & Older

Sensor

28360 (315 MHz)

Pontiac; Vibe; 2008-2010
Scion; FR-S; 2013
Scion; FR-S; 2014-2016
Scion; iM; 2015-2016
Subaru; BRZ; 2013-2014
Subaru; BRZ; 2015-2016
Toyota; Avalon; 2006; Aug. & Newer
Toyota; Avalon; 2007-2014
Toyota; Avalon; 2015-2016
Toyota; Camry; 2007-2011; Models made in USA; OEM Part No. 4260706011
Toyota; Camry; 2012-2014
Toyota; Camry; 2015; Lo Line Sensor
Toyota; Corolla; 2007; Models made in USA; OEM Part No. 4260706011; Jun. & Newer
Toyota; Corolla; 2008; Models made in USA; OEM Part No. 4260706011
Toyota; Corolla; 2009-2012; Models made in USA; W/16" Or 17" Wheels
Toyota; Corolla; 2013; Models made in USA; W/16" Or 17" Wheels
Toyota; Corolla; 2014; Models made in USA; W/16" Or 17" Wheels
Toyota; Corolla; 2015-2016; Models made in USA; W/16" Or 17" Wheels
Toyota; FJ Cruiser; 2015; Models made in USA; W/16" Or 17" Wheels
Toyota; Highlander; 2011-2015
Toyota; Highlander; 2016
Toyota; Matrix; 2007; Models made in USA; OEM Part No. 4260706011; Jun. & Newer
Toyota; Matrix; 2008-2013; Models made in USA; OEM Part No. 4260706011
Toyota; Prius; 2013
Toyota; RAV4; 2012; Electric
Toyota; Solara; 2006; May & Newer
Toyota; Solara; 2007-2008
Toyota; Tacoma; 2006; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor; Aug. & Newer
Toyota; Tacoma; 2007-2013; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor
Toyota; Tacoma; 2014; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor
Toyota; Tacoma; 2015; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor
Toyota; Venza; 2009-2014
Toyota; Venza; 2015-2016
Toyota; Yaris; 2013

28362 (315 MHz)

Volvo; XC90; 2012-2014
Volvo; XC90; 2015

Numerical Listing

Sensor
28365 (315 MHz)

Lexus; GX470; 2006; Feb. & Newer; W/Valve Cap
Lexus; LX470; 2005
Lexus; LX470; 2006; Jul. & Older
Scion; iQ; 2012-2014
Scion; iQ; 2015
Scion; tC; 2006; May & Newer
Scion; tC; 2007-2014
Scion; tC; 2015-2016
Scion; xB; 2008-2014
Scion; xB; 2015-2016
Scion; xD; 2008-2014
Toyota; 4Runner; 2006; OEM Part No. 4260733011
Toyota; 4Runner; 2007; W/Valve Cap
Toyota; 4Runner; 2008; W/Valve Cap; OEM Part No. 4260733011
Toyota; 4Runner; 2009; W/Valve Cap
Toyota; Camry; 2007-2011; Models made in Japan; OEM Part No. 4260733011
Toyota; Corolla; 2007; Models made in Japan; OEM Part No. 4260733011; Jun. & Newer
Toyota; Corolla; 2008; Models made in Japan; OEM Part No. 4260733011
Toyota; Corolla; 2009; Models made in Japan; OEM Part No. 4260733011
Toyota; Corolla; 2009-2010; Models made in USA; W/15" Wheels
Toyota; Corolla; 2010; Models made in Japan; OEM Part No. 4260733011
Toyota; Corolla; 2011; Models made in USA; W/15" Wheels
Toyota; Corolla; 2011-2012; Models made in Japan; OEM Part No. 4260733011
Toyota; Corolla; 2012; Models made in USA; W/15" Wheels
Toyota; Corolla; 2013; Models made in Japan
Toyota; FJ Cruiser; 2008-2014
Toyota; Highlander; 2007; May & Newer
Toyota; Highlander; 2008-2010
Toyota; Land Cruiser; 2005; May & Newer
Toyota; Land Cruiser; 2006
Toyota; Land Cruiser; 2007-2011
Toyota; Land Cruiser; 2013-2014
Toyota; Land Cruiser; 2015
Toyota; Matrix; 2007; Models made in Japan; OEM Part No. 4260733011; Jun. & Newer
Toyota; Matrix; 2008-2013; Models made in Japan; OEM Part No. 4260733011
Toyota; Prius; 2005-2013
Toyota; Prius; 2014-2016
Toyota; RAV4; 2006; exc Electric
Toyota; Yaris; 2007; Aug. & Newer
Toyota; Yaris; 2008-2012

Sensor
28370 (315 MHz)

Lexus; CT200h; 2011
Lexus; CT200h; 2012-2015
Lexus; CT200h; 2016
Lexus; ES300h; 2013
Lexus; ES300h; 2014-2016
Lexus; ES350; 2007-2013
Lexus; ES350; 2014-2016
Lexus; GS350; 2007-2011
Lexus; GS350; 2013; 315 MHz
Lexus; GS350; 2014-2016; 315 MHz
Lexus; GS430; 2006; Jul. & Newer
Lexus; GS430; 2007
Lexus; GS450h; 2007-2011
Lexus; GS450h; 2013-2016
Lexus; GS460; 2008-2011
Lexus; GS460; 2012-2016
Lexus; GX460; 2010-2015
Lexus; GX460; 2016
Lexus; GX470; 2007-2009
Lexus; IS F; 2008-2015
Lexus; IS F; 2016
Lexus; IS250; 2006; Apr. 1 & Newer
Lexus; IS250; 2007
Lexus; IS250; 2008-2015
Lexus; IS250; 2016
Lexus; IS350; 2006; Apr. 1 & Newer
Lexus; IS350; 2007-2015
Lexus; IS350; 2016
Lexus; LFA; 2012
Lexus; LFA; 2016
Lexus; LS460; 2007-2016
Lexus; LS600h; 2008-2016
Lexus; LX470; 2006; Aug. & Newer
Lexus; LX470; 2007
Lexus; LX570; 2008-2011
Lexus; LX570; 2013-2014
Lexus; LX570; 2016
Lexus; RX330; 2006; Models made in Japan; Feb. & Newer
Lexus; RX350; 2007-2010; Models made in Japan
Lexus; RX350; 2011-2012
Lexus; RX350; 2013; exc F Sport
Lexus; RX350; 2014-2015; F Sport; Vehicle Made for Canada
Lexus; RX400h; 2006
Lexus; RX400h; 2007-2008; Models made in Japan
Lexus; RX450h; 2010-2013
Lexus; RX450h; 2014-2015
Lexus; SC430; 2006; Aug. & Newer
Lexus; SC430; 2007-2010
Toyota; 4Runner; 2006; OEM Part No. 4260733021
Toyota; 4Runner; 2007; W/O Valve Cap
Toyota; 4Runner; 2008; W/O Valve Cap; OEM Part No. 4260733021
Toyota; 4Runner; 2009; W/O Valve Cap
Toyota; 4Runner; 2010-2016
Toyota; Corolla; 2009-2012; Models made in Japan; OEM Part No. 4260733021
Toyota; RAV4; 2007-2011; exc Electric
Toyota; RAV4; 2012; exc Electric
Toyota; RAV4; 2013; exc Electric

Numerical Listing

Sensor
28380 (315 MHz)

Toyota; Tacoma; 2005; W/40 Deg. Angled Valve Sensor; Dec. 1 & Newer
Toyota; Tacoma; 2006; W/Steel Wheels; W/40 Deg. Angled Valve Sensor
Toyota; Tacoma; 2007-2013; W/Steel Wheels; W/40 Deg. Angled Valve Sensor
Toyota; Tacoma; 2015; W/Steel Wheels; W/20 Deg. Angled Valve Sensor
Toyota; Tundra; 2014; W/Steel Wheels
Toyota; Tundra; 2015; W/Steel Wheels

28385 (315 MHz)

Ford; Crown Victoria; 2006-2011
Ford; Edge; 2007-2008; W/Chrome Plated Almnm. Wheels
Ford; Escape; 2005; Oct. 3, 2005 & Newer
Ford; Escape; 2006-2008
Ford; E-Series Van; 2007
Ford; Explorer; 2006-2010
Ford; Explorer Sport Trac; 2007-2010
Ford; F-150; 2007
Ford; F-150; 2008; W/O H.D. Payload Pkg
Ford; Focus; 2007
Ford; Freestar; 2006-2007
Ford; Fusion; 2007-2009
Ford; Mustang; 2007-2009
Ford; Ranger; 2007-2011
Lincoln; Mark LT; 2007-2008
Lincoln; MKX; 2007-2008; W/Chrome Plated Almnm. Wheels
Lincoln; MKZ; 2007-2009
Lincoln; Town Car; 2006-2010
Lincoln; Zephyr; 2006
Mazda; B2300; 2007-2009
Mazda; B3000; 2007-2008
Mazda; B4000; 2007-2009
Mazda; Tribute; 2006
Mazda; Tribute; 2008
Mercury; Grand Marquis; 2006-2011
Mercury; Mariner; 2005; Oct. 3, 2005 & Newer
Mercury; Mariner; 2006-2008
Mercury; Milan; 2007-2009
Mercury; Monterey; 2006-2007
Mercury; Mountaineer; 2006-2010

Sensor
28390 (315 MHz)

Ford; Edge; 2007-2008; W/O Chrome Plated Almnm. Wheels
Ford; Edge; 2009-2010
Ford; Expedition; 2007-2010
Ford; Five Hundred; 2006-2007
Ford; Flex; 2009-2010
Ford; Focus; 2008-2009
Ford; Taurus; 2008-2009
Ford; Taurus; 2010; Apr. & Older
Lincoln; MKS; 2009-2010
Lincoln; MKT; 2010
Lincoln; MKX; 2007-2008; W/O Chrome Plated Almnm. Wheels
Lincoln; MKX; 2009-2010
Lincoln; Navigator; 2007-2010
Mercury; Montego; 2006-2007
Mercury; Sable; 2008-2009

28395 (315 MHz)

Ford; E-Series Van; 2007
Ford; E-Series Van; 2008-2009
Ford; E-Series Van; 2010
Ford; E-Series Van; 2010; W/Alloy Wheels
Ford; F-150; 2008; W/H.D. Payload Pkg
Ford; F-250 Super Duty; 2008-2010
Ford; F-350 Super Duty; 2008-2010
Ford; F-450 Super Duty; 2008
Ford; F-450 Super Duty; 2009
Ford; F-450 Super Duty; 2010
Ford; F-550 Super Duty; 2010

28423 (314.9 MHz)

Cadillac; ATS; 2014; V
Cadillac; ATS; 2015; V
Cadillac; CTS; 2014-2015; V
Chevrolet; Camaro; 2012; ZL1
Chevrolet; Camaro; 2013-2015; ZL1
Chevrolet; Caprice; 2016
Chevrolet; SS; 2014-2016
Chevrolet; SS; 2017

Numerical Listing

Sensor

28434 (433 MHz)

Chrysler; 300; 2007; Can also use 28155 until depleted
Chrysler; 300; 2008
Chrysler; Town & Country; 2008; Can also use 28155 until depleted
Chrysler; Town & Country; 2009-2010
Dodge; Challenger; 2008; OEM No. 56029481AB; 433 MHz Sensor; Rubber Valve
Dodge; Charger; 2008
Dodge; Grand Caravan; 2008
Dodge; Grand Caravan; 2009-2010
Dodge; Journey; 2009
Dodge; Journey; 2010; Replaces clamp-in Sensor
Dodge; Magnum; 2008
Dodge; Ram 4500; 2010; W/Rubber Stem Snap-in Sensor
Dodge; Ram 5500; 2010; W/Rubber Stem Snap-in Sensor
Dodge; Ram Series; 2009
Dodge; Ram Series; 2010; W/Rubber Stem Snap-in Sensor
Jeep; Commander; 2008-2010
Jeep; Grand Cherokee; 2008-2010
Jeep; Liberty; 2009; W/433 MHz Clamp-in Sensor
Jeep; Wrangler; 2009
Jeep; Wrangler; 2010
Volkswagen; Routan; 2009-2010

28461 (315 MHz)

Dodge; Dakota; 2008-2010
Dodge; Ram Series; 2008
Dodge; Ram Series; 2009
Mitsubishi; Raider; 2008-2009

28500 (315 MHz)

Hyundai; Tucson; 2014
Kia; Sportage; 2014-2015

Sensor

28505 (315 MHz)

Hyundai; Veloster; 2012-2015
Hyundai; Veloster; 2016

28586 (433 MHz)

Chrysler; 200; 2015-2016
Dodge; Dart; 2013-2016
Jeep; Renegade; 2015-2016

28670 (315 MHz)

Toyota; Sequoia; 2008-2013
Toyota; Sienna; 2006-2014
Toyota; Tundra; 2006; W/Alloy Wheels; W/TRW Sensor
Toyota; Tundra; 2007; W/Alloy Wheels; W/TRW Sensor
Toyota; Tundra; 2008-2011; W/Alloy Wheels; W/TRW Sensor
Toyota; Tundra; 2012
Toyota; Tundra; 2013; W/Alloy Wheels; W/TRW Sensor
Toyota; Tundra; 2014; W/Alloy Wheels
Toyota; Tundra; 2015; W/Alloy Wheels

28720 (315 MHz)

Acura; CSX; 2008-2011
Honda; Civic; 2008-2014
Honda; CR-Z; 2011-2014
Honda; CR-Z; 2015
Honda; Element; 2009-2011
Honda; Fit; 2009-2014
Honda; Insight; 2010-2014
Honda; Odyssey; 2011-2016

Numerical Listing

Sensor
28849 (315 MHz)

Hyundai; Accent; 2008-2011
Hyundai; Equus; 2011-2013
Hyundai; Genesis; 2009-2014
Hyundai; Santa Fe XL; 2013
Hyundai; Sonata; 2008
Hyundai; Sonata; 2009-2010
Hyundai; Tucson; 2010-2013
Kia; Borrego; 2009-2011
Kia; Rio; 2007-2011
Kia; Rio5; 2007-2011
Kia; Spectra; 2006
Kia; Spectra; 2007-2009
Kia; Spectra5; 2006
Kia; Spectra5; 2007-2009
Kia; Sportage; 2009-2012
Kia; Sportage; 2013

28981 (315 MHz)

Acura; MDX, RDX; 2004-2006
Acura; RL; 2005-2012
Acura; TL; 2005-2008
Honda; Odyssey; 2005-2007; Touring
Honda; Odyssey; 2008; Touring
Honda; Pilot; 2005; W/Short Stem Valve
Honda; Pilot; 2006-2008
Honda; Ridgeline; 2006; RTL, RTS
Honda; Ridgeline; 2007-2008; RTL, RTS, RTX
Honda; Ridgeline; 2009
Honda; Ridgeline; 2010; W/Alloy Wheels
Honda; Ridgeline; 2010; W/Steel Wheels
Honda; Ridgeline; 2011-2014

28982 (315 MHz)

Honda; Pilot; 2005; LX; W/Long Stem Valve
Honda; Ridgeline; 2006; RT
Honda; Ridgeline; 2007-2008; RT

Sensor
28983 (315 MHz)

Honda; Odyssey; 2008
Honda; Odyssey; 2009-2010
Hyundai; Accent; 2006-2007
Hyundai; Sonata; 2007
Hyundai; Sonata; 2008
Hyundai; Tiburon; 2007-2008
Hyundai; Tucson; 2006-2009
Kia; Amanti; 2007-2009
Kia; Sorento; 2007-2009
Kia; Sportage; 2005; Jun. 15, 2005 & Newer
Kia; Sportage; 2006-2008

28984 (315 MHz)

Jeep; Cherokee; 2014
Jeep; Cherokee; 2015
Jeep; Cherokee; 2016-2017
Ram; Ram Series; 2014-2015
Ram; Ram Series; 2016-2017

Numerical Listing

Sensor	Service Pack
INDIRECT	20002
Audi; A3, A4,A5 & Quattro; 2013-2016 Audi; A4 allroad; 2013-2016 Audi; A6; 2013-2016 Audi; A7 Quattro; 2013-2014 Audi; A8; 2013-2016 Audi; Q5; 2013-2016 Audi; Q7; 2013-2016 Audi; RS5; 2013-2015 Audi; S4; 2013-2014 Audi; S5; 2013-2015 Audi; S6; 2013-2015 Audi; S7; 2013-2015 Audi; S8; 2013-2014 Audi; S8; 2015 Audi; SQ5; 2013-2014 Audi; TT; 2013-2015 Buick; Allure; 2006 Buick; Century; 1999-2005 Buick; LeSabre; 2000-2005 Buick; Park Avenue; 1998-2005 Buick; Regal; 1999-2004 Buick; Rendezvous; 2003-2007 Chevrolet; Impala; 2000-2005 Chevrolet; Monte Carlo; 2000-2005 Honda; Accord; 2013-2016 Honda; CR-V; 2014-2015 Honda; Fit; 2015-2016 Lexus; LS430; 2004-2006 Lexus; RX330; 2004-2005 Mazda; 3; 2014-2015 Mazda; 6; 2014-2016 Mazda; CX-5; 2013-2016 Mazda; MX-5 Miata; 2016 Oldsmobile; Alero; 1999-2000 Oldsmobile; Aurora; 2001-2003 Pontiac; Aztek; 2003-2005 Pontiac; Bonneville; 2000-2005 Pontiac; Grand Am; 1999-2002 Pontiac; Grand Prix; 2004-2006 Pontiac; Vibe; 2005-2007 Toyota; Sienna; 2005 Toyota; Yaris; 2015 Volkswagen; Beetle; 2013-2014 Volkswagen; Golf; 2013-2015 Volkswagen; GTI; 2013-2015 Volkswagen; Jetta; 2013-2015 Volkswagen; Passat; 2013-2015 Volkswagen; Routan; 2015 Volkswagen; Tiguan; 2014-2015 Volvo; XC60; 2015	Ford; Expedition; 2003-2004 Ford; Expedition; 2005-2006 Ford; Explorer; 2002-2003; Exc. Sport Ford; Explorer; 2004-2005 Ford; Freestar; 2004-2005; W/Aluminium Valve Stem Lincoln; Aviator; 2003-2005 Lincoln; Navigator; 2003-2004 Lincoln; Navigator; 2005-2006 Mercury; Monterey; 2004-2005 Mercury; Mountaineer; 2002-2005

Numerical Listing

Service Pack 20003

Cadillac; DeVille; 2001-2005
Cadillac; Seville; 2001-2004
Chevrolet; Corvette; 2001-2004
Chrysler; 300M; 2002-2004; W/Schrader Sensor
Chrysler; Concorde; 2002-2004; W/Schrader Sensor
Chrysler; Crossfire; 2004; W/Schrader Sensor
Chrysler; Crossfire; 2005; exc Siemens OE Sensor; Service Pack contains cap, core, grommet, and nut
Chrysler; Crossfire; 2006-2008; W/Schrader Sensor
Chrysler; Intrepid; 2002-2004; W/Schrader Sensor
Chrysler; Pacifica; 2004; W/Schrader Sensor
Chrysler; Prowler; 2001; W/Red Sensor Body
Chrysler; Prowler; 2002; W/Schrader Sensor
Chrysler; Town & Country; 2002-2003
Chrysler; Voyager; 2002-2003
Dodge; Caravan; 2002-2003
Dodge; Grand Caravan; 2002-2003
Dodge; Intrepid; 2002-2004
Dodge; Viper; 2003-2006
Dodge; Viper; 2008-2010
Isuzu; Rodeo; 2004
Jeep; Grand Cherokee; 2002-2004
Jeep; Liberty; 2002-2004
Mitsubishi; Eclipse; 2006-2007; W/Alloy Wheels
Mitsubishi; Eclipse; 2008-2010
Mitsubishi; Eclipse; 2011
Mitsubishi; Eclipse; 2012
Mitsubishi; Endeavor; 2004-2005
Mitsubishi; Endeavor; 2006
Mitsubishi; Endeavor; 2007
Mitsubishi; Endeavor; 2008
Mitsubishi; Endeavor; 2010
Mitsubishi; Endeavor; 2011; W/Alloy Wheels
Mitsubishi; Galant; 2004-2006
Mitsubishi; Galant; 2007-2009; W/Alloy Wheels
Mitsubishi; Galant; 2010-2012; W/Alloy Wheels
Mitsubishi; Montero; 2003-2006
Mitsubishi; Montero Sport; 2003-2004
Plymouth; Prowler; 1997; W/Red Sensor Body
Plymouth; Prowler; 1999-2001; W/Red Sensor Body

Service Pack 20004

Buick; Allure; 2007-2008; W/Schrader Sensor
Buick; Enclave; 2008; W/Schrader Sensor
Buick; LaCrosse; 2006; W/Schrader Sensor
Buick; LaCrosse; 2007-2008; W/Schrader Sensor
Buick; Rainier; 2006-2007
Cadillac; ATS; 2014; V
Cadillac; ATS; 2015; V
Cadillac; CTS; 2004-2007
Cadillac; CTS; 2009-2011; OEM Part No. 15268606; CTS V; W/315 MHz Sensor
Cadillac; CTS; 2012; OEM Part No. 15268606; CTS V; W/315 MHz Sensor
Cadillac; CTS; 2013; OEM Part No. 15268606; CTS V; W/315 MHz Sensor
Cadillac; CTS; 2014-2015; V
Cadillac; DTS; 2006
Cadillac; Escalade; 2004
Cadillac; Escalade; 2005-2006
Cadillac; SRX; 2004-2006
Cadillac; STS; 2005
Cadillac; STS; 2006-2008
Cadillac; XLR; 2004
Cadillac; XLR; 2005-2009
Chevrolet; Camaro; 2012; ZL1
Chevrolet; Camaro; 2013-2015; ZL1
Chevrolet; Caprice; 2011-2013
Chevrolet; Caprice; 2016
Chevrolet; Cobalt; 2008; Clamp-In Style Only; W/Aluminium Valve Stem
Chevrolet; Cobalt; 2009; Clamp-In Style Only; W/Aluminium Valve Stem
Chevrolet; Corvette; 2005-2009
Chevrolet; Corvette; 2010-2011
Chevrolet; Corvette; 2012; Z06; Base
Chevrolet; Corvette; 2013
Chevrolet; Equinox; 2007-2009; W/Schrader Sensor
Chevrolet; Express; 2008-2009; W/Schrader Sensor
Chevrolet; HHR; 2008-2009; Clamp-In Style Only; W/Aluminium Valve Stem
Chevrolet; Impala; 2006; W/Alloy Wheels
Chevrolet; Impala; 2007; Clamp-In Style Only; W/Aluminium Valve Stem
Chevrolet; Malibu; 2008; Clamp-In Style Only; W/Aluminium Valve Stem
Chevrolet; Monte Carlo; 2006; W/Alloy Wheels
Chevrolet; Monte Carlo; 2007; Clamp-In Style Only; W/Aluminium Valve Stem
Chevrolet; Silverado Series; 2004
Chevrolet; Silverado Series; 2005-2006
Chevrolet; Silverado Series; 2007; Classic
Chevrolet; SS; 2014-2016
Chevrolet; SS; 2017
Chevrolet; SSR; 2006
Chevrolet; Suburban; 2004
Chevrolet; Suburban; 2005-2006
Chevrolet; Tahoe; 2004
Chevrolet; Tahoe; 2005-2006
Chevrolet; Trailblazer; 2006-2009
Chevrolet; Uplander; 2008-2009
GMC; Acadia; 2007-2008; W/Schrader Sensor
GMC; Envoy; 2006
GMC; Envoy; 2007-2009
GMC; Savana Series; 2008-2009; W/Schrader Sensor
GMC; Sierra Series; 2004
GMC; Sierra Series; 2005-2006
GMC; Sierra Series; 2007; Classic
GMC; Yukon; 2004
GMC; Yukon; 2005-2006
Isuzu; Ascender; 2006-2008

Numerical Listing

Pontiac; G Series; 2008; W/Schrader Sensor
Pontiac; Grand Prix; 2007; W/Schrader Sensor
Pontiac; Grand Prix; 2008; Clamp-In Style Only; W/Aluminium Valve Stem
Pontiac; Montana; 2008; W/Schrader Sensor
Pontiac; Solstice; 2008-2009; W/Schrader Sensor
Pontiac; Torrent; 2007-2009; W/Schrader Sensor
Saab; 9-7x; 2005-2009
Saturn; Aura; 2007; W/Schrader Sensor
Saturn; Outlook; 2007-2008; W/Schrader Sensor
Saturn; Sky; 2008-2010; W/Schrader Sensor
Suzuki; XL-7; 2007-2009; W/Schrader Sensor

20005

Infiniti; QX56; 2004
Infiniti; QX56; 2005-2006; W/Steel Wheels
Nissan; Armada; 2005-2006; W/Steel Wheels
Nissan; Frontier; 2005-2007; W/Steel Wheels
Nissan; Pathfinder; 2004; Armada
Nissan; Pathfinder; 2004; Exc. Armada; Aug. & Newer
Nissan; Quest; 2004
Nissan; Quest; 2005-2006; W/Steel Wheels
Nissan; Titan; 2004
Nissan; Titan; 2005; Mar. & Older
Nissan; Xterra; 2006; Submodel X

20006

Chevrolet; Colorado; 2007-2012
GMC; Canyon; 2007-2012
Hummer; H3; 2006-2010
Hummer; H3T; 2009-2010
Isuzu; i-290; 2007-2008
Isuzu; i-370; 2007-2008
Pontiac; Montana; 2009

Service Pack

20007

Infiniti; FX35; 2003-2006
Infiniti; FX35; 2007; Jun. & Older
Infiniti; FX45; 2003-2006
Infiniti; FX45; 2007; Jun. & Older
Infiniti; G35; 2003; Jun. & Newer
Infiniti; G35; 2004-2006
Infiniti; M35; 2006-2007
Infiniti; M45; 2003-2004
Infiniti; M45; 2006-2007
Infiniti; Q45; 2002
Infiniti; Q45; 2003-2005
Infiniti; Q45; 2006; Jul. & Older
Infiniti; QX4; 2003
Infiniti; QX56; 2005-2006; W/Alloy Wheels
Infiniti; QX56; 2007; Mar. & Older
Nissan; 350Z; 2003-2006
Nissan; Armada; 2005-2006; W/Alloy Wheels
Nissan; Armada; 2007
Nissan; Armada; 2008; SE
Nissan; Frontier; 2003-2004
Nissan; Frontier; 2005-2007; W/Alloy Wheels
Nissan; Frontier; 2008; W/Alloy Wheels
Nissan; Maxima; 2006; Jun. & Newer
Nissan; Maxima; 2007; Mar. & Older
Nissan; Murano; 2003-2006
Nissan; Pathfinder; 2003
Nissan; Pathfinder; 2004; Exc. Armada; Jul. & Older
Nissan; Pathfinder; 2005-2006
Nissan; Quest; 2005-2006; W/Alloy Wheels
Nissan; Sentra; 2007; W/Alloy Wheels
Nissan; Titan; 2005; Apr. 1 & Newer
Nissan; Titan; 2006
Nissan; Titan; 2007; Mar. & Older
Nissan; Xterra; 2003-2004
Nissan; Xterra; 2005
Nissan; Xterra; 2006; Exc. Submodel X

Numerical Listing

Service Pack

20008

Buick; Allure; 2009
Buick; Allure; 2010
Buick; Enclave; 2009-2015
Buick; Enclave; 2016
Buick; Enclave; 2017
Buick; Encore; 2013-2015
Buick; Encore; 2016
Buick; Encore; 2017
Buick; Envision; 2017
Buick; LaCrosse; 2009
Buick; LaCrosse; 2010-2015
Buick; LaCrosse; 2016
Buick; LaCrosse; 2017; Exc. ZL1
Buick; Lucerne; 2007-2011
Buick; Regal; 2011-2016
Buick; Regal; 2017
Buick; Verano; 2012-2015
Buick; Verano; 2016-2017
Cadillac; ATS; 2013; exc V
Cadillac; ATS; 2014; exc V
Cadillac; ATS; 2015; exc V
Cadillac; ATS; 2016; exc V
Cadillac; ATS; 2017; exc V
Cadillac; CT6; 2016-2017; Exc. ZL1
Cadillac; CTS; 2008
Cadillac; CTS; 2009-2011; OEM Part No. 25920615; Exc. CTS V
Cadillac; CTS; 2012; OEM Part No. 25920615; Exc. CTS V
Cadillac; CTS; 2013; OEM Part No. 25920615; Exc. CTS V
Cadillac; CTS; 2014-2015; exc V
Cadillac; CTS; 2016; exc V
Cadillac; CTS; 2017; exc V
Cadillac; DTS; 2007-2011
Cadillac; ELR; 2014
Cadillac; ELR; 2015-2016
Cadillac; ELR; 2017
Cadillac; Escalade; 2007; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem
Cadillac; Escalade; 2008
Cadillac; Escalade; 2009-2011
Cadillac; Escalade; 2012-2013
Cadillac; Escalade; 2014-2015
Cadillac; Escalade; 2016
Cadillac; Escalade; 2017
Cadillac; SRX; 2007-2009
Cadillac; SRX; 2010-2015
Cadillac; SRX; 2016
Cadillac; STS; 2009; OEM Part No. 25920615; Exc. STS V
Cadillac; STS; 2010
Cadillac; STS; 2011
Cadillac; XTS; 2013-2015
Cadillac; XTS; 2016
Cadillac; XTS; 2017
Chevrolet; Avalanche; 2007; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem
Chevrolet; Avalanche; 2008
Chevrolet; Avalanche; 2009-2013
Chevrolet; Aveo; 2007
Chevrolet; Aveo; 2008-2011
Chevrolet; Aveo5; 2007
Chevrolet; Aveo5; 2008-2011
Chevrolet; Camaro; 2010-2011
Chevrolet; Camaro; 2012; Exc. ZL1
Chevrolet; Camaro; 2013-2015; Exc. ZL1
Chevrolet; Camaro; 2016; Exc. ZL1
Chevrolet; Camaro; 2017; Exc. ZL1
Chevrolet; Caprice; 2017
Chevrolet; Captiva Sport; 2012-2013
Chevrolet; Cobalt; 2008; Snap-In Style Only; W/Rubber Valve Stem
Chevrolet; Cobalt; 2009; Snap-In Style Only; W/Rubber Valve Stem
Chevrolet; Cobalt; 2010
Chevrolet; Colorado; 2015
Chevrolet; Colorado; 2016
Chevrolet; Colorado; 2017
Chevrolet; Cruze; 2011-2015
Chevrolet; Cruze; 2016
Chevrolet; Cruze; 2017; Exc. ZL1
Chevrolet; Equinox; 2010-2014
Chevrolet; Equinox; 2015-2016
Chevrolet; Equinox; 2017
Chevrolet; Express; 2010-2015
Chevrolet; Express; 2016
Chevrolet; Express; 2017
Chevrolet; HHR; 2008-2009; Snap-In Style Only; W/Rubber Valve Stem
Chevrolet; HHR; 2010
Chevrolet; HHR; 2011
Chevrolet; Impala; 2007; Snap-In Style Only; W/Rubber Valve Stem
Chevrolet; Impala; 2008-2013
Chevrolet; Impala; 2014-2015
Chevrolet; Impala; 2016
Chevrolet; Impala; 2017
Chevrolet; Malibu; 2008; Snap-In Style Only; W/Rubber Valve Stem
Chevrolet; Malibu; 2009
Chevrolet; Malibu; 2010
Chevrolet; Malibu; 2011-2012
Chevrolet; Malibu; 2013-2015
Chevrolet; Malibu; 2016
Chevrolet; Malibu; 2017
Chevrolet; Monte Carlo; 2007; Snap-In Style Only; W/Rubber Valve Stem
Chevrolet; Orlando; 2012-2014
Chevrolet; Orlando; 2017
Chevrolet; Silverado Series; 2007; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem; Exc. Classic
Chevrolet; Silverado Series; 2008
Chevrolet; Silverado Series; 2008; W/Single Rear Wheels
Chevrolet; Silverado Series; 2009
Chevrolet; Silverado Series; 2009; W/Single Rear Wheels
Chevrolet; Silverado Series; 2010
Chevrolet; Silverado Series; 2010; W/Single Rear Wheels
Chevrolet; Silverado Series; 2011
Chevrolet; Silverado Series; 2011; W/Single Rear Wheels
Chevrolet; Silverado Series; 2012
Chevrolet; Silverado Series; 2012; W/Single Rear Wheels
Chevrolet; Silverado Series; 2013; W/Single Rear Wheels
Chevrolet; Silverado Series; 2014-2015; W/Single Rear Wheels
Chevrolet; Silverado Series; 2016; W/Single Rear Wheels
Chevrolet; Silverado Series; 2017; W/Single Rear Wheels
Chevrolet; Sonic; 2012-2015
Chevrolet; Sonic; 2016
Chevrolet; Sonic; 2017
Chevrolet; Spark; 2013-2015
Chevrolet; Spark; 2016
Chevrolet; Spark; 2017
Chevrolet; Suburban; 2007; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem
Chevrolet; Suburban; 2008-2014
Chevrolet; Suburban; 2015
Chevrolet; Suburban; 2016
Chevrolet; Suburban; 2017
Chevrolet; Tahoe; 2007; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem
Chevrolet; Tahoe; 2008-2013
Chevrolet; Tahoe; 2014-2015
Chevrolet; Tahoe; 2016
Chevrolet; Tahoe; 2017
Chevrolet; Traverse; 2009-2015

Numerical Listing

Chevrolet; Traverse; 2016
Chevrolet; Traverse; 2017
Chevrolet; Trax; 2013-2015
Chevrolet; Trax; 2016
Chevrolet; Trax; 2017
Chevrolet; Volt; 2011-2015
Chevrolet; Volt; 2016
Chevrolet; Volt; 2017; Exc. ZL1
GMC; Acadia; 2009-2015
GMC; Acadia; 2016
GMC; Acadia; 2017
GMC; Canyon; 2015-2016
GMC; Canyon; 2017
GMC; Savana Series; 2010-2015
GMC; Savana Series; 2016
GMC; Savana Series; 2017
GMC; Sierra Series; 2007; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem; Exc. Classic
GMC; Sierra Series; 2008
GMC; Sierra Series; 2008; W/Single Rear Wheels
GMC; Sierra Series; 2009
GMC; Sierra Series; 2009; W/Single Rear Wheels
GMC; Sierra Series; 2010
GMC; Sierra Series; 2010; W/Single Rear Wheels
GMC; Sierra Series; 2011
GMC; Sierra Series; 2011; W/Single Rear Wheels
GMC; Sierra Series; 2012
GMC; Sierra Series; 2012; W/Single Rear Wheels
GMC; Sierra Series; 2013; W/Single Rear Wheels
GMC; Sierra Series; 2014; W/Single Rear Wheels
GMC; Sierra Series; 2015
GMC; Sierra Series; 2015; W/Single Rear Wheels
GMC; Sierra Series; 2016
GMC; Sierra Series; 2016; W/Single Rear Wheels
GMC; Sierra Series; 2017
GMC; Sierra Series; 2017; W/Single Rear Wheels
GMC; Terrain; 2010-2014
GMC; Terrain; 2015; Rubber Valve
GMC; Terrain; 2016; Rubber Valve
GMC; Terrain; 2017; Rubber Valve
GMC; Yukon; 2007; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem
GMC; Yukon; 2008-2013
GMC; Yukon; 2014-2015
GMC; Yukon; 2016
GMC; Yukon; 2017
Hummer; H2; 2008-2009
Hyundai; Veloster; 2012-2015
Hyundai; Veloster; 2016
Pontiac; G Series; 2008
Pontiac; G Series; 2009-2010
Pontiac; Grand Prix; 2008; Snap-In Style Only; W/Rubber Valve Stem
Pontiac; Wave; 2008
Saab; 9-4X; 2011
Saturn; Aura; 2008-2009
Saturn; Outlook; 2009-2010
Saturn; Vue; 2007-2010
Subaru; Forester; 2008-2015
Subaru; Forester; 2016
Subaru; Impreza; 2008-2015
Subaru; Impreza; 2016
Subaru; Legacy; 2008; W/18" Wheels
Subaru; Legacy; 2009-2015
Subaru; Legacy; 2016
Subaru; Outback; 2008-2015
Subaru; Outback; 2016-2017
Subaru; Tribeca; 2008
Subaru; Tribeca; 2009; Rubber Valve
Subaru; Tribeca; 2010
Subaru; Tribeca; 2011; Rubber Valve
Subaru; Tribeca; 2012-2014
Subaru; WRX; 2013-2015
Subaru; WRX; 2016
Subaru; XV Crosstrek; 2013-2015
Subaru; XV Crosstrek; 2016
Suzuki; Forenza; 2007-2008
Suzuki; Reno; 2007-2008
Volvo; XC90; 2012-2014
Volvo; XC90; 2015

20009

Lotus; Elise; 2008-2015
Lotus; Evora; 2010-2013
Lotus; Evora; 2014
Lotus; Evora; 2015
Lotus; Exige; 2008-2015
Porsche; 911; 2012
Saab; 9-3; 2003-2007
Saab; 9-3; 2008-2011
Saab; 9-3X; 2010-2011
Saab; 9-5; 2003-2007
Saab; 9-5; 2008-2009
Saab; 9-5; 2010-2011
Saturn; Astra; 2008-2009
Suzuki; Grand Vitara; 2007-2013
Suzuki; SX4; 2007-2013
Suzuki; SX4 Crossover; 2012
Suzuki; Verona; 2005-2006
Suzuki; XL-7; 2005-2006

20010

Mitsubishi; Eclipse; 2006-2007; W/Steel Wheels
Mitsubishi; Endeavor; 2011; W/Steel Wheels
Mitsubishi; Galant; 2007-2009; W/Steel Wheels
Mitsubishi; Galant; 2010-2012; W/Steel Wheels
Volvo; S60,S80; 2004
Volvo; S60,S80; 2004; W/315 MHz Sensor
Volvo; S60,S80; 2005
Volvo; S60,S80; 2005; W/315 MHz Sensor
Volvo; S60,S80; 2006-2009
Volvo; V70; 2004-2007; W/315 MHz Sensor
Volvo; XC70; 2004-2007; W/315 MHz Sensor
Volvo; XC90; 2004
Volvo; XC90; 2005-2007; W/315 MHz Sensor
Volvo; XC90; 2008-2011

Numerical Listing

Service Pack 20011

Subaru; B9 Tribeca; 2006-2007
Subaru; Legacy; 2004-2007
Subaru; Legacy; 2008; W/16" Or 17" Wheels
Subaru; Outback; 2004-2007
Subaru; Tribeca; 2008; W/Metal Stem Clamp-in Sensor
Subaru; Tribeca; 2009; W/Metal Stem Clamp-in Sensor
Subaru; Tribeca; 2010; W/Metal Stem Clamp-in Sensor
Subaru; Tribeca; 2011; W/Metal Stem Clamp-in Sensor

Service Pack 20012

Chevrolet; Corvette; 1997-2000
Chrysler; Prowler; 2001; W/Black Sensor Body
Plymouth; Prowler; 1997; W/Black Sensor Body
Plymouth; Prowler; 1999-2001; W/Black Sensor Body

Service Pack 20013

Chrysler; 200; 2011; Fits Schrader Alum stem sensor. Does not include stem.
Chrysler; 200; 2012; Fits Schrader Alum stem sensor. Does not include stem.
Chrysler; 300; 2005-2006; Fits Schrader Alum stem sensor. Does not include stem.
Chrysler; 300; 2007; Fits Schrader Alum stem sensor. Does not include stem.
Chrysler; 300; 2008; Fits Schrader Alum stem sensor. Does not include stem.
Chrysler; Aspen; 2007-2011; Fits Schrader Alum stem sensor. Does not include stem.
Chrysler; Crossfire; 2005; Fits Schrader Alum stem sensor. Does not include stem.
Chrysler; Pacifica; 2006-2007; Fits Schrader Alum stem sensor. Does not include stem.
Chrysler; Pacifica; 2008; Fits Schrader Alum stem sensor. Does not include stem.
Chrysler; PT Cruiser; 2008-2010; Fits Schrader Alum stem sensor. Does not include stem.
Chrysler; Sebring; 2007-2009; Fits Schrader Alum stem sensor. Does not include stem.
Chrysler; Sebring; 2010; Fits Schrader Alum stem sensor. Does not include stem.
Chrysler; Town & Country; 2006-2007; Fits Schrader Alum stem sensor. Does not include stem.
Chrysler; Town & Country; 2008; Fits Schrader Alum stem sensor. Does not include stem.
Chrysler; Town & Country; 2009-2010; Fits Schrader Alum stem sensor. Does not include stem.
Dodge; Avenger; 2008-2009; Fits Schrader Alum stem sensor. Does not include stem.
Dodge; Avenger; 2010-2012; Fits Schrader Alum stem sensor. Does not include stem.
Dodge; Caliber; 2007-2010; Fits Schrader Alum stem sensor. Does not include stem.
Dodge; Caliber; 2011-2012; Fits Schrader Alum stem sensor. Does not include stem.
Dodge; Caravan; 2006-2007; Fits Schrader Alum stem sensor. Does not include stem.
Dodge; Charger; 2006-2007; Fits Schrader Alum stem sensor. Does not include stem.
Dodge; Charger; 2008; Fits Schrader Alum stem sensor. Does not include stem.
Dodge; Dakota; 2008-2010; Fits Schrader Alum stem sensor. Does not include stem.
Dodge; Durango; 2007; Fits Schrader Alum stem sensor. Does not include stem.
Dodge; Durango; 2008; Fits Schrader Alum stem sensor. Does not include stem.
Dodge; Durango; 2009; Fits Schrader Alum stem sensor. Does not include stem.
Dodge; Grand Caravan; 2006-2007; Fits Schrader Alum stem sensor. Does not include stem.
Dodge; Grand Caravan; 2008; Fits Schrader Alum stem sensor. Does not include stem.
Dodge; Grand Caravan; 2009-2010; Fits Schrader Alum stem sensor. Does not include stem.
Dodge; Journey; 2009; Fits Schrader Alum stem sensor. Does not include stem.
Dodge; Journey; 2010; Fits Schrader Alum stem sensor. Does not include stem.
Dodge; Magnum; 2005-2007; Fits Schrader Alum stem sensor. Does not include stem.
Dodge; Magnum; 2008; Fits Schrader Alum stem sensor. Does not include stem.
Dodge; Nitro; 2007-2008; Fits Schrader Alum stem sensor. Does not include stem.
Dodge; Nitro; 2009-2011; Fits Schrader Alum stem sensor. Does not include stem.
Dodge; Ram Series; 2008; Fits Schrader Alum stem sensor. Does not include stem.
Dodge; Ram Series; 2009; Fits Schrader Alum stem sensor. Does not include stem.
Dodge; Ram Series; 2010; Fits Schrader Alum stem sensor. Does not include stem.
Jeep; Commander; 2006-2007; Fits Schrader Alum stem sensor. Does not include stem.
Jeep; Commander; 2008-2010; Fits Schrader Alum stem sensor. Does not include stem.

Numerical Listing

Jeep; Compass; 2007-2010; Fits Schrader Alum stem sensor. Does not include stem.
Jeep; Compass; 2011; Fits Schrader Alum stem sensor. Does not include stem.
Jeep; Grand Cherokee; 2005-2007; Fits Schrader Alum stem sensor. Does not include stem.
Jeep; Grand Cherokee; 2008-2010; Fits Schrader Alum stem sensor. Does not include stem.
Jeep; Liberty; 2005-2008; Fits Schrader Alum stem sensor. Does not include stem.
Jeep; Liberty; 2009; Fits Schrader Alum stem sensor. Does not include stem.
Jeep; Liberty; 2010-2012; Fits Schrader Alum stem sensor. Does not include stem.
Jeep; Patriot; 2007-2010; Fits Schrader Alum stem sensor. Does not include stem.
Jeep; Patriot; 2011-2012; Fits Schrader Alum stem sensor. Does not include stem.
Jeep; Wrangler; 2007-2008; Fits Schrader Alum stem sensor. Does not include stem.
Jeep; Wrangler; 2009; Fits Schrader Alum stem sensor. Does not include stem.
Jeep; Wrangler; 2010; Fits Schrader Alum stem sensor. Does not include stem.
Jeep; Wrangler; 2011; Fits Schrader Alum stem sensor. Does not include stem.
Mitsubishi; Raider; 2008-2009; Fits Schrader Alum stem sensor. Does not include stem.
Suzuki; Kizashi; 2010-2012; Fits Schrader Alum stem sensor. Does not include stem.

Service Pack

20014

Infiniti; EX35; 2008-2010
Infiniti; FX35; 2007; Jul. & Newer
Infiniti; FX35; 2008
Infiniti; FX35; 2009-2010
Infiniti; FX45; 2007; Jul. & Newer
Infiniti; FX45; 2008
Infiniti; FX50; 2009-2010
Infiniti; G35; 2007
Infiniti; G35; 2008
Infiniti; G37; 2008-2010
Infiniti; M35; 2008-2010
Infiniti; M35h; 2012
Infiniti; M37; 2011-2012
Infiniti; M45; 2008-2009
Infiniti; M45; 2010
Infiniti; M56; 2011-2012
Infiniti; Q45; 2006; Aug. & Newer
Infiniti; QX56; 2007; Apr. 1 & Newer
Infiniti; QX56; 2008-2010
Nissan; 350Z; 2007-2009
Nissan; 370Z; 2009-2010
Nissan; Altima; 2006; Oct. 1 & Newer
Nissan; Altima; 2007-2010
Nissan; Altima; 2011-2012
Nissan; Armada; 2008; LE
Nissan; Armada; 2009-2011
Nissan; Armada; 2012-2015
Nissan; Armada; 2016
Nissan; Cube; 2009-2010
Nissan; Cube; 2011-2012; non-Ikey
Nissan; Frontier; 2008; W/Steel Wheels
Nissan; Frontier; 2009-2011
Nissan; Frontier; 2012-2015
Nissan; Frontier; 2016
Nissan; GT-R; 2009
Nissan; GT-R; 2010
Nissan; GT-R; 2011-2016
Nissan; GT-R; 2017
Nissan; Juke; 2011
Nissan; Juke; 2012
Nissan; Maxima; 2007; Apr. 1 & Newer
Nissan; Maxima; 2008-2010
Nissan; Maxima; 2011-2012
Nissan; Murano; 2007
Nissan; Murano; 2009
Nissan; Murano; 2010
Nissan; Murano; 2011
Nissan; Murano; 2012-2014
Nissan; NV; 2012
Nissan; NV; 2013-2015
Nissan; NV; 2016
Nissan; Pathfinder; 2007
Nissan; Pathfinder; 2008-2011
Nissan; Pathfinder; 2012
Nissan; Quest; 2007-2009
Nissan; Rogue; 2008-2009
Nissan; Rogue; 2011
Nissan; Rogue; 2012
Nissan; Sentra; 2007; W/Steel Wheels
Nissan; Sentra; 2008

Numerical Listing

Nissan; Sentra; 2009-2010
Nissan; Sentra; 2011-2013
Nissan; Titan; 2007; Apr. 1 & Newer
Nissan; Titan; 2008-2011
Nissan; Titan; 2012-2015
Nissan; Versa; 2007
Nissan; Versa; 2008-2010
Nissan; Versa; 2011-2012
Nissan; Xterra; 2007
Nissan; Xterra; 2008-2011
Nissan; Xterra; 2012-2015
Nissan; Xterra; 2016
Suzuki; Equator; 2009-2012

20015

Cadillac; Escalade; 2007; Clamp-In Style Only; TRW Sensor; W/Aluminium Valve Stem
Chevrolet; Avalanche; 2007; Clamp-In Style Only; TRW Sensor; W/Aluminium Valve Stem
Chevrolet; Silverado Series; 2007; Clamp-In Style Only; TRW Sensor; W/Aluminium Valve Stem; Exc. Classic
Chevrolet; Suburban; 2007; Clamp-In Style Only; TRW Sensor; W/Aluminium Valve Stem
Chevrolet; Tahoe; 2007; Clamp-In Style Only; TRW Sensor; W/Aluminium Valve Stem
GMC; Sierra Series; 2007; Clamp-In Style Only; TRW Sensor; W/Aluminium Valve Stem; Exc. Classic
GMC; Yukon; 2007; Clamp-In Style Only; TRW Sensor; W/Aluminium Valve Stem

Service Pack

20016

Chrysler; 300; 2009-2010; Does Not Include Stem
Chrysler; 300; 2012; W/Metal Stem Clamp-in Sensor; Does Not Include Stem
Dodge; Challenger; 2008; Does Not Include Stem
Dodge; Challenger; 2009; Does Not Include Stem
Dodge; Challenger; 2010-2012; W/Metal Stem Clamp-in Sensor; Does Not Include Stem
Dodge; Charger; 2009; Does Not Include Stem
Dodge; Charger; 2010; W/Metal Stem Clamp-in Sensor; Does Not Include Stem
Dodge; Viper; 2012-2013; W/Metal Stem Clamp-in Sensor; Does Not Include Stem
Dodge; Viper; 2014-2015; W/Metal Stem Clamp-in Sensor; Does Not Include Stem
Dodge; Viper; 2016; W/Metal Stem Clamp-in Sensor; Does Not Include Stem
Dodge; Viper; 2017; W/Metal Stem Clamp-in Sensor; Does Not Include Stem
Mercedes-Benz; 550,63AMG; 2007-2009; Does Not Include Stem
Mercedes-Benz; C Series; 2007; Jun. & Newer; Does Not Include Stem
Mercedes-Benz; C Series; 2008-2009; Does Not Include Stem
Mercedes-Benz; C Series; 2010-2012; Does Not Include Stem
Mercedes-Benz; C Series; 2013; W/O Valve
Mercedes-Benz; C250; 2012; Does Not Include Stem
Mercedes-Benz; C250; 2013; W/O Valve
Mercedes-Benz; C280; 2007; Mar. & Newer; Does Not Include Stem
Mercedes-Benz; CLK; 2006; Does Not Include Stem
Mercedes-Benz; CLK350; 2006-2009; Does Not Include Stem
Mercedes-Benz; CLS550; 2012; Does Not Include Stem
Mercedes-Benz; CLS550; 2013; W/O Valve
Mercedes-Benz; E350; 2010-2012; Does Not Include Stem
Mercedes-Benz; E350; 2013; W/O Valve
Mercedes-Benz; E550; 2010-2011; Does Not Include Stem
Mercedes-Benz; E550; 2012-2013; W/O Valve
Mercedes-Benz; E63 AMG; 2010-2011; Does Not Include Stem
Mercedes-Benz; E63 AMG; 2012-2013; W/O Valve
Mercedes-Benz; G500; 2007; Mar. & Newer; Does Not Include Stem
Mercedes-Benz; G500; 2008; Does Not Include Stem
Mercedes-Benz; G55 AMG; 2007; Mar. & Newer; Does Not Include Stem
Mercedes-Benz; G55 AMG; 2008-2010; Does Not Include Stem
Mercedes-Benz; G55 AMG; 2011; Mar. & Newer; Does Not Include Stem
Mercedes-Benz; G550; 2009-2010; Does Not Include Stem
Mercedes-Benz; G550; 2011; Mar. & Newer; Does Not Include Stem
Mercedes-Benz; G550; 2012-2013; W/O Valve
Mercedes-Benz; GL; 2010; Does Not Include Stem
Mercedes-Benz; GL; 2011; Mar. & Newer; Does Not Include Stem
Mercedes-Benz; GL; 2012-2013; W/O Valve
Mercedes-Benz; GL350; 2010; Does Not Include Stem
Mercedes-Benz; GL350; 2011; Mar. & Newer; Does Not Include Stem
Mercedes-Benz; GL350; 2012-2013; W/O Valve
Mercedes-Benz; GL63 AMG; 2013; W/O Valve
Mercedes-Benz; GLK350; 2010; Does Not Include Stem
Mercedes-Benz; GLK350; 2011; Mar. & Newer; Does Not Include Stem
Mercedes-Benz; GLK350; 2012; Does Not Include Stem
Mercedes-Benz; GLK350; 2013; W/O Valve
Mercedes-Benz; ML350; 2010; Does Not Include Stem
Mercedes-Benz; ML350; 2011; Mar. & Newer; Does Not Include Stem
Mercedes-Benz; ML350; 2012; Does Not Include Stem
Mercedes-Benz; ML350; 2013; W/O Valve
Mercedes-Benz; ML450; 2010; Does Not Include Stem
Mercedes-Benz; ML450; 2011; Mar. & Newer; Does Not Include Stem
Mercedes-Benz; ML550; 2010; Does Not Include Stem
Mercedes-Benz; ML550; 2011-2012; Mar. & Newer; Does Not Include Stem
Mercedes-Benz; ML63 AMG; 2010; Does Not Include Stem
Mercedes-Benz; ML63 AMG; 2011; Mar. & Newer; Does Not Include Stem
Mercedes-Benz; ML63 AMG; 2012-2013; W/O Valve

Numerical Listing

Mercedes-Benz; R350; 2010; Does Not Include Stem
Mercedes-Benz; R350; 2011; Mar. & Newer; Does Not Include Stem
Mercedes-Benz; R350; 2012; Does Not Include Stem
Mercedes-Benz; R350; 2013; W/O Valve
Mercedes-Benz; S Series; 2011; Does Not Include Stem
Mercedes-Benz; S Series; 2012; W/O Valve
Mercedes-Benz; S Series; 2013; W/O Valve
Mercedes-Benz; S550; 2011; Does Not Include Stem
Mercedes-Benz; S550; 2012-2013; W/O Valve
Mercedes-Benz; S600; 2011; Does Not Include Stem
Mercedes-Benz; S600; 2012-2013; W/O Valve
Mercedes-Benz; S63 AMG; 2011; Does Not Include Stem
Mercedes-Benz; S63 AMG; 2012-2013; W/O Valve
Mercedes-Benz; S65 AMG; 2011; Does Not Include Stem
Mercedes-Benz; S65 AMG; 2012-2013; W/O Valve
Mercedes-Benz; SL550; 2012; Does Not Include Stem
Mercedes-Benz; SL550; 2013; W/O Valve
Mercedes-Benz; SL63 AMG; 2012; Does Not Include Stem
Mercedes-Benz; SL63 AMG; 2013; W/O Valve
Mercedes-Benz; SLK250; 2012; Does Not Include Stem
Mercedes-Benz; SLK250; 2013; W/O Valve
Mercedes-Benz; SLK280; 2007; May & Newer; Does Not Include Stem
Mercedes-Benz; SLK280; 2008; Does Not Include Stem
Mercedes-Benz; SLK300; 2009-2011; Does Not Include Stem
Mercedes-Benz; SLK350; 2007; May & Newer; Does Not Include Stem
Mercedes-Benz; SLK350; 2008-2012; Does Not Include Stem
Mercedes-Benz; SLK350; 2013; W/O Valve
Mercedes-Benz; SLK55 AMG; 2007; May & Newer; Does Not Include Stem
Mercedes-Benz; SLK55 AMG; 2008-2010; Does Not Include Stem
Mercedes-Benz; SLS AMG; 2011-2012; Does Not Include Stem
Mercedes-Benz; SLS AMG; 2013; W/O Valve
Mercedes-Benz; Sprinter 2500; 2014-2016; Does Not Include Stem
Mercedes-Benz; Sprinter 2500; 2017; Does Not Include Stem
Mercedes-Benz; Sprinter 3500; 2014-2016; Does Not Include Stem
Mercedes-Benz; Sprinter 3500; 2017; Does Not Include Stem
Smart; Fortwo; 2008-2012; Does Not Include Stem
Smart; Fortwo; 2013; W/O Valve

20017

Audi; A3, A4,A5 & Quattro; 2008
Audi; A3, A4,A5 & Quattro; 2009-2012
Audi; Q5; 2009-2012
Audi; S4; 2010-2011
Audi; S5; 2008-2012
Audi; TT; 2008-2009
Audi; TT Quattro; 2008-2009
Volkswagen; Beetle; 2008-2010
Volkswagen; CC; 2009-2011
Volkswagen; CC; 2012-2014
Volkswagen; Eos; 2007-2016
Volkswagen; Golf; 2006
Volkswagen; Golf; 2010
Volkswagen; GTI; 2006-2007; W/16" Or 17" Wheels
Volkswagen; GTI; 2008-2010
Volkswagen; Jetta; 2006-2007
Volkswagen; Jetta; 2008-2009
Volkswagen; Jetta; 2010
Volkswagen; Passat; 2006-2008; W/16" Or 17" Wheels
Volkswagen; Passat; 2009-2010
Volkswagen; R32; 2008
Volkswagen; Rabbit; 2006-2007; W/15" Wheels
Volkswagen; Rabbit; 2008-2009
Volkswagen; Tiguan; 2009-2010
Volkswagen; Tiguan; 2011-2012

Service Pack

20018

Alfa Romeo; 4C; 2012-2016; Rubber Valve
Chevrolet; Trax; 2016; Rubber Valve
Chrysler; 200; 2011; Rubber Valve
Chrysler; 200; 2012; Rubber Valve
Chrysler; 200; 2013-2014; Rubber Valve
Chrysler; 300; 2005-2006; Rubber Valve
Chrysler; 300; 2007; Rubber Valve
Chrysler; 300; 2008; Rubber Valve
Chrysler; 300; 2009-2010; Rubber Valve
Chrysler; 300; 2011; Rubber Valve
Chrysler; 300; 2012; Rubber Valve
Chrysler; 300; 2012; W/Rubber Stem Snap-in Sensor
Chrysler; 300; 2013-2015; Rubber Valve
Chrysler; 300; 2016; Rubber Valve
Chrysler; 300; 2017; Rubber Valve
Chrysler; Aspen; 2007-2011; Rubber Valve
Chrysler; Aspen; 2012-2015; Rubber Valve
Chrysler; Crossfire; 2005; Rubber Valve
Chrysler; Pacifica; 2006-2007; Rubber Valve
Chrysler; Pacifica; 2008; Rubber Valve
Chrysler; PT Cruiser; 2008-2010; Rubber Valve
Chrysler; Sebring; 2007-2009; Rubber Valve
Chrysler; Sebring; 2010; Rubber Valve
Chrysler; Town & Country; 2006-2007; Rubber Valve
Chrysler; Town & Country; 2008; Rubber Valve
Chrysler; Town & Country; 2009-2010; Rubber Valve
Chrysler; Town & Country; 2011-2014; Rubber Valve
Chrysler; Town & Country; 2015; Rubber Valve
Chrysler; Town & Country; 2016; Rubber Valve
Chrysler; Town & Country; 2017; Rubber Valve
Dodge; Avenger; 2008-2009; Rubber Valve
Dodge; Avenger; 2010-2012; Rubber Valve
Dodge; Avenger; 2013-2014; Rubber Valve
Dodge; Caliber; 2007-2010; Rubber Valve
Dodge; Caliber; 2011-2012; Rubber Valve
Dodge; Caravan; 2006-2007; Rubber Valve
Dodge; Challenger; 2008; Rubber Valve
Dodge; Challenger; 2010-2012; Rubber Valve
Dodge; Challenger; 2013-2015; W/Rubber Stem Snap-in Sensor
Dodge; Challenger; 2016; W/Rubber Stem Snap-in Sensor
Dodge; Challenger; 2017; W/Rubber Stem Snap-in Sensor
Dodge; Charger; 2006-2007; Rubber Valve
Dodge; Charger; 2008; Rubber Valve
Dodge; Charger; 2010; Rubber Valve
Dodge; Charger; 2011; Rubber Valve
Dodge; Charger; 2012-2015; Rubber Valve
Dodge; Charger; 2016; Rubber Valve
Dodge; Charger; 2017; Rubber Valve
Dodge; Dakota; 2008-2010; Rubber Valve
Dodge; Durango; 2007; Rubber Valve
Dodge; Durango; 2008; Rubber Valve
Dodge; Durango; 2009; Rubber Valve
Dodge; Durango; 2011-2015; Rubber Valve
Dodge; Durango; 2016; Rubber Valve
Dodge; Grand Caravan; 2006-2007; Rubber Valve
Dodge; Grand Caravan; 2008; Rubber Valve
Dodge; Grand Caravan; 2009-2010; Rubber Valve
Dodge; Grand Caravan; 2011-2015; Rubber Valve
Dodge; Grand Caravan; 2016; Rubber Valve
Dodge; Grand Caravan; 2017; Rubber Valve

Numerical Listing

Dodge; Journey; 2009; Rubber Valve
Dodge; Journey; 2010; Rubber Valve
Dodge; Journey; 2011-2015; Rubber Valve
Dodge; Journey; 2016; Rubber Valve
Dodge; Journey; 2017; Rubber Valve
Dodge; Magnum; 2005-2007; Rubber Valve
Dodge; Magnum; 2008; Rubber Valve
Dodge; Magnum; 2009-2011; Rubber Valve
Dodge; Nitro; 2007-2008; Rubber Valve
Dodge; Nitro; 2009-2011; Rubber Valve
Dodge; Ram 4500; 2010; W/Rubber Stem Snap-in Sensor
Dodge; Ram 5500; 2010; W/Rubber Stem Snap-in Sensor
Dodge; Ram Series; 2008; Rubber Valve
Dodge; Ram Series; 2009; Rubber Valve
Dodge; Ram Series; 2010; Rubber Valve
Dodge; Ram Series; 2010; W/Rubber Stem Snap-in Sensor
Dodge; Ram Series; 2011-2013; Rubber Valve
Fiat; 500; 2012-2015; Rubber Valve
Fiat; 500; 2016; Rubber Valve
Fiat; 500; 2017; Rubber Valve
Ford; C-Max; 2012-2015; Rubber Valve
Ford; C-Max; 2016; Rubber Valve
Ford; C-Max; 2017; Rubber Valve
Ford; Edge; 2011-2014; Rubber Valve
Ford; Edge; 2015-2016; Rubber Valve
Ford; Edge; 2017; Rubber Valve
Ford; Escape; 2009-2010; Rubber Valve
Ford; Escape; 2012-2015; Rubber Valve
Ford; Escape; 2016; Rubber Valve
Ford; Escape; 2017; Rubber Valve
Ford; E-Series Van; 2010; Rubber Valve
Ford; E-Series Van; 2010; W/Steel Wheels
Ford; E-Series Van; 2011-2013; Rubber Valve
Ford; E-Series Van; 2014-2015; Rubber Valve
Ford; E-Series Van; 2016; Rubber Valve
Ford; E-Series Van; 2017; Rubber Valve
Ford; Expedition; 2011-2015; Rubber Valve
Ford; Expedition; 2016; Rubber Valve
Ford; Expedition; 2017; Rubber Valve
Ford; Explorer; 2011-2014; Rubber Valve
Ford; Explorer; 2015; Rubber Valve
Ford; Explorer; 2016; Rubber Valve
Ford; Explorer; 2017; Rubber Valve
Ford; F-150; 2009-2014; Rubber Valve
Ford; F-150; 2015-2016; Rubber Valve
Ford; F-150; 2017; Rubber Valve
Ford; F-250 Super Duty; 2011-2015; Rubber Valve
Ford; F-250 Super Duty; 2016; Rubber Valve
Ford; F-350 Super Duty; 2011-2015; Rubber Valve
Ford; F-350 Super Duty; 2016; Rubber Valve
Ford; F-450 Super Duty; 2014; Rubber Valve
Ford; F-450 Super Duty; 2015-2016; Rubber Valve
Ford; Fiesta; 2011-2015; Rubber Valve
Ford; Fiesta; 2016; Rubber Valve
Ford; Fiesta; 2017; Rubber Valve
Ford; Flex; 2011-2015; Rubber Valve
Ford; Flex; 2016; Rubber Valve
Ford; Focus; 2010; Rubber Valve
Ford; Focus; 2011; Rubber Valve
Ford; Focus; 2012-2015; Rubber Valve
Ford; Focus; 2016; Rubber Valve
Ford; Focus; 2017; Rubber Valve
Ford; Fusion; 2010-2015; Rubber Valve
Ford; Fusion; 2016; Rubber Valve
Ford; Mustang; 2010-2011; Rubber Valve
Ford; Mustang; 2012; exc Shelby GT500
Ford; Mustang; 2013; exc Shelby GT500
Ford; Mustang; 2014; exc Shelby GT500
Ford; Mustang; 2015-2016; Rubber Valve
Ford; Mustang; 2017; Rubber Valve
Ford; Taurus; 2010; May & Newer
Ford; Taurus; 2011-2015; Rubber Valve
Ford; Taurus; 2016; Rubber Valve
Ford; Taurus; 2017; Rubber Valve
Ford; Transit; 2014-2015; Rubber Valve
Ford; Transit; 2016; Rubber Valve
Ford; Transit; 2017; Rubber Valve
Ford; Transit Connect; 2010-2015; Rubber Valve
Ford; Transit Connect; 2016; Rubber Valve
Ford; Transit Connect; 2017; Rubber Valve
Jeep; Cherokee; 2014; Rubber Valve
Jeep; Cherokee; 2015; Rubber Valve
Jeep; Commander; 2006-2007; Rubber Valve
Jeep; Commander; 2008-2010; Rubber Valve
Jeep; Compass; 2007-2010; Rubber Valve
Jeep; Compass; 2011; Rubber Valve
Jeep; Compass; 2012-2015; Rubber Valve
Jeep; Compass; 2016; Rubber Valve
Jeep; Compass; 2017; Rubber Valve
Jeep; Grand Cherokee; 2005-2007; Rubber Valve
Jeep; Grand Cherokee; 2008-2010; Rubber Valve
Jeep; Grand Cherokee; 2011-2015; Rubber Valve
Jeep; Liberty; 2005-2008; Rubber Valve
Jeep; Liberty; 2009; Rubber Valve
Jeep; Liberty; 2010-2012; Rubber Valve
Jeep; Patriot; 2007-2010; Rubber Valve
Jeep; Patriot; 2011-2012; Rubber Valve
Jeep; Patriot; 2013-2015; Rubber Valve
Jeep; Patriot; 2016; Rubber Valve
Jeep; Patriot; 2017; Rubber Valve
Jeep; Wrangler; 2007-2008; Rubber Valve
Jeep; Wrangler; 2009; Rubber Valve
Jeep; Wrangler; 2010; Rubber Valve
Jeep; Wrangler; 2011; Rubber Valve
Jeep; Wrangler; 2012; Rubber Valve
Jeep; Wrangler; 2013-2015; Rubber Valve
Jeep; Wrangler; 2016; Rubber Valve
Jeep; Wrangler; 2017; Rubber Valve
Lincoln; Continental; 2017; Rubber Valve
Lincoln; Mark LT; 2013-2014; Rubber Valve
Lincoln; Mark LT; 2015-2016; Rubber Valve
Lincoln; MKC; 2015; Rubber Valve
Lincoln; MKC; 2016; Rubber Valve
Lincoln; MKC; 2017; Rubber Valve
Lincoln; MKS; 2011-2015; Rubber Valve
Lincoln; MKS; 2016; Rubber Valve
Lincoln; MKT; 2011-2016; Rubber Valve
Lincoln; MKT; 2017; Rubber Valve
Lincoln; MKX; 2011-2014; Rubber Valve
Lincoln; MKX; 2015-2016; Rubber Valve
Lincoln; MKX; 2017; Rubber Valve
Lincoln; MKZ; 2010-2015; Rubber Valve
Lincoln; MKZ; 2016; Rubber Valve
Lincoln; Navigator; 2011-2015; Rubber Valve
Lincoln; Navigator; 2016; Rubber Valve
Lincoln; Navigator; 2017; Rubber Valve
Lincoln; Town Car; 2011; Rubber Valve
Mazda; Tribute; 2009-2011; Rubber Valve
Mercury; Mariner; 2009-2011; Rubber Valve
Mercury; Milan; 2010-2011; Rubber Valve
Mitsubishi; Lancer; 2012; Rubber Valve
Ram; 4500; 2012; Rubber Valve
Ram; 5500; 2012; Rubber Valve
Ram; C/V; 2012; Rubber Valve
Ram; C/V; 2013-2015; Rubber Valve
Ram; ProMaster; 2014-2015; Rubber Valve
Ram; ProMaster; 2016; Rubber Valve
Ram; ProMaster; 2017; Rubber Valve
Ram; Ram Series; 2011; W/Rubber Stem Snap-in Sensor
Ram; Ram Series; 2012-2013; Rubber Valve
Ram; Ram Series; 2014-2015; Rubber Valve
Rolls Royce; Ghost; 2011-2016; Rubber Valve
Rolls Royce; Phantom; 2012-2016; Rubber Valve
Rolls Royce; Silver Dawn; 2016; Rubber Valve
Rolls Royce; Wraith; 2014-2016; Rubber Valve
Volkswagen; Routan; 2009-2010; Rubber Valve
Volkswagen; Routan; 2011-2013; Rubber Valve
VPG; MV-1; 2011; Rubber Valve
VPG; MV-1; 2012; Rubber Valve
VPG; MV-1; 2013-2016; Rubber Valve

Numerical Listing

Service Pack
20019

Acura; CSX; 2008-2011
Acura; TL; 2009-2013
Acura; ZDX; 2010-2013
Honda; Civic; 2008-2014
Honda; CR-Z; 2011-2014
Honda; CR-Z; 2015
Honda; Element; 2009-2011
Honda; Fit; 2009-2014
Honda; Insight; 2010-2014
Honda; Odyssey; 2011-2016
Hyundai; Elantra; 2010
Hyundai; Elantra; 2011
Hyundai; Elantra; 2012
Hyundai; Elantra; 2013

Service Pack
20020

Chrysler; 200; 2011; Fits Schrader Sensor; Includes Stem Only
Chrysler; 200; 2012; Fits Schrader Sensor; Includes Stem Only
Chrysler; 300; 2005-2006; Fits Schrader Sensor; Includes Stem Only
Chrysler; 300; 2007; Fits Schrader Sensor; Includes Stem Only
Chrysler; 300; 2008; Fits Schrader Sensor; Includes Stem Only
Chrysler; 300; 2009-2010; Fits Schrader Sensor; Includes Stem Only
Chrysler; 300; 2012; Fits Schrader Sensor; Includes Stem Only
Chrysler; Aspen; 2007-2011; Fits Schrader Sensor; Includes Stem Only
Chrysler; Crossfire; 2005; Fits Schrader Sensor; Includes Stem Only
Chrysler; Pacifica; 2006-2007; Fits Schrader Sensor; Includes Stem Only
Chrysler; Pacifica; 2008; Fits Schrader Sensor; Includes Stem Only
Chrysler; PT Cruiser; 2008-2010; Fits Schrader Sensor; Includes Stem Only
Chrysler; Sebring; 2007-2009; Fits Schrader Sensor; Includes Stem Only
Chrysler; Sebring; 2010; Fits Schrader Sensor; Includes Stem Only
Chrysler; Town & Country; 2006-2007; Fits Schrader Sensor; Includes Stem Only
Chrysler; Town & Country; 2008; Fits Schrader Sensor; Includes Stem Only
Chrysler; Town & Country; 2009-2010; Fits Schrader Sensor; Includes Stem Only
Dodge; Avenger; 2008-2009; Fits Schrader Sensor; Includes Stem Only
Dodge; Avenger; 2010-2012; Fits Schrader Sensor; Includes Stem Only
Dodge; Caliber; 2007-2010; Fits Schrader Sensor; Includes Stem Only
Dodge; Caliber; 2011-2012; Fits Schrader Sensor; Includes Stem Only
Dodge; Caravan; 2006-2007; Fits Schrader Sensor; Includes Stem Only
Dodge; Challenger; 2008; Fits Schrader Sensor; Includes Stem Only
Dodge; Challenger; 2009; Fits Schrader Sensor; Includes Stem Only
Dodge; Challenger; 2010-2012; Fits Schrader Sensor; Includes Stem Only
Dodge; Charger; 2006-2007; Fits Schrader Sensor; Includes Stem Only
Dodge; Charger; 2008; Fits Schrader Sensor; Includes Stem Only
Dodge; Charger; 2009; Fits Schrader Sensor; Includes Stem Only
Dodge; Charger; 2010; Fits Schrader Sensor; Includes Stem Only
Dodge; Dakota; 2008-2010; Fits Schrader Sensor; Includes Stem Only
Dodge; Durango; 2007; W/Schrader Sensor; Includes Stem Only
Dodge; Durango; 2008; Fits Schrader Sensor; Includes Stem Only
Dodge; Durango; 2009; Fits Schrader Sensor; Includes Stem Only
Dodge; Grand Caravan; 2006-2007; Fits Schrader Sensor; Includes Stem Only
Dodge; Grand Caravan; 2008; Fits Schrader Sensor; Includes Stem Only
Dodge; Grand Caravan; 2009-2010; Fits Schrader Sensor; Includes Stem Only
Dodge; Journey; 2009; Fits Schrader Sensor; Includes Stem Only
Dodge; Journey; 2010; Fits Schrader Sensor; Includes Stem Only
Dodge; Magnum; 2005-2007; Fits Schrader Sensor; Includes Stem Only
Dodge; Magnum; 2008; Fits Schrader Sensor; Includes Stem Only
Dodge; Nitro; 2007-2008; Fits Schrader Sensor; Includes Stem Only
Dodge; Nitro; 2009-2011; Fits Schrader Sensor; Includes Stem Only
Dodge; Ram Series; 2008; Fits Schrader Sensor; Includes Stem Only
Dodge; Ram Series; 2009; Fits Schrader Sensor; Includes Stem Only
Dodge; Ram Series; 2010; Fits Schrader Sensor; Includes Stem Only
Dodge; Viper; 2012-2013; Fits Schrader Sensor; Includes Stem Only
Jeep; Commander; 2006-2007; Fits Schrader Sensor; Includes Stem Only
Jeep; Commander; 2008-2010; Fits Schrader Sensor; Includes Stem Only
Jeep; Compass; 2007-2010; Fits Schrader Sensor; Includes Stem Only
Jeep; Compass; 2011; Fits Schrader Sensor; Includes Stem Only
Jeep; Grand Cherokee; 2005-2007; Fits Schrader Sensor; Includes Stem Only
Jeep; Grand Cherokee; 2008-2010; Fits Schrader Sensor; Includes Stem Only
Jeep; Liberty; 2005-2008; Fits Schrader Sensor; Includes Stem Only
Jeep; Liberty; 2009; Fits Schrader Sensor; Includes Stem Only
Jeep; Liberty; 2010-2012; Fits Schrader Sensor; Includes Stem Only
Jeep; Patriot; 2007-2010; Fits Schrader Sensor; Includes Stem Only
Jeep; Patriot; 2011-2012; Fits Schrader Sensor; Includes Stem Only
Jeep; Wrangler; 2007-2008; Fits Schrader Sensor; Includes Stem Only
Jeep; Wrangler; 2009; Fits Schrader Sensor; Includes Stem Only
Jeep; Wrangler; 2010; Fits Schrader Sensor; Includes Stem Only

Numerical Listing

Jeep; Wrangler; 2011; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; 550,63AMG; 2007-2009; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; C Series; 2007; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; C Series; 2008-2009; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; C Series; 2010-2012; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; C Series; 2013; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; C250; 2012; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; C250; 2013; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; C280; 2007; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; CLK; 2006; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; CLK350; 2006-2009; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; CLS550; 2012; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; CLS550; 2013; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; E350; 2010-2012; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; E350; 2013; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; E550; 2010-2011; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; E550; 2012-2013; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; E63 AMG; 2010-2011; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; E63 AMG; 2012-2013; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; G500; 2007; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; G500; 2008; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; G55 AMG; 2007; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; G55 AMG; 2008-2010; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; G55 AMG; 2011; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; G550; 2009-2010; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; G550; 2011; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; G550; 2012-2013; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; GL; 2010; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; GL; 2011; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; GL; 2012-2013; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; GL350; 2010; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; GL350; 2011; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; GL350; 2012-2013; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; GL63 AMG; 2013; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; GLK350; 2010; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; GLK350; 2011; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; GLK350; 2012; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; GLK350; 2013; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; ML350; 2010; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; ML350; 2011; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; ML350; 2012; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; ML350; 2013; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; ML450; 2010; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; ML450; 2011; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; ML550; 2010; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; ML550; 2011-2012; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; ML63 AMG; 2010; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; ML63 AMG; 2011; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; ML63 AMG; 2012-2013; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; R350; 2010; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; R350; 2011; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; R350; 2012; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; R350; 2013; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; S Series; 2011; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; S Series; 2012; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; S Series; 2013; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; S550; 2011; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; S550; 2012-2013; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; S600; 2011; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; S600; 2012-2013; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; S63 AMG; 2011; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; S63 AMG; 2012-2013; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; S65 AMG; 2011; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; S65 AMG; 2012-2013; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; SL550; 2012; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; SL550; 2013; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; SL63 AMG; 2012; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; SL63 AMG; 2013; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; SLK250; 2012; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; SLK250; 2013; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; SLK280; 2007; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; SLK280; 2008; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; SLK300; 2009-2011; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; SLK350; 2007; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; SLK350; 2008-2012; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; SLK350; 2013; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; SLK55 AMG; 2007; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; SLK55 AMG; 2008-2010; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; SLS AMG; 2011-2012; Fits Schrader Sensor; Includes Stem Only
Mercedes-Benz; SLS AMG; 2013; Fits Schrader Sensor; Includes Stem Only
Mitsubishi; Raider; 2008-2009; Fits Schrader Sensor; Includes Stem Only
Smart; Fortwo; 2008-2012; Fits Schrader Sensor; Includes Stem Only
Smart; Fortwo; 2013; Fits Schrader Sensor; Includes Stem Only
Suzuki; Kizashi; 2010-2012; Fits Schrader Sensor; Includes Stem Only

20022

Hyundai; Accent; 2008-2011
Hyundai; Equus; 2011-2013
Hyundai; Genesis; 2009-2014
Hyundai; Santa Fe; 2013
Hyundai; Santa Fe XL; 2013
Hyundai; Sonata; 2009-2010
Hyundai; Tucson; 2010-2013
Kia; Borrego; 2009-2011
Kia; Rio; 2007-2011
Kia; Rio5; 2007-2011
Kia; Spectra; 2006
Kia; Spectra; 2007-2009
Kia; Spectra5; 2006
Kia; Spectra5; 2007-2009
Kia; Sportage; 2009-2012
Kia; Sportage; 2013
Toyota; Sequoia; 2008-2013
Toyota; Sienna; 2006-2014
Toyota; Tundra; 2006; Nov. 1 & Newer
Toyota; Tundra; 2007; W/Alloy Wheels; W/TRW Sensor
Toyota; Tundra; 2008-2011
Toyota; Tundra; 2012
Toyota; Tundra; 2013
Toyota; Tundra; 2014
Toyota; Tundra; 2015

Numerical Listing

Service Pack

20023

Audi; A3, A4,A5 & Quattro; 2002-2007; Does Not Include Valve
Audi; A3, A4,A5 & Quattro; 2008; Does Not Include Valve
Audi; A6; 2002-2004; Does Not Include Valve
Audi; A6; 2006-2008; Does Not Include Valve
Audi; A6; 2009; Does Not Include Valve
Audi; A6; 2010; Does Not Include Valve
Audi; A6; 2011; Does Not Include Valve
Audi; A6 Quattro; 2006-2008; Does Not Include Valve
Audi; A6 Quattro; 2010; Does Not Include Valve
Audi; A6 Quattro; 2011; Does Not Include Valve
Audi; A8; 2000; Does Not Include Valve
Audi; A8 Quattro; 2000-2002; Does Not Include Valve
Audi; A8 Quattro; 2003; Does Not Include Valve
Audi; A8 Quattro; 2004-2011; Does Not Include Valve
Audi; Allroad Quattro; 2001-2005; Does Not Include Valve
Audi; Q7; 2007-2009; Does Not Include Valve
Audi; Q7; 2010; Does Not Include Valve
Audi; Q7; 2011; Does Not Include Valve
Audi; Q7; 2012; Does Not Include Valve
Audi; R8; 2008-2009; Does Not Include Valve
Audi; R8; 2010; Does Not Include Valve
Audi; R8; 2011; Does Not Include Valve
Audi; R8; 2012; Does Not Include Valve
Audi; R8; 2014-2015; Does Not Include Valve
Audi; RS4; 2007-2008; Does Not Include Valve
Audi; RS6; 2003; Does Not Include Valve
Audi; RS7; 2014-2016; Does Not Include Valve
Audi; S4; 2002; Does Not Include Valve
Audi; S4; 2003; Does Not Include Valve
Audi; S4; 2004-2009; Does Not Include Valve
Audi; S6; 2007-2009; Does Not Include Valve
Audi; S6; 2010; Does Not Include Valve
Audi; S6; 2011; Does Not Include Valve
Audi; S8; 2001-2002; Does Not Include Valve
Audi; S8; 2003; Does Not Include Valve
Audi; S8; 2004-2006; Does Not Include Valve
Audi; S8; 2007-2008; Does Not Include Valve
Audi; S8; 2009; Does Not Include Valve
Audi; S8; 2015; Does Not Include Valve
Bentley; Azure; 2007-2009; Does Not Include Valve
Bentley; Continental; 2003-2005; Does Not Include Valve
Bentley; Continental; 2006-2010; Does Not Include Valve
Bentley; Continental; 2012-2014; Does Not Include Valve
Bentley; Mulsanne; 2011-2015; Does Not Include Valve
BMW; 1 Series; 2008; Does Not Include Valve
BMW; 1 Series; 2009-2010; Does Not Include Valve
BMW; 1 Series; 2011-2013; Does Not Include Valve
BMW; 228i; 2015
BMW; 320i; 2001-2002; Does Not Include Valve
BMW; 320i; 2003-2005; Does Not Include Valve
BMW; 323Ci; 2000; Does Not Include Valve
BMW; 323i; 2000; Does Not Include Valve
BMW; 323i; 2003; Does Not Include Valve
BMW; 323i; 2006; Does Not Include Valve; Jun. & Newer
BMW; 323i; 2007-2010; Does Not Include Valve
BMW; 325; 2001-2002; Does Not Include Valve
BMW; 325; 2003-2006; Does Not Include Valve
BMW; 325; 2007; Does Not Include Valve
BMW; 328Ci; 2000; Does Not Include Valve
BMW; 328i; 2000; Does Not Include Valve
BMW; 328i; 2007-2008; Does Not Include Valve
BMW; 328i; 2009; Does Not Include Valve
BMW; 328i; 2010-2013; Does Not Include Valve
BMW; 328i; 2014-2016; Does Not Include Valve
BMW; 328i GT xDrive; 2014-2016; Does Not Include Valve
BMW; 328i xDrive; 2009; Does Not Include Valve
BMW; 328i xDrive; 2010-2013; Does Not Include Valve
BMW; 328i xDrive; 2014-2015; Does Not Include Valve
BMW; 328xi; 2007-2008; Does Not Include Valve
BMW; 330; 2001-2002; Does Not Include Valve
BMW; 330; 2003-2006; Does Not Include Valve
BMW; 335d; 2009; Does Not Include Valve
BMW; 335d; 2010-2011; Does Not Include Valve
BMW; 335i; 2007-2008; Does Not Include Valve
BMW; 335i; 2009; Does Not Include Valve
BMW; 335i; 2010-2012; Does Not Include Valve
BMW; 335i; 2013-2014; Does Not Include Valve
BMW; 335i GT xDrive; 2014-2015; Does Not Include Valve
BMW; 335i xDrive; 2009; Does Not Include Valve
BMW; 335i xDrive; 2010-2012; Does Not Include Valve
BMW; 335i xDrive; 2013-2015; Does Not Include Valve
BMW; 335is; 2012-2013; Does Not Include Valve
BMW; 335xi; 2007-2008; Does Not Include Valve
BMW; 428i; 2014; Does Not Include Valve
BMW; 428i; 2015; Does not include valve
BMW; 428i xDrive; 2014; Does Not Include Valve
BMW; 428i xDrive; 2015; Does not include valve
BMW; 435i; 2014; Does Not Include Valve
BMW; 435i; 2015; Does not include valve
BMW; 435i; 2016; Does not include valve
BMW; 435i xDrive; 2014; Does Not Include Valve
BMW; 435i xDrive; 2015; Does not include valve
BMW; 525i; 2001; Does Not Include Valve
BMW; 525i; 2002; Does Not Include Valve
BMW; 525i; 2003-2005; Does Not Include Valve
BMW; 525i; 2006-2007; Does Not Include Valve
BMW; 525xi; 2006-2007; Does Not Include Valve
BMW; 528; 1997-1998; Does Not Include Valve
BMW; 528; 1999-2000; Does Not Include Valve
BMW; 528; 2008; Does Not Include Valve
BMW; 528; 2009-2011; Does Not Include Valve
BMW; 528; 2012-2014; Does Not Include Valve
BMW; 528; 2015-2016; Does Not Include Valve
BMW; 528xi; 2008; Does Not Include Valve
BMW; 530; 2001; Does Not Include Valve
BMW; 530; 2002; Does Not Include Valve
BMW; 530; 2003-2005; Does Not Include Valve
BMW; 530; 2006-2007; Does Not Include Valve
BMW; 535; 2008-2010; Does Not Include Valve
BMW; 535; 2011; Does Not Include Valve
BMW; 535; 2012-2014; Does Not Include Valve
BMW; 535; 2015-2016; Does Not Include Valve
BMW; 535d; 2014; Does Not Include Valve
BMW; 535d; 2015-2016; Does Not Include Valve
BMW; 535d xDrive; 2014; Does Not Include Valve
BMW; 535d xDrive; 2015-2016; Does Not Include Valve
BMW; 535xi; 2008; Does Not Include Valve
BMW; 540i; 1997-1998; Does Not Include Valve
BMW; 540i; 1999-2000; Does Not Include Valve
BMW; 540i; 2001; Does Not Include Valve
BMW; 540i; 2002; Does Not Include Valve
BMW; 540i; 2003; Does Not Include Valve
BMW; 540i; 2008-2011; Does Not Include Valve
BMW; 540i; 2012-2016; Does Not Include Valve
BMW; 545i; 2004-2005; Does Not Include Valve
BMW; 550; 2006-2011; Does Not Include Valve
BMW; 550; 2012-2014; Does Not Include Valve
BMW; 550; 2015-2016; Does Not Include Valve
BMW; 640; 2012-2015; Does Not Include Valve
BMW; 640; 2016; Does Not Include Valve
BMW; 645Ci; 2004-2005; Does Not Include Valve
BMW; 650; 2006-2010; Does Not Include Valve
BMW; 650; 2012-2015; Does Not Include Valve
BMW; 650; 2016; Does Not Include Valve
BMW; 650i Gran Coupe xDrive; 2016; Does Not Include Valve

Numerical Listing

BMW; 740i; 1997-1998; Does Not Include Valve
BMW; 740i; 1999-2001; Does Not Include Valve
BMW; 740i; 2011; Does Not Include Valve
BMW; 740i; 2012-2014; Does Not Include Valve
BMW; 740i; 2015-2016; Does Not Include Valve
BMW; 740iL; 1997-1998; Does Not Include Valve
BMW; 740iL; 1999-2000; Does Not Include Valve
BMW; 740iL; 2001; Does Not Include Valve
BMW; 740Li; 2011; Does Not Include Valve
BMW; 740Li; 2012-2016; Does Not Include Valve
BMW; 740Li xDrive; 2013-2016; Does Not Include Valve
BMW; 745; 2002; Does Not Include Valve
BMW; 745; 2003; Does Not Include Valve
BMW; 745; 2004-2005; Does Not Include Valve
BMW; 750; 2006-2010; Does Not Include Valve
BMW; 750; 2011; Does Not Include Valve
BMW; 750; 2012-2016; Does Not Include Valve
BMW; 750iL; 1997-1998; Does Not Include Valve
BMW; 750iL; 1999-2000; Does Not Include Valve
BMW; 750iL; 2001; Does Not Include Valve
BMW; 760i; 2004-2005; Does Not Include Valve
BMW; 760i; 2006; Does Not Include Valve
BMW; 760Li; 2003; Does Not Include Valve
BMW; 760Li; 2004-2008; Does Not Include Valve
BMW; 760Li; 2010; Does Not Include Valve
BMW; 760Li; 2011; Does Not Include Valve
BMW; 760Li; 2012-2014; Does Not Include Valve
BMW; 760Li; 2015; Does Not Include Valve
BMW; 760Li; 2016; Does Not Include Valve
BMW; ActiveHybrid 3; 2013-2014; Does Not Include Valve
BMW; ActiveHybrid 5; 2012-2014; Does Not Include Valve
BMW; ActiveHybrid 5; 2015; Does Not Include Valve
BMW; ActiveHybrid 7; 2013-2015; Does Not Include Valve
BMW; Alpina B7; 2007-2008; Does Not Include Valve
BMW; Alpina B7; 2011-2015; Does Not Include Valve
BMW; Alpina B7 xDrive; 2011; Does Not Include Valve
BMW; Alpina B7L; 2011; Does Not Include Valve
BMW; Alpina B7L xDrive; 2011; Does Not Include Valve
BMW; M; 2000-2001; Does Not Include Valve
BMW; M; 2002; Does Not Include Valve
BMW; M; 2003; Does Not Include Valve
BMW; M; 2004-2010; Does Not Include Valve
BMW; M; 2011-2012; Does Not Include Valve
BMW; M; 2013; Does Not Include Valve
BMW; M; 2014; Does Not Include Valve
BMW; M; 2015-2016; Does Not Include Valve
BMW; X; 1999-2004; Does Not Include Valve
BMW; X; 2005-2007; Does Not Include Valve
BMW; X; 2008-2010; Does Not Include Valve
BMW; X; 2011; Does Not Include Valve
BMW; X; 2012-2014; Does Not Include Valve
BMW; X; 2015; Does Not Include Valve
BMW; X; 2016; Does Not Include Valve
BMW; Z3; 2000-2002; Does Not Include Valve
BMW; Z4; 2003-2010; Does Not Include Valve
BMW; Z4; 2011; Does Not Include Valve
BMW; Z4; 2012-2015; Does Not Include Valve
BMW; Z4; 2016; Does Not Include Valve
BMW; Z8; 2000-2002; Does Not Include Valve
BMW; Z8; 2003; Does Not Include Valve
Bugatti; Veyron 16.4; 2006; Does Not Include Valve
Ferrari; 612 Scaglietti; 2004-2011; Does Not Include Valve
Ferrari; Enzo; 2003-2004; Does Not Include Valve
Ferrari; F430; 2006-2007; Does Not Include Valve
Ferrari; F430; 2008-2009; Does Not Include Valve
Ferrari; Maranello; 1998-2006; Does Not Include Valve
Land Rover; LR3; 2002-2005; Does Not Include Valve
Land Rover; Range Rover; 2002; Does Not Include Valve
Land Rover; Range Rover; 2003-2005; Does Not Include Valve
Maserati; Coupe; 2004-2006; Does Not Include Valve
Maserati; Quattroporte; 2004-2008; Does Not Include Valve
Maserati; Spyder; 2004-2006; Does Not Include Valve
Mercedes-Benz; C Series; 2001-2006; Does Not Include Valve
Mercedes-Benz; CL; 2000-2006; Does Not Include Valve
Mercedes-Benz; E320; 2001-2005; Does Not Include Valve
Mercedes-Benz; E430; 2001-2002; Does Not Include Valve
Mercedes-Benz; E500; 2003-2005; Does Not Include Valve
Mercedes-Benz; E55 AMG; 1999; Does Not Include Valve; Jul. & Newer
Mercedes-Benz; E55 AMG; 2000-2005; Does Not Include Valve
Mercedes-Benz; S Series; 2006; Does Not Include Valve
Mercedes-Benz; S430; 2000-2006; Does Not Include Valve
Mercedes-Benz; S500; 2000; Does Not Include Valve
Mercedes-Benz; S500; 2001; Does Not Include Valve
Mercedes-Benz; S500; 2002-2006; Does Not Include Valve
Mercedes-Benz; S55 AMG; 2001-2006; Does Not Include Valve
Mercedes-Benz; S600; 2001-2006; Does Not Include Valve
Mercedes-Benz; S65 AMG; 2006; Does Not Include Valve
Mercedes-Benz; SL500; 2000-2005; Does Not Include Valve
Mercedes-Benz; SL55 AMG; 2003; Does Not Include Valve
Mercedes-Benz; SL55 AMG; 2005; Does Not Include Valve
Mercedes-Benz; SL600; 2001-2002; Does Not Include Valve
Mercedes-Benz; SL600; 2004-2005; Does Not Include Valve
Mercedes-Benz; SL65 AMG; 2005; Does Not Include Valve
Mercedes-Benz; SLR McLaren; 2004-2006; Does Not Include Valve
Mercedes-Benz; SLR McLaren; 2007; Does Not Include Valve
Mini; Cooper; 2008-2009; Does Not Include Valve
Mini; Cooper; 2010-2013; Does Not Include Valve
Mini; Cooper; 2014; Does Not Include Valve
Mini; Cooper; 2015-2016; Does Not Include Valve
Porsche; 911; 2005-2006; Does Not Include Valve
Porsche; 911; 2007-2009; Does Not Include Valve
Porsche; 911; 2010; Does Not Include Valve
Porsche; 911; 2011; Does Not Include Valve
Porsche; 911; 2012; Does Not Include Valve
Porsche; 911; 2013-2014; Does Not Include Valve
Porsche; 911; 2015-2016; Does Not Include Valve
Porsche; 918 Spyder; 2015-2016; Does Not Include Valve
Porsche; Boxster; 2005-2007; Does Not Include Valve
Porsche; Boxster; 2008-2010; Does Not Include Valve
Porsche; Boxster; 2011; Does Not Include Valve
Porsche; Boxster; 2012-2013; Does Not Include Valve
Porsche; Boxster; 2014-2016; Does Not Include Valve
Porsche; Carrera GT; 2004-2005; Does Not Include Valve
Porsche; Cayenne; 2003-2006; Does Not Include Valve
Porsche; Cayenne; 2008-2010; Does Not Include Valve
Porsche; Cayenne; 2011-2013; Does Not Include Valve
Porsche; Cayenne; 2014-2016; Does Not Include Valve
Porsche; Cayman; 2005-2007; Does Not Include Valve
Porsche; Cayman; 2008; Does Not Include Valve
Porsche; Cayman; 2009-2010; Does Not Include Valve
Porsche; Cayman; 2011; Does Not Include Valve
Porsche; Cayman; 2012-2016; Does Not Include Valve
Porsche; Macan; 2016; Does Not Include Valve
Porsche; Macan; 2017; Does Not Include Valve
Porsche; Panamera; 2010; Does Not Include Valve
Porsche; Panamera; 2014; Does Not Include Valve
Rolls Royce; Ghost; 2011-2016; Does Not Include Valve
Rolls Royce; Phantom; 2007-2011; Does Not Include Valve
Rolls Royce; Phantom; 2012-2016; Does Not Include Valve
Rolls Royce; Silver Dawn; 2016; Does Not Include Valve
Rolls Royce; Wraith; 2014-2016; Does Not Include Valve
Volkswagen; Phaeton; 2004-2006; Does Not Include Valve; W/315 MHz Sensor
Volkswagen; Touareg; 2004-2006; Does Not Include Valve
Volkswagen; Touareg; 2007; Does Not Include Valve
Volkswagen; Touareg; 2008-2009; Does Not Include Valve
Volkswagen; Touareg; 2010; Does Not Include Valve
Volkswagen; Touareg; 2011-2013; Does Not Include Valve; W/315 MHz Sensor
Volkswagen; Touareg; 2014-2016; Does Not Include Valve; W/315 MHz Sensor

Numerical Listing

Service Pack

20030

Buick; Allure; 2007-2008; W/Siemens Sensor
Buick; Enclave; 2008; W/Siemens Sensor
Buick; LaCrosse; 2007-2008; W/Siemens Sensor
Chevrolet; Equinox; 2007-2009; W/Siemens Sensor
Chevrolet; Express; 2008-2009; W/Siemens Sensor
Chrysler; 300; 2005-2006; W/Siemens Sensor
Chrysler; 300; 2007; W/Siemens Sensor
Chrysler; 300; 2008; W/Siemens Sensor
Chrysler; 300M; 2002-2004; W/Siemens Sensor
Chrysler; Aspen; 2007-2011; W/Siemens Sensor
Chrysler; Concorde; 2002-2004; W/Siemens Sensor
Chrysler; Crossfire; 2004; W/Siemens Sensor
Chrysler; Crossfire; 2006-2008; W/Siemens Sensor
Chrysler; Intrepid; 2002-2004; W/Siemens Sensor
Chrysler; Pacifica; 2004; W/Siemens Sensor
Chrysler; Pacifica; 2005
Chrysler; Pacifica; 2006-2007; W/Siemens Sensor
Chrysler; Pacifica; 2008; W/Siemens Sensor
Chrysler; Prowler; 2002; W/Siemens Sensor
Chrysler; PT Cruiser; 2008-2010; W/Siemens Sensor
Chrysler; Sebring; 2007-2009; W/Siemens Sensor
Chrysler; Town & Country; 2004-2005
Chrysler; Town & Country; 2006-2007; W/Siemens Sensor
Chrysler; Town & Country; 2008; W/Siemens Sensor
Chrysler; Town & Country; 2009-2010; W/Siemens Sensor
Dodge; Avenger; 2008-2009; W/Siemens Sensor
Dodge; Caliber; 2007-2010; W/Siemens Sensor
Dodge; Caravan; 2004-2005
Dodge; Caravan; 2006-2007; W/Siemens Sensor
Dodge; Charger; 2006-2007; W/Siemens Sensor
Dodge; Charger; 2008; W/Siemens Sensor
Dodge; Durango; 2007; W/Siemens Sensor
Dodge; Durango; 2008; W/Siemens Sensor
Dodge; Grand Caravan; 2004-2005
Dodge; Grand Caravan; 2006-2007; W/Siemens Sensor
Dodge; Grand Caravan; 2008; W/Siemens Sensor
Dodge; Grand Caravan; 2009-2010; W/Siemens Sensor
Dodge; Journey; 2009; W/Siemens Sensor
Dodge; Journey; 2010; W/Siemens Sensor
Dodge; Magnum; 2005-2007; W/Siemens Sensor
Dodge; Magnum; 2008; W/Siemens Sensor
Dodge; Nitro; 2007-2008; W/Siemens Sensor
GMC; Acadia; 2007-2008; W/Siemens Sensor
GMC; Savana Series; 2008-2009; W/Siemens Sensor
Jaguar; Jaguar; 2004-2012
Jeep; Commander; 2006-2007; W/Siemens Sensor
Jeep; Compass; 2007-2010; W/Siemens Sensor
Jeep; Grand Cherokee; 2005-2007; W/Siemens Sensor
Jeep; Liberty; 2005-2008; W/Siemens Sensor
Jeep; Patriot; 2007-2010; W/Siemens Sensor
Jeep; Wrangler; 2007-2008; W/Siemens Sensor
Land Rover; LR2; 2008-2015
Land Rover; LR3; 2006-2009
Land Rover; LR4; 2010-2011
Land Rover; LR4; 2012-2014
Land Rover; Range Rover; 2006-2011
Land Rover; Range Rover; 2012-2014
Land Rover; Range Rover Evoque; 2012-2015
Land Rover; Range Rover Sport; 2006-2011
Land Rover; Range Rover Sport; 2012-2014
Mitsubishi; i-MiEV; 2012-2016
Mitsubishi; i-MiEV; 2017
Mitsubishi; Lancer; 2008-2010
Mitsubishi; Lancer; 2011
Mitsubishi; Lancer; 2012
Mitsubishi; Lancer; 2013-2014
Mitsubishi; Lancer; 2015-2016
Mitsubishi; Mirage; 2014
Mitsubishi; Outlander; 2007-2010
Mitsubishi; Outlander; 2011-2015
Mitsubishi; Outlander; 2016
Mitsubishi; Outlander Sport; 2011-2015
Mitsubishi; RVR; 2011-2014
Pontiac; G Series; 2008; W/Siemens Sensor
Pontiac; Grand Prix; 2007; W/Siemens Sensor
Pontiac; Montana; 2008; W/Siemens Sensor
Pontiac; Solstice; 2008-2009; W/Siemens Sensor
Pontiac; Torrent; 2007-2009; W/Siemens Sensor
Saturn; Aura; 2007; W/Siemens Sensor
Saturn; Outlook; 2007-2008; W/Siemens Sensor
Saturn; Sky; 2008-2010; W/Siemens Sensor
Suzuki; Kizashi; 2010-2012; W/Siemens Sensor
Suzuki; XL-7; 2007-2009; W/Siemens Sensor

20031

Lexus; GS300; 2006
Lexus; GS430; 2005
Lexus; GS430; 2006; Jun. & Older
Lexus; GX470; 2004-2005
Lexus; GX470; 2006; Jan. 31 & Older
Lexus; IS250; 2006; Mar. & Older
Lexus; IS350; 2006; Mar. & Older
Lexus; LX470; 2005
Lexus; LX470; 2006; Jul. & Older
Lexus; RX330; 2006; Jan. 31 & Older
Toyota; 4Runner; 2003-2005
Toyota; 4Runner; 2006; May & Older
Toyota; Land Cruiser; 2005; May & Newer
Toyota; Land Cruiser; 2006; Mar. & Older
Toyota; Sequoia; 2004-2007
Toyota; Tacoma; 2005
Toyota; Tacoma; 2006; Jul. & Older
Toyota; Tundra; 2005
Toyota; Tundra; 2006; Oct. 31 & Older

Numerical Listing

Service Pack

20032

Honda; Accord; 2008-2012
Honda; CR-V; 2007-2011
Honda; Fit; 2008
Honda; Pilot; 2009; W/Alloy Wheels
Honda; Pilot; 2010-2011; Exc. LX
Honda; Pilot; 2012-2015; W/Alloy Wheels
Honda; S2000; 2008-2009
Lexus; CT200h; 2011
Lexus; CT200h; 2012-2015
Lexus; CT200h; 2016
Lexus; ES300h; 2013
Lexus; ES300h; 2014-2016
Lexus; ES350; 2007-2013
Lexus; ES350; 2014-2016
Lexus; GS350; 2007-2011
Lexus; GS350; 2013
Lexus; GS350; 2014-2016
Lexus; GS430; 2006; Jul. & Newer
Lexus; GS430; 2007
Lexus; GS450h; 2007-2011
Lexus; GS450h; 2013-2016
Lexus; GS460; 2008-2011
Lexus; GS460; 2012-2016
Lexus; GX460; 2010-2015
Lexus; GX460; 2016
Lexus; GX470; 2006; Feb. & Newer
Lexus; GX470; 2007-2009
Lexus; HS250h; 2010-2012
Lexus; IS F; 2008-2015
Lexus; IS F; 2016
Lexus; IS250; 2006; Apr. 1 & Newer
Lexus; IS250; 2007
Lexus; IS250; 2008-2015
Lexus; IS250; 2016
Lexus; IS350; 2006; Apr. 1 & Newer
Lexus; IS350; 2007-2015
Lexus; IS350; 2016
Lexus; LFA; 2012
Lexus; LFA; 2016
Lexus; LS460; 2007-2016
Lexus; LS600h; 2008-2016
Lexus; LX470; 2006; Aug. & Newer
Lexus; LX470; 2007
Lexus; LX570; 2008-2011
Lexus; LX570; 2013-2014
Lexus; LX570; 2016
Lexus; RX330; 2006; Feb. & Newer
Lexus; RX350; 2007-2010
Lexus; RX350; 2011-2012
Lexus; RX350; 2013; exc F Sport
Lexus; RX350; 2014-2015
Lexus; RX400h; 2006
Lexus; RX400h; 2007-2008
Lexus; RX450h; 2010-2013
Lexus; RX450h; 2014-2015
Lexus; SC430; 2006; Aug. & Newer
Lexus; SC430; 2007-2010
Nissan; 370Z; 2010
Nissan; 370Z; 2011-2013
Pontiac; Vibe; 2008-2010
Scion; FR-S; 2013
Scion; FR-S; 2014-2016
Scion; iM; 2015-2016
Scion; iQ; 2012-2014
Scion; iQ; 2015
Scion; tC; 2006; May & Newer
Scion; tC; 2007-2014
Scion; tC; 2015-2016
Scion; xB; 2008-2014
Scion; xB; 2015-2016
Scion; xD; 2008-2014
Subaru; BRZ; 2013-2014
Subaru; BRZ; 2015-2016
Toyota; 4Runner; 2006; Jun. & Newer
Toyota; 4Runner; 2007
Toyota; 4Runner; 2008
Toyota; 4Runner; 2009
Toyota; 4Runner; 2010-2016
Toyota; Avalon; 2006; Aug. & Newer
Toyota; Avalon; 2007-2014
Toyota; Avalon; 2015-2016
Toyota; Camry; 2007-2011
Toyota; Camry; 2012-2014
Toyota; Camry; 2015
Toyota; Corolla; 2007; Jun. & Newer
Toyota; Corolla; 2008
Toyota; Corolla; 2009-2012
Toyota; Corolla; 2013
Toyota; Corolla; 2014
Toyota; Corolla; 2015-2016
Toyota; FJ Cruiser; 2008-2014
Toyota; FJ Cruiser; 2015
Toyota; Highlander; 2007; May & Newer
Toyota; Highlander; 2008-2010
Toyota; Highlander; 2011-2015
Toyota; Highlander; 2016
Toyota; Land Cruiser; 2006; Apr. 1 & Newer
Toyota; Land Cruiser; 2007-2011
Toyota; Land Cruiser; 2013-2014
Toyota; Land Cruiser; 2015
Toyota; Matrix; 2007; Jun. & Newer
Toyota; Matrix; 2008-2013
Toyota; Prius; 2005-2013
Toyota; Prius; 2014-2016
Toyota; RAV4; 2006; exc Electric
Toyota; RAV4; 2007-2011; exc Electric
Toyota; RAV4; 2012
Toyota; RAV4; 2013; exc Electric
Toyota; Solara; 2006; May & Newer
Toyota; Solara; 2007-2008
Toyota; Tacoma; 2006; Aug. & Newer
Toyota; Tacoma; 2007-2013
Toyota; Tacoma; 2014
Toyota; Tacoma; 2015
Toyota; Venza; 2009-2014
Toyota; Venza; 2015-2016
Toyota; Yaris; 2007; Aug. & Newer
Toyota; Yaris; 2008-2012
Toyota; Yaris; 2013

20035

Honda; Pilot; 2005; LX; W/Long Stem Valve; Includes Valve
Honda; Ridgeline; 2006; RT; Includes Valve
Honda; Ridgeline; 2007-2008; RT; Includes Valve

Numerical Listing

Service Pack

20036

Acura; MDX, RDX; 2004-2006; Includes Valve
Acura; RL; 2005-2012; Includes Valve
Acura; TL; 2005-2008; Includes Valve
Dodge; Sprinter; 2007-2009; Includes Valve
Freightliner; Sprinter; 2007-2008; Includes Valve
Freightliner; Sprinter; 2013; Includes Valve
Honda; Element; 2007-2008; Includes Valve
Honda; Odyssey; 2005-2007; Touring; Includes Valve
Honda; Odyssey; 2008; Includes Valve
Honda; Odyssey; 2008; Touring; Includes Valve
Honda; Odyssey; 2009-2010; Includes Valve
Honda; Pilot; 2005; EX; Includes Valve
Honda; Pilot; 2005; LX; W/Short Stem Valve; Includes Valve
Honda; Pilot; 2006-2008; Includes Valve
Honda; Ridgeline; 2006; RTL, RTS; Includes Valve
Honda; Ridgeline; 2007-2008; RTL, RTS, RTX; Includes Valve
Honda; Ridgeline; 2009; Includes Valve
Honda; Ridgeline; 2010; RT; Includes Valve
Honda; Ridgeline; 2011-2014; RT; Includes Valve
Hyundai; Accent; 2006-2007; Includes Valve
Hyundai; Azera; 2006; Includes Valve
Hyundai; Azera; 2007-2012; Includes Valve
Hyundai; Azera; 2013; Includes Valve
Hyundai; Elantra; 2007-2009; Includes Valve
Hyundai; Elantra; 2010; exc Touring; Includes Valve
Hyundai; Elantra; 2011; exc Touring; Includes Valve
Hyundai; Elantra; 2012; exc Touring; Includes Valve
Hyundai; Elantra; 2013; Includes Valve
Hyundai; Elantra Coupe; 2013; Includes Valve
Hyundai; Entourage; 2007-2009; Includes Valve
Hyundai; Santa Fe; 2007; Includes Valve
Hyundai; Santa Fe; 2008; Includes Valve
Hyundai; Santa Fe; 2009; Includes Valve
Hyundai; Sonata; 2007; Includes Valve
Hyundai; Sonata; 2008; Includes Valve
Hyundai; Tiburon; 2007-2008; Includes Valve
Hyundai; Tucson; 2006-2009; Includes Valve
Hyundai; Veracruz; 2006-2007; Includes Valve
Hyundai; Veracruz; 2008; Includes Valve
Hyundai; Veracruz; 2009-2012; Includes Valve
Kia; Amanti; 2007-2009; Includes Valve
Kia; Magentis; 2008; Includes Valve
Kia; Magentis; 2009; Includes Valve
Kia; Magentis; 2010; Includes Valve
Kia; Optima; 2006-2010; Includes Valve
Kia; Rondo; 2007-2011; Includes Valve
Kia; Sedona; 2006-2008; Includes Valve
Kia; Sedona; 2009-2012; Includes Valve
Kia; Sorento; 2007-2009; Includes Valve
Kia; Sportage; 2005; Jun. 15, 2005 & Newer; Includes Valve
Kia; Sportage; 2006-2008; Includes Valve
Mercedes-Benz; C Series; 2007; Includes Valve
Mercedes-Benz; C Series; 2008-2009; Includes Valve
Mercedes-Benz; CL; 2008-2009; Includes Valve
Mercedes-Benz; CLS; 2006; Includes Valve
Mercedes-Benz; CLS550; 2007-2011; Includes Valve
Mercedes-Benz; E320; 2006-2009; Includes Valve
Mercedes-Benz; E350; 2006-2009; Includes Valve
Mercedes-Benz; E500; 2006; Includes Valve
Mercedes-Benz; E55 AMG; 2006; Includes Valve
Mercedes-Benz; E550; 2007-2009; Includes Valve
Mercedes-Benz; E63 AMG; 2007-2009; Includes Valve
Mercedes-Benz; GL; 2007-2009; Includes Valve
Mercedes-Benz; GL320; 2007-2009; Includes Valve
Mercedes-Benz; ML320; 2007-2009; Includes Valve
Mercedes-Benz; ML350; 2006-2009; Includes Valve
Mercedes-Benz; ML500; 2006-2007; Includes Valve
Mercedes-Benz; ML550; 2008-2009; Includes Valve
Mercedes-Benz; ML63 AMG; 2007-2009; Includes Valve
Mercedes-Benz; R320; 2007-2009; Includes Valve
Mercedes-Benz; R350; 2006-2009; Includes Valve
Mercedes-Benz; R500; 2006-2007; Includes Valve
Mercedes-Benz; R63 AMG; 2007; Includes Valve
Mercedes-Benz; S Series; 2010; Includes Valve
Mercedes-Benz; S550; 2007-2010; Includes Valve
Mercedes-Benz; S600; 2007-2010; Includes Valve
Mercedes-Benz; S63 AMG; 2008-2010; Includes Valve
Mercedes-Benz; S65 AMG; 2007-2010; Includes Valve
Mercedes-Benz; SL500; 2006; Includes Valve
Mercedes-Benz; SL55 AMG; 2006-2008; Includes Valve
Mercedes-Benz; SL550; 2007-2009; Includes Valve
Mercedes-Benz; SL600; 2006-2009; Includes Valve
Mercedes-Benz; SL63 AMG; 2009; Includes Valve
Mercedes-Benz; SL65 AMG; 2006-2009; Includes Valve
Mercedes-Benz; SLR McLaren; 2008-2009; Includes Valve
Mercedes-Benz; Sprinter 2500; 2010; Includes Valve
Mercedes-Benz; Sprinter 2500; 2011-2012; Includes Valve
Mercedes-Benz; Sprinter 3500; 2010-2012; Includes Valve

Numerical Listing

Service Pack

20037 (W/43mm Silver Insert)

20038 (W/48mm Green Insert)

20039 (W/49mm Black Insert)

20040 (W/51mm Orange Insert)

Audi; A3, A4,A5 & Quattro; 2002-2007; W/48mm Green Insert
Audi; A3, A4,A5 & Quattro; 2008; W/48mm Green Insert
Audi; A6; 2002-2004; W/48mm Green Insert
Audi; A6; 2006-2008; W/48mm Green Insert
Audi; A6; 2009; W/48mm Green Insert
Audi; A6; 2010; W/48mm Green Insert
Audi; A6; 2011; W/48mm Green Insert
Audi; A6 Quattro; 2006-2008; W/48mm Green Insert
Audi; A6 Quattro; 2010; W/48mm Green Insert
Audi; A6 Quattro; 2011; W/48mm Green Insert
Audi; A8; 2000; W/48mm Green Insert
Audi; A8 Quattro; 2000-2002; W/48mm Green Insert
Audi; A8 Quattro; 2003; W/48mm Green Insert
Audi; A8 Quattro; 2004-2011; W/48mm Green Insert
Audi; Allroad Quattro; 2001-2005; W/48mm Green Insert
Audi; Q7; 2007-2009; W/48mm Green Insert
Audi; Q7; 2010; W/48mm Green Insert
Audi; Q7; 2011; W/48mm
Audi; Q7; 2012; W/48mm
Audi; R8; 2008-2009; W/48mm
Audi; R8; 2010; W/48mm
Audi; R8; 2011; W/48mm
Audi; R8; 2012; W/48mm
Audi; R8; 2014-2015; W/48mm
Audi; RS4; 2007-2008; W/48mm
Audi; RS6; 2003; W/48mm
Audi; RS7; 2014-2016; W/48mm
Audi; S4; 2002; W/48mm
Audi; S4; 2004-2009; W/48mm
Audi; S6; 2007-2009; W/48mm
Audi; S6; 2010; W/48mm
Audi; S6; 2011; W/48mm
Audi; S8; 2003; W/48mm
Audi; S8; 2004-2006; W/48mm
Audi; S8; 2007-2008; W/48mm
Audi; S8; 2009; W/48mm
Audi; S8; 2015; W/48mm
Bentley; Azure; 2007-2009; W/48mm
Bentley; Continental; 2003-2005; W/48mm
Bentley; Continental; 2006-2010; W/48mm
Bentley; Continental; 2012-2014; W/48mm
Bentley; Continental; 2015-2016; W/48mm
Bentley; Mulsanne; 2011-2015; W/48mm
Bentley; Mulsanne; 2016; W/48mm
BMW; 1 Series; 2008; W/48mm
BMW; 1 Series; 2009-2010; W/48mm
BMW; 1 Series; 2011-2013; W/48mm
BMW; 228i; 2014; W/48mm
BMW; 228i; 2015; W/48mm
BMW; 320i; 2001-2002; W/48mm
BMW; 320i; 2003-2005; W/48mm
BMW; 320i; 2014; W/48mm
BMW; 320i xDrive; 2014; W/48mm
BMW; 323Ci; 2000; W/48mm
BMW; 323i; 2000; W/48mm
BMW; 323i; 2003; W/48mm
BMW; 323i; 2006; W/48mm; Jun. & Newer BMW; 323i; 2007-2010; W/48mm
BMW; 325; 2001-2002; W/48mm
BMW; 325; 2003-2006; W/48mm
BMW; 325; 2007; W/48mm
BMW; 328Ci; 2000; W/48mm
BMW; 328d; 2014; W/48mm
BMW; 328d xDrive; 2014; W/48mm
BMW; 328i; 2000; W/48mm
BMW; 328i; 2007-2008; W/48mm
BMW; 328i; 2009; W/48mm
BMW; 328i; 2010-2013; W/48mm
BMW; 328i; 2014-2016; W/48mm
BMW; 328i GT xDrive; 2014-2016; W/48mm
BMW; 328i xDrive; 2009; W/48mm
BMW; 328i xDrive; 2010-2013; W/48mm
BMW; 328i xDrive; 2014-2015; W/48mm
BMW; 328xi; 2007-2008; W/48mm
BMW; 330; 2001-2002; W/48mm
BMW; 330; 2003-2006; W/48mm
BMW; 335d; 2009; W/48mm
BMW; 335d; 2010-2011; W/48mm
BMW; 335i; 2007-2008; W/48mm
BMW; 335i; 2009; W/48mm
BMW; 335i; 2010-2012; W/48mm
BMW; 335i; 2013-2014; W/48mm
BMW; 335i GT xDrive; 2014-2015; W/48mm
BMW; 335i xDrive; 2009; W/48mm
BMW; 335i xDrive; 2010-2012; W/48mm
BMW; 335i xDrive; 2013-2015; W/48mm
BMW; 335is; 2012-2013; W/48mm
BMW; 335xi; 2007-2008; W/48mm
BMW; 428i; 2014; W/48mm
BMW; 428i xDrive; 2014; W/48mm
BMW; 428i xDrive; 2015; W/48mm

Numerical Listing

BMW; 435i; 2014; W/48mm
BMW; 435i; 2015; W/48mm
BMW; 435i; 2016; W/48mm
BMW; 435i xDrive; 2014; W/48mm
BMW; 435i xDrive; 2015; W/48mm
BMW; 525i; 2001; W/48mm
BMW; 525i; 2002; W/48mm
BMW; 525i; 2003-2005; W/48mm
BMW; 525i; 2006-2007; W/48mm
BMW; 525xi; 2006-2007; W/48mm
BMW; 528; 1997-1998; W/48mm
BMW; 528; 1999-2000; W/48mm
BMW; 528; 2008; W/48mm
BMW; 528; 2009-2011; W/48mm
BMW; 528; 2012-2014; W/48mm
BMW; 528; 2015-2016; W/48mm
BMW; 528xi; 2008; W/48mm
BMW; 530; 2001; W/48mm
BMW; 530; 2002; W/48mm
BMW; 530; 2003-2005; W/48mm
BMW; 530; 2006-2007; W/48mm
BMW; 535; 2008-2010; W/48mm
BMW; 535; 2011; W/48mm
BMW; 535; 2012-2014; W/48mm
BMW; 535; 2015-2016; W/48mm
BMW; 535d; 2014; W/48mm
BMW; 535d; 2015-2016; W/48mm
BMW; 535d xDrive; 2014; W/48mm
BMW; 535d xDrive; 2015-2016; W/48mm
BMW; 535xi; 2008; W/48mm
BMW; 540i; 1997-1998; W/48mm
BMW; 540i; 1999-2000; W/48mm
BMW; 540i; 2001; W/48mm
BMW; 540i; 2002; W/48mm
BMW; 540i; 2003; W/48mm
BMW; 540i; 2008-2011; W/48mm
BMW; 540i; 2012-2016; W/48mm
BMW; 545i; 2004-2005; W/48mm
BMW; 550; 2006-2011; W/48mm
BMW; 550; 2012-2014; W/48mm
BMW; 550; 2015-2016; W/48mm
BMW; 640; 2012-2015; W/48mm
BMW; 640; 2016; W/48mm
BMW; 645Ci; 2004-2005; W/48mm
BMW; 650; 2006-2010; W/48mm
BMW; 650; 2012-2015; W/48mm
BMW; 650; 2016; W/48mm
BMW; 650i Gran Coupe xDrive; 2016; W/48mm
BMW; 740i; 1997-1998; W/48mm
BMW; 740i; 1999-2001; W/48mm
BMW; 740i; 2011; W/48mm
BMW; 740i; 2012-2014; W/48mm
BMW; 740i; 2015-2016; W/48mm
BMW; 740iL; 1997-1998; W/48mm
BMW; 740iL; 1999-2000; W/48mm
BMW; 740iL; 2001; W/48mm
BMW; 740Li; 2011; W/48mm
BMW; 740Li; 2012-2016; W/48mm
BMW; 740Li xDrive; 2013-2016; W/48mm
BMW; 745; 2002; W/48mm
BMW; 745; 2003; W/48mm
BMW; 745; 2004-2005; W/48mm
BMW; 750; 2006-2010; W/48mm
BMW; 750; 2011; W/48mm
BMW; 750; 2012-2016; W/48mm
BMW; 750iL; 1997-1998; W/48mm
BMW; 750iL; 1999-2000; W/48mm
BMW; 750iL; 2001; W/48mm
BMW; 760i; 2004-2005; W/48mm
BMW; 760i; 2006; W/48mm
BMW; 760Li; 2003; W/48mm
BMW; 760Li; 2004-2008; W/48mm
BMW; 760Li; 2010; W/48mm
BMW; 760Li; 2004-2008; W/48mm
BMW; 760Li; 2010; W/48mm
BMW; 760Li; 2011; W/48mm
BMW; 760Li; 2012-2014; W/48mm
BMW; 760Li; 2015; W/48mm
BMW; 760Li; 2016; W/48mm
BMW; ActiveHybrid 3; 2013-2014; W/48mm
BMW; ActiveHybrid 5; 2012-2014; W/48mm
BMW; ActiveHybrid 5; 2015; W/48mm
BMW; ActiveHybrid 7; 2013-2015; W/48mm
BMW; Alpina B7; 2007-2008; W/48mm
BMW; Alpina B7; 2011-2015; W/48mm
BMW; Alpina B7 xDrive; 2011; W/48mm
BMW; Alpina B7L; 2011; W/48mm
BMW; Alpina B7L xDrive; 2011; W/48mm
BMW; M; 2000-2001; W/48mm
BMW; M; 2002; W/48mm
BMW; M; 2003; W/48mm
BMW; M; 2004-2010; W/48mm
BMW; M; 2011-2012; W/48mm
BMW; M; 2013; W/48mm
BMW; M; 2014; W/48mm
BMW; M; 2015-2016; W/48mm
BMW; X; 1999-2004; W/48mm
BMW; X; 2005-2007; W/48mm
BMW; X; 2008-2010; W/48mm
BMW; X; 2011; W/48mm
BMW; X; 2012-2014; W/48mm
BMW; X; 2015; W/48mm
BMW; X; 2016; W/48mm
BMW; Z3; 2000-2002; W/48mm
BMW; Z4; 2003-2010; W/48mm
BMW; Z4; 2011; W/48mm
BMW; Z4; 2012-2015; W/48mm
BMW; Z4; 2016; W/48mm
BMW; Z8; 2000-2002; W/48mm
Bugatti; Veyron 16.4; 2006; W/48mm
Ferrari; 612 Scaglietti; 2004-2011; W/48mm
Ferrari; Enzo; 2003-2004; W/48mm
Ferrari; F430; 2006-2007; W/48mm
Ferrari; F430; 2008-2009; W/48mm
Ferrari; Maranello; 1998-2006; W/48mm
Land Rover; LR3; 2002-2005; W/48mm
Land Rover; Range Rover; 2002; W/48mm
Land Rover; Range Rover; 2003-2005; W/48mm
Maserati; Coupe; 2004-2006; W/48mm
Maserati; GranTurismo; 2014; W/48mm
Maserati; Quattroporte; 2004-2008; W/48mm
Maserati; Spyder; 2004-2006; W/48mm
Mercedes-Benz; C Series; 2001-2006; W/48mm
Mercedes-Benz; CL; 2000-2006; W/48mm
Mercedes-Benz; E320; 2001-2005; W/48mm
Mercedes-Benz; E430; 2001-2002; W/48mm
Mercedes-Benz; E500; 2003-2005; W/48mm
Mercedes-Benz; E55 AMG; 1999; W/48mm; Jul. & Newer
Mercedes-Benz; E55 AMG; 2000-2005; W/48mm
Mercedes-Benz; S Series; 2006; W/48mm
Mercedes-Benz; S430; 2000-2006; W/48mm
Mercedes-Benz; S500; 2000; W/48mm
Mercedes-Benz; S500; 2001; W/48mm
Mercedes-Benz; S500; 2002-2006; W/48mm
Mercedes-Benz; S55 AMG; 2001-2006; W/48mm
Mercedes-Benz; S600; 2001-2006; W/48mm
Mercedes-Benz; S65 AMG; 2006; W/48mm
Mercedes-Benz; SL500; 2000-2005; W/48mm
Mercedes-Benz; SL55 AMG; 2003; W/48mm
Mercedes-Benz; SL55 AMG; 2004; W/48mm
Mercedes-Benz; SL55 AMG; 2005; W/48mm
Mercedes-Benz; SL600; 2001-2002; W/48mm
Mercedes-Benz; SL600; 2004-2005; W/48mm

Numerical Listing

Mercedes-Benz; SL65 AMG; 2005; W/48mm
Mercedes-Benz; SLR McLaren; 2004-2006; W/48mm
Mercedes-Benz; SLR McLaren; 2007; W/48mm
Mini; Cooper; 2008-2009; W/48mm
Mini; Cooper; 2010-2013; W/48mm
Mini; Cooper; 2014; W/48mm
Mini; Cooper; 2015-2016; W/48mm
Porsche; 911; 2005-2006; W/48mm
Porsche; 911; 2007-2009; W/48mm
Porsche; 911; 2010; W/48mm
Porsche; 911; 2011; W/48mm
Porsche; 911; 2012; W/48mm
Porsche; 911; 2013-2014; W/48mm
Porsche; 911; 2015-2016; W/48mm
Porsche; 918 Spyder; 2015-2016; W/48mm
Porsche; Boxster; 2005-2007; W/48mm
Porsche; Boxster; 2008-2010; W/48mm
Porsche; Boxster; 2011; W/48mm
Porsche; Boxster; 2012-2013; W/48mm
Porsche; Boxster; 2014-2016; W/48mm
Porsche; Carrera GT; 2004-2005; W/48mm
Porsche; Cayenne; 2003-2006; W/48mm
Porsche; Cayenne; 2008-2010; W/48mm
Porsche; Cayenne; 2011-2013; W/48mm
Porsche; Cayenne; 2014-2016; W/48mm
Porsche; Cayman; 2005-2007; W/48mm
Porsche; Cayman; 2008; W/48mm
Porsche; Cayman; 2009-2010; W/48mm
Porsche; Cayman; 2011; W/48mm
Porsche; Cayman; 2012-2016; W/48mm
Porsche; Macan; 2016; W/48mm
Porsche; Macan; 2017; W/48mm
Porsche; Panamera; 2010; W/48mm
Porsche; Panamera; 2011; W/48mm
Porsche; Panamera; 2014; W/48mm
Rolls Royce; Ghost; 2011-2016; W/48mm
Rolls Royce; Phantom; 2007-2011; W/48mm
Rolls Royce; Phantom; 2012-2016; W/48mm
Rolls Royce; Silver Dawn; 2016; W/48mm
Rolls Royce; Wraith; 2014-2016; W/48mm
Volkswagen; Phaeton; 2004-2006; W/48mm
Volkswagen; Touareg; 2004-2006; W/48mm
Volkswagen; Touareg; 2007; W/48mm
Volkswagen; Touareg; 2008-2009; W/48mm
Volkswagen; Touareg; 2010; W/48mm
Volkswagen; Touareg; 2011-2013; W/48mm
Volkswagen; Touareg; 2014-2016; W/48mm

20043

Chrysler; 200; 2015-2016
Dodge; Dart; 2013-2016
Jeep; Renegade; 2015-2016

20046

Hyundai; Sonata; 2015-2016; Rubber Valve
Hyundai; Tucson; 2015-2016; Rubber Valve
Kia; Sedona; 2015-2016; Rubber Valve
Kia; Sedona; 2017; Rubber Valve
Kia; Soul; 2014
Kia; Soul; 2015-2016; Rubber Valve

20047

Chevrolet; Caprice; 2014
Chevrolet; Caprice; 2015
Chevrolet; Corvette; 2014-2015
Chevrolet; Corvette; 2016
Maserati; Ghibli; 2014-2016
Maserati; Quattroporte; 2014-2016

Numerical Listing

Service Pack

20049

Mercedes-Benz; B200; 2014
Mercedes-Benz; B200; 2015-2016
Mercedes-Benz; B200; 2017
Mercedes-Benz; B250; 2015
Mercedes-Benz; B250; 2016
Mercedes-Benz; B250; 2017
Mercedes-Benz; C Series; 2014-2015
Mercedes-Benz; C Series; 2016-2017
Mercedes-Benz; C250; 2014-2017
Mercedes-Benz; CLA250; 2014-2016
Mercedes-Benz; CLA250; 2017
Mercedes-Benz; CLA45 AMG; 2014-2016
Mercedes-Benz; CLA45 AMG; 2017
Mercedes-Benz; CLS550; 2014-2016
Mercedes-Benz; CLS63 AMG S; 2014-2016
Mercedes-Benz; E250; 2014-2016
Mercedes-Benz; E250; 2017
Mercedes-Benz; E350; 2014-2016
Mercedes-Benz; E350; 2017
Mercedes-Benz; E400; 2014-2016
Mercedes-Benz; E400; 2017
Mercedes-Benz; E550; 2014-2016
Mercedes-Benz; E550; 2017
Mercedes-Benz; E63 AMG; 2014-2016
Mercedes-Benz; E63 AMG; 2017
Mercedes-Benz; E63 AMG S; 2014-2016
Mercedes-Benz; E63 AMG S; 2017
Mercedes-Benz; G550; 2014-2016
Mercedes-Benz; G550; 2017
Mercedes-Benz; G63 AMG; 2014-2016
Mercedes-Benz; G63 AMG; 2017
Mercedes-Benz; GL; 2014-2016
Mercedes-Benz; GL; 2017
Mercedes-Benz; GL350; 2014-2015
Mercedes-Benz; GL350; 2016
Mercedes-Benz; GL350; 2017
Mercedes-Benz; GL63 AMG; 2014-2016
Mercedes-Benz; GL63 AMG; 2017
Mercedes-Benz; GLK250; 2014-2016
Mercedes-Benz; GLK250; 2017
Mercedes-Benz; GLK350; 2014-2016
Mercedes-Benz; GLK350; 2017
Mercedes-Benz; ML350; 2015
Mercedes-Benz; ML350; 2016
Mercedes-Benz; ML350; 2017
Mercedes-Benz; ML550; 2015-2016
Mercedes-Benz; ML550; 2017
Mercedes-Benz; ML63 AMG; 2014-2016
Mercedes-Benz; ML63 AMG; 2017
Mercedes-Benz; S Series; 2013
Mercedes-Benz; S Series; 2014-2016
Mercedes-Benz; S Series; 2017
Mercedes-Benz; S550; 2014-2016
Mercedes-Benz; S550; 2017
Mercedes-Benz; S600; 2014-2016
Mercedes-Benz; S600; 2017
Mercedes-Benz; S63 AMG; 2014-2016
Mercedes-Benz; S63 AMG; 2017
Mercedes-Benz; SL550; 2014-2016
Mercedes-Benz; SL63 AMG; 2014-2015
Mercedes-Benz; SL63 AMG; 2016
Mercedes-Benz; SL65 AMG; 2014-2016
Mercedes-Benz; SLK250; 2014-2016
Mercedes-Benz; SLK250; 2017
Mercedes-Benz; SLK350; 2014-2016
Mercedes-Benz; SLK350; 2017
Mercedes-Benz; SLK55 AMG; 2014
Mercedes-Benz; SLK55 AMG; 2015-2017
Mercedes-Benz; SLS AMG; 2014-2015
Smart; Fortwo; 2014
Smart; Fortwo; 2015-2016
Smart; Fortwo; 2017

20635

Jeep; Cherokee; 2014
Jeep; Cherokee; 2015; Rubber Valve
Jeep; Cherokee; 2016-2017; Rubber Valve
Ram; Ram Series; 2014-2015
Ram; Ram Series; 2016-2017

NOTES

NOTES

NOTES

NHTSA TREAD Act

The Transportation Recall Enhancement, Accountability and Documentation (TREAD) Act was passed in the fall of 2000. The TREAD Act mandated that every new car manufactured for sale in the U.S. after September 1, 2007 must be equipped with sensors that monitor the pressure in all four tires. Sensors installed in the vehicle's wheels send a signal via RF to the vehicle's computer. The computer then processes the sensor data to alert the driver if pressure drops 25% below the specified cold placard pressure for the tire.



DID YOU KNOW

- 40% tire under-inflation increases braking distance by 10%.
- If every vehicle in the United States had properly inflated tires, we'd realize a savings of 4 million gallons of gasoline per day, everyday.
- An estimated 23,000 accidents and 535 fatal accidents annually involve blowouts or flat tires.
- 20% tire under-inflation reduces tire life by 20% and reduces fuel economy by 2% to 3%.
- Approximately 27% of passenger cars and 33% of light trucks on U.S. roadways are driven with one or more tires substantially under-inflated.



Schrader
1940 Opdyke Court
Auburn Hills, MI 48326

Customer Support // 1.800.288.1804
E-mail // *techsvc@schraderintl.com*

Visit our websites:
- *EZ-sensor.com*
- *TPMSMadeEasy.com*
- *Sensata.com*

TPMS-CAT 100116

Sensata Technologies

The World Depends on Sensors and Controls

SCHRADER® PERFORMANCE SENSORS