

▶▶ **Schrader TPMS Service Kit 20021**

Schrader Customer Bulletin

Release Date: July 2, 2013

Doc. No.: CSB -2013-02

This bulletin serves as notice to all Schrader customers that Schrader will no longer be supplying TPMS service kits 20021, 20021-10 or 20021-25 for servicing the applicable adjustable angle stem sensors.

Schrader has made this application decision based upon the OEM valve and sensor supplier requirements. Both the valve and sensor manufacturer state that if the valve is removed from the rim, it must be replaced with a new valve, and the 20021 service kit does not contain a valve.

In place of ordering the 20021 service kit, Schrader already offers TPMS service kits 20035 and 20036. These kits contain the same cap, core, grommet and nut with the addition of the proper aluminum valve stem, providing all of the required replacement service components.



20021 Service Kit
DO NOT ORDER



20035 Kit w/ long valve
(Grommet & core installed)
ORDER IN PLACE OF 20021*



20036 Kit w/ short valve
(Grommet & core installed)
ORDER IN PLACE OF 20021*

**Reference the Schrader TPMS Application Catalog for all sensor and service pack applications.*

For more information on TPMS service and access to all Schrader bulletins please visit our website at
www.Schrader-eLearning.com

For information on this bulletin contact us by Email at
aftermarketsupportNA@schraderintl.com